

Messrs Grab Rentals Pte Ltd

Estimate To Repair Mazda3 4-Door Sedan 1.5L SP
Vehicle No : SLQ9323C
Chassis No : JM6BN22A8H0151597

*not about
run
1/5 3000
4/5
18/12/17
take pre. Appr*

LKK Auto Consultants hence notify
Third Party Insurer following: **AIG**
• To resurvey before after spray painting **SLG7565L**
• To display damaged part(s) during resurvey
• Date of accident : **10.12.2017**
• Third party survey is on a "Without Prejudice" basis
• No legal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Date: **12.12.2017**

Acknowledged by Repairer
Signature: *LKK Mar 0945*
Date: *12/12/17*

Pages : 1 of 1

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	n/s rear door <i>Body</i>	\$ 1,006.00	\$ 1,006.00
2	1 pc	n/s rear door weatherstirp <i>run</i>	\$ 121.00	\$ 121.00
3	1 pc	n/s rear door window glass channel weatherstirp <i>run</i>	\$ 117.00	\$ 117.00
4	1 pc	n/s rear door outer weatherstirp moulding <i>run</i>	\$ 140.00	\$ 140.00
5	1 pc	n/s rear door inner lock <i>run</i>	\$ 180.00	\$ 180.00
6	1 pc	n/s rear door inner lock striker <i>run</i>	\$ 26.00	\$ 26.00
7	1 pc	n/s rear door 1/4 glass pillar <i>run</i>	\$ 110.00	\$ 110.00
8	1 pc	n/s rear door 1/4 glass pillar weatherstirp <i>run</i>	\$ 41.00	\$ 41.00
9	1 pc	n/s rear door inner trimboard <i>run</i>	\$ 424.00	\$ 424.00
10	1 pc	n/s rear door power window motor <i>Shut</i>	\$ 290.00	\$ 290.00
11	1 pc	n/s rear door regulator <i>Best</i>	\$ 120.70	\$ 120.70
12	1 pc	n/s rear fender <i>n</i>	\$ 1,175.00	\$ 1,175.00
13	1 pc	rear windshield glass weatherstrip <i>run</i>	\$ 117.00	\$ 117.00
14	1 pc	rear bumper <i>Deep cut</i>	\$ 1,075.00	\$ 1,075.00
15	1 pc	rear bumper side retainer n/s <i>run</i>	\$ 46.00	\$ 46.00
16	10 ps	rear bumper clip <i>run</i>	\$ 5.00	\$ 50.00
				\$ 5,038.70
Less 20 %				\$ 1,007.74
<i>rear wheel hub cap guard - 80</i>				\$ 4,030.96
SPECIAL NETT ITEMS				
17	1 pc	rear windshield glass sealant <i>run</i>	\$ 180.00	\$ 180.00
18	1 pc	rear windshield glass sponge seal <i>run</i>	\$ 100.00	\$ 100.00
				\$ 280.00
LABOUR & MISC. CHARGES				
1		To remove and refit rear windscreen glass. <i>run</i>	\$ 180.00	\$ 180.00
2		To reinstall of rear bumper parking sensor. <i>50</i>	\$ 120.00	\$ 120.00
3		To rust-proofing of the affected areas. <i>50</i>	\$ 150.00	\$ 150.00
4		To check electrical lighting concerned. <i>20</i>	\$ 60.00	\$ 60.00
5		To transfer of doors fittings and perform water seepage test. <i>60</i>	\$ 150.00	\$ 150.00
6		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. <i>600</i>	\$ 850.00	\$ 850.00
7		Putty and spray painting of the affected portion. <i>750</i>	\$ 800.00	\$ 800.00
				\$ 2,310.00
Grand Total				\$ 6,620.96

*2788.7
2230.96
3760.96*

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216