



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

NO. : 32219

DATE : 14/12/2017
CLAIM NO. : 11071
POLICY NO. :
FROM : RAYMOND

VEHICLE NO. : FBL7512G
MAKE/MODEL : SYM / MAXSYM 400I CVT

*Not Admin
for
Raymond. Attorney
P/L
S.L.
18/12/17*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 29008	REPLACE	1.00	\$37.00	37.00 ✓
2	BAR HANDLE	REPLACE	1.00	\$52.00	52.00 ✓
3	BOX FR-INNER P/N: 55078	REPLACE	1.00	\$66.00	66.00 ✓
4	BOX REAR (GIVI) V56N MAXIA 4 P/N: 54026	REPLACE	1.00	\$875.00	875.00 ✓
5	CAMERA (V_SYS) M6 (NON-WIFI VERSION) P/N: 55576	REPLACE	1.00	\$378.00	378.00 ?
6	COVER GARNISH FRONT RH P/N: 55474	REPLACE	1.00	\$6.00	6.00 ✓
7	COVER L-BODY ASSY	REPLACE	1.00	\$195.00	195.00 ✓
8	COVER RR ASSY P/N: 55084	REPLACE	1.00	\$82.00	82.00 ✓
9	COVER R-SIDE ASSY P/N: 55087	REPLACE	1.00	\$110.00	110.00 ✓
10	COVER TAIL REAR RH	REPLACE	1.00	\$9.00	9.00 ?
11	COVER WINDSHIELD LOWER	REPLACE	1.00	\$35.00	35.00 ✓
12	CUSHION ASSY RR P/N: 55070	REPLACE	2.00	\$240.00	480.00 ?
13	DAMPER BOX INNER LID	REPLACE	1.00	\$12.00	12.00



S/N	Description	Action	Qty	Unit Price	Amount
14	DAMPER COVER TAIL RH	REPLACE	1.00	\$3.00	3.00 ?
15	DOUBLE SEAT COMP P/N: 55086	REPLACE	1.00	\$556.00 <i>one/215</i>	556.00
16	EXH.MUFFLER ASSY P/N: 55107	REPLACE	1.00	\$2,548.00 <i>20</i>	2,548.00
17	FRONT UNDER SPOILER P/N: 55352	REPLACE	1.00	\$262.00 <i>200/217</i>	262.00
18	GRIP HANDLE RH	REPLACE	1.00	\$14.00 <i>70.0</i>	14.00
19	INNER BOX 4D P/N: 55088	REPLACE	1.00	\$66.00	66.00 ?
20	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install <i>↓</i>	15.00	\$35.00 <i>450</i>	525.00
21	LICENCE LIGHT ASSY P/N: 55054	REPLACE	1.00	\$24.00	24.00 ?
22	LIGHT L-TAIL ASSY P/N: 55105	REPLACE	1.00	\$273.00 <i>520</i>	273.00
23	LUGGAGE BOX STAY	REPLACE	1.00	\$9.00 <i>9.00</i>	9.00
24	METER PANEL BK-001U P/N: 55090	REPLACE	1.00	\$32.00 <i>32.00</i>	32.00
25	MIRROR LH	REPLACE	1.00	\$147.00 <i>147</i>	147.00 X
26	MIRROR RH	REPLACE	1.00	\$147.00 <i>147</i>	147.00
27	PANEL RH- FLOOR P/N: 55065	REPLACE	1.00	\$42.00 <i>42.00</i>	42.00
28	RR FENDER BK 001U P/N: 55057	REPLACE	1.00	\$48.00 <i>48.00</i>	48.00
29	RR-CAST WHEEL COMP P/N: 55056	REPLACE	1.00	\$534.00	534.00 ?
30	SIDE DEFLEY REFLECTOR P/N: 55097	REPLACE	1.00	\$9.00	9.00 ?
31	SPRAY PAINTING (Whole Bike)	Spray <i>✗</i>	1.00	\$750.00 <i>600</i>	750.00
32	STICKER (ORANGEFORCE) BOX REAR NEW P/N: 54254	REPLACE	1.00	\$50.00 <i>50.00</i>	50.00
33	STICKER (ORANGEFORCE) COVER SIDE NEW P/N: 54256	REPLACE	2.00	\$70.00 <i>70.00</i>	140.00
34	STICKER(ORANGEFORCE) WINDSHIELD NEW P/N: 54253	REPLACE	2.00	\$70.00 <i>70.00</i>	140.00



S/N	Description	Action	Qty	Unit Price	Amount
35	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2A P/N: 45835 - TOW BACK FOR ACCIDENT REPAIR.		1.00	\$55.00	35 55.00
36	VALVE RIM P/N: 55062	REPLACE	1.00	\$9.00	? 9.00
37	WINDSCREEN SET	REPLACE	1.00	\$230.00	cu 230.00
SUB TOTAL					\$8,950.00
GST @ 7 %					\$626.50
GRAND TOTAL					\$9,576.50

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

