

CASE OWNER: Ming Yao

CC 61AIG17023948 / Uka35

LKK:

IDAC:

Surveyor: MARCUSDOI: 18/12/17Date / Time: 18/12/17Registered in Merimen: 18/12/17

Pre-assign / CCU / FTE

Insured Vehicle No.: SLR 9760TName of Insured: CHUN JIAK LUI

Insured Tel No.: _____

Excess Sec II :SS _____

Is driver the owner? (YES / NO)

Nature of Accident: _____

If NO, Driver Name / Age: JONATHAN FOO JIA HAODriver Tel No.: 9822 7464

(V/L: YES / NO)

Claim No.: 5173562564SGPolicy No.: 1700046817Make / Model: AUDI A3 SEDAN 1.0 TFSIPlace of Accident: ALONG PIE (TWS) NEAR ADAM EXITOI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SHB 2244USLR 9760TSJJ 7275GOTTP

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP: Kim Chwee

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

Date / Time	STAGE	DATE / PIC
20/12/17 (2am)	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler	Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

RECEIVED 10 JAN 2018

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS	() days	Reduction: %
FINAL SETTLEMENT		Date/Time: 09/01/2018	Confirm with: JASON
Final Liability:	% 100	(Agreed / Assessed)	BOLA S/N No.: 28
Repair Cost: (with ST)	SS 6,206.00		
Loss of Rental (LOR):	SS 500.00	(5 days)	x \$100.00
Loss of Use (LOU):	SS	(\$)	x days
Loss of Income (LOI):	SS	(\$)	x days
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	SS		
Medical:	SS		
Disbursement:	SS		
Legal Cost	SS		
Total:	SS 6,706.00	Global Sum SS:	
FINAL PAYMENT		Date/Time: 09/01/2018	Confirm with: Jason
Payee 1:	SS 6,706.00	Name 1:	Kim Chwee Auto pte. Ltd.
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 4320 + \$20.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG17023948/Uka3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 18-12-2017		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLR 9760T	Veh. Inspected	SJJ 7275G	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	18/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damage:				
5. General Information				
Accident Date	15/12/2017	Inspection Date	18/12/2017	
Survey held at	KIM CHWEE AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

not added
 1/5 \$5800
 5 day.
 18/11/17

KIM CHWEE AUTO PTE LTD

VEHICLE NO : SJJ7275G

QTY	PARTICULAR	AMOUNT S\$
-----	------------	------------

LIST ITEMS :

1PCS	REAR WINDSCREEN MOULDING
1PCS	TAILGATE
1PCS	TAIGATE 'SUBARU' EMBLEM
1PCS	TAILGATE ' IMPREZA' EMBLEM
2PCS	TAILGATE REFLECTORS @\$266
1PCS	TAILGATE INNER LOCK
1PCS	TAILAGATE INNER TRIM BOARD
1SET	TAILGATE INNER TRIM BOARD CLPS
1PCS	TAILGATE WEATHERSTRIPS
1PCS	REAR BUMPER
1PCS	REAR BUMPER REINFORCEMENT
2PCS	REAR BUMPER SIDERETAINERS @32.50
1SET	REAR BUMPER CLIPS
2PCS	REAR BUMPER REFLECTORS @\$38
1PCS	REAR BUMPER LOWER BRACKET
2PCS	TAILLAMPS @\$416.30
1PCS	REAR END PANEL
1PCS	REAR END PANEL TOP GARNISH
1PCS	REAR FLOOR PANEL TOP BOARD
1PCS	REAR FLOOR PANEL
2PCS	REAR FLOOR PANEL TOP SIDE SPONGES @245
1PCS	REAR EXHAUST 765.
2PCS	REAR EXHAUST MOUNTINGES @35.00
2PCS	REAR FENDER @991
2PCS	REAR FENDER INNER TRIM BOARDS @325

rec	\$68.00	—
sub	\$1,148.30	—
rec	\$49.00	—
rec	\$48.00	—
11	\$532.00	X
Page	\$145.20	✓
11	\$322.10	X
rec	\$45.00	—
twi	\$172.00	—
DIS	\$689.00	—
sub	\$245.00	—
sub	\$65.00	—
rec	\$50.00	—
11	\$76.00	X
sub	\$45.00	—
one	\$832.60	—
sub	\$395.40	—
twi	\$146.80	—
20	\$425.00	—
11	\$685.00	X
700	\$490.00	—
20	\$820.00	—
rec	\$70.00	—
11	\$1,982.00	X
11	\$650.00	X

TOTAL : \$10,196.40
 40 5894.3
 4715.14

(2020)

SPECIAL NETT ITEMS :

1SET	REAR BUMPER REVERSE SENSOR
1PCS	REAR END PANEL SEALANT
1PCS	REAR WINDSCREEN SEALANT
1PCS	REAR LICENCE PLATE W/HOLDER
1PCS	REAR FLOOR PANEL INSULATOR

shut	\$300.00	200
rec	\$50.00	✓
rec	\$50.00	40
11	\$50.00	X
11	\$300.00	X

LABOUR CHARGES :

TO CHECK WIRING
TO DISMENTLE & REPLACE REVERSE SEENSOR
TO DISMENTLE & REFIX REAR WINDSCREEN
TO DISMENTLE & REFIX SEAT CUSHION UPHOLSTERY

\$80.00	30
\$80.00	10
\$150.00	120
\$150.00	80

TO TRANSFER TAILGATE MECHANISM

\$100.00 60

TO DISMANTLE & REPLACE REAR EXHAUST

\$100.00 60

TO SPRAY ANTI RUST PROOFING

\$100.00 60

TO CONDUCT CHASSIS ALIGNMENT

11 \$380.00 X

LABOUR FOR PANEL BEATING , CUT , WEILD , STRAIGHTEN & REPLACE PARTS

\$1,500.00 800

TO PUTTY AND SPRAY PAINTING

\$1,500.00 1100

TOTAL : \$15,086.60

40

786.40

5892

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Zaini (LKK Auto)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Friday, 5 January 2018 3:24 PM
To: Zaini (LKK Auto)
Cc: Hsiao Tong (LKKAuto)
Subject: RE: Your Ref: SJJ 7275G_ACCIDENT INVOLVING SLR 9760T / SJJ 7275G / OTHERS ON 15/12/2017

Follow Up Flag: Follow up
Flag Status: Flagged

Without Prejudice

Dear Zaini,

We are pleased to accept your offer of \$ 6,706.00 all in.

Thank you.

Best Regards

Jason Tang
Fastech Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Zaini (LKK Auto) [mailto:Zaini@lkkauto.com]
Sent: Friday, January 5, 2018 3:00 PM
To: jason@fastechauto.com.sg
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Your Ref: SJJ 7275G_ACCIDENT INVOLVING SLR 9760T / SJJ 7275G / OTHERS ON 15/12/2017

Your Ref: SJJ 7275G
Our Ref: CC6/AIG17023948/Uka3

Without Prejudice

Dear Jason,

ACCIDENT INVOLVING SLR 9760T / SJJ 7275G / OTHERS ON 15/12/2017

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 6,206.00
2. Loss of Rental(5days x \$100.00)	\$ 500.00
3. LTA/GIA Search Fee	\$ (Wrong DOA)
TOTAL	<u>\$ 6,706.00</u>

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Dec 2017 Edit Reg		18 Dec 2017 00:00 Edit Adj Rpt	S\$5,800.00 Edit Estimates	S\$5,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured: CHUN JIOK LUI , ID: S1769078G, Tel: +6598227464									
Main Claimant: SEOW MIN KEONG , ID: S1431991C									
Vehicle Reg. No.: SJJ7275G		Date of Loss: 15/12/2017 00:00 - :59							
Claim Type: TP / 5173562564SG		Policy/Cover Note No.: 1700046817							
Vehicle Reg. No. (Insured): SLR9760T		Policy No. (Claimant): 5094301260CLASSIC							
Excess:									
Repairer: Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 28/12/2017]									
Driver/Custodian (Insured): JONATHAN FOO JIA HAO (), NRIC: S1769078G									
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
• AIG_SG (19/12/2017): TP GIA REPORT									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJJ7275G (5173562564SG)**
[SLR9760T]

TP
SEOW MIN KEONG
Dec 15 2017 12:00AM
[CHUN JIOK LUI]
Kim Chwee Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser v	
Letters/Correspondences			1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	
Assessment Reports			1 per page v ☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	19/12/17 11:30	Accident Statement From: SC - Reg. No: SLR9760T, Claimant: CHUN JIOK LUI	 Load HTM	
Photos/Images			3 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 18:45	Odometer Reading	 Load JPG	☒
2	18/12/17 18:45	General View	 Load JPG	☒
3	18/12/17 18:45	Chassis Number	 Load JPG	☒
4	18/12/17 18:45	General View	 Load JPG	☒
5	18/12/17 18:45	General View	 Load JPG	☒
6	18/12/17 18:45	General View	 Load JPG	☒
7	18/12/17 18:45	General View	 Load JPG	☒
8	18/12/17 18:45	General View	 Load JPG	☒
9	18/12/17 18:45	General View	 Load JPG	☒
10	18/12/17 18:45	General View	 Load JPG	☒
11	18/12/17 18:45	General View	 Load JPG	☒
12	18/12/17 18:45	General View	 Load JPG	☒
13	18/12/17 18:45	General View	 Load JPG	☒
14	18/12/17 18:45	General View	 Load JPG	☒
15	18/12/17 18:45	General View	 Load JPG	☒
16	18/12/17 18:45	General View	 Load JPG	☒
17	18/12/17 18:45	General View	 Load JPG	☒
18	18/12/17 18:46	General View	 Load JPG	☒
19	18/12/17 18:46	General View	 Load JPG	☒
20	18/12/17 18:46	General View	 Load JPG	☒
21	18/12/17 18:46	General View	 Load JPG	☒
22	18/12/17 18:46	General View	 Load JPG	☒
23	18/12/17 18:46	General View	 Load JPG	☒
24	18/12/17 18:46	General View	 Load JPG	☒
25	18/12/17 18:46	General View	 Load JPG	☒
26	18/12/17 18:46	General View	 Load JPG	☒
27	18/12/17 18:46	General View	 Load JPG	☒
28	18/12/17 18:46	General View	 Load JPG	☒

29	18/12/17 18:46	General View		Load JPG	☒
30	18/12/17 18:46	General View		Load JPG	☒
31	18/12/17 18:46	General View		Load JPG	☒
32	18/12/17 18:46	General View		Load JPG	☒
33	18/12/17 18:46	General View		Load JPG	☒
34	18/12/17 18:46	General View		Load JPG	☒
35	18/12/17 18:46	General View		Load JPG	☒
36	18/12/17 18:46	General View		Load JPG	☒
37	18/12/17 18:46	General View		Load JPG	☒
38	18/12/17 18:46	General View		Load JPG	☒
39	18/12/17 18:46	General View		Load JPG	☒
40	18/12/17 18:46	General View		Load JPG	☒
41	18/12/17 18:46	General View		Load JPG	☒
42	18/12/17 18:46	General View		Load JPG	☒
43	18/12/17 18:46	General View		Load JPG	☒
44	18/12/17 18:46	General View		Load JPG	☒
45	18/12/17 18:46	General View		Load JPG	☒
46	18/12/17 18:46	General View		Load JPG	☒
47	18/12/17 18:46	General View		Load JPG	☒
48	18/12/17 18:46	Reinspection Photo		Load JPG	☒
49	18/12/17 18:46	Reinspection Photo		Load JPG	☒
50	18/12/17 18:46	Reinspection Photo		Load JPG	☒
51	18/12/17 18:46	Reinspection Photo		Load JPG	☒
52	18/12/17 18:46	Reinspection Photo		Load JPG	☒
53	18/12/17 18:46	Reinspection Photo		Load JPG	☒
54	18/12/17 18:46	Reinspection Photo		Load JPG	☒
55	18/12/17 18:46	Reinspection Photo		Load JPG	☒
56	18/12/17 18:46	Reinspection Photo		Load JPG	☒
57	18/12/17 18:46	Reinspection Photo		Load JPG	☒
58	18/12/17 18:46	Reinspection Photo		Load JPG	☒
59	18/12/17 18:46	Reinspection Photo		Load JPG	☒
60	18/12/17 18:46	Reinspection Photo		Load JPG	☒
61	18/12/17 18:46	Reinspection Photo		Load JPG	☒
62	18/12/17 18:46	Reinspection Photo		Load JPG	☒
63	18/12/17 18:46	Reinspection Photo		Load JPG	☒
64	18/12/17 18:46	Reinspection Photo		Load JPG	☒
65	18/12/17 18:46	Reinspection Photo		Load JPG	☒
66	18/12/17 18:46	Reinspection Photo		Load JPG	☒
67	18/12/17 18:46	Reinspection Photo		Load JPG	☒
68	18/12/17 18:46	Reinspection Photo		Load JPG	☒
69	18/12/17 18:46	Reinspection Photo		Load JPG	☒
70	18/12/17 18:46	Reinspection Photo		Load JPG	☒
71	18/12/17 18:46	Reinspection Photo		Load JPG	☒
72	18/12/17 18:46	Reinspection Photo		Load JPG	☒
73	18/12/17 18:46	Reinspection Photo		Load JPG	☒
74	18/12/17 18:46	Reinspection Photo		Load JPG	☒
75	18/12/17 18:46	Reinspection Photo		Load JPG	☒
76	18/12/17 18:46	Reinspection Photo		Load JPG	☒
77	18/12/17 18:46	Reinspection Photo		Load JPG	☒
78	18/12/17 18:46	Reinspection Photo		Load JPG	☒

79	18/12/17 18:46	Reinspection Photo		Load JPG	☒
80	18/12/17 18:46	Reinspection Photo		Load JPG	☒
81	18/12/17 18:46	Reinspection Photo		Load JPG	☒
82	18/12/17 18:46	Reinspection Photo		Load JPG	☒
83	18/12/17 18:46	Reinspection Photo		Load JPG	☒
84	18/12/17 18:46	Reinspection Photo		Load JPG	☒
85	18/12/17 18:46	Reinspection Photo		Load JPG	☒
86	18/12/17 18:46	Reinspection Photo		Load JPG	☒
87	18/12/17 18:46	Reinspection Photo		Load JPG	☒
88	18/12/17 18:46	Reinspection Photo		Load JPG	☒
89	18/12/17 18:46	Reinspection Photo		Load JPG	☒
90	18/12/17 18:46	Reinspection Photo		Load JPG	☒
91	18/12/17 18:46	Reinspection Photo		Load JPG	☒
92	18/12/17 18:46	Reinspection Photo		Load JPG	☒
93	18/12/17 18:46	Reinspection Photo		Load JPG	☒
94	18/12/17 18:46	Reinspection Photo		Load JPG	☒
95	09/01/18 15:25	Reinspection Photo		Load JPG	☒
96	09/01/18 15:25	Reinspection Photo		Load JPG	☒
97	09/01/18 15:25	Reinspection Photo		Load JPG	☒
98	09/01/18 15:25	Reinspection Photo		Load JPG	☒

Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/12/17 09:47	TP GIA REPORT	Load PDF	
2	18/01/18 09:41	AUTHORISATION TO ACT	Load PDF	
3	18/01/18 09:41	LETTER TO OI	Load PDF	
4	18/01/18 09:42	RELEASE VOUCHER	Load PDF	
5	18/01/18 09:42	RENTAL RECEIPT	Load PDF	
6	18/01/18 09:42	WORKSHOP INVOICE	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLR9760T (Insd veh)	Model:	SUBARU IMPREZA 5D 1.5 R
	SJJ7275G (TP veh)		AWD (A)
Date of Accident:	15/12/2017		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	16,142.45
Final Repair Cost	:	\$	6,206.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	500.00 5 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum	:	\$	6,706.00

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kim Chwee Auto Pte Ltd	:	\$ 6,706.00
2)		:	\$

NUR SHAQILAH BTE ABDOL
WAHAB

LKK Auto Consultants Pte Ltd

18 Jan
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17023948/UKA3S2

Date: 18/01/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700046817
 Claimant Vehicle No: SJJ7275G Insured Vehicle No: SLR9760T
 Date of Loss: 15/12/2017 Nature of Claim: TP Claim No: 5173562564SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJJ7275G
 Make & Model: SUBARU IMPREZA 5D, 1.5 R AWD (A) Engine No: EL15D417226
 Reg. Date: 24/09/2008 (Man. Year: 2008) Chassis No: JF1GH3KS58G018122
 Colour: Red Odometer: 126164 km
 Engine Capacity: 1498 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,946.40	5,005.44	5,940.96	54.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,140.00	2,360.00	1,780.00	43.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,086.40	7,365.44	7,720.96	51.18
Approved Total (Overridden) (\$\$)		5,800.00		
(\$\$)	15,086.40	5,800.00	9,286.40	61.55
+ GST 7.00/7.00% (\$\$)	1,056.05	406.00	650.05	61.55
Nett Amount (\$\$)	16,142.45	6,206.00	9,936.45	61.55
+ Car Rental (5.0 x S\$100.00/day) (\$\$)		500.00		
Nett Liability (\$\$)		6,706.00		

INSPECTION

Date of Assignment: 18/12/2017
 Date Inspected: 18/12/2017 Inspected At:

Kim Chwee Auto Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6 #01-48,
 AutoBay@Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Zaini Bin Kusaini

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	68.00 F	*68.00 FL
2	1		*TAILGATE	Badly Dented	1,148.30 F	*1,148.30 FL
3	1		*TAILGATE SUBARU EMBLEM	Necessary	49.00 F	*49.00 FL
4	1		*TAILGATE IMPREZA EMBLEM	Necessary	48.00 F	*48.00 FL
5	2		*TAILGATE REFLECTORS	Not Necessary	532.00 F	*- FL
6	1		*TAILGATE INNER LOCK	Damaged	145.20 F	*145.20 FL
7	1		*TAILGATE INNER TRIM BOARD	Not Necessary	322.10 F	*- FL
8	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	45.00 F	*45.00 FL
9	1		*TAILGATE WEATHERSTRIPS	Twisted	172.00 F	*172.00 FL
10	1		*REAR BUMPER	Distorted	689.00 F	*689.00 FL
11	1		*REAR BUMPER REINFORCEMENT	Bent	245.00 F	*245.00 FL
12	2		*REAR BUMPER SIDE RETAINERS	Bent	65.00 F	*65.00 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
14	2		*REAR BUMPER REFLECTORS	Not Necessary	76.00 F	*- FL
15	1		*REAR BUMPER LOWER BRACKET	Bent	45.00 F	*45.00 FL
16	2		*TAILLAMPS	Cracked	832.60 F	*832.60 FL
17	1		*REAR END PANEL	Badly Dented	395.40 F	*395.40 FL
18	1		*REAR END PANEL TOP GARNISH	Twisted	146.80 F	*146.80 FL
19	1		*REAR FLOOR PANEL TOP BOARD	Dented	425.00 F	*425.00 FL
20	1		*REAR FLOOR PANEL	Repair	685.00 F	*- FL
21	2		*REAR FLOOR PANEL TOP SIDE SPONGES	Torn	490.00 F	*490.00 FL
22	1		*REAR EXHAUST	Dented	820.00 F	*765.00 FL
23	2		*REAR EXHAUST MOUNTINGS	Necessary	70.00 F	*70.00 FL
24	2		*REAR FENDER	Repair	1,982.00 F	*- FL
25	2		*REAR FENDER INNER TRIM BOARDS	Not Necessary	650.00 F	*- FL
26	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
27	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
29	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
30	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,946.40	6,184.30
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,178.86
Total Parts (\$\$)	10,946.40	5,005.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING.	New	80.00	30.00
2	TO DISMANTLE & REPLACE REVERSE SENSOR.	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN.	New	150.00	120.00
4	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY.	New	150.00	80.00
5	TO TRANSFER TAILGATE MECHANISM.	New	100.00	60.00
6	TO DISMANTLE & REPLACE REAR EXHAUST.	New	100.00	60.00
7	TO SPRAY ANTI RUST PROOFING.	New	100.00	60.00
8	TO CONDUCT CHASSIS ALIGNMENT.	New	380.00	0.00
9	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACE PARTS.	New	1,500.00	800.00
10	TO PUTTY AND SPRAY PAINTING.	New	1,500.00	1,100.00
Gross Labour Cost (S\$)			4,140.00	2,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >