

15/09/18

INS. CASE OWNER:

Chee Heng

CC6 / AIG17023951 / Aca3

LKJ:

IDAC:

Surveyor:

ADRIAN

DOI:

13/2/17

Date / Time:

13/2/17

Registered in Merimen:

18/2/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFR 6262E

Name of Insured:

CHAN WAI KIN

Insured Tel No.:

HP: 9816 6376

Excess Sec II: SS

D.O.A: 09/4/17

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

676987104456

Policy No.:

2100233082

Make / Model:

NISSAN QASHQAI - 2.0 J10CA

Place of Accident:

MARYMOUNT RD TO JUNCTION
OF LIN MING AVE / BISHAN ST

If NO, Driver Name / Age:

Driver Tel No.:

(VA / YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLT 2674 U



INSRS:

WSP: Pegasus

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

21/12/17 (Ashur)

SLT 2674 U - X

SFR 6262E - CCB / AIG15008392 / K19362 RA: 27/9/17

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

SEEK APPROVAL TO REJECT TP CLAIM.

MANDATE APPROVE TO REJECT TP CLAIM.

ENSH WSP LIABILITY CLERK.

TP company is unaware of
accident circumstances
hence why they attempted
to claim for damage.

Reject Case

By (staff): Ashur

Approved by: Ashur

Date: 16/12/17

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

N

Repair Cost:

SS

TP REPAIR ENDED 01

(TP REPAIR NO COLLISION)

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

Legal Cost

SS

(e.g. Tow/Independent)

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

+320 + +20

27/8/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG17023951/Aes3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 18-12-2017



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFR 6262E	Veh. Inspected	SLT 2674U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damage

--

5. General Information

Accident Date	09/11/2017	Inspection Date	13/12/2017
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 174 WESTWOOD CRESCENT, WESTVILLE SINGAPORE 648541		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Third Party Insurer :
Insured's Veh No :
Date of accident : 09.

Messrs Grab Rentals Pte Ltd

Date : 12.12.2017

Estimate To Repair : Honda Vezel 1.5 Hybrid X (A)
Vehicle No : SLT2674U
Chassis No : RU31253148

Pages : 1 of 1
13/12/17C 1715h

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	front bumper <i>Dehd</i>	\$ 927.50	\$ ⁸⁰¹ 927.50 ✓
2	1 pc	front bumper reinforcement <i>Best</i>	\$ 321.00	\$ 321.00 ✓
3	1 pc	n/s front bumper side retainer <i>me</i>	\$ 23.00	\$ 23.00 ✓
4	1 pc	n/s front bumper spot lamp <i>me</i>	\$ 327.70	\$ 327.70 ✓
	1 pc	n/s front bumper spot lamp garnish <i>Dehd</i>	\$ 45.20	\$ 45.20 ✓
	1 pc	front bumper lower <i>at</i>	\$ 391.00	\$ 391.00 ✓
	1 pc	front bumper lower splashshield cover <i>me</i>	\$ 99.80	\$ 99.80 ✓
	6 ps	front bumper lower splashshield cover clips <i>me</i>	\$ 3.90	\$ 23.40 ✓
	8 ps	front bumper clips <i>me</i>	\$ 3.90	\$ 31.20 ✓
	1 pc	n/s headlamp <i>me</i>	\$ 1,859.40	\$ 1,859.40 ✓
	1 pc	n/s headlamp bracket <i>me</i>	\$ 35.00	\$ 35.00 ✓
	1 pc	radiator grille <i>me</i>	\$ 285.00	\$ 285.00 ✓
	1 pc	radiator grille outer granish <i>me</i>	\$ 385.00	\$ 385.00 ✓
	10 ps	radiator grille clips <i>me</i>	\$ 3.90	\$ 39.00 ✓
	1 pc	n/s front fender <i>Py</i>	\$ 580.00	\$ 580.00 ✓
	1 pc	n/s front fender inner cowling	\$ 130.00	\$ 130.00 ✓
	8 ps	n/s front fender inner cowling clips <i>me</i>	\$ 3.90	\$ 31.20 ✓
	1 pc	n/s front fender Hybrid badge <i>me</i>	\$ 62.90	\$ 62.90 ✓
	1 pc	n/s front fender wheel arc garnish <i>me</i>	\$ 195.00	\$ 195.00 ✓
		Less 20%		\$ 5,792.30
				\$ 1,158.46
				\$ 4,633.84
LABOUR & MISC. CHARGES				
1		To check electrical lighting concerned.	30	\$ 30.00 ✓
2		To rust-proofing of the affected areas.		\$ 80.00 ✓
3		Panel beating, knocking and straighten the necessary portion,	7.00	\$ 700.00 ✓
4		remove and renewal of parts, adjust and realign the same.		\$ 800.00 ✓
		Putty and spray painting of the affected portion.		\$ 1,610.00
		Grand Total		\$ 6,243.84

LKK Auto Corp
the Repairer of the following:
• To resurvey before and after spray painting
• To spray damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary survey must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Li
13/12/17.
03 Apr.

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	7200G
Vehicle Details	
Vehicle No.	SLT2674U
Vehicle to be Exported	Yes
Intended De-registration Date	12 Dec 2017
Vehicle Make	HONDA
Vehicle Model	VEZEL 1.5X HYBRID A
Primary Colour	Black
Manufacturing Year	2017
Engine No.	LEB5953165
Chassis No.	RJ31253148
Maximum Power Output	112.0 kW (150 bhp)
Open Market Value	\$24,622.00
Original Registration Date	24 Oct 2017
First Registration Date	24 Oct 2017
Transfer Count	0
Actual ARF Paid	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	23 Oct 2027
PARF Rebate Amount	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date	23 Oct 2027
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$49,189.00
COE Rebate Amount	\$39,351.00
Total Rebate Amount	\$43,101.00

The information contained herein is correct as at 12 Dec 2017

OK

Asher Sng (LKKAuto)

From: Loh, Chee-Heng <Chee-Heng.Loh@aig.com>
Sent: Monday, 22 January 2018 3:10 PM
To: Asher Sng (LKKAuto)
Cc: Vic (LKKAuto)
Subject: RE: Your ref: 6769871044SG, ACCIDENT INVOLVING SFR 6262E (OI) & SLT 2674U (TP) ON 09/11/2017

Dear Asher,

You may proceed to reject claim.

Thank you.

Best regards,
Loh Chee Heng
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1881 | Fax +(65) 6835 7416

Chee-Heng.Loh@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Asher Sng (LKKAuto) [mailto:AsherSng@lkkauto.com]
Sent: Monday, January 22, 2018 3:06 PM
To: Loh, Chee-Heng
Cc: Vic (LKKAuto)
Subject: Your ref: 6769871044SG, ACCIDENT INVOLVING SFR 6262E (OI) & SLT 2674U (TP) ON 09/11/2017

Your ref: **6769871044SG**
Our Ref: CC6/AIG1702395/Aea3

Dear Sir/Madam,

ACCIDENT INVOLVING SFR 6262E (OI) & SLT 2674U (TP) ON 09/11/2017

We refer to the above matter.

TP reported that as no collision, not aware of accident.

OI reported that TP rear ended OI vehicle while he was in the midst of changing lane to the right.

In view of the above, we are intending to reject TP claim as third party reported no collision.

For your approval/ comments/ instruction.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 16 August 2018 12:28 PM
To: 'Pegasus Engineering'
Subject: ACCIDENT INVOLVING SLT 2674U AND SFR 6262E ON 09/11/2017
Attachments: OI SKETCH PLAN.pdf

Your Ref: SLT 2674U
Our Ref: CC6/AIG17023951/Aea3

Without Prejudice

Hi Sir/Mdm,

We refer to the above matter.

ACCIDENT INVOLVING SLT 2674U AND SFR 6262E ON 09/11/2017

We attached here with a copy of our insured's accident statement for your easy reference.

Our principal has reiterated that the accident was caused due to the entire negligence of your client rear ended our insured vehicle.

We are of the opinion that liability is not in your client's favor.

Under such a circumstances, we regret to inform you that we have our principal instruction to deny liability and unable to look into your client's claim.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING


Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Nov 2017 Edit Reg		13 Dec 2017 00:00 Edit Adj Rpt	S\$3,535.44 Edit Estimates	S\$3,535.44 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: CHAN WAI KIN , ID: S2557069C									
Main Claimant: GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G									
Vehicle Reg. No.: SLT2674U		Date of Loss: 09/11/2017 09:00 - :59 [16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6769871044SG		Policy/Cover Note No.: 2100333082 (Comprehensive)							
Vehicle Reg. No. (Insured): SFR6262E		Policy No. (Claimant): MTGRAB20172700							
		Excess:							
Repairer: Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Claimant's Insurer: Great American Insurance Company (HQ) - Tel: 6804 6047									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 28/12/2017]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLT2674U (6769871044SG)**
[SFR6262E]
TP
GRAB RENTALS PTE LTD
Nov 9 2017 9:00AM
[CHAN WAI KIN]
Pegasus Engineering & Trading Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	19/12/17 10:47	Accident Statement <small>From: SC - Reg. No: SFR6262E, Claimant: CHAN WAI KIN</small>	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
2	29/03/18 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
3	29/03/18 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
4	29/03/18 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
5	29/03/18 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
6	29/03/18 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
7	29/03/18 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
8	29/03/18 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
9	29/03/18 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
10	29/03/18 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
11	29/03/18 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
12	29/03/18 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
13	29/03/18 11:04	General View	Load JPG	<input checked="" type="checkbox"/>
14	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
15	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
16	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
17	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
18	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
19	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
20	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
22	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
23	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
24	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	29/03/18 11:04	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 15:44	TP GIA REPORT	Load PDF	<input type="checkbox"/>
2	16/08/18 12:29	APPROVAL TO REJECT TP CLAIM	Load PDF	<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
3	16/08/18 12:29	EMAIL WSP TO REJECT TP CLAIM	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17023951/AEA3Q2

Date: 23/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100333082

Claimant Vehicle No: SLT2674U

Insured Vehicle No: SFR6262E

Date of Loss: 09/11/2017

Nature of Claim:

TP

Claim No: 6769871044SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT2674U

Make & Model: HONDA VEZEL, 1.5 X (A)

Engine No: LEB5953165

Reg. Date: 24/10/2017 (Man. Year: 2017)

Chassis No: RU31253148

Colour: Black

Odometer: 1048 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,633.84	2,805.44	1,828.40	39.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	730.00	880.00	54.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,243.84	3,535.44	2,708.40	43.38
+ GST 7.00/7.00% (S\$)	437.07	247.48	189.59	43.38
Nett Amount (S\$)	6,680.91	3,782.92	2,897.99	43.38
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 13/12/2017

Date Inspected: 13/12/2017 Inspected At:

Pegasus Engineering & Trading Pte Ltd (HQ)

51 DEFU LANE 10

Singapore 539216

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	927.50 FL	*801.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	321.00 FL	*321.00 FL
3	1		*N/S FRONT BUMPER SIDE RETAINER	Necessary	23.00 FL	*23.00 FL
4	1		*N/S FRONT BUMPER SPOT LAMP	Not Necessary	327.70 FL	*- FL
5	1		*N/S FRONT BUMPER SPOT LAMP GARNISH	Deformed	45.20 FL	*45.20 FL
6	1		*FRONT BUMPER LOWER	Cut	391.00 FL	*391.00 FL
7	1		*FRONT BUMPER LOWER SPLASHIELD COVER	Not Necessary	99.80 FL	*- FL
8	6		*FRONT BUMPER LOWER SPLASHIELD COVER CLIPS	Not Necessary	23.40 FL	*- FL
9	8		*FRONT BUMPER CLIPS	Necessary	31.20 FL	*31.20 FL
10	1		*N/S HEADLAMP	Cracked	1,859.40 FL	*1,859.40 FL
11	1		*N/S HEADLAMP BRACKET	Cracked	35.00 FL	*35.00 FL
12	1		*RADIATOR GRILLE	Not Necessary	285.00 FL	*- FL
13	1		*RADIATOR GRILLE OUTER GARNISH	Not Necessary	385.00 FL	*- FL
14	10		*RADIATOR GRILLE CLIPS	Not Necessary	39.00 FL	*- FL
15	1		*N/S FRONT FENDER	Repair	580.00 FL	*- FL
16	1		*N/S FRONT FENDER INNER COWLING	Not Necessary	130.00 FL	*- FL
17	8		*N/S FRONT FENDER INNER COWLING CLIPS	Not Necessary	31.20 FL	*- FL
18	1		*N/S FRONT FENDER HYBRID BADGE	Not Necessary	62.90 FL	*- FL
19	1		*N/S FRONT FENDER WHEEL ARC GARNISH	Not Necessary	195.00 FL	*- FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	5,792.30	3,506.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,158.46	701.36

Total Parts (\$\$)	4,633.84	2,805.44
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	30.00	30.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	80.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	700.00	300.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	800.00	400.00
Gross Labour Cost (\$\$)			1,610.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >