

ASS. REC. BY:

REF: CS/ III 17023983 / 49d3 n2

Special Instruction:

Surveyor: Munmen

ASSIGNMENT (Office)

From (Person): Gabriel Wee

of III

Date/Time: 5:11pm @ 18/12/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SIW 31234

Insured:

GBE 365Y

at Workshop m/s:

Max Motors

Tel:

96505539

of 1 Kaki Bukit Ave 6 # 01-98 Autobay, 417883

Policy No:

M492819

Claim No:

MC2017/3203

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15/12/17

CA / REV / REP. / REV 24 HRS (wp)

19/12/17

H.O.D. Endorsement:

Date/Time: 5:45pm @ 18/12/17

Person Contacted:

Mr. Tan

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate
	<u>SIW 31234 - CC6/AIG/15002869/4293w2</u>	<u>D.O.A: 13/02/2015</u>
	<u>GBE 365Y - X</u>	

REF: III

ASSIGNMENT

From: _____ Date: 19/12/17
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJW 31234
 at Workshop m/s Max Motors
 of 3 kaki Bukit Ave 6 #01-98 417883
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 66
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS (up) 7/11/2018
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SJW 31234 Yr Regn: 11 06
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or (A)
 Make: Toyota Camry C.O. 2362
 Colour: Grey A/C Insured / Std / NI / NA
 Sp. Reading: 341180 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR0533K 4007203722
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 15/1/17 D.O.I. 19/12/17
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S
 The U/C / Chassis frame / Body Structure affected due to collision:

Date/Time Action/Instruction LTA 49687
3/1/18 confirmed L/S @ 3000 w.b. MR Tan.
(Pzd @ 6665.70, 69%)

RECEIVED 03 JAN 2018

Date/Time, File Pass to? ☐ : Preli. Report

03/11 Ampr ☐ : Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.F. (\$) 3000MR-TPDays Of Repair: 4Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation

E-RS \$

Photos

Others

TOTAL

250

10

260




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CS/III17023983/Uqd3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 18-12-2017	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBE 365Y	Veh. Inspected	SJW 3123U
Policy No.		Coverage (\$)	0.00
Claim No.	L.17.1884.AT//	Excess (\$)	0.00
Assign From	GABRIEL WEE	Assign Date	18/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/12/2017	Inspection Date	
Survey held at	MAX MOTORS 1 KAKI BUKIT AVE 6 #01-98 SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Survey Department Check List (Case Handler)

Reference No.: *C9/10/7023983/4443*
Policy Type: OD / TP / RES / TL / EVA

SJW 31234

Case Handler

Typist

Admin (*Nivitha*): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			

Surveyor (*Mavan*): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

<input checked="" type="checkbox"/>		
-------------------------------------	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>		

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

<input checked="" type="checkbox"/>		
-------------------------------------	--	--

Check By:

[Signature] *03/10/18*

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 18 December, 2017 5:11 PM
To: Kuru & Co; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: C Meenachi - III
Subject: RE: Our Ref: L.17.1884.AT// Your Ref: GBE 365Y//PRS
Attachments: img-Z18150437.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJW 3123U and let us have your report urgently.

This claim will be handled by Ms Meena.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Kuru & Co [mailto:kurulegal@yahoo.com.sg]
Sent: 18 December, 2017 4:56 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Our Ref: L.17.1884.AT// Your Ref: GBE 365Y//PRS

Dear Sirs

Our client is agreeable to the following surveyor(s) as the SJE: **LKK Auto Consultants Pte Ltd**

Please arrange for your surveyor to survey our client's vehicle at the following address:

MAX MOTORS

1 Kaki Bukit Ave 6

#01-98 AutoBay@Kaki Bukit

Singapore 417883

Mr Tan 96505539

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey(s).

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Best regards

Anne
Kuru & Co
150 South Bridge Road
#04-06 Fook Hai Building
Singapore 058727
Tel: 6532 2009
Fax: 6532 2007

From: Motor Claim - III <motorclaim@iii.com.sg>
To: Kuru & Co <kurulegal@yahoo.com.sg>
Sent: Monday, 18 December 2017, 15:56
Subject: RE: Our Ref: L.17.1884.AT// Your Ref: GBE 365Y//PRS

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- Automobile Inspection Services Pte Ltd
- Autoprobe Consultants
- VP Appraisal
- Quantum Risk Management
- Ajax Inspection Services Pte Ltd
- Form Team Adjusters Pte Ltd
- Infiniti Appraisal Service
- JP Knights Adjusters
- LBS Auto Consultants Pte Ltd
- Premier Appraisers Services
- Priority Services
- RT Appraisal
- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee
Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 248

From: Kuru & Co [<mailto:kurulegal@yahoo.com.sg>]
Sent: 18 December, 2017 3:05 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Our Ref: L.17.1884.AT// Your Ref: GBE 365Y//PRS

Dear Sirs

ACCIDENT INVOLVING SJW 3123U & GBE 365Y ON 15.12.2017

AT/ALONG UBI ROAD 3
NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

We act for **Independent Mover Pte Ltd**, whose vehicle registration number **SJW 3123U** was damaged in the above accident.

A copy of the Accident statement is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Anne

Kuru & Co

150 South Bridge Road

#04-06 Fook Hai Building

Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling

and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1460Z
Vehicle Details	
Vehicle No.:	SJW3123U
Vehicle to be Exported:	No
Intended De-registration Date:	26 Dec 2017
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.4 AUTO ABS AIRBAG
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	2AZE013721
Chassis No.:	MR053BK4007003722
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$29,897.00
Original Registration Date:	08 Nov 2006
First Registration Date:	08 Nov 2006
Transfer Count:	5
Actual ARF Paid:	\$32,887.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Nov 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$56,053.00
COE Rebate Amount:	\$49,697.00

Today's After repair
Not Authorised
Mark
2/5 @ 3000
4 day.
19/11/17

MAX MOTOR

VEHICLE NO : SJW3123U

QTY	PARTICULAR	AMOUNT S
-----	------------	----------

LIST ITEMS :

1PCS	BOOTLID <i>Bent/Buc</i>	\$1,091.70 ✓
1PCS	BOOTLID REAR LOGO <i>neu</i>	\$61.80 ✓
1PCS	BOOTLID CAMRY EMBLEM <i>neu</i>	\$59.20 ✓
1PCS	BOOTLID REFLECTOR O/S <i>scr</i>	\$329.10 ✓
1PCS	BOOTLID INNER LOCK <i>11</i>	\$409.10 x
1PCS	BOOTLID WEATHERSTRIP <i>11</i>	\$285.75 x
1PCS	REAR BUMPER <i>20/02</i>	\$468.30 ✓
1PCS	REAR BUMPER SIDE RETAINER O/S <i>Bent</i>	\$48.15 ✓
1PCS	REAR BUMPER REINFORCEMENT <i>20</i>	\$326.40 ✓
1SET	REAR BUMPER CLIPS <i>neu</i>	\$50.00 ✓
1PCS	REAR BUMPER REFLECTOR O/S <i>11</i>	\$62.10 x
1PCS	REAR END PANEL <i>2</i>	\$509.80 x
1PCS	REAR END PANEL TOP GARNISH <i>11</i>	\$481.10 x
1PCS	REAR FLOOR PANEL <i>2</i>	\$991.70 x
1PCS	TAILLAMP O/S <i>cm</i>	\$389.80 ✓
1SET	REAR BUMPER REVERSE SENSOR <i>shel</i>	\$260.00 ✓
1PCS	REAR EXHAUST <i>11</i>	\$691.75 x

TOTAL : \$6,515.75

3084.45
2313.33

LABOUR CHARGES :

TO CHECK WIRING	\$50.00 20
TO SPRAY RUST PROOFING	\$100.00 40
TO DISMENTLE & REFIX REAR EXHAUST	11 \$100.00 x
TO DISMENTLE & REPLACE REVERSE SENSOR	\$80.00 50
TO DISMENTLE & REFIX SEAT CUSHIONING UPHOLSTERY	\$120.00 80
LABOUR FOR PANEL BEATING , CUT , WEILD , STRAIGHTEN & REPLACING PARTS	\$1,200.00 150
TO PUTTY & SPRAY PAINTING	\$1,500.00 700

TOTAL : \$9,665.70

75

LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from Insurance Company
- To display damaged part(s) during resurvey
- To resurvey before/after spray painting

Signature: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III17023983/UQD3N2

Date: 08/01/2018

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	M492819
Claimant Vehicle No :	SJW3123U	Insured Vehicle No :	GBE365Y
Date of Loss:	15/12/2017	Nature of Claim:	TP
		Claim No:	MC2017/3203

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW3123U	Engine No:	2AZE013721
Make & Model:	TOYOTA CAMRY, 2.4 (A)	Chassis No:	MR053BK4007003722
Reg. Date:	08/11/2006 (Man. Year: 2006)	Odometer:	341180 km
Colour:	Grey		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,515.75	2,313.34	4,202.41	64.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,150.00	1,440.00	1,710.00	54.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,665.75	3,753.34	5,912.41	61.17
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	9,665.75	3,000.00	6,665.75	68.96

INSPECTION

Date of Assignment:	18/12/2017	
Date Inspected:	19/12/2017	Inspected At:
		Max Motors (HQ)
		1 Kaki Bukit Ave 6, #01-98 Autobay @
		Kaki Bukit
		Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2018)
Parts: 143	TOYOTA CAMRY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJW3123U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent/Buckled	1,091.70 F	*1,091.70 FL
2	1		*BOOTLID REAR LOGO	Necessary	61.80 F	*61.80 FL
3	1		*BOOTLID CAMRY EMBLEM	Necessary	59.20 F	*59.20 FL
4	1		*BOOTLID REFLECTOR O/S	Scratched	329.10 F	*329.10 FL
5	1		*BOOTLID INNER LOCK	Not Necessary	409.10 F	*- FL
6	1		*BOOTLID WEATHERSTRIP	Not Necessary	285.75 F	*- FL
7	1		*REAR BUMPER	Dented/Deformed	468.30 F	*468.30 FL
8	1		*REAR BUMPER SIDE RETAINER O/S	Bent	48.15 F	*48.15 FL
9	1		*REAR BUMPER REINFORCEMENT	Dented	326.40 F	*326.40 FL
10	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
11	1		*REAR BUMPER REFLECTOR O/S	Not Necessary	62.10 F	*- FL
12	1		*REAR END PANEL	Repair	509.80 F	*- FL
13	1		*REAR END PANEL TOP GARNISH	Not Necessary	481.10 F	*- FL
14	1		*REAR FLOOR PANEL	Repair	991.70 F	*- FL
15	1		*TAILLAMP O/S	Cracked	389.80 F	*389.80 FL
16	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	260.00 F	*260.00 FL
17	1		*REAR EXHAUST	Not Necessary	691.75 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,515.75	3,084.45
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	771.11
Total Parts (\$\$)	6,515.75	2,313.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	100.00	40.00
3	TO DISMENTLE & REFIX REAR EXHAUST	New	100.00	-
4	TO DISMENTLE & REPLACE REVERSE SENSOR	New	80.00	50.00
5	TO DISMENTLE & REFIX SEAT CUSHIONING UPHOLSTERY	New	120.00	80.00
6	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS	New	1,200.00	550.00
7	TO PUTTY & SPRAY PAINTING	New	1,500.00	700.00
Gross Labour Cost (S\$)			3,150.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >