

ASS REC. BY:

REF:

F02/

CS/TP17023990/Kob2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sub Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum. Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 893Z

Yr Regn:

07, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy With

C.C

1799

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

426568

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDER12W603002739

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

8

mm

R/Bal.

6

mm

L/Bal.

8

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

26/6/14

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHD 893Z - 003/AXA 11017393 / KHC321

DCA: 22032011

45 \$ 6250

Cred: 12531.09 , 679.

* have to sent invoice 1st once payment receive just send the report.

No resurvey photo.

RECEIVED 20 DEC 2011

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

8

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: TP

Lum. Sum / I.B.I: (\$ 6250

2x15

1704 120

50

24

364




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP17023990/Kgb	
NO.2 ANG MO KIO STREET 63 SINGAPORE 569111		Date : 19-12-2017	
		Code : TP378	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	Veh. Inspected		SHD 893Z
Policy No.	Coverage (\$)		0.00
Claim No.	Excess (\$)		0.00
Assign From	Assign Date		26/06/2014
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No. HIDDEN	Year of Reg.		
Chassis No.	Colour		
Odometer -	Steering		
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	26/06/2014	Inspection Date	26/06/2014
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Veron Chen (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Thursday, 19 October, 2017 11:50 AM
To: SUR; Kenneth Kong (LKKAUTO)
Cc: Ng Wai Yin; 'jasminetan@transcab.com.sg'; claims@transcab.com.sg; Esther Lim Choy Peng; Sereneler@first-insurance.com.sg
Subject: RE: FCIL REF: D14/7385/TC/HB; TCS REF: AAD1406-365--Accident involving SHB7978C & SHD0893Z on 26.06.14
Attachments: image001.emz; image006.emz; image010.emz; image001.emz; 14102017182813-0001.pdf; FW: Our ref: D14/7385/TC/HB, Your Ref: 1406-365, Acc on 26/6/14 involving SHB7978C & SHD893Z

Hi Team SUR/ Kenneth,

Kindly assist.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin [<mailto:waiyin.ng@transcab.com.sg>]
Sent: Thursday, 19 October, 2017 11:45 AM
To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Esther Lim Choy Peng' <EstherLim@first-insurance.com.sg>; 'Jasmine Tan' <jasminetan@transcab.com.sg>; claims@transcab.com.sg; 'Seren Ler' <Sereneler@first-insurance.com.sg>
Subject: FW: FCIL REF: D14/7385/TC/HB; TCS REF: AAD1406-365--Accident involving SHB7978C & SHD0893Z on 26.06.14

WITHOUT PREJUDICE

Dear Hsiao Tong

May we have a copy of the survey report?

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Esther Lim Choy Peng [<mailto:EstherLim@first-insurance.com.sg>]
Sent: Saturday, October 14, 2017 6:29 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; CWS Motor Claims <cwsmotorclaims@first-insurance.com.sg>
Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>; claims@transcab.com.sg; Serene Ler <SereneLer@first-insurance.com.sg>
Subject: RE: FCIL REF: D14/7385/TC/HB; TCS REF: AAD1406-365--Accident involving SHB7978C & SHD0893Z on 26.06.14

Hi Wai Yin

Please refer to the appended email which is self explanatory.

Please expedite.

Thank you.

Regards
Esther Lim
Motor Claims Department
First Capital Insurance Ltd
DID 6507 3803

Personal Data Protection Act 2012 ("PDPA"):
Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Ng Wai Yin [<mailto:waiyin.ng@transcab.com.sg>]
Sent: Wednesday, 20 September, 2017 5:23 PM
To: CWS Motor Claims
Cc: 'Jasmine Tan'; claims@transcab.com.sg; Serene Ler; Esther Lim Choy Peng
Subject: FW: FCIL REF: D14/7385/TC/HB; TCS REF: AAD1406-365--Accident involving SHB7978C & SHD0893Z on 26.06.14

WITHOUT PREJUDICE

Dear Sirs

May I know the latest claim settlement?

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Ng Wai Yin [mailto:waiyin.ng@transcab.com.sg]**Sent:** Wednesday, August 23, 2017 8:14 AM**To:** 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>**Cc:** 'Jasmine Tan' <jasminetan@transcab.com.sg>; 'claims@transcab.com.sg' <claims@transcab.com.sg>**Subject:** FCIL REF: D14/7385/TC/HB; TCS REF: AAD1406-365--Accident involving SHB7978C & SHD0893Z on 26.06.14

WITHOUT PREJUDICE

Dear Sirs

Please refer to the below mentioned, may I know the latest claim settlement?

TCS Ref. No.	FCIL Ref. No.	TCS Vehicle No.	3rd Party Vehicle No.	Accident Date	Place of Accident
AAD1406-365	D14/7385/TC/HB	SHD0893Z	SHB7978C	26-06-14 9:00	ECP (City)

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

Janet Tan Gek Keow

From: Janet Tan Gek Keow
Sent: Monday, 22 June, 2015 4:51 PM
To: 'claims@transcabservices.com.sg'
Subject: RE: Our ref: D14/7385M/TC/JT, Your ref: 1406-365-Acc on 26/6/14 INVOLVING shb7978c AND sshd893z

Dear Claims,

Please refer to the above matter.

We are unable to revert with an offer as yet as there is no survey report.

Please inform the surveyor to expedite.

Thank you.

Best regards
Janet Tan
Motor Claims Dept
First Capital Insurance Ltd
36 Robinson Rd
#16-01 City House
Singapore 068877
Email: JanetTan@first-insurance.com.sg
DID: 65073860
Tel: 65073848 (x115)
Fax: 65073849

Personal Data Protection Act 2012 ("PDPA"):
Under the PDPA, there are various requirements that regulate the processing of your personal data.
Please refer to www.first-insurance.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.
If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.
If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Janet Tan Gek Keow
Sent: Monday, 8 December, 2014 4:53 PM
To: report@lkkauto.com
Subject: Our ref: D14/7385M/TC/JT-Acc on 26/6/14 INVOLVING shb7978c AND sshd893z

Dear Surveyor,

Please let us have the survey report of SHD893Z on an urgent basis.

Best regards
Janet Tan
Motor Claims Dept
First Capital Insurance Ltd
36 Robinson Rd
#16-01 City House

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/06/2014 13:21
Date Of Accident	26/06/2014 09:00
Exact Location Of Accident	ECP (City)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD893Z
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	Hire and Reward
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Taxi

Insurance Company

Name of Insurance Company	First Capital Insurance Ltd
Type Of Coverage	Third Party
Fleet Policy	Yes
Policy Number	D-12047359MFSH/3513
Cover Note Number	

Driver

Name of Driver	CHIU NG KEK
NRIC No	S2005610Z
Date Of Birth	24/08/1949
Occupation	Outdoor
Date Of Driving Pass	31/03/1957
Driving Experience	57 Years And 2 Months
Gender	Male
Mobile Number	(Local) +65-97283389
Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	BLK 716 PASIR RIS ST 72 #09-13
Postcode	510716
Was driver an employee of the Insured's Company	No

If No, Relationship of the Driver with the Insured	Other - Hirer
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Collision- Head to Rear (TP Hit Insured)
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	No

Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

On 26.06.2014 at about 0900hrs, I was traveling at the extreme right lane along ECP towards City when vehicle in front of me stop so I followed suit. Moment later while I was stationary, I felt an impact from the rear. Vehicle B (SHB7978C) collided onto my taxi's left rear portion. Vehicle A: 1 passenger Vehicle B: 1 passenger /rc

Are accident photos available for attachment?	Yes
---	-----

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB7978C
Vehicle Make/Model/Colour	TRANSCAB TAXI
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan

<p>→ ECP (CITY)</p> <p>→</p> <p>→</p> <p>→</p> <p>→</p>	<p>A SHD89132</p> <p>B SHD 3978C</p>
---	--------------------------------------

B

A

Describe Circumstances of the Accident

Declaration

I/We declare the foregoing particulars are true in every respect.

Chin

Policyholder's Signature / Date & Time

Chin

Driver's Signature (If driver is not the policyholder) / Date & Time

paa

Witnessed by Reporting Centre Personnel

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STREET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 893Z - FCIL**ROEL**

DOLU

Not Attached

C/Sing \$ 6,250.00

76 : 9 6,687.50

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 893Z - FCIL

JTDER12W603002739

TOYOTA

WISH 1.8 BI-FUEL

26.06.2014

FCIL**PART****LIST**

1	1	Rear Bumper	\$	184/187 487.80 ✓ ✓
2	1	Rear Bumper Stay LH	\$	Ort 20.00 ✓ ✓
3	1	Rear Bumper Side Retainer LH	\$	CM 57.30 ✓ ✓
4	1	Rear Bumper Reflectors LH	\$	CM 55.00 ✓ ✓
5	1	Rear Bumper Stay RH	\$	Sm 20.00 X
6	1	Rear Bumper Side Retainer RH	\$	Sm 57.30 X
7	1	Rear Bumper Reflectors RH	\$	Sm 55.00 X
8	1	Rear End panel Inner	\$	R 280.70 X
9	1	Rear End Panel Outer	\$	R 519.80 ✓ ✓
10	1	Rear End Panel Inner Trim	\$	Bu 219.87 ✓ ✓
11	1	Rear Luggage Floor Panel	\$	R 791.70 X
12	1	Rear Luggage Floor Panel Trim Board	\$	Sm 311.90 X
13	1	Rear Luggage Floor Panel Insulator *	\$	Sm 481.40 X
14	1	Tailgate Lid	\$	Bt 1,233.70 ✓ ✓
15	1	Tailgate Lid Centre 'TOYOTA' Logo Badge	\$	Mc 68.00 ✓ ✓
16	1	Tailgate Lid Weatherstrip	\$	Deformed 286.90 5085N 43-46
17	1	Tailgate Lid Lock - Top	\$	R 388.80 X
18	1	Tailgate Lid Lock - Bottom	\$	R 32.83 X
19	1	Tailgate Lid Outer Chrome Garnish	\$	Sm 214.50 X
20	1	Tailgate Lid Inner Handle	\$	Sm 17.47 X
21	1	Tailgate Lid Inner Trim Board	\$	Sm 258.28 X
22	1	Rear Fender LH	\$	Bt 1,013.60 ✓ ✓
23	1	Rear Fender Panel Deck Trim Side LH	\$	Bu 615.00 ✓ ✓
24	1	Rear fender 1/4 glass with moulding LH	\$	Shatter 429.80 ✓ ✓
25	1	Rear fender air vent louver LH *	\$	Sm 86.70 X
26	1	Rear Exhaust Box	\$	R 788.50 X
27	1	Rear Lamp LH	\$	Bu 496.43 ✓ ✓
28	1	Rear Lamp Inner Panel LH	\$	Bt 540.00 ✓ ✓
29	1	Rocker Panel outer LH	\$	R 711.90 X
30	1	Rear Door RH	\$	R 1,198.00 X
31	1	Rear Door weatherstrip LH	\$	Sm 161.40 X
32	1	Rear Door top hinge LH *	\$	R 76.40 X
33	1	Rear Door bottom hinge LH *	\$	R 76.40 X

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STREET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 891Z - FCIL**ROEL**

34	1	Rear Door weatherstrip LH	\$	<i>Sn</i> 161.40 X
35	1	Rear Door inner lock LH	\$	<i>R</i> 426.60 X
TOTAL			\$	12,640.38
25%			\$	3,160.10
			\$	9,480.29

Special Nett

1	Set	Licence Plate	\$	<i>Sn</i> 35.00 X
1	Set	Rear Bumper Fastener Clip	\$	<i>Mr</i> 30.00 ✓
1	Set	Rear End Panel Inner Trim Clip	\$	<i>Mr</i> 30.00 ✓
1	Set	Rear Bumper Parking Sensor	\$	<i>Red/White</i> 300.00 <i>220.00</i>
1	Set	Rear Fender Inner Trim Clip	\$	<i>Mr</i> 60.00 ✓
2		Rear fender 1/4 glass inner sponge seal	\$	<i>Mr</i> 80.00 <i>30.00</i>
2		Rear fender 1/4 glass sealant	\$	<i>Mr</i> 80.00 <i>40.00</i>
1		CNG Sticker	\$	<i>Mr</i> 30.00 <i>15.00</i>
1		Tailgate Sticker 'Trans-cab'	\$	<i>Mr</i> 30.00 ✓
1		Tailgate Sticker '6555-3333'	\$	<i>Mr</i> 30.00 ✓
1		Tailgate Sticker 'Trans-link'	\$	<i>Mr</i> 30.00 ✓
1		Rear Door Sticker '6555-3333'	\$	<i>Mr</i> 80.00 X
2		Rear Windscreen Sealant	\$	<i>Mr</i> 80.00 <i>40.00</i>
1		Rear Windscreen Inner Sponge Seal	\$	<i>Mr</i> 60.00 <i>30.00</i>
1		Rear Exhaust Mounting	\$	<i>Sn</i> 45.80 X
1		Rear tyre LH	\$	<i>Sn</i> 180.00 X
1		Rear tyre Rim LH	\$	<i>Mr</i> 120.00 X

TOTAL	\$	1,300.80
--------------	-----------	-----------------

TOTAL PARTS	\$	10,781.09
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening
The Necessary Portion, Remove And
Renewal Of Parts, Adjust And Realign The
Same

\$	2,800.00 <i>1200</i>
----	----------------------

Putty And Spray Painting Of The Affected
Portion

\$	2,700.00 <i>1000</i>
----	----------------------

To Rust-Proofing Of The Affected Areas.

\$	220.00 <i>1200</i>
----	--------------------

To Check Electrical Lighting Concerned.

\$	120.00 <i>200</i>
----	-------------------

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT STREET 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019676G

SHD 893Z - FCIL**ROEL**

To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To Remove And Refit Interior Fittings, Trimings, Garnish, Fittings And Other, To Enable Repair.	\$	380.00 100%
To Remove And Refit Rear W/Screen Glass And 1/4 Quarter Glass To Facilitate Bodywork Repair.	\$	380.00 180%
To Transfer Of Tailgate Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 60%
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	Replaced 170.00 X
Towing Fees	\$	120.00 50%
To reinstall rear bumper parking sensor.	\$	170.00 50%
To transfer of door fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00 X

TOTAL	\$	8,000.00
--------------	-----------	-----------------

Over All Total	\$	18,781.09
-----------------------	-----------	------------------

REPAIR DAYS**10 DAYS**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP17023990/Kgbe2		
NO.2 ANG MO KIO STREET 63 SINGAPORE 569111		Date : 26-12-2017		
		Code : TP378		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SHD 893Z	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		26/06/2014	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1794	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTDER12W603002739	Colour	RED	
Odometer	426568	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	8 mm	
L/H Front Tyre	195/65 R15	FALKEN	8 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/06/2014	Inspection Date	26/06/2014	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 893Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BENT / CRACKED	487.80	487.80
1	REAR BUMPER STAY LH	DISTORTED	20.00	20.00
1	REAR BUMPER SIDE RETAINER LH	CRACKED	57.30	57.30
1	REAR BUMPER REFLECTORS LH	CRACKED	55.00	55.00
1	REAR BUMPER STAY RH	SERVICEABLE	20.00	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	57.30	-
1	REAR BUMPER REFLECTORS RH	SERVICEABLE	55.00	-
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	280.70	-
1	REAR END PANEL OUTER	BENT	519.80	519.80
1	REAR END PANEL INNER TRIM	BUCKLED	219.87	219.87
1	REAR LUGGAGE FLOOR PANEL	TO REPAIR SEE LABOUR	791.70	-
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	SERVICEABLE	311.90	-
1	REAR LUGGAGE FLOOR PANEL INSULATOR	SERVICEABLE	481.40	-
1	TAILGATE LID	BENT	1,233.70	1,233.70
1	TAILGATE LID CENTRE 'TOYOTA' LOGO BADGE	NECESSARY	68.00	68.00
1	TAILGATE LID LOCK - TOP	TO REPAIR SEE LABOUR	388.80	-
1	TAILGATE LID LOCK - BOTTOM	TO REPAIR SEE LABOUR	32.83	-
1	TAILGATE LID OUTER CHROME GARNISH	SERVICEABLE	214.50	-
1	TAILGATE LID INNER HANDLE	SERVICEABLE	17.47	-
1	TAILGATE LID INNER TRIM BOARD	SERVICEABLE	258.28	-
1	REAR FENDER LH	BENT	1,013.60	1,013.60
1	REAR FENDER PANEL DECK TRIM SIDE LH	BUCKLED	615.00	615.00
1	REAR FENDER 1/4 GLASS WITH MOULDING LH	SHATTERED	429.80	429.80
1	REAR FENDER AIR VENT LOURVE LH	SERVICEABLE	86.70	-
1	REAR EXHAUST BOX	TO REPAIR SEE LABOUR	788.50	-
1	REAR LAMP LH	BROKEN	496.43	496.43
1	REAR LAMP INNER PANEL LH	BENT	540.00	540.00
1	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	711.90	-
1	REAR DOOR RH	TO REPAIR SEE LABOUR	1,198.00	-

Report Ref No. CS/TP17023990/Kgbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DOOR WEATHERSTRIP LH	SERVICEABLE	161.40	-
1	REAR DOOR TOP HINGE LH	TO REPAIR SEE LABOUR	76.40	-
1	REAR DOOR BOTTOM HINGE LH	TO REPAIR SEE LABOUR	76.40	-
1	REAR DOOR WEATHERSTRIP LH	SERVICEABLE	161.40	-
1	REAR DOOR INNER LOCK LH	TO REPAIR SEE LABOUR	426.60	-
	LESS 25% DISCOUNT		-3,088.36	-1,439.07
			9,265.12	4,317.23
1	TAILGATE LID WEATHERSTRIP (SN) (50%)	DEFORMED	286.90	143.45
	LESS 25% DISCOUNT		-71.73	-
			215.17	143.45
	SPECIAL NETT ITEMS			
1	SET LICENCE PLATE (SN)	SERVICEABLE	35.00	-
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	30.00	30.00
1	SET REAR END PANEL INNER TRIM CLIP (SN)	NECESSARY	30.00	30.00
1	SET REAR BUMPER PARKING SENSOR (SN)	DENTED / SHATTERED	300.00	220.00
2	SET REAR FENDER INNER TRIM CLIP (SN)	NECESSARY-1 PC ONLY	60.00	30.00
2	REAR FENDER 1/4 GLASS INNER SPONGE SEAL (SN)	NECESSARY	80.00	30.00
2	REAR FENDER 1/4 GLASS SEALANT (SN)	NECESSARY	80.00	40.00
1	CNG STICKER (SN)	NECESSARY	30.00	15.00
1	TAILGATE STICKER 'TRANS-CAB' (SN)	NECESSARY	30.00	30.00
1	TAILGATE STICKER '6555-3333' (SN)	NECESSARY	30.00	30.00
1	TAILGATE STICKER 'TRANS-LINK' (SN)	NECESSARY	30.00	30.00
1	REAR DOOR STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	60.00	30.00
1	REAR EXHAUST MOUNTING (SN)	SERVICEABLE	45.80	-
1	REAR TYRE LH (SN)	SERVICEABLE	180.00	-
1	REAR TYRE RIM LH (SN)	SERVICEABLE	120.00	-
			1,300.80	555.00

Report Ref No. CS/TP17023990/Kgbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER, REAR LUGGAGE FLOOR PANEL, TAILGATE LID LOCK - TOP, TAILGATE LID LOCK - BOTTOM, REAR EXHAUST BOX, ROCKER PANEL OUTER LH, REAR DOOR RH, REAR DOOR TOP HINGE LH, REAR DOOR BOTTOM HINGE LH AND REAR DOOR INNER LOCK LH.		2,800.00	1,200.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,700.00	1,080.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		220.00	120.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		120.00	20.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH, FITTINGS AND OTHERS, TO ENABLE REPAIR.		380.00	100.00
	TO REMOVE AND REFIT REAR W/SCREEN GLASS AND 1/4 QUARTER GLASS TO FACILITATE BODYWORK REPAIR.		380.00	180.00
	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	REPEATED	170.00	-
	TOWING FEES.		120.00	50.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DOR REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
			8,000.00	2,860.00
	GRAND TOTAL		18,781.09	7,875.68

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,250.00
---	--	--	-----------------

Report Ref No. CS/TP17023990/Kgbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.