

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Tan Kah Leong of AWA Date/Time: 18/22/17 3:03 pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: S6L 1171L Insured: GBC 1068J

at Workshop m/s Mei Solution Tel: 6744 4165

of 23 Kaki Bukit Ave 4 #02-038

Policy No: AVCP38 0080971701 Claim No: GBC1068J / BT

Sum Insured: Excess:

Make of Veh: D.O.A. 17/12/2017

(Client's Record) CA / REV / REP. / REV 24 HRS 'Wp' 19-12-2017

Date/Time: 18/22/17 Person Contacted: Hong H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	S6L 1171L - X
	GBC 1068J - CS/AWA17015746 / K1hbm2 DIA: 14/12/17
	lump sum \$3250 - (Red: 4095 to 55%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD		Ref : CS/AWA17023993/Atb	
(SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Date : 19-12-2017	
		Code : AWA	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 1068J	Veh. Inspected	SGL 1171L
Policy No.	AVCPSB0080971701	Coverage (\$)	0.00
Claim No.	GBC1068J/BT	Excess (\$)	0.00
Assign From	TAN KAH LEONG	Assign Date	18/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/12/2017	Inspection Date	19/12/2017
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Catherine Chong (LKK Auto)

From: Tan, KahLeong <KahLeong.Tan@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Monday, 18 December, 2017 3:03 PM
To: LKK (assignments@lkkauto.com)
Cc: SUR (sur@lkkauto.com); 'mg3solution@gmail.com'
Subject: TP Survey assignment for SGL 1171L - DOA: 17.12.2017 Our ref: GBC 1068J / BT

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us **do** have consensus in the appointment of **Mr Adrian Ling Wai Ping**, as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SGL 1171 L
Insured Vehicle	:	GBC 1068 J (Accident Not Reported)
Policy Number	:	AVCPSB0080971701
Name of Workshop	:	MG Solution Pte Ltd
Contact Number	:	6744 4165
Person to Contact	:	Ms Heng Yoke Hong
Estimated Cost of repairs	:	\$ N.A

Regards,
Claims Division

Copy to MG Solution Pte Ltd via Email

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards
Motor Claims
Claims Group
Global Market

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This Report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/12/2017 19:35
Date Of Accident	17/12/2017 11:00
Exact Location Of Accident	368 WOODLAND AVE 1 MSCP LEVEL 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGL1171L
Insured/Policyholder	
Name Of Registered Owner	AARON TONG WEN YANG
NRIC No	S9040046J
Email Address	AARONTWY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97522492
Alternative Phone No	OFFICE-97522492

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	POLO 1.4 AT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10743225
Cover Note Number	N.A.

Driver

Name of Driver	AARON TONG WEN YANG
NRIC No	S9040046J
Date Of Birth	16/10/1990
Occupation	INDOOR
Date Of Driving Pass	29/09/2011
Driving Experience	6 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97522492
Fax Number	
Contact Number	OFFICE-97522492
EMail Address	AARONTWY@GMAIL.COM

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

My vehicle was parked, stationary inside the parking Lot. When I returned back to my vehicle, I discovered there was a damages on my vehicle front right portion. And there was note left on my windscreen saying that he accidentally hit onto my vehicle.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC1068J

Vehicle Make/Model/Colour TOYOTA HIACE 280 2.5 M

Details Of Properties NIL

Name of Driver NICHOLAS LIM

NRIC/Passport Number

Contact Number 90121721

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

Details of Witness

Name

Phone Number

Email Address

ACCIDENT STATEMENT (2000 characters)

My vehicle was parked, stationary inside the parking Lot. When I returned back to my vehicle, I discovered there was a damages on my vehicle front right portion. And there was note left on my windscreen saying that he accidentally hit onto my vehicle.

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?


No, Claim 3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
AIZAM BIN ATAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

17 December, 2017 5:00 pm

Date/Time:

17 December, 2017 5:00 pm

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: ALLIED WORLD ASSURANCE	DATE	: 18/12/2017
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SGL1171L		
MODEL	: VOLKSWAGEN POLO	<i>Denise</i>	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 17-12-2017
		TIME	: 11:00HRS
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>del</i>	1	\$1,255.30	\$ 1,255.30
2	FRONT BUMPER SIDE RETAINER <i>in RH</i>	2	\$62.40	\$ 124.80
3	FRONT BUMPER REINFORCEMENT <i>2nd</i>	1	\$697.00	\$ 697.00
4	FRONT BUMPER REINFORCEMENT SPONGE <i>1st</i>	1	\$180.00	\$ 180.00
5	FRONT BUMPER FOGLAMP GARNISH <i>lit</i>	1	\$182.00	\$ 182.00
6	HEADLAMP RH <i>lit</i>	1	\$812.40	\$ 812.40
7	HEADLAMP LOWER BRACKET RH <i>new</i>	1	\$92.60	\$ 92.60
8	FRONT FENDER RH <i>Distorted</i>	1	\$822.30	\$ 822.30
9	FRONT FENDER INNER COWLING RH <i>torn</i>	1	\$255.30	\$ 255.30

TOTAL PRICE \$ 4,421.70

LESS 0% \$ -

SUB TOTAL PRICE \$ 4,421.70

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Not Nec</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIPS (SET) <i>new</i>	1	\$ 22.00	\$ 22.00
3	FRONT FENDER INNER COWLING(CLIPS) <i>new</i>	1	\$ 22.00	\$ 22.00

TOTAL \$ 94.00

44

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,000.00	400	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	400	
3	WIRING CHECK	\$ 250.00	30	
4	TUFF COAT	\$ 250.00	X	
5	REFOCUS HEADLAMP BEAM	\$ 150.00	X	
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X	

TOTAL **\$2,830.00** 830

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,515.70
 TOTAL LABOUR COST : \$ 2,830.00
 TOTAL REPAIR COST : \$ 7,345.70

*Adrian King told 408421
 L/S 19/12/17. L/S 3250.
 OADays. 3250*

APPROVED DETAILS

EXCESS :
 NO. OF WORKING DAYS :
 RE-SURVEY :
 PART BY PART OR LUMP SUM :
 DATE & TIME OF SURVEY :
 SURVEYED BY :
 CONTACT NUMBER :
 FAX NUMBER :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA17023993/Atbn2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 17-01-2018



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 1068J	Veh. Inspected	SGL 1171L
Policy No.	AVCPSTB0080971701	Coverage (\$)	0.00
Claim No.	GBC1068J/BT	Excess (\$)	0.00
Assign From	TAN KAH LEONG	Assign Date	18/12/2017

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN POLO	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WVWZZZ6RZAU033374	Colour	WHITE
Odometer	100277	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
L/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/12/2017	Inspection Date	19/12/2017
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGL 1171L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	1,255.30	1,255.30
2	FRONT BUMPER SIDE RETAINER @\$62.40	O/S NECESSARY	124.80	62.40
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	697.00	-
1	FRONT BUMPER REINFORCEMENT SPONGE	NOT NECESSARY	180.00	-
1	FRONT BUMPER FOGLAMP GARNISH	CUT	182.00	182.00
1	HEADLAMP RH	CUT	812.40	812.40
1	HEADLAMP LOWER BRACKET RH	NOT NECESSARY	92.60	-
1	FRONT FENDER RH	DISTORTED	822.30	822.30
1	FRONT FENDER INNER COWLING RH	TORN	255.30	255.30
	LESS 5% DISCOUNT		-	-169.49
			4,421.70	3,220.21
SPECIAL NETT ITEMS				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	22.00	22.00
1	FRONT FENDER INNER COLWING CLIPS (SN)	NECESSARY	22.00	22.00
			94.00	44.00
LABOUR				
	PANEL BEATING, REMOVING AND REPLACING PARTS.		1,000.00	400.00
	SPRAY PAINTING TO AFFECTED AREA.		1,000.00	400.00
	WIRING CHECK.		250.00	30.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	REFOCUS HEADLAMP BEAM.	NOT NECESSARY	150.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			2,830.00	830.00
GRAND TOTAL			7,345.70	4,094.21
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,250.00

Report Ref No. CS/AWA17023993/Atbn2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.