

INS. CASE OWNER:

CC 6/ATG1702 3944, A wbb

LKK:

IDAC:

Surveyor:

Adnan

DOI:

18/11/17

Date / Time:

18/11/17

Registered in Merimen:

18/11/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLK 3504T

Name of Insured:

UR

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

20/10/17

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

1097885476

Policy No.:

AHHAN76

Make / Model:

TOYOTA

Place of Accident:

261 1/15 km 1 km 10 up

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

GBE 6Y38P



INSRS:

WSP:

Tel:

Liability:

RMKS:

TAN
UM

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

11/11/17
vivan

GBE 6Y38P - X

GBE 6Y38P - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

12/11/17 email.

After call ltr to OI:

vivan

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

IMINARY ADVICE Date/Time:

Sent By:

ALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

days)

Reduction:

%

Email

Call

FIN. L SETTLEMENT

Date/Time:

Confirm with:

Johnson

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

NIL.

If NO or B 28, Ass. Lia:

Repair Cost:

SS

2728.50

Cost of Rental (LOR):

SS

days)

Cost of Use (LOU):

SS

400.00

(\$ 100 x 4

days)

Cost of Income (LOI):

SS

(\$

x

days)

LOI only

☐

LOU only

☐

LOR + LOU

☐

LOR + LOI

☐

[Tick only one]

LTA Search

SS

5.35

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Repair Cost

SS

3133.85

Global Sum SS:

Email

Call

AL PAYMENT

Date/Time:

Confirm with:

Payee 1:

SS

3133.85

Name 1:

Tan Lim Motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT
18/6/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/LCR17023994/Awb3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 19-12-2017



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 3504T	Veh. Inspected	GBE 6738R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	20/10/2017	Inspection Date	18/12/2017
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

ALGAsia Insured's Veh No : SLK3504T
Date of Accident : 20 October 2017

星期(一)



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs Peter Seafood Supplier

Date : 14 December 2017

TP LCR
Vivian

reg: LKK

18-12-2017 @ 1325hrs

Estimate To Repair GBE6738R - Toyota DYNA 3.0 M

Chassis No : JTFAT35Y60K205863

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	o/s front door <i>dent</i>	\$ 1,600.00
02	1 pc	front door weatherstrip <i>garn</i>	\$ 121.00
03	1 pc	front door arc weatherstrip	\$ 128.00
04	1 pc	front door edge weatherstrip <i>new</i>	\$ 55.00
05	1 pc	front door step garnish <i>new</i>	\$ 306.00
06	1 pc	front bumper <i>new</i>	\$ 335.00
07	1 pc	o/s front corner panel <i>new</i>	\$ 288.00
08	1 pc	o/s front apron garnish <i>new</i>	\$ 138.00
09	1 pc	o/s head lamp <i>new</i>	\$ 799.80
Less 25 %			\$ 3,770.80
			\$ 942.70
			\$ 2,828.10
SPECIAL NETT ITEMS			
10	1 LC	front door corporate sticker <i>new</i>	\$ 380.00
11	1 pc	front door corporate name/address <i>new</i>	\$ 50.00
			\$ 430.00
LABOUR & MISC. CHARGES			
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 650.00
02		Putty and spray painting of the affected portion.	\$ 700.00
03		To check electrical lighting concerned.	\$ 60.00
04		To rust-proofing of the affected areas.	\$ 150.00
			\$ 1,560.00
Total			\$ 4,818.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey.
- Parts prices are based on confirmation.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification is allowed.
- Supplementary charges must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer:

Signature:

Date:

Total: 319325

1/3: 2550

1/3 Admin Lj
18/12/12
6 Days



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref TP013122017
Your Ref SLK3504T

Date 13.06.2018

Claims Department - Executive in charge LKK
40 ALH ASIA PACIFIC INSURANCE PTE. LTD.

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING GBE 6738R & SLK3504T on 20-10-2017

Refer to the above accident and please acknowledge receipt of this letter within 14 days.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

- ☐ Original survey report / copies of photographs
- ☒ Original Tax-Invoice number TP03181027 ☐ Original rental invoice number
- ☒ SAS / AS & IS / police report ☐ police result
- ☒ Certificate Of Insurance NTUE INCOME ☒ Vehicle search result
- ☒ Authorization to act ☐

LKK
*Survey under insurance instruction / Independent surveyor / No ~~survey~~.

a)	Cost of repair (inclusive GST)	\$ <u>2,1728.50</u>
b)	Survey fees / Photographs as per request	\$ <u>-</u>
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ <u>5.35</u>
d)	Loss of hire / use / rental / earnings / rental fees <u>1180 x 4 days</u>	\$ <u>720.00</u>
e)	Scene photographs	\$ <u>-</u>
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$ <u>-</u>
g)	<u> </u>	\$ <u>-</u>
	Total	\$ <u>3,453.85</u>

* Driver's injury and other losses exclude in this claim.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Patricia Tan / Sam Low / Johnson Chua

Email: pt@tlimotor.com.sg / sam@tlimotor.com.sg / johnson.chua@tlimotor.com.sg

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Business
Owner ID	2100D
Vehicle Details	
Vehicle No.	GBE6738R
Vehicle to be Exported	Yes
Intended De-registration Date	14 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	TOYOTA DYNA 150 MANUAL
Primary Colour	Blue
Manufacturing Year	2015
Engine No.	1KD2582459
Chassis No.	JTFAT35Y60K205863
Maximum Power Output	-
Open Market Value	\$24,944.00
Original Registration Date	19 Feb 2016
First Registration Date	19 Feb 2016
Transfer Count	0
Actual ARF Paid	\$1,248.00
Intended PARF Rebate Details	
PARF Eligibility	No
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00
Intended COE Rebate Details	
COE Expiry Date	18 Feb 2026
COE Category	C - Goods Vehicle & Bus
COE Period(Years)	10
QP Paid	\$46,001.00
COE Rebate Amount	\$36,800.00
Total Rebate Amount	\$36,800.00

The information contained herein is correct as at 14 Dec 2017

OK

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Thursday, 1 February, 2018 10:26 AM
To: 'eyap@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: ACCIDENT INVOLVING SLK 3504T & GBE 6738R ON 20/10/2017

Our Ref: CC6/LCR17023994/Awb3

01 February 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLK 3504T & GBE 6738R ON 20/10/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Peter Seafood Supplier ("the third party claimant")
of 23 Lich field Road Singapore 556843 (address),
owner of GBE 6738R (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. GBE 6738R that was
damaged pursuant to the accident which occurred on 20/10/2017 (date) along
Block 361 Fishon Road Ring Carpark (location)
involving vehicle no/s SLK 3504T ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.


I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 23rd day of Oct (month) 20 17 (year)

PETER SEAFOOD SUPPLIER
10 Anson Road #10-06
International Plaza Singapore 079903



Signed by "the third party claimant"



Signed by "the workshop"

RELEASE VOUCHER
(AIG ASIA PACIFIC-EXPRESS THIRD PARTY CLAIM)

"We/I, TAN LIM MOTOR PTE LTD (the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 2,728.50 (repair cost), S\$ 400.00 (loss of ~~rental~~/use), S\$ 5.35 (disbursement), for vehicle no. GBE 6738R that was damaged pursuant to the accident which occurred on 20/10/2017 (date) along BLK 361 YISHUN RING ROAD CP (location) involving vehicle no/s SLK 3504T.

This is pursuant to the inspection conducted on 18/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner PETER SEAFOOD SUPPLIER (the third party claimant") of vehicle no. GBE 6738R make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to GBE 6738R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 14th (day) of JUNE (month) 2018 (year)

LWP

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



TAX-INVOICE
NUMBER: TP0318/027

(Please quote our reference number TP013122017 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD


Peter Seafood Supplier

Date: 27/03/2018

Vehicle No: GBE6738R
Model: TOYOTA DYNA 3.0

Description	Amount
To lump sum repair as recommended by surveyor.	\$2,550.00
Reimbursement of LTA search fees.	\$5.00

Sub Total	\$2,555.00
Add 7% GST	\$178.85
Total	\$2,733.85



Tan Lim Motor Pte Ltd

Enquire Vehicle & Owner Information (Vehicle No. SLK3504T As At 20 Oct 2017 / 06:40:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: TL-GBE6738R

Current Owner Details

Owner ID Type: Company
Owner ID: 201624597K
Owner Name: LCRF PTE LTD
Registered Address Type: Private Residential (non-Condo Apt / non-House)
Registered Block/House No.: 60
Registered Street Name: ANSON ROAD
Registered Unit No.: # 11 - 01
Registered Building Name: MAPLETREE ANSON
Registered Postal Code: 079914

Current Vehicle Details

Vehicle No.: SLK3504T
Make Description/Model: TOYOTA / PRIUS HYBRID 1.8 CVT
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Thank you



Kirpal Singh Sharma has successfully logged out.

Your last login date and time was 14 Dec 2017, 09:22:20.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please [CLEAR YOUR CACHE](#) after each session.

Session Transaction History

<u>S/No</u>	<u>Asset</u> <u>Type</u>	<u>Asset ID</u>	<u>Asset</u> <u>Owner ID</u>	<u>Transaction Type</u>	<u>Transaction</u> <u>Amount(S\$)</u>	<u>Log</u> <u>Date/Time</u>
1	Vehicle	SLK3504T	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	5.35	14 Dec 2017 / 09:23:21

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Dec 2017 Edit Reg		18 Dec 2017 00:00 Edit Adj Rpt	S\$2,550.00 Edit Estimates	S\$2,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF Pte Ltd, Co. Reg. No.: -		
Main Claimant:	PETER SEAFOOD SUPPLIER, Co. Reg. No.: 43942100D		
Vehicle Reg. No.:	GBE6738R	Date of Loss:	20/10/2017 06:00 - :59 [20 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1097885197SG	Policy/Cover Note No.:	0999995006
Vehicle Reg. No. (Insured):	SLK3504T	Policy No. (Claimant):	5087315165
		Excess:	
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tee, Chee-Wah] Chee-Wah.Tee@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 29/12/2017]		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

- AIG_SG (16/01/2018): No OI GIA Report
- AIG_SG (20/12/2017): NO OI GIA REPORT

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBE6738R (1097885197SG)
[SLK3504T]
TP
PETER SEAFOOD SUPPLIER
Oct 20 2017 6:00AM
[LCRF Pte Ltd]
Tan Lim Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 12:08	General View		Load JPG
2	29/03/18 12:08	General View		Load JPG
3	29/03/18 12:08	General View		Load JPG
4	29/03/18 12:08	General View		Load JPG
5	29/03/18 12:08	General View		Load JPG
6	29/03/18 12:08	General View		Load JPG
7	29/03/18 12:08	General View		Load JPG
8	29/03/18 12:08	General View		Load JPG
9	29/03/18 12:08	General View		Load JPG
10	29/03/18 12:08	General View		Load JPG
11	29/03/18 12:08	General View		Load JPG
12	29/03/18 12:08	General View		Load JPG
13	29/03/18 12:08	General View		Load JPG
14	29/03/18 12:08	General View		Load JPG
15	29/03/18 12:08	General View		Load JPG
16	29/03/18 12:08	General View		Load JPG
Documentation			1 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/12/17 18:49	TP GIA REPORT		Load PDF
2	21/12/17 11:53	Email non reporting letter ACCIDENT INVOLVING SLK 3504T AND GBE 6738R ON 20.10.2017 0640 Hrs ALONG B		Load PDF
3	01/02/18 10:28	Email from AIG to settle at best 1.2.18.		Load PDF
4	01/02/18 10:28	Email letter to OI ACCIDENT INVOLVING SLK 3504T & GBE 6738R ON 20.10.2017		Load PDF
5	19/06/18 10:18	WORKSHOP INVOICE		Load PDF
6	19/06/18 10:18	AUTHORISATION TO ACT FORM		Load PDF
7	19/06/18 10:18	Release Voucher		Load PDF
8	19/06/18 10:18	LTA SEARCH		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	01/02/18 08:47	Singapore Accident Statement OI GIA		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST			Reset Save Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLK3504T (Insd veh)	Model:	TOYOTA DYNA 1.5T 3.0 (A)
	GBE6738R (TP veh)		
Date of Accident:	20/10/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	5,155.37
Final Repair Cost	:	\$	2,728.50
Loss of Use	:	\$	400.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	5.35
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,133.85

4.00 days at \$100.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	:	\$ 3,133.85
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

19 Jun
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR17023994/AWB3Q2

Date: 19/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995006
 Claimant Vehicle No: GBE6738R Insured Vehicle No: SLK3504T
 Date of Loss: 20/10/2017 Nature of Claim: TP Claim No: 1097885197SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE6738R
 Make & Model: TOYOTA DYNA 1.5T, 3.0 (A) Engine No: 1KD2582459
 Reg. Date: 19/02/2016 (Man. Year: 2015) Chassis No: JTFAT35Y60K205863
 Colour: Blue Odometer: 99450 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C
 Front Left Side: Bridgestone 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,258.10	2,233.25	1,024.85	31.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	960.00	600.00	38.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,818.10	3,193.25	1,624.85	33.72
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	4,818.10	2,550.00	2,268.10	47.07
+ GST 7.00/7.00% (S\$)	337.27	178.50	158.77	47.08
Nett Amount (S\$)	5,155.37	2,728.50	2,426.87	47.07
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		3,133.85		

INSPECTION

Date of Assignment: 18/12/2017
 Date Inspected: 18/12/2017 Inspected At: Tan Lim Motor Pte Ltd (Defu)
 51 Defu Lane 10
 Singapore 539216

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S FRONT DOOR	Dented	1,600.00 FL	*1,600.00 FL
2	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	121.00 FL	*- FL
3	1		*FRONT DOOR ARC WEATHERSTRIP	Not Necessary	128.00 FL	*- FL
4	1		*FRONT DOOR EDGE WEATHERSTRIP	Not Necessary	55.00 FL	*- FL
5	1		*FRONT DOOR STEP GARNISH	Not Necessary	306.00 FL	*- FL
6	1		*FRONT BUMPER	Repair	335.00 FL	*- FL
7	1		*O/S FRONT CORNER PANEL	Distorted	288.00 FL	*288.00 FL
8	1		*O/S FRONT APRON GARNISH	Cut	138.00 FL	*138.00 FL
9	1		*O/S HEAD LAMP	Cut	799.80 FL	*645.00 FL
10	1		*FRONT DOOR CORPORATE STICKER	Necessary	380.00 FS	*200.00 FS
11	1		*FRONT DOOR CORPORATE NAME /ADDRESS	Necessary	50.00 FS	*30.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (\$\$)	4,200.80	2,901.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	942.70	667.75
Total Parts (\$\$)	3,258.10	2,233.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	650.00	400.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	700.00	500.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	30.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (S\$)			1,560.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >