

Not Authored
6/1/2017

Vehicle No.:	SHB 7739B - CANDY
Chassis No.:	KL1LA69RJBB106915
Vehicle Make:	CHEVROLET
Vehicle Model:	CHEVROLET EPICA 2.0
Date of Accident :	10.12.2017
Third Party Insurer :	AIG

		PART		LIST
1	1	Front Bumper	\$	1,202.00 ✓
2	1	Front Bumper Lower Absorber	\$	180.00 ✓
3	1	Front Bumper Reinforcement	\$	356.00 ✓
4	1	Front Bumper Retainer LH	\$	102.00 ✓
5	1	Front Fender LH	\$	837.60 ✓
6	1	Front Fender Liner LH	\$	47.00 ✓
7	1	Front Door LH	\$	1,133.00 ✓
8	1	Front Door Glass Guide LH Chrome Moulding	\$	60.00 ✓
9	1	Front Door Outer Handle LH	\$	125.00 ✓
10	1	Front Door Hinge Upper LH	\$	65.00 ✓
11	1	Front Door Hinge Lower LH	\$	65.00 ✓
12	1	Front Side View Mirror LH	\$	939.00 ✓
13	1	Side Rocker Panel Garnish LH	\$	236.40 ✓
14	1	Rear Door LH	\$	1,133.00 ✓
15	1	Rear Door Guide LH Chrome Moulding	\$	60.00
16	1	Rear Door Outer Handle LH	\$	125.00
17	1	Rear Door Weatherstrip LH	\$	138.79
18	1	Rear Fender LH	\$	1,145.00
19	1	Rear Fender Inner Cowling LH	\$	298.00
20	1	Rear Tail Lamp LH	\$	479.30
21	1	Rear Bumper	\$	1,202.00
22	1	Rear Bumper Beam	\$	239.94
23	1	Rear Bumper Centre Absorber	\$	260.00
24	1	Rear Bumper Side Retainer LH	\$	68.76
25	1	Rear Bumper Reflectors LH	\$	119.74
26	1	Rear Bumper Tow Hook Cover	\$	93.00

TOTAL	\$	10,710.53
10%	\$	1,071.05
	\$	9,639.48

Special Nett

1	1 Set Front Fender Liner Clip LH	\$	nn 30.00 X
2	1 Door Sticker "Trans-cab" LH	\$	nn 80.00 60sn
3	1 Door Sticker "6555-3333" LH	\$	nn 80.00 60sn
4	1set Side Rocker Panel Garnish Clip LH	\$	nn 60.00 X
5	1 Rear Tyre LH	\$	sn 360.00
6	1 Rear Wheel Rim LH	\$	sn 254.00
7	2 Rear Windscreen Sealant	\$	nn 80.00
8	1 Rear Windscreen Inner Sponge Seal	\$	nn 100.00
9	1Set Rear Bumper Parking Sensor	\$	sn 300.00
10	1Set Rear Bumper Fastener Clip	\$	nn 30.00
11	1Set Rear Fender inner cowling clip LH	\$	nn 30.00

TOTAL	\$	1,404.00
TOTAL PARTS	\$	11,043.48

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,700.00 400
To Rust-Proofing Of The Affected Areas.	\$	220.00 60
Putty and Spray Painting Of The Affected Portion.	\$	2,800.00 600
To Check Electrical Lighting Concerned.	\$	170.00 20
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 120
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	nn 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST63 SINGAPORE 569111
TEL NO. 6287 6666 FAX NO. 6257 1330
CO/GST REG NO. 201019626G
SHB 7739B - AIG

AAD1712-140

Towing Fees	\$	<i>~</i> 120.00 <i>X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>~</i> 170.00 <i>X</i>

TOTAL	\$	6,910.00
Over All Total	\$	17,953.48

REPAIR DAYS

10 DAYS

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: