

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : China Taiping Insurance (Singapore) Pte Ltd

TEL: - FAX: -
 ATTN: Motor Claim Department
 Your Ref No: YONG LEI SERVICES PL
 Claim Type: Third Party
 Accident Date: 14/12/2017

Estimate No: ES1700149
 Date: 27 Dec 2017
 Policy No: DMCVSN1732691700
 Veh Reg No: XD3141B
 Make/Model: ISUZU CYZ52L
 Chassis No: JALCYZ52L87000069
 Engine No: 6WG1408632
 Reg. Date: 13/09/2008

Estimate Repair Cost to Vehicle No :XD3141B

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 Rear Mudguard RH	580.00	1 PC	580.00	580.00
2 Rear Tipper Tail Gate	1,950.00	1 PC	1,950.00	1,950.00
3 Rear Tipper Gate Hinge & Pin	480.00	1 ST	480.00	480.00
4 Lock Tail Board	60.00	2 PC	120.00	120.00
5 Tail Board U Sticker Lock	80.00	2 PC	160.00	160.00
			3,290.00	3,290.00
Labour				
6 Labour to cut & weld & renew rear tipper tail gate ,hinge & pin .	950.00	1 JOB	950.00	950.00
7 Labour to renew rear mudguard .	680.00	1 JOB	680.00	680.00
8 To spray & painting at accident area .	800.00	1 JOB	800.00	800.00
			2,430.00	2,430.00
Total			S\$ 5,720.00	
Add GST @ 7%			394.80	
Total Amount Payable			S\$ 6,114.80	

TOTAL: SINGAPORE DOLLAR SIX THOUSAND ONE HUNDRED FOURTEEN AND CENTS EIGHTY ONLY.

For MAH LIAN MOTOR VEHICLE
 REPAIRER

AUTHORISED SIGNATURE

UKK Auto-Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Acknowledged
 16/12
 2/12 @ 1200
 take photo after repair
 2 day.