

INS CASE OWNER:

Maenachi

CC 4/III170 23999, U

ea39

LKK:
IDAC:

Surveyor:

MARUS

DOI:

ASSIGNMENT

27/1/17

Date / Time:

12/1/17

Registered in Merimen:

19/1/17

Pre-assign / CCU / FTE

PA 8928B



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

XD 3141B



INSRS:

WSP:

Tel:

Liability:

RMKS:

Mah Lian



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

3/1/17

XD 3141B. W/LINE 14006487/21 ; D.O.A: 3/4/14

PA 8928B. X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lin:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle /wop

2) Report Format:

TP

3) Survey fee:

280.

Surveyor

REF:

III

en3

100.

ASSIGNMENT

From: _____ Date: **27/12/17**
 Estimated Cost: _____
 OD ☒ TP ☐ WS ☐ TP RES ☐ CD RES ☐ EVA ☐ INV ☐ MV
 To inspect Vehicle No: **XD 3141B**
 at Workshop no: **Mah Lion Motor**
 of **38 Defu Lane 9**
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record) **After 1pm**
 Make of Veh: _____

NIS	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GLA / PR Seen: **2** Consistent? : Yes or No
 Est. Repairs: **2** days Res: Yes or No
 Lum Sum: **1.5-1** % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS **1wp**
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **XD 3141B** Yr Regn: **9 08**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
☒ Truck / Trailer or
 Make: **15420 CYZ52L 15681**
 Colour: **white** A.C. Insured / Std / NI / NA
 Sp. Reading: **693914** T.Radio: Insured / Std / NI / NA
 Eng No: _____
 C.No: **JALCYZ52L87000069**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brakes: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **295/80R22.5**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Finmax**
 Front: **6** mm Rear: **6/6 6/6**
 R/Bal: **6** mm L/Bal: **6/6 6/6**
 D.O.A. **14/1/17** D.OI: **27/1/17**
 Survey held at: _____
 Des. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or
Rear o/s.
 The U/C / Chassis frame / Body Structure affected due to collision

27/12/17 conf. and final of 1200 with AM Tech.
only labour labour case

RED + 4,520 79%.

Date/Time File Pass to? ☐ : Prel. Report
☐ : Final Report
 Date/Time File Return to? _____

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp \$
☐ Interview \$
☐ Tech Insp \$
☐ Working \$

Survey Fee _____
 Transporter _____

Report Format: _____
 Lump Sum / I.B. : _____

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278
 TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg
 GST:M90362564P RCB NO:201327339E

M/S : China Taiping Insurance (Singapore) Pte Ltd

TEL: - FAX: -
 ATTN: Motor Claim Department
 Your Ref No: YONG LEI SERVICES PL
 Claim Type: Third Party
 Accident Date: 14/12/2017

Estimate No: ES1700149
 Date: 27 Dec 2017
 Policy No: DMCVSN1732691700
 Veh Reg No: XD3141B
 Make/Model: ISUZU CYZ52L
 Chassis No: JALCYZ52L87000069
 Engine No: 6WG1408632
 Reg. Date: 13/09/2008

Estimate Repair Cost to Vehicle No :XD3141B

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 Rear Mudguard RH	580.00	1 PC	580.00	580.00
2 Rear Tipper Tail Gate	1,950.00	1 PC	1,950.00	1,950.00
3 Rear Tipper Gate Hinge & Pin	480.00	1 ST	480.00	480.00
4 Lock Tail Board	60.00	2 PC	120.00	120.00
5 Tail Board U Sticker Lock	80.00	2 PC	160.00	160.00
			3,290.00	3,290.00
Labour				
6 Labour to cut & weld & renew rear tipper tail gate ,hinge & pin .	950.00	1 JOB	950.00	950.00
7 Labour to renew rear mudguard .	680.00	1 JOB	680.00	680.00
8 To spray & painting at accident area .	800.00	1 JOB	800.00	800.00
			2,430.00	2,430.00
			Total	SS 5,720.00
			Add GST @ 7%	394.80
			Total Amount Payable	SS 6,114.80

TOTAL: SINGAPORE DOLLAR SIX THOUSAND ONE HUNDRED FOURTEEN AND CENTS EIGHTY ONLY.

For MAH LIAN MOTOR VEHICLE
 REPAIRER

AUTHORISED SIGNATURE

Not Authorised
Lab
2/2 \$1200
take photo after repair
2 day.

Auto-Consultants hence notify the Repairer of the following:

- To receive before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This parts survey is on a "Without Prejudice" basis
- No single modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9858C
Vehicle Details	
Vehicle No.:	XD3141B
Vehicle to be Exported:	No
Intended De-registration Date:	27 Dec 2017
Vehicle Make:	ISUZU
Vehicle Model:	CYZ52L
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	6WG1408632
Chassis No.:	JALCY52L87000069
Maximum Power Output:	-
Open Market Value:	\$82,459.00
Original Registration Date:	13 Sep 2008
First Registration Date:	13 Sep 2008
Transfer Count:	2
Actual ARF Paid:	\$4,123.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Sep 2018
COE Category:	C - Goods Vehicle & Bus

COE Period(Years):	10
QP Paid:	\$12,989.00
COE Rebate Amount:	\$923.00
Total Rebate Amount:	\$923.00

The information contained herein is correct as at 27 Dec 2017

OK

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 18 December, 2017 8:48 AM
To: ct-admin@visionlawllc.com; 'jactan@visionlawllc.com'; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: C Meenachi - III
Subject: RE: ACCIDENT ON 14/12/2017 INVOLVING PA8928B (III) & XD3141B
Attachments: 3061_001.pdf; 3117_001.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle XD3141B and let us have your report urgently.

This claim will be handled by Ms Meena.

*Kindly upload this survey request email to merimen.

Thank You.

9.51am @ 18/12/2017
Vehicle Not In
Person @ Pei Fang

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Motor Claim - III
Sent: 15 December, 2017 12:05 PM
To: 'ct-admin@visionlawllc.com' <ct-admin@visionlawllc.com>; 'jactan@visionlawllc.com' <jactan@visionlawllc.com>
Subject: ACCIDENT ON 14/12/2017 INVOLVING PA8928B (III) & XD3141B

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- Automobile Inspection Services Pte Ltd
- Autoprobe Consultants
- VP Appraisal
- Quantum Risk Management
- Ajax Inspection Services Pte Ltd
- Form Team Adjusters Pte Ltd
- Infiniti Appraisal Service
- JP Knights Adjusters
- LBS Auto Consultants Pte Ltd
- Premier Appraisers Services
- Priority Services
- RT Appraisal
- LKK Auto Consultants Pte Ltd

- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: ct-admin@visionlawllc.com [<mailto:ct-admin@visionlawllc.com>]

Sent: 15 December, 2017 10:35 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Scan Image

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D/O MUNIANDY
SEGA PARAM
TIWARY ANURADHA
SHARON PARWANI
ONG BOCK KEE
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YING XIAN SELWYN

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.M46.105299.17 (sj)
Your Ref: PA 8928 B

15 December 2017

INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street
#04/#05 IOB Building
Singapore 049711
Attention: Motor Claims Department

BY FAX: 6224 4174

motorclaim@iii.com.sg

Dear Sirs,

ACCIDENT INVOLVING XD 3141 B & PA 8928 B ON 14 DECEMBER 2017 ALONG PIE TOWARDS TUAS AT ABOUT 0800 HOURS

We refer to your letter dated 15 December 2017 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Marcus from LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Mah Lian Motor Vehicle Repairer
No.38 Defu Lane 9
Singapore 539278
Contact Person: Mr Goh / Ms Si Hui (6282 3336)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALI M
(HEAD OFFICE)

cc: XD 3141 B – by fax only : 6289 3336only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Dec 2017 Edit Reg		18 Dec 2017 00:00 Edit Adj Rpt	S\$1,200.00 Edit Estimates	S\$1,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	RIC-TAT TRANSPORT SERVICE , Co. Reg. No.: 52933528W		
Main Claimant:	YONG LEI SERVICES PTE LTD , Co. Reg. No.: 201109858C		
Vehicle Reg. No.:	XD3141B	Date of Loss:	14/12/2017 08:00 - :59
Claim Type:	TP / MC2017/3201	Policy/Cover Note No.:	M489303
Vehicle Reg. No. (Insured):	PA89288	Policy No. (Claimant):	DMCVSN1732691700
	Excess:		
Repairer:	Mah Lian Motor Vehicle Repairer (HQ) NO. 38 DEFU LANE 9, 539278 Defu Lane - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 29/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XD31418 (MC2017/3201)
[PA8928B]
TP
YONG LEI SERVICES PTE LTD
Dec 14 2017 8:00AM
[RIC-TAT TRANSPORT SERVICE]
Mah Lian Motor Vehicle Repairer

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/01/18 11:24	Odometer Reading		Load JPG	
2	04/01/18 11:24	General View		Load JPG	
3	04/01/18 11:24	Chassis Number		Load JPG	
4	04/01/18 11:24	General View		Load JPG	
5	04/01/18 11:24	General View		Load JPG	
6	04/01/18 11:24	General View		Load JPG	
7	04/01/18 11:24	General View		Load JPG	
8	04/01/18 11:24	General View		Load JPG	
9	04/01/18 11:24	General View		Load JPG	
10	04/01/18 11:24	General View		Load JPG	
11	04/01/18 11:24	General View		Load JPG	
12	04/01/18 11:24	General View		Load JPG	
13	04/01/18 11:24	General View		Load JPG	
14	04/01/18 11:24	General View		Load JPG	
15	04/01/18 11:24	General View		Load JPG	
16	04/01/18 11:24	General View		Load JPG	
17	04/01/18 11:24	General View		Load JPG	
18	04/01/18 11:24	General View		Load JPG	
19	04/01/18 11:24	General View		Load JPG	
20	04/01/18 11:24	General View		Load JPG	
21	04/01/18 11:24	General View		Load JPG	
22	04/01/18 11:24	General View		Load JPG	
23	04/01/18 11:24	General View		Load JPG	

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/12/17 11:41	ACKNOWLEDGEMENT EMAIL TO III DD 18.12.2017		Load PDF	
2	19/12/17 11:41	NOTIFICATION FROM LAWYER		Load PDF	
3	19/12/17 11:41	NOTIFICATION FROM LAWYER		Load PDF	
4	28/12/17 17:08	TP ESTIMATE- MARKED		Load PDF	
5	03/01/18 20:03	TP GIA REPORT		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	20/12/17 08:58	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III17023999/UEA3Q2

Date: 11/01/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: M489303

Claimant Vehicle No: XD3141B

Insured Vehicle No: PA8928B

Date of Loss: 14/12/2017

Nature of Claim: TP Claim No: MC2017/3201

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD3141B

Make & Model: ISUZU CYZ52L, 15.7 D (M)

Engine No: 6WG1408632

Reg. Date: 13/09/2008 (Man. Year: 2008)

Chassis No: JALCYZ52L87000069

Colour: White

Odometer: 693914 km

Engine Capacity: 15681 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D/D)

Front Left Side: Firemax 6 mm

Rear Left Side: Firemax 6/6/6 mm

Front Right Side: Firemax 6 mm

Rear Right Side: Firemax 6/6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,290.00	0.00	3,290.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,430.00	1,200.00	1,230.00	50.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,720.00	1,200.00	4,520.00	79.02
+ GST 7.00/7.00% (S\$)	400.40	84.00	316.40	79.02
Nett Amount (S\$)	6,120.40	1,284.00	4,836.40	79.02
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 18/12/2017

Date Inspected: 27/12/2017 Inspected At:

Mah Lian Motor Vehicle Repairer (HQ)
NO. 38 DEFU LANE 9
Singapore 539278

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Jan 2018)	
Parts:	N/A	ISUZU CYZ52L 15.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD3141B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR MUDGUARD RH	Repair	580.00 F	*- F
2	1		*REAR TIPPER TAIL GATE	Repair	1,950.00 F	*- F
3	1		*SET REAR TIPPER GATE HINGE & PIN	Not Necessary	480.00 F	*- F
4	2		*LOCK TAIL BOARD	Not Necessary	120.00 F	*- F
5	2		*TAIL BOARD U STICKER LOCK	Not Necessary	160.00 F	*- F
Total Parts (S\$)						3,290.00 0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO CUT & WELD & RENEW REAR TIPPER TAIL GATE ,HINGE & PIN }	New	950.00	800.00
2	LABOUR TO RENEW REAR MUDGUARD)	New	680.00	0.00
3	TO SPRAY & PAINTING AT ACCIDENT AREA	New	800.00	400.00
Gross Labour Cost (S\$)			2,430.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >