

INS. CASE OWNER:

CC 4 / LCR170

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II : \$5

D.O.A.:

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check ltr: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

\$5 2272.92

Loss of Rental (LOR):

\$5

( days)

Loss of Use (LOU):

\$5

2w.w (51w x 2 days)

Loss of Income (LOI):

\$5

( \$ x days)

LOR only

LOU only

LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

\$5 3498.27

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

Name 1:

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

SIN

REF: LCR

24006 / 14p3. (P)

A

## ASSIGNMENT

From: \_\_\_\_\_ Date: 26/12/2017

Estimated Cost: \_\_\_\_\_

OD / CV / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKB 6681D

at Workshop m/s: Lim Tan

of: 176 Sin Ming Drive #03-09

Insured: \_\_\_\_\_

Policy No.: \_\_\_\_\_

Claims No.: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_


(Client's Record)

Make of Veh: \_\_\_\_\_

after 10am

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 02 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKB 6681D Yr Regn: 06 11

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw <sup>A</sup> 523i cc: 2497

Colour: M. Grey A/C Insured / Std / NI / NA

Sp. Reading: 91850 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBAFP32080 C866786

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_ R: 245/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal: 4 mm R/Bal: 7 mm

L/Bal: 4 mm L/Bal: 7 mm

D.O.A. 12/12/17 D.O.I. 26/12/17

Survey held at: \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/12 File pass to Corbin

PIP \$ 3058.80 (Red \$ 3764.05 / 524)

Date/Time: File Pass to? ☐ : Preli. Report

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp. (\$

☐ : Interview (\$

☐ : Tech. Insp. (\$

☐ : Weekend (\$

1 \_\_\_\_ \$ + PD \_\_\_\_ \$

Phone

Others

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/LCR17024006/pa3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 19-12-2017		
		Code : LCR		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLM 7079S	Veh. Inspected	SKB 6681D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	19/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	12/12/2017	Inspection Date		
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Kp

Not Authorised  
11 Lng 87  
Putty And Paint  
2 days



**LTM**  
LIM TAN MOTOR  
Kenneth LKK

**ESTIMATE TO REPAIR**

VEHICLE NO. : SKB 6681 D  
MAKE : B.M.W  
MODEL : 523i 2.5 AT ABS D/AB 2WD 4DR GAS/D  
YEAR : 2011  
CHASSIS NO : WBAFP32080C866786

SURVEYOR NAME :  
DATE OF SURVEY : 26 DEC 2017  
TIME OF SURVEY : 10.35am

DATE : 16-Nov-17  
DATE OF ACCIDENT : 12-Dec-17  
THIRD PARTY REF : SLM 7079 S / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper			Butt	\$ 1,610.35 ✓
1 pc	Rear Bumper Tow Cover			\$ 23.25	X
1 pc	O/S Rear Bumper Reflector			\$ 34.35	✓
1 pc	Rear Bumper Diffuser			\$ 170.45	✓
2 pcs	Rear Bumper Retainer	1/5	\$ 141.65	✓ 0/300	\$ 283.30 L+
1 pc	Rear Bumper Reinforcement			\$ 696.80	2x
2 pcs	Rear Bumper Sensor		\$ 231.10	\$ 462.20	X
1 pc	Rear Boot			\$ 1,563.30	X
1 pc	Rear Boot Emblem			\$ 67.80	X
1 pc	Rear Boot Emblem "523i"			\$ 61.05	X
				\$ 4,972.85	
	To putty and spray painting.	PARTS	2448.80		300
		labour	610.00		
	To check rear wiring and replace sensor.	PBP	3058.80	✓	60
	To anti-rust.			01 days run	\$ 50.00 X
	Labour Charges.				\$ 450.00 250
TG-RA/-					\$ 6,322.85
<p>LKK Auto Consultants hereby notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts price are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer: Signature: Date:</p>					APPROVED
			2/1	02 JAN 2018	
			RA	ML	

Lim Tan Motor Pte Ltd

114-116 Sin Ming Drive #03-01 Sin Ming Autocare Singapore 575837

Tel: 65-64589127 Fax: 65-64589127

Email: edmund@LTM.sg

Website: www.LTM.sg

S. Reg No. 199307277D

GST Reg No. M2-0010630-0

This document must not be reproduced in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd



SURVEYOR NAME :	26 DEC 2017
DATE OF SURVEY :	
TIME OF SURVEY :	

DATE : 16-Nov-17  
DATE OF ACCIDENT : 12-Dec-17  
THIRD PARTY REF : SLM 7079 S / AIG

Lien Tan Motor Pte Ltd

Tel: 65-64520893 Fax: 65-64589127 Email: [edmund@LTM.sg](mailto:edmund@LTM.sg) Website: [www.LTM.sg](http://www.LTM.sg)  
 Reg No: 199307277D GST Reg No: M2-0019068-0

## Hsiao Tong (LKKAUTO)

---

**From:** Mandy <mandy@lrm.sg>  
**Sent:** Thursday, 18 January 2018 9:38 AM  
**To:** Shu Pei (LKKAUTO); 'richard'  
**Cc:** Admin A; Hsiao Tong (LKKAUTO); Zaini (LKK Auto)  
**Subject:** RE: Accident Involving SKB6681D & SLM7079S (AIG) on 12/12/2017  
**Attachments:** 0304\_001.pdf

WITHOUT PREJUDICE

Dear Hsiao Tong,

Enclosed please find the LOD for your consideration. Pls seek approval from your Mandate.

Hope to hear from you soon.

Thank you and regards,

*Mandy Lim*

Lim Tan Motor Pte Ltd

[www.LTM.sg](http://www.LTM.sg)

+65 6452 0893 (Office)

+65 6458 9127 (Facsimile)

**Like us in Facebook!!**

[www.facebook.com/LTMsg](https://www.facebook.com/LTMsg)

[www.facebook.com/LTM.Performance.Singapore](https://www.facebook.com/LTM.Performance.Singapore)



# **LIM TAN MOTOR PTE LTD 林陈摩哆私人有限公司**

COMPANY REGISTRATION NO: 199307277D GST REGISTRATION NO: M2-0119086-0

## **MAIN OFFICE / WORKSHOP**

BLK 176 SIN MING DRIVE  
SIN MING AUTOCARE #03-09/10/06  
SINGAPORE 575721

TEL: +65 6452 0893 FAX: +65 6458 9127

EMAIL: [SALES@LTM.SG](mailto:SALES@LTM.SG)

Operating Hours: Mon – Fri 9am – 6 pm Sat 9am – 5pm

24hrs Helpline: +65 64520893

## **BRANCH**

BLK 9 SECTOR C #01-38/40/42  
SIN MING INDUSTRIAL ESTATE  
SINGAPORE 575644

TEL: +65 6452 2135 FAX: +65 6452 2159



[WWW.LTM.SG](http://WWW.LTM.SG)

## **IMPORTANT NOTICE**

This email, including all attachments may contain confidential or legally privileged information.

The sending of this email to any person other than the intended recipient is not a waiver of confidentiality or privilege of the information. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of the company.

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]

**Sent:** Tuesday, January 16, 2018 11:34 AM

**To:** richard <richard@ltm.sg>

**Cc:** mandy@ltm.sg; Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Zaini (LKK Auto) <Zaini@lkkauto.com>

**Subject:** FW: Accident Involving SKB6681D & SLM7079S (AIG) on 12/12/2017

**Importance:** High

Dear Richard,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CC4/LCR17024006/Kpa3	Hsiao Tong - 6742 3197

*To check availability of the case handler, you may contact the undersigned.*

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** richard [mailto:richard@lrm.sg]  
**Sent:** Tuesday, 16 January 2018 10:18 AM  
**To:** Shu Pei (LKKAUTO) <shupeil@lkkauto.com>  
**Cc:** mandy@lrm.sg  
**Subject:** Accident Involving SKB6681D & SLM7079S (AIG) on 12/12/2017  
**Importance:** High

WITHOUT PREJUDICE

Our ref : **LTP112017/152 (SKB 6681 D)**

Good Morning Shu Pei,

We refer to the above claim.

We shall appreciate if you could advise us your file reference and officer-in-charge so as for us to forward the letter of demand.

We look forward hearing from you soonest.

Thank you and regards,

*Richard Ang*

Claims Executive  
Lim Tan Motor Pte Ltd

[www.LTM.sg](http://www.LTM.sg)

+65 6452 0893 (Office)  
+65 6458 9127 (Facsimile)  
+65 8484 5418 (Mobile)

**Like us in Facebook!!**

[www.facebook.com/LTMsg](https://www.facebook.com/LTMsg)

[www.facebook.com/LTM.Performance.Singapore](https://www.facebook.com/LTM.Performance.Singapore)





**LIM TAN MOTOR PTE LTD 林陈摩哆私人有限公司**

COMPANY REGISTRATION NO: 199307277D GST REGISTRATION NO: M2-0119086-0

**MAIN OFFICE / WORKSHOP**

BLK 176 SIN MING DRIVE  
SIN MING AUTOCARE #03-09/10/06  
SINGAPORE 575721

TEL: +65 6452 0893 FAX: +65 6458 9127

**BRANCH**

BLK 9 SECTOR C #01-38/40/42  
SIN MING INDUSTRIAL ESTATE  
SINGAPORE 575644

TEL: +65 6452 2135 FAX: +65 6452 2159

EMAIL: [SALES@LTM.SG](mailto:SALES@LTM.SG)

Operating Hours: Mon – Fri 9am – 6 pm

Sat 9am – 5pm

24hrs Helpline: +65 64520893

[WWW.LTM.SG](http://WWW.LTM.SG)



**IMPORTANT NOTICE**

This email, including all attachments may contain confidential or legally privileged information.

The sending of this email to any person other than the intended recipient is not a waiver of confidentiality or privilege of the information. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of the company.



Date: 17-Jan-18

Your Ref: CC4/LCR17024006/Kpa3

Our ref: LTP122017/152 (SKB 6681 D)

( WITHOUT PREJUDICE )

Attention To : MS CHEW HSIAO TONG (From LKK Auto Consultants Pte Ltd)

Insurance Company : AIG ASIA PACIFIC INSURANCE PTE LTD

Dear Sir/Mdm,

IN THE MATTER OF ACCIDENT INVOLVING SKB6681D & SLM7079S ON 12.12.2017

We refer to the above matter.

We are instructed and authorised by our client to quantify, to act and negotiate settlement in related to the above road traffic accident that was caused by your insured.

All supporting documents are enclosed herewith:-

<input checked="" type="checkbox"/> Authorization To Act	<input checked="" type="checkbox"/> Original Tax Invoice no. INV31928
<input type="checkbox"/> Original Rental Receipt and Agreement	<input checked="" type="checkbox"/> LTA search receipt
<input type="checkbox"/> Letter Of Discharge	<input type="checkbox"/> _____

Survey was done by Insurance instruction and was surveyed by Mr Kenneth  
on 28-Dec-17

As a result of the accident, our client's vehicle was damaged and has been put to loss and Expenses, particulars of which are as follows:-

1 ] Cost of repair (inclusive of 7% GST)	\$ 3,272.92 ✓
2 ] Loss of Use @ \$120.00 x 2 Days	\$ 240.00 ✓
3 ] LTA Search Fees	\$ 5.35 ✓
	<u>\$ 3,518.27</u>

Please acknowledge receipt of this letter within 14 days. If you agreeable to the above, please forward your payment. Payment to be issued directly to LIM TAN MOTOR PTE LTD within 4 weeks. Should there be any injury related to this matter, any settlement agreed is WITHOUT PREJUDICE to the related injury claim.

Your faithfully

**Mandy Lim**

Email: mandy@ltm.sg

Lim Tan Motor Pte Ltd

511 125 5th May Drive #03-05 5th May Arcade Singapore 395221

Tel: 65-64520883 Fax: 65-64589127

Website: www.LTM.sg

Co.Reg No. 1993072771

UEN: Reg No. A0500154086-4

(This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd)

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Thursday, 18 January 2018 6:27 PM  
**To:** 'Mandy'; Shu Pei (LKKAuto); 'richard'  
**Cc:** Admin A; Zaini (LKK Auto)  
**Subject:** RE: Accident Involving SKB6681D & SLM7079S (AIG) on 12/12/2017

Without Prejudice

Hi Mandy,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 3,272.92
2. Loss of Use (2days x \$100.00)	\$ 200.00
3. LTA/ GIA Search Fee	\$ 5.35
<b>TOTAL</b>	<b><u>\$ 3,478.27</u></b>

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mandy [mailto:[mandy@ltm.sg](mailto:mandy@ltm.sg)]  
**Sent:** Thursday, 18 January 2018 9:38 AM  
**To:** Shu Pei (LKKAuto) <[shupeil@lkkauto.com](mailto:shupeil@lkkauto.com)>; 'richard' <[richard@ltm.sg](mailto:richard@ltm.sg)>  
**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>; Zaini (LKK Auto) <[Zaini@lkkauto.com](mailto:Zaini@lkkauto.com)>  
**Subject:** RE: Accident Involving SKB6681D & SLM7079S (AIG) on 12/12/2017

WITHOUT PREJUDICE

Dear Hsiao Tong,

Enclosed please find the LOD for your consideration. Pls seek approval from your Mandate.

## Hsiao Tong (LKKAUTO)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Thursday, 21 December, 2017 11:45 AM  
**To:** 'Eileen, May Hwee Yap'  
**Subject:** ACCIDENT INVOLVING SLM 7079S(AIG) & SKB 6681D ON 12/12/2017

Your Ref: **SLM 7079S**  
Our Ref: CC4/LCR17024006/pa3

Dear Sirs/Madam,

### **ACCIDENT INVOLVING SLM 7079S(AIG) & SKB 6681D ON 12/12/2017**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SKB 6681D against your insurance policy.

Based on the information on hand, we are of the opinion that liability is not in our favour.  
We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

*"Wishes you a Merry Christmas & Happy New Year 2018"*

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


To Whom It May Concern

**AUTHORIZATION TO ACT**

I/We, WONG YING YING GINA (HUANG YINGYING) ('the third party Claimant') of 23 LORONG 3 TOA PAYOH #15-11 SINGAPORE 319582 (Address) Owner of SKB6681D (vehicle number) hereby authorize LIM TAN MOTOR PTE LTD ('the workshop') to act for me with respect to my/our claim for repair costs and/or rental and/or Loss of use ('claim') for my/our vehicle number SKB6681D that was damaged pursuant to the accident which occurred on 12-Dec-17 (date) Along UPPER CHANGI ROAD (locate on) involving vehicle number SLM7079S (the accident').

I/We further authorize the workshop to settle my above mentioned claim in a Manner that they deem fit and the workshop is further authorized to receive Payment further to settlement of my claim with payment cheque/s being made In favour of the workshop.

Dated this 16 (day) of December (month) 2017 (year)

  
Signed By ' the third party claimant'



  
Signed By ' the workshop'

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, LIM TAN MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 3,272.92 (Repair Cost), S\$ 200.00 (Loss of Use), S\$ 5.35 (Disbursement) for vehicle no. SKB 6681 D that was damaged pursuant to the accident which occurred on 12 DECEMBER 2017 (date) along UPPER CHANGI ROAD (location) involving vehicle no/s SLM 7079 S. This is pursuant to the inspection conducted on 26 DECEMBER 2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner WONG YING YING GINA (HUANG YINGYING) ("the third party claimant") of vehicle no. SKB 6681 D make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKB 6681 D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 9<sup>th</sup> (day) of MARCH (month) 2018 (year)



KSC

Signed by appointed surveyor



Signed by "the workshop" (with chop)



**LIM TAN MOTOR PTE LTD**  
**林陳摩哆私人有限公司**

Company's Registration No: 199501273D  
GST Registration No: M2-011808A-01

**Branch**  
(Warranty and Performance) Blk 9 Sector C #01-38/40/42  
Sin Ming Industrial Estate, Singapore 575644  
Tel: +65 6452 2135 Fax: +65 6452 2159

Blk 17 Sector A #01-65  
Sin Ming Industrial Estate, Singapore 575675

**Main Office / Workshop**  
Blk 176 Sin Ming Drive #03-09/10/06  
Sin Ming Autocare Singapore 575721

Tel: +65 6452 0893 (24Hrs)  
Fax: +65 6458 9127  
Email: sales@LTM.sg

**WWW.LTM.SG**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120

ATTN : MOTOR CLAIMS DEPT  
TEL :  
FAX :  
A/C NO. : 30A0/097

MILEAGE :  
W.O NO. : SO32596  
CAR NO. : SKB6681D  
MAKE : BMW  
MODEL : 523I

**TAX INVOICE**

NO : INV31928  
DATE : 13-01-2018  
TERMS : CASH  
PAGE : 1

DESCRIPTION	QTY	U.PRICE	DIS	AMOUNT
1 REAR BUMPER	1 PCS	1,610.35		1,610.35
2 C/S REAR BUMPER RETAINER	1 PCS	141.65		141.65
3 REAR BUMPER REINFORCEMENT	1 PCS	696.80		696.80
4 TO PUTTY & SPRAY PAINT	1 UNIT	300.00		300.00
5 TO CHECK REAR WIRING AND REPLACE SENSOR	1 UNIT	60.00		60.00
6 LABOUR CHARGES	1 UNIT	250.00		250.00

SINGAPORE DOLLARS : THREE THOUSAND TWO HUNDRED SEVENTY TWO AND NINETY TWO CENTS ONLY

REMARKS: DATE OF ACCIDENT: 12.12.2017  
REF: SLM7079S

TOTAL QTY: 6.00

SUBTOTAL	3,058.80
DISCOUNT	0.00
TOTAL	3,058.80
GST 7 %	214.12
NET	3,272.92
Deposit	0.00
Balance	3,272.92



AUTHORISED SIGNATURE(S)

CUSTOMER NAME / SIGNATURE / DATE

Customer Acknowledgement

I/We confirm that I/We incurred the repair costs herein and will observe my/our Agreement with the repairer. I/We declare the repair for the above vehicle have been completed to my/our satisfaction



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 15 Dec 2017 / 11:33:39

Receipt Date/Time : 15 Dec 2017 / 11:33:39

## Tax Invoice/Receipt

Receipt No. : ITNET-00000-171215-000888

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SLM7079S			
	As at 12 Dec 2017/10:00:00			
	Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.			
1	Insurance Enquiry - SLM7079S			
	Enquiry Fee	5.00	0.35	5.35
	20171215113159686525			
	<b>Sub-Total</b>	5.00	0.35	5.35
	<b>Total Before Rounding</b>	5.00	0.35	5.35
	<b>Rounding Difference</b>			0.00
	<b>Total Amount Payable</b>			5.35
	<b>Paid By</b>			
	xxxxxxxxxxxx7458			
	Credit Card:			
	Visa/MasterCard			5.35
	<b>Total</b>			5.35
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			5.35
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Dec 2017 <a href="#">Edit Reg</a>		18 Dec 2017 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,058.80</b> <a href="#">Edit Estimates</a>	<b>S\$3,058.80</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Main Claimant:	WONG YING YING GINA, ID: S7006300Z		
Vehicle Reg. No.:	SKB6681D	Date of Loss:	12/12/2017 10:00 - :59
Claim Type:	TP / 3038131407SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLM7079S	Policy No. (Claimant):	10506394
	Excess:		
Repairer:	Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care, 575721 Sin Ming - Tel: 6452 0893		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]		
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/12/2017]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SKB6681D (3038131407SG)**  
**[SLM7079S]**

**TP**

**WONG YING YING GINA**

**Dec 12 2017 10:00AM**

**[LCRF PTE LTD]**

**Lim Tan Motor Pte Ltd**

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)
**View**
[View in Browser](#)

### Letters/Correspondences

No	Finalized On		1 per page	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit	

### Documentation

No	Relabel/Reorder		1 per page	Thumbnail	Print
1	19/12/17 11:54	ACKNOWLEDGEMENT EMAIL TO AIG DD 18.12.2017	1	Load PDF	
2	19/12/17 11:54	EMAIL FROM AIG DD 18.12.2017	1	Load PDF	
3	19/12/17 11:54	TP GIA REPORT	1	Load PDF	
4	27/12/17 18:28	TP ESTIMATE - MARKED	1	Load PDF	
5	12/03/18 12:12	WORKSHOP INVOICE	1	Load PDF	
6	12/03/18 12:12	AUTHORISATION TO ACT FORM	1	Load PDF	
7	12/03/18 12:12	Release Voucher	1	Load PDF	
8	12/03/18 12:12	LTA SEARCH	1	Load PDF	
9	12/03/18 12:12	LETTER TO OI	1	Load PDF	
No	Finalized On			Thumbnail	Print
1	20/12/17 11:33	OI GIA REPORT	1	Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SLM7079S (Insd veh)	Model:	BMW 523I 2.5 AT ABS D/AB
	SKB6681D (TP veh)		2WD 4DR GAS/D NAV (A)
Date of Accident:	12/12/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	6,765.45
Final Repair Cost	:	\$	3,272.92
Loss of Use	:	\$	200.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	5.35
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,478.27

2.00 days at \$100.00 per day  
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Lim Tan Motor Pte Ltd	:	\$ 3,478.27
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

12 Mar  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR17024006/KPA3Q2

Date: 12/03/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No: SKB6681D

Insured Vehicle No: SLM7079S

Date of Loss: 12/12/2017

Nature of Claim: TP

Claim No: 3038131407SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKB6681D

Make &amp; Model: BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) Engine No: 11297787N52B25AF

Reg. Date: 17/06/2011 (Man. Year: 2011)

Chassis No: WBAFP32080C866786

Colour: Metallic Grey

Odometer: 91950 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/45 R18

Rear Tyre Size: 245/45 R18

Front Left Side: Yokohama 4 mm

Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 4 mm

Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,972.85	2,448.80	2,524.05	50.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	610.00	740.00	54.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,322.85</b>	<b>3,058.80</b>	<b>3,264.05</b>	<b>51.62</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>442.60</b>	<b>214.12</b>	<b>228.48</b>	<b>51.62</b>
<b>Nett Amount (S\$)</b>	<b>6,765.45</b>	<b>3,272.92</b>	<b>3,492.53</b>	<b>51.62</b>
<b>+ Loss of Use (2.0 x S\$100.00/day) (S\$)</b>		<b>200.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>5.35</b>		
<b>Nett Liability (S\$)</b>		<b>3,478.27</b>		

### INSPECTION

Date of Assignment: 18/12/2017

Date Inspected: 26/12/2017 Inspected At:

 Lim Tan Motor Pte Ltd (HQ)  
 Blk 176 Sin Ming Drive #03-09/10, Sin  
 Ming Auto Care  
 Singapore 575721

Estimated Period of Repair: 2.0 days

---

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	1,610.35 F	*1,610.35 F
2	1		*REAR BUMPER TOW COVER	Serviceable	23.25 F	*- F
3	1		*O/S REAR BUMPER REFLECTOR	Serviceable	34.35 F	*- F
4	1		*REAR BUMPER DIFFUSER	Serviceable	170.45 F	*- F
5	1		*REAR BUMPER RETAINER	O/S Distorted	283.30 F	*141.65 F
6	1		*REAR BUMPER REINFORCEMENT	Bent	696.80 F	*696.80 F
7	2		*REAR BUMPER SENSOR	Serviceable	462.20 F	*- F
8	1		*REAR BOOT	Repair	1,563.30 F	*- F
9	1		*REAR BOOT EMBLEM	Not Necessary	67.80 F	*- F
10	1		*REAR BOOT EMBLEM 523I	Not Necessary	61.05 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>4,972.85</b>	<b>2,448.80</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY AND SPRAY PAINTING	New	700.00	300.00
2	TO CHECK REAR WIRING AND REPLACE SENSOR	New	150.00	60.00
3	TO ANTI-RUST	New	50.00	0.00
4	LABOUR CHARGES	New	450.00	250.00
Gross Labour Cost (S\$)			1,350.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >