

Not Authorised  
11 days 87  
Rearview After Paint  
2 days



# ESTIMATE TO REPAIR

VEHICLE NO. : SKB 6681 D  
MAKE : B.M.W  
MODEL : 523i 2.5 AT ABS D/AB 2WD 4DR GAS/D  
YEAR : 2011  
CHASSIS NO : WBAFP32080C866786

SURVEYOR NAME :  
DATE OF SURVEY : 26 DEC 2017  
TIME OF SURVEY :

DATE : 16-Nov-17  
DATE OF ACCIDENT : 12-Dec-17  
THIRD PARTY REF : SLM 7079 S / AIG

| Qty                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | Parts Description/ Labour                | Type | Unit Price | Nett Item Amt | Amount        |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------|------|------------|---------------|---------------|
| 1 pc                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | Rear Bumper                              |      |            | Butler        | \$ 1,610.35 ✓ |
| 1 pc                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | Rear Bumper Tow Cover                    |      |            | \$ 23.25      | X             |
| 1 pc                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | O/S Rear Bumper Reflector                |      |            | \$ 34.35      | 7             |
| 1 pc                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | Rear Bumper Diffuser                     |      |            | \$ 170.45     | 7             |
| 2 pcs                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | Rear Bumper Retainer                     |      | \$ 141.65  | disney        | \$ 283.30 4   |
| 1 pc                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | Rear Bumper Reinforcement                |      |            | \$ 696.80     | 7             |
| 2 pcs                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | Rear Bumper Sensor                       |      | \$ 231.10  | in            | \$ 462.20 X   |
| 1 pc                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | Rear Boot                                |      |            | \$ 1,563.30   | X             |
| 1 pc                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | Rear Boot Emblem                         |      |            | \$ 67.80      | X             |
| 1 pc                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   | Rear Boot Emblem "523i"                  |      |            | \$ 61.05      | X             |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |                                          |      |            |               | \$ 4,972.85   |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | To putty and spray painting.             |      |            |               | \$ 700.00 300 |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | To check rear wiring and replace sensor. |      |            |               | \$ 150.00 60  |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | To anti-rust.                            |      |            | un            | \$ 50.00 X    |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | Labour Charges.                          |      |            |               | \$ 450.00 250 |
| TG-RA/-                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |                                          |      |            |               | \$ 6,322.85   |
| <div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div> |                                          |      |            |               |               |

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel: 65-64520893 Fax: 65-64589127

Email: edmund@LTM.sg

Website: www.LTM.sg

Co Reg No. 199307277D

GST Reg No M2-0019086-0