

ASSIGNMENT

DOI: 18/12/17

Date / Time: 18/12/18

Registered in Merimen: 19/12/18

Pre-assign / CCU / FTE

Insured Vehicle No.: SLL 2497 G

Name of Insured: CHOW PIN CHENG

Insured Tel No.: HP: 87337445

Excess Sec II :SS: D.O.A: 18/12/17

Is driver the owner? (YES / NO) Nature of Accident:

If NO, Driver Name / Age: JANE CHIA LING HUAN

Driver Tel No.: 87780816 (V/L: YES / NO)

Claim No.: 2100501303

Policy No.: MISSAN EASTERN

Make / Model: JB CHICKPOINT - WOODLAND

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

80019734

INSRS:
WSP: HUA MANG
Tel:
Liability:
RMKS:

INSRS:
WSP:
Tel:
Liability:
RMKS:

INSRS:
WSP:
Tel:
Liability:
RMKS:

INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time		STAGE	DATE / PIC
21.11	80019734 - call AIA 20/11/18 / Hua Mang	Non-Reporting ltr (1st):	
1/12	80019734 / AIG 170 23924 / 24 - 08/12/18	Non-Reporting ltr (2nd):	
	* Pending Estimate.	Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	THIN
		After call ltr to OI:	22/11/18
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice	
		LTA / GIA :	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE

Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 28/1/19

Confirm with: June

Email

Call

Final Liability:

% 50

(Agreed / Assessed) BOLA S/N No.: NIL

If NO or B 28, Ass. Lia:

Repair Cost:

SS 800.00

SS 400.00

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS 100.00

(SS x 2 days)

Loss of Income (LOI):

SS

(SS x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS 5.35

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format: 1

3) Survey fee: 320.00

Total:

SS 500.35

Global Sum SS: 500.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 500.00

Name 1: Hua Mang Spray Painting Workshop

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF:

SURVEY

ASSIGNMENT

From _____ Date _____

Estimated Cost _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No _____

Claims No _____

Sum Insured _____

Excess _____

(Client's Record)

Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bel. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / FR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or NoLump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date _____ Person Contacted _____

Vehicle: IN / OUT

Veh No: SLD1978Y Yr Reg: 2010 JunType: M/Car M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish C.C. 1987Colour: Silver A/C Insured / Std / NI / NASp Reading: 109417 T.Radio: Insured / Std / NI / NA

Eng/No: _____

C/Nr: JTDGJ20W805201802Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orMod: Nil / SiRim / STD A/Rim orTyre Size: F: 155/65 R15R: 195/65 R15BS / DUN / EXNOVA / GY / FS / LIZA / MAX / OHTSU / PIR / SUMI /TOYO / YOKO or Maxtrex

Front

Rear

R/Bal: 06 mm R/Bal: 06 mmL/Bal: 06 mm L/Bal: 06 mmD.O.A. _____ D.O.I. 18/12/17Survey held at Hua MengDes. of Damages: Frt / Rear / O/S N/S / V/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

TP ~~MAINT~~ ALG.

45 \$ SW CRD \$ 455.13 / 866

Date/Time File Pass to?

☐ : Prel. Report

Days Of Repair: _____

Date/Time File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time File Return to?

Transportation: _____

Date/Time File Return to?

Add Fee: ☐ Site Insp \$☐ Interview \$☐ Techn. Ins \$☐ Weekend \$

Photo: _____

Other: _____

Report Format: _____

Lump Sum / I.B.I: \$ _____

TOTAL: _____

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

DAWN ENTERPRISE
21 SELETAR WEST FARMWAY 1
S 798125

TP. ALG.
Thin Thin

Date :19.01.2018
Vehicle no :SLD 1973 Y
Make/Model :TOYOTA WISH
Accident date :18.12.2017

No	Description	Qty	Amount (\$S)
List Items			
1	Rear bumper <i>Rp</i>	1	\$ 541.1 ✓
2	Rear bumper side holder @ \$98.90 <i>new</i>	2	\$ 197.8 ✓
3	Rear RH fender <i>Rp</i>	1	\$ 1002.5 ✓
4	Rear RH fender quarter glass rubber <i>new</i>	1	\$ 496.2 ✓
5	Rear RH door <i>Rp</i>	1	\$ 1533.5 ✓
			\$ 3771.1
Less 25% Disc			\$ 942.77
Total			\$ 2828.33

Special Nett Items

1	Rear RH sport rim <i>et</i>	1	\$ 800 <i>400</i> <i>100</i>
2	Rear RH tyre <i>new</i>	1	\$ 280 ✓
Total			\$ 1080

Labour Cost

1	Remove ,replace & repair consistent to the accident	700	\$ 900 <i>150</i> <i>100</i>
2	Respray painting		\$ 150 <i>300</i> <i>600</i>
3	Remove & reinstall rear RH quarter glass		\$ 800 ✓
Total			\$ 1850
Grand Total			\$ 5758.33

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price are subject to confirmation
- Third party liability is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 1100
+ 5 = 800 ✓
02 Days.



華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680

Reg. No.: 25487B/00M



Your Ref :

Our Ref :

Date: 25.05.2018

Attn: Motor Claims Dept

ACCIDENT ON 18.12.2017 INVOLVING VEHICLE SLD 1973 Y & SLL 2497 G ALONG
MALAYSIA CHECKPOINT

With regards to the above, we are writing on behalf of the registered owner of vehicle SLD 1973 Y which was involved in the above mentioned accident.

We are informed that the above accident was caused solely by the negligence of your insured vehicle SLL 2497 G. As a result of the accident, our client's vehicle was damaged and our client had instructed us to submit his claims for loss and expenses, particulars of which are follows:

1) Repair Cost	\$	800.00
2) Loss of use-\$150 X 03days	\$	450.00
3) LTA serach	\$	5.35
Total	\$	1,255.35

We hereby enclosed herewith the following documents for your consideration of the above claim.

a) Final Repair Bill Of SLD 1973 Y

c) LTA SEARCH

b) GIA report

d) Owner / Driver NRIC & Driving License

華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP
AUTOBAY@KAKI BUKIT

1, KAKI BUKIT AVE 6 #01-34 SINGAPORE 417883
Yours faithfully,
Tel: 6747 8064, 6746 5519 FAX: 6743 4896
HUA MENG SPRAY PAINTING WORKSHOP

Hsiao Tong (LKKAuto)

From: Hua Meng <huameng@live.com.sg>
Sent: Monday, 25 March 2019 2:10 PM
To: Hsiao Tong (LKKAuto)
Subject: Re: ACCIDENT ON 18/12/2017 INVOLVING VEHICLES SLD 1973Y AND SLL 2497G
//LKK REF: CC6/AIG17024007/Apa3

Dear HsiaoTong

Please let us have your DV asap.

Thanks & Regards

June

Hua Meng Spray Painting Workshop

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Friday, March 15, 2019 8:09 AM
To: Hua Meng
Cc: Admin A
Subject: RE: ACCIDENT ON 18/12/2017 INVOLVING VEHICLES SLD 1973Y AND SLL 2497G //LKK REF: CC6/AIG17024007/Apa3


Without Prejudice

Dear Sirs/Mdm.

We refer to the above matter.

We are of the opinion that this is a case of conflicting versions. There is no concrete evidence (ie: Video footage) yet to support either party's version. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 18/1/17 02:47 I was travelling along JB checkpoint road
 JB checkpoint road and it was congested along the way. My vehicle
 was stationary stopped along lane 2. Suddenly vehicle A travelling along
 lane 3 trying cut into my lane and collided into my vehicle front
 left portion.

For an amicable settlement, we are prepared to offer at a global sum of \$500.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hua Meng <huameng@live.com.sg>

Sent: Tuesday, 5 March 2019 2:47 PM

To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>

Subject: Re: ACCIDENT ON 18/12/2017 INVOLVING VEHICLES SLD 1973Y AND SLL 2497G

URGENT

Dear HsiaoTong

We refer our tele-conversation last week, please revert urgently.

Thanks & Regards

June

Hua Meng Spray Painting Workshop

From: Hua Meng <huameng@live.com.sg>

Sent: Friday, October 19, 2018 4:29 PM

To: Thin Thin (LKKAUTO)

Subject: Re: ACCIDENT ON 18/12/2017 INVOLVING VEHICLES SLD 1973Y AND SLL 2497G

Dear ThinThin

We have sent you numerous email for offer revert but till-to-date we have no heard from you.

We will pass to lawyer to settle.

Thanks & Regards

June

Hua Meng Spray Painting Workshop

From: Hua Meng <huameng@live.com.sg>

Sent: Thursday, October 4, 2018 2:25:16 PM

To: Thin Thin (LKKAUTO)

Subject: Re: ACCIDENT ON 18/12/2017 INVOLVING VEHICLES SLD 1973Y AND SLL 2497G

URGENT

Dear ThinThin

Please revert us your offer soonest.

Thanks & Regards

June

Hua Meng Spray Painting Workshop

From: Hua Meng <huameng@live.com.sg>

Sent: Monday, October 1, 2018 4:29:10 PM

To: Thin Thin (LKKAUTO)

Subject: Re: ACCIDENT ON 18/12/2017 INVOLVING VEHICLES SLD 1973Y AND SLL 2497G

Dear ThinThin

Kindly revert your offer urgently.

Thanks & Regards

June

From: Hua Meng <huameng@live.com.sg>
Sent: Friday, September 28, 2018 4:46:35 PM
To: Thin Thin (LKKAuto)
Subject: Re: ACCIDENT ON 18/12/2017 INVOLVING VEHICLES SLD 1973Y AND SLL 2497G

Dear ThinThin

We do not have evidence.

Photo is taken after accident.

Kindly let us have your revert urgently.

Thanks & Regards

June

From: Thin Thin (LKKAuto) <thinthin@lkkauto.com>
Sent: Thursday, January 11, 2018 11:47:08 AM
To: Hua Meng
Subject: ACCIDENT ON 18/12/2017 INVOLVING VEHICLES SLD 1973Y AND SLL 2497G

"Without Prejudice"

Dear June,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is unclear for the above mentioned case. There is no conclusive evidence to substantiate either party's version. Enclosed herewith is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request the CCTV footage / accident scene photos / evidence in order to seek further instruction from our principal.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG17024007/Aua3

22 NOVEMBER 2018

CHEW PIN CHENG

BLK 816 WOODLANDS STREET 82

#06-453

SINGAPORE 730816

Dear Sir/Madam,

ACCIDENT INVOLVING SLL 2497G & SLD 1973Y ON 18/12/2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter. Based on both parties statement, we are of the opinion that this is a case of conflicting versions (both parties reported changing lane). There is no conclusive evidence to substantiate either's parties version. Therefore, we will proceed to negotiate and settle with Third Party at 50/50 liability due to lack of evidence from both parties.

If you have evidence/information to proof that we should not settle the third party claim, kindly let us have them in writing within the next 7 days i.e. by 30/11/2018, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING

Case Handler

DID: 6841 2360

Fax: 6741 4108

Email: thinthin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT

I/We, Dawn Enterprises ("the third party claimant") of
21 Sultan West Farmway, S(798175) (address),
owner of SLD1983Y (vehicle no.) hereby authorise **HUA MENG SPRAY PAINTING**
WORKSHOP ("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLD1983Y that was damaged pursuant
to the accident which occurred on 18.12.2017 (date) along Malaysia checkpoint
(location) involving vehicle no/s SLL2897G ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem
fit and the workshop is further authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 18 (day) of 12 (month) 20 17 (year)



Signed by "the third party claimant"
(with company stamp if applicable)

華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP
AUTOBAI@KAKI BUKIT
1 KAKI BUKIT AVE 6 #01-34 SINGAPORE 417885
TEL: 6747 8064, 6748 5519 FAX: 6743 4896

Signed by "the workshop"
(with company stamp)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, HUA MENG SPRAY PAINTING WKSP ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$500.00 (Global Sum) for vehicle no. SLD 1973Y that was damaged pursuant to the accident which occurred on 18/12/2017 (date) along MALAYSIA CHECKPOINT involving vehicle no/s SLL 2497G.

This is pursuant to the inspection conducted on 18/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner DAWN ENTERPRISE (the third party claimant") of vehicle no. SLD 1973Y make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLD 1973Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 29 (day) of 03 (month) 2019 (year)



Signed by appointed surveyor

華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOI
AUTOBAY@KAKI BUKIT
1 KAKI BUKIT AVE 6 #01-34 SINGAPORE 41788
TEL: 6747 8064, 6746 5519 FAX: 6743 489

Signed by "the workshop" (with chop)

WITHOUT PREJUDICE
TO OUR CLIENTS PERSONAL INJURY
CLAIM (PRESENT OR FUTURE) WHICH IS
EXPRESSLY RESERVED



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP
AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
Reg. No.: 254678/00M



Your Ref :

Our Ref :

18/5/2018

Date:

VEHICLE NO :SLD 1973 Y
MAKE / MODEL :TOYOTA WISH
NAME :DAWN ENTERPRISES
ADDRESS :21 SELETAR WEST FARMWAY 1
S 798125

FINAL REPAIR BILL FOR VEHICLE NO:SLD 1973 Y

TO SUPPLY AND REPLACE PARTS, LABOUR CHARGES FOR
REPAIRING, KNOCKING, WELDING AND TO RESPRAY PAINTING
(LUMP SUM REPAIR)

\$ 800.00

SINGAPORE DOLLARS:EIGHT HUNDRED ONLY



Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 18 Dec 2017 / 12:20:40

Receipt Date/Time : 18 Dec 2017 / 12:20:40

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171218-000860

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLM7542X As at 12 Dec 2017/19:40:00 Insurance Co: GREAT AMERICAN INSURANCE COMPANY				
1	Insurance Enquiry - SLM7542X Enquiry Fee 20171218121944246143	5.00	0.35	5.35
Sub-Total		5.00	0.35	5.35
Result of Insurance Enquiry - SLR7558A As at 09 Dec 2017/09:30:00 Insurance Co: NTUC INCOME INS CO-OP LTD				
2	Insurance Enquiry - SLR7558A Enquiry Fee 20171218121944294269	5.00	0.35	5.35
Sub-Total		5.00	0.35	5.35
Result of Insurance Enquiry - SJL7035Y As at 15 Dec 2017/18:30:00 Insurance Co: TOKIO MARINE INSURANCE SINGAPORE LTD				
3	Insurance Enquiry - SJL7035Y Enquiry Fee 20171218121944325664	5.00	0.35	5.35
Sub-Total		5.00	0.35	5.35
Result of Insurance Enquiry - SLL2497G As at 18 Dec 2017/02:40:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
4	Insurance Enquiry - SLL2497G Enquiry Fee 20171218121944366819	5.00	0.35	5.35
Sub-Total		5.00	0.35	5.35
Total Before Rounding		20.00	1.40	21.40
Rounding Difference				0.00
Total Amount Payable				21.40
Paid By				
	20171218121957636	Direct Debit: eNETS Debit (Internet Banking)		21.40
Total				21.40
Cash Change				0.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Dec 2017 Edit Reg		18 Dec 2017 00:00 Edit Adj Rpt	S\$800.00 Edit Estimates	S\$800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CHEW PIN CHENG, ID: S8315259A								
Main Claimant:	DAWN ENTERPRISES, Co. Reg. No.: 43005800D								
Vehicle Reg. No.:	SLD1973Y	Date of Loss:	18/12/2017 02:00 - :59 [95 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 11534847905G	Policy/Cover Note No.:	2100501303						
Vehicle Reg. No. (Insured):	SLL2497G	Policy No. (Claimant):	SD17V09247/VPZ/R06						
		Excess:							
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 29/12/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLD1973Y (1153484790SG)
[SLL2497G]
TP
DAWN ENTERPRISES
Dec 18 2017 2:00AM
[CHEW PIN CHENG]
Hua Meng Spray Painting Workshop

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <div>View in Browser</div>		
Video														1 per page		<div></div>	<div></div>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail	Print		
1	26/06/18 17:27	Video - Accident From: SC - Reg. No: SLL2497G, Claimant: CHEW PIN CHENG											<div></div>	Load MP4			
2	26/06/18 17:27	Video - Accident From: SC - Reg. No: SLL2497G, Claimant: CHEW PIN CHENG											<div></div>	Load MP4			
3	26/06/18 17:27	Video - Accident From: SC - Reg. No: SLL2497G, Claimant: CHEW PIN CHENG											<div></div>	Load MP4			
Letters/Correspondences														1 per page		<div></div>	<div></div>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown											<div></div>	Edit			
Assessment Reports														1 per page		<div></div>	<div></div>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail	Print		
1	20/12/17 11:24	Accident Statement From: SC - Reg. No: SLL2497G, Claimant: CHEW PIN CHENG											<div></div>	Load HTM			
Photos/Images														3 per page		<div></div>	<div></div>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	09/05/18 13:51	General View											<div></div>	Load JPG	<div></div>		
2	09/05/18 13:51	General View											<div></div>	Load JPG	<div></div>		
3	09/05/18 13:51	General View											<div></div>	Load JPG	<div></div>		
4	09/05/18 13:51	General View											<div></div>	Load JPG	<div></div>		
5	09/05/18 13:51	General View											<div></div>	Load JPG	<div></div>		
6	09/05/18 13:51	General View											<div></div>	Load JPG	<div></div>		
7	09/05/18 13:51	General View											<div></div>	Load JPG	<div></div>		
8	09/05/18 13:51	General View											<div></div>	Load JPG	<div></div>		
9	09/05/18 13:51	Reinspection Photo											<div></div>	Load JPG	<div></div>		
10	09/05/18 13:51	Reinspection Photo											<div></div>	Load JPG	<div></div>		
Documentation														1 per page		<div></div>	<div></div>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	20/12/17 09:28	TP GIA REPORT											<div></div>	Load PDF			
2	29/03/19 10:57	TP ESTIMATE_MARKED											<div></div>	Load PDF			
3	29/03/19 10:57	LETTER TO OI_											<div></div>	Load PDF			
4	04/04/19 15:11	WORKSHOP INVOICE											<div></div>	Load PDF			
5	04/04/19 15:11	AUTHORISATION TO ACT FORM											<div></div>	Load PDF			
6	04/04/19 15:11	Release Voucher											<div></div>	Load PDF			
7	04/04/19 15:11	LTA SEARCH											<div></div>	Load PDF			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail	Print		
1	26/06/18 17:29	TP GIA											<div></div>	Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLL2497G (Insd veh)	Model:	TOYOTA WISH 2.0 (A)
	SLD1973Y (TP veh)		
Date of Accident:	18/12/2017		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	6,508.32
Final Repair Cost	:	\$	500.00
Loss of Use	:	\$	2.00 days at \$100.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	500.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability 50 (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Hua Meng Spray Painting Workshop	:	\$ 500.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

04 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17024007/APA3Q2

Date: 04/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100501303
Claimant Vehicle No : SLD1973Y **Insured Vehicle No :** SLL2497G
 Date of Loss: 18/12/2017 Nature of Claim: TP Claim No: 1153484790SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD1973Y**
 Make & Model: TOYOTA WISH, 2.0 (A) Engine No: 3ZRA434229
 Reg. Date: 04/01/2010 (Man. Year: 2009) Chassis No: JTDGJ20W805001802
 Colour: Silver Odometer: 109417 km
 Engine Capacity: 1987 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Maxtrex 6 mm Rear Left Side: Maxtrex 6 mm
 Front Right Side: Maxtrex 6 mm Rear Right Side: Maxtrex 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,908.32	400.00	3,508.32	89.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	700.00	1,900.00	73.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,508.32	1,100.00	5,408.32	83.10
Approved Total (Overridden) (S\$)		800.00		
Nett Amount (S\$)	6,508.32	800.00	5,708.32	87.71
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
(S\$)		1,000.00		
Liabe Amount (50.00%) (S\$)		500.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		505.35		
Global Sum Settlement (S\$)		500.00		

INSPECTION

Date of Assignment: 18/12/2017
 Date Inspected: 18/12/2017 Inspected At:

Hua Meng Spray Painting Workshop (HQ)
No 1 Kaki Bukit Avenue 6, #01-61
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	541.10 FL	*- FL
2	2		*REAR BUMPER SIDE HOLDER	Not Necessary	197.80 FL	*- FL
3	1		*REAR RH FENDER	Repair	1,002.50 FL	*- FL
4	1		*REAR RH FENDER QUARTER GLASS RUBBER	Not Necessary	496.20 FL	*- FL
5	1		*REAR RH DOOR	Repair	1,533.50 FL	*- FL
6	1		*REAR RH SPORT RIM	Cut	800.00 FS	*400.00 FS
7	1		*REAR RH TYRE	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,851.10	400.00
- List Item Discount on L Items 25.00/25.00% (S\$)	942.78	0.00
Total Parts (S\$)	3,908.32	400.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	900.00	100.00
2	RESPRAY PAINTING	New	900.00	600.00
3	REMOVE & REINSTALL REAR RH QUARTER GLASS	New	800.00	0.00
Gross Labour Cost (S\$)			2,600.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >