

Survivor

DOI:

ASSIGNMENT

Date / Time

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II : S\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

OS reversed into parking lot and collided onto TP vehicle.

27/5/18

Received D.V.

RECEIVED 28 MAR 2018

PRELIMINARY ADVICE		Date/Time:	Sent By:		Confirm by:	
Repair Cost:	S\$	(days)	Reduction:	%	Email ☐	Call ☐
FINAL SETTLEMENT		Date/Time: 20/3/18	Confirm with: Marco		Email ☐ Call ☐	
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:		IF NO or B 28, Ass. Lia:		
Repair Cost:	S\$ 749.00					
Loss of Rental (LOR):	S\$ 214.00	(2 days)	x 100163T			
Loss of Use (LOU):	S\$	(\$ x days)				
Loss of Income (LOI):	S\$	(\$ x days)				
LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]		
GIA/LTA Search	S\$					
Medical	S\$					
Disbursement:	S\$	(e.g. Tow/ Independent)				
Legal Cost	S\$					
Total:	S\$ 963.00	Global Sum S\$:				
FINAL PAYMENT		Date/Time:	Confirm with:		Email ☐ Call ☐	
Payee 1:	S\$ 963.00	Name 1:		HUI YANG MOTOR PTE LTD		
Payee 2: (Strike if N.A.)	S\$	Name 2:				
Payee 3: (Strike if N.A.)	S\$	Name 3:				

Signature

REF:

III

ASSIGNMENT

From: _____ Date: 20/12/17

Estimated Cost: _____

OD ☒ WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SKE 9461L
at Workshop m/s: Hui Yang Motor
of Blk 176 Sin Ming Drive #04-02

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Morning

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GI/A / PR. Scan: _____ Consistent?: Yes or No

Est. Repairs: 02 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Van No: SKE 9461L Yr Regn: 04 12

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy wish cc 1788

Colour: M. Grey A/C Insured / Std / NI / NA

Sp. Reading: 166980 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTOGG20W805002706

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA ☒ OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 7 mm R/Bal: 7 mm

L/Bal: 7 mm L/Bal: 7 mm

D.O.A. 16/12/17 D.O.I. 20/12/17

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/12 File res to Customer
in 11 Sep 8700

(Red: \$ 360.50 / 34 %)

Date/Time: File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time: File Return to?

Survey Fee: _____

2)

Add Fee: ☐ Site Insp \$

Transportation: _____

☐ Interview \$

Photo: _____

☐ Tech. Insp \$

Other: _____

☐ Weekend \$

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC4/III17024011/Kua3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 19-12-2017



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8043G	Veh. Inspected	SKE 9461L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/12/2017	Inspection Date	20/12/2017
Survey held at	HUI YANG MOTOR SERVICE BLOCK 176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

16/12/2017

Owner: TAN JOO JIN

ESTIMATE TO REPAIR TOYOTA WISH 1.8 - SKE9461L

1pc	front bumper
1pc	front bumper LH side retainer

mgm \$ 481.90 ✓
Dix \$ 132.10 ✓

less 25%

\$	614.00
\$	153.50
\$	460.50

spray painting	
labour charges	
Total	

\$	300.00	220
\$	300.00	200
\$	1,060.50	

Not Authored
C1 Ly 87001
Recovery After Point
2 days



LINKAGE Conditions hence notify the Receiver of the following:

- To Assess the existing condition
- To identify the existing survey
- Parts of the existing survey
- That the existing survey is not a
- No issue with the existing survey
- Supplement the existing survey and is subject to the existing survey

Acknowledgement to the Receiver

Signature: _____

Date: _____

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 19 December, 2017 9:00 AM
To: Hui Yang Motor; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Sundari Nagarajan - III
Subject: RE: TP Claim for SKE9461L against SH8043G
Attachments: SKM_C28717121816360.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKE9461L and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

9:30am @ 19/12/2017
vehicle Not In
person @ Marco
arrange on 20/12/17

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]
Sent: 18 December, 2017 5:38 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: TP Claim for SKE9461L against SH8043G
Importance: High

Hi Gabriel,

Our choice of surveyor will be LKK Auto Consultants Pte Ltd.

Thank you & Regards,
Sandra

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, December 18, 2017 5:02 PM
To: Hui Yang Motor
Subject: RE: TP Claim for SKE9461L against SH8043G

Dear Sir / Mdm,

We acknowledge receipt of your email.

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

Date: 13/01/2018

India International Insurance Pte Ltd

Motor Claims Department

64 Cecil Street

#04-00 IOB Building

Singapore 049711

**RE: ACCIDENT INVOLVING SKE9461L & SH8043G ON 16-12-2017
ALONG 299 COMPASSVALE ST MSCP LOT 135 DECK 3A**

SETTLEMENT OF OUR CLAIM FOR SKE9461L

Lump sum repair cost as recommended by surveyor (TP0269)	\$ 749.00
2 days Loss of Rental @ \$107.00 per day	\$ 214.00
Total	<u>\$ 963.00</u>

**The above claim applies only to vehicle damage and expressly exclude all personal injuries and other consequential loss.*

Please let us have your reply soonest possible, thank you.

Best Regards,

Marco Neo

HUI YANG MOTOR PTE LTD

DID: 64515752

Fax: 64514658

email: hui_yang_motor@hotmail.com

AUTHORIZATION LETTER

TO WHOM IT MAY CONCERN

I/We, Tan Joo Jin hereby declare and agree to use the address of **Hui Yang Motor Pte Ltd**, that is at Blk 176 Sin Ming Drive, #04-02 Sin Ming Autocare Singapore 575721 in all my/our correspondences with any party in connection with my/our claim arising from an accident involving my/our motor vehicle registration number SKE9461L and other vehicles registration number SH 80436 along 299 Compassvale Street MSCP Lot 135 Deck 3A on 16/12/2017

I/We, further grant authority to Messrs **Hui Yang Motor Pte Ltd** or any of their representatives to open all my/our letters and to negotiate my/our claim on my/our behalf.

I/We wish to inform you that you could issue the cheque payment in favour of my/our repairer Messrs **Hui Yang Motor Pte Ltd**.



.....
Signature of registered owner

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT17120636
Claimant Ref: SKE 9461L

We/I, Hui Yang Motor Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 749.00 (repair cost), S\$ 214.00 (loss of use/rental), S\$ - (search fee), vehicle no. SKE 9461L that was damaged pursuant to the accident which occurred on 16/12/2017 (date) at MSCP OF BLK 299 COMPASSVALE STREET (location) involving vehicle no. SH 8043G (insured vehicle). This is pursuant to the inspection conducted on 20/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner TAN JOO JIN ("the third party claimant") of vehicle no. SKE 9461L to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKE 9461L (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 963.00 to Hui Yang Motor Pte Ltd

Dated this 20 day of Mar 20 18

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

Mareo Neo

NRIC:

379323201

Address:

Sin Ming Autocare 3575721
BLK 176 sin ming drive 804-02

Nationality:

Singaporean

Occupation:

Director

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

NRIC:

199607198R

Address:

Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1, #02-25 | S(408933)

Nationality:

-

Occupation:

-

HUI YANG MOTOR PTE LTD

Bill To:

India International Insurance Pte Ltd
Motor Claims Department
64 Cecil Street
#04-00 IOB Building
Singapore 049711

TAX INVOICE

TP Claim Invoice No: TP0269
Bill Date: 13/01/2018

	Description	Amount
	Date of Accident : 16/12/2017 Owner : TAN JOO JIN Vehicle No : <u>SKE9461L</u> Make & Model : <u>TOYOTA WISH</u>	
	<u>Lump Sum repair cost as recommended by surveyor</u>	\$ 700.00
	Sub-Total :	\$ 700.00
	Add 7% GST :	\$ 49.00
	Total Amount SGD :	\$ 749.00

Reg No.:201629438M

GST No.:201629438M

HUI YANG MOTOR PTE LTD



Authorised Signature

Hui Yang Motor Pte Ltd

Sin Ming Autocare Blk 176 Sin Ming Drive

#04-02 Singapore 575721

Email: hui_yang_motor@hotmail.com

H/P: 98625891 Office: 64515752 Fax : 64514658

RENT RECEIPT

No.: RC 17-36

Date: 23/12/17

Received from Huiyang Motor Pte Ltd

the sum of Dollars Two hundred and fourteen only

being the rent of SKR3925L (\$100 x 2 days) + 7% GST ALG: 134.80

due for the period from 20/12/17 to 22/12/17

payable in advance.

\$ 214.00

Cash / Cheque No.:

Important: No subletting of the above premise or any part thereof, or assigning the tenancy of the premise is allowed without the written consent of the landlord.



Signature of Landlord

SKE 9461 L


HYMS CAR LEASING PTE LTD

Blk 176 Sin Ming Drive #04-02 Sin Ming AutoCare Singapore 575721

Hp: 8333 6725 Fax 6451 4658

RENTAL TERMS AND CONDITIONS

No.: 13480

NAME <u>HUI YANG MOTOR PTE LTD</u>			REG. NO. <u>SKR35WZ</u>	CAR MAKE <u>Hyundai Accent</u>
ADDRESS <u>BLK 176 SIN MING DRIVE #04-02</u>			KM OUT <u>109342</u>	DATE & TIME OUT <u>20/12/17 8:48am</u>
<u>SIN MING AUTOCARE (51575721)</u>			KM IN <u>109458</u>	DATE & TIME IN <u>20/12/17 2:00PM</u>
TEL <u>HP 97882075</u>			KM DRIVEN	TIME USED
NAMED DRIVER <u>Tan Joo Sim</u>				
DRIVING LICENCE NO.	DATE OF EXPIRY	PLACE OF ISSUE	HOURS	@\$
PASSPORT NO.	DATE OF ISSUE	PLACE OF ISSUE	2 DAYS	@\$ 100
ADD NAMED DRIVER			WEEKS	@\$ 100
DRIVING LICENCE NO.	DATE OF EXPIRY	PLACE OF ISSUE	MONTHS	@\$
PASSPORT NO.	DATE OF ISSUE	PLACE OF ISSUE	BY INITIALING, RENTER AGREES TO PAY ADD FEE FOR COLLISION DAMAGES WAIVER (C.D.W.)	
REMARKS 			SUB-TOTAL	
			77.0 GST \$14	
			TOTAL RENTAL \$214	
			DELIVERY FEE	
			COLLECTION FEE	
			PER DAY \$	PER WEEK \$
			PER MONTH \$	
			BY INITIALING, RENTER AGREES TO PAY ADD FEE FOR PERSONAL ACCIDENT INSURANCE (P.A.I.)	
			PER DAY \$	PER WEEK \$
			PER MONTH \$	
			PREPAYMENT	TOTAL CHARGE \$214
			CHECK	DEPOSIT
			CASH	
			RECEIPT NO.	NETT CHARGE
			AMOUNT DUE/ REFUND	
FORM OF PAYMENT IN ADVANCE CASH BILL CHARGE CLUB CHEQUE NO.				
I HAVE READ THE TERMS AND CONDITIONS ON BOTH SIDES OF THIS RENTAL AGREEMENT AND AGREE THEREOF. I UNDERTAKE NOT TO USE OR LET OTHERS USE THE VEHICLE TO CARRYOUT ANY ILLEGAL OR CRIMINAL ACTS INCLUDING CARRYING OF DUTY UNPAID GOODS ESPECIALLY CIGARETTES.				
SIGNED BY THE PARTIES HERETO ON THE _____ DAY OF _____				
X _____ 			X _____ RENTER'S/DRIVER'S SIGNATURE	
OWNER				

HYMS CAR LEASING PTE LTD

BLK 176 SIN MING DRIVE
#04-02 AUTOCARE
SINGAPORE 575721
HP : 8333 6725 FAX : 6451 4658
REG NO : 201320561K
GST REGISTER NO: 201320561K

TAX INVOICE

BILL TO: HUIYANG MOTOR PTE LTD
BLK 176 SIN MING DRIVE
#04-02 SIN MING AUTOCARE
SINGAPORE 575721

TAX INVOICE NO : LT122017-025
DATE : 23/12/2017
REFERENCE NO : SKE9461L

NO.	DESCRIPTION	AMOUNT
	AGREEMENT NO : 13480 HIRER'S NAME : TAN JOO JIN REGISTRATION NO : SKR3925L MAKE : HYUNDAI ACCENT DURATION : 20/12/17 - 22/12/17 PER DAY \$100X2DAYS	\$200.00
	SUB TOTAL	\$200.00
	7% GST	\$14.00
	TOTAL AMOUNT	\$214.00

Payment:

- A. For Cheque Payment, Please Crossed And Issue to "HYMS CAR LEASING PTE LTD".
Please Indicate Vehicle Number On The Back Of The Cheque And Mail The Cheque To:
HYMS CAR LEASING PTE LTD
Blk 176 Sin Ming Drive
#04-02 Sin Ming AutoCare
Singapore 575721
- B. For Internet Banking Transfer, Please Indicate Vehicle Number And Transfer To:
Bank OCBC Current Account 531-756864-001



Print Received Message

This mail is associated with :

*SKE9461L (MCT17120636)

[SH8043G]

TP

TAN JOO JIN

Dec 16 2017 7:00PM

[COMFORT TRANSPORTATION PTE LTD]

Hui Yang Motor Service

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 15/03/2018 09:54 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$963.00) - SKE9461L - Claim Handler: Sundari Nagarajan

Approved:963.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Dec 2017 Edit Reg		19 Dec 2017 00:00 Edit Adj Rpt	S\$700.00 Edit Estimates	S\$700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	TAN JOO JIN, ID: S7118244D		
Vehicle Reg. No.:	SKE9461L	Date of Loss:	16/12/2017 19:00 - :59
Claim Type:	TP / MCT17120636	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SH8043G	Policy No. (Claimant):	2100297510-05000
		Excess:	
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/12/2017]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- III_SG (15/03/2018): Alert - Adj Mandate Approved (S\$963.00) - SKE9461L - Claim Handler: Sundari Naga...
- III_SG (29/12/2017): Alert - Adj Mandate Approved (S\$0.00) - SKE9461L - Claim Handler: Sundari Nagara...
- III_SG (29/12/2017): Alert - Adj Mandate Approved (S\$0.00) - SKE9461L - Claim Handler: Sundari Nagara...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKE9461L (MCT17120636)
[SH8043G]
TP
TAN JOO JIN
Dec 16 2017 7:00PM
[COMFORT TRANSPORTATION PTE LTD]
Hui Yang Motor Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images			3 per page	☒
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/12/17 14:06	General View	 Load JPG	☒
2	29/12/17 14:06	General View	 Load JPG	☒
3	29/12/17 14:06	General View	 Load JPG	☒
4	29/12/17 14:06	General View	 Load JPG	☒
5	29/12/17 14:06	General View	 Load JPG	☒
6	29/12/17 14:06	General View	 Load JPG	☒
7	29/12/17 14:06	General View	 Load JPG	☒
8	29/12/17 14:06	General View	 Load JPG	☒
9	29/12/17 14:06	Odometer Reading	 Load JPG	☒
10	29/12/17 14:06	Chassis Number	 Load JPG	☒

Documentation			1 per page	☒
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/12/17 12:12	ACKNOWLEDGEMENT EMAIL TO III DD 19.12.2017	 Load PDF	
2	19/12/17 12:12	NOTIFICATION FROM WORKSHOP + TP ESTIMATE + TP GIA REPORT	 Load PDF	
3	21/12/17 17:57	TP ESTIMATE - MARKED	 Load PDF	
4	12/03/18 16:29	WORKSHOP INVOICE	 Load PDF	
5	12/03/18 16:29	RENTAL RECEIPT	 Load PDF	
6	12/03/18 16:29	LOD	 Load PDF	
7	29/03/18 11:41	DISCHARGE VOUCHER	 Load PDF	
8	29/03/18 11:41	AUTHORISATION TO ACT FORM	 Load PDF	
No.	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	20/12/17 08:57	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III17024011/KUA3Q2

Date: 29/03/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle
No : SKE9461L

Insured Vehicle No : SH8043G

Date of Loss: 16/12/2017

Nature of Claim:

TP

Claim No: MCT17120636

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKE9461L

Make & Model: TOYOTA WISH, 1.8 CVT (A)

Engine No: 2ZR1006233

Reg. Date: 18/04/2012 (Man. Year: 2012)

Chassis No: JTDGG20W805002706

Colour: Metallic Grey

Odometer: 166980 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Michelin 7 mm

Rear Left Side:

Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side:

Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	460.50	460.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	420.00	180.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,060.50	880.50	180.00	16.97
Approved Total (Overridden) (S\$)		700.00		
(S\$)	1,060.50	700.00	360.50	33.99
+ GST 7.00/7.00% (S\$)	74.24	49.00	25.24	34.00
Nett Amount (S\$)	1,134.74	749.00	385.74	33.99
+ Car Rental (2.0 x S\$100.00/day + 7.00% GST) (S\$)		214.00		
Nett Liability (S\$)		963.00		

INSPECTION

Date of Assignment: 19/12/2017

Date Inspected: 20/12/2017 Inspected At:

Hui Yang Motor Pte Ltd

176 Sin Min Drive #04-02/03, #04-02/03

Sin Ming Autocare

Singapore 575721

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2018)
Parts:	M1-MPV	TOYOTA WISH 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKE9461L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	481.90 FL	*481.90 FL
2	1		*FRONT BUMPER LH SIDE RETAINER	Distorted	132.10 FL	*132.10 FL
					Sub Total (S\$)	614.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	153.50
					Total Parts (S\$)	460.50

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING	New	300.00	220.00
2	LABOUR CHARGES	New	300.00	200.00
Gross Labour Cost (S\$)			600.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >