

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

18-Dec-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHD 1649 G

1 pc	Front bumper	\$	811.11 ^{DE}
1 pc	Front o/s fog lamp	\$	840.90 [?]
1 pc	Front bumper tow cap	\$	60.10 ^X
1 pc	o/s headlamp	\$	1,531.57 [?]
1 pc	Front o/s side bracket	\$	32.51 ^{ac}
1 pc	Front o/s fender	\$	514.02 ^{Bruc}
1 pc	Front o/s fender inner shield	\$	176.72 [?]
1 pc	Front o/s fender signal lamp	\$	32.10 ^X
1 pc	Washer tank	\$	51.40 [?]
1 pc	Washer tank motor	\$	75.00 [?]
		\$	4,125.43
Less 20%		\$	825.09
		\$	3,300.34

S/NETT

1 set	Front bumper clips	\$	48.00 ^{ac}
1 pc	Front o/s fender sticker	\$	30.00 ^{ac}
1 pc	Front n/s fender inner shield clips	\$	28.00 ^{ac}
	Sundry	\$	50.00 [?]
	To check wheel alignment	\$	80.00 ^X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same	\$	750.00 ^{\$400}
	To putty and spray painting on front bumper, front o/s fender	\$	400.00 [✓]
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 ⁸⁰
		\$	4,806.34

(ALL THE REPAIR COSTS ARE SUBJECT TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged parts
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: