

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: EQ INSURANCE COMPANY LTD	Document No.	: SQT17005125	Page	1
	5 MAXWELL ROAD	Date	: 18. Dec 2017		
	#17-00 TOWER BLK MND BUILDING	Customer No.	: WZE011		
	SINGAPORE 069110	Svc Advisor	: NG SIN HAI		
Registration No	: SKA2467M	Engine No	: R16A15000167		
Chassis No	: JHMF4620AS200108	Date Time	: 18. Dec 2017 3:08:42 PM		
Model	: CIVIC 1.6L AUTO	Surveyor Name	:		
Owner's Name	: CHAN MEE LEEN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 15/12/2017				

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	OWNER:CHAN MEE LEEN						
	OWNER INSURER:AXA						
	ACC DATE:15/12/2017						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:EQ INSURANCE COMPANY LTD						
	TP VEH:GBF4429R						
66100-SNA-U02ZZ	PANELREAR	1	305.40	25	229.05	16.03	245.08
74895-SNA-000ZA	GARNISH ASSYR.TRUNK HINGE	1	23.50	25	17.62	1.23	18.85
74896-SNA-000ZA	GARNISH ASSYL.TRUNK HINGE	1	23.50	25	17.62	1.23	18.85
68500-SNB-G00ZZ	LIDTRUNK	1	610.70	25	458.02	32.06	490.08
68610-SNA-000ZZ	HINGE COMPR.TRUNK.	1	50.90	25	38.17	2.67	40.84
68660-SNA-000ZZ	HINGE COMPL.TRUNK.	1	50.90	25	38.17	2.67	40.84
74862-SE3-003	STRIKERTRUNK	1	11.60	25	8.70	0.61	9.31
74851-SNA-G22	LOCK TRUNK	1	203.60	25	152.70	10.69	163.39
84505-SNA-A11ZE	TRAY COMPAREAR	1	190.20	25	142.65	9.99	152.64
84521-SNA-A01ZA	LID COMPSPARE TIRE	1	311.80	25	233.85	16.37	250.22
84541-SNA-A00	BOXTOOL	1	48.40	25	36.30	2.54	38.84
84601-SNA-A21ZA	LINING ASSYR.TRUNK.	1	152.80	25	114.60	8.02	122.62
84620-SNB-J01ZA	LININGTRUNK LID	1	135.90	25	101.92	7.13	109.05
84640-SNA-A01ZA	LININGRR.PANEL	1	61.80	25	46.35	3.24	49.59
84651-SNA-A21ZA	LINING ASSYL.TRUNK.	1	152.80	25	114.60	8.02	122.62
75701-SNB-003	EMBLEMRR (H)	1	28.00	25	21.00	1.47	22.47
75722-SNB-J01	EMBLEMRR (CIVIC)	1	30.50	25	22.87	1.60	24.47
75725-SNA-K01	EMBLEMRR (I-VTEC)	1	34.70	25	26.02	1.82	27.84
75731-SNB-K31	EMBLEMREAR (1.6)	1	17.80	25	13.35	0.93	14.28
04715-SNB-010ZZ	FACE,REAR BUMPER	1	730.00	25	547.50	38.33	585.83
71593-SNA-A01	SPACERR.RR.BUMPER SIDE	1	15.30	25	11.47	0.80	12.27
71598-SNA-A01	SPACERL RR BPR SIDE	1	15.30	25	11.47	0.80	12.27

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110

Registration No : SKA2467M

Chassis No : JHMF04620AS200108

Model : CIVIC 1.6L AUTO

Owner's Name : CHAN MEE LEEN

Ins Policy No. :

Date of Accident : 15/12/2017

Document No. : SQT17005125

Date : 18. Dec 2017

Customer No. : WZE011

Svc Advisor : NG SIN HAI

Engine No : R16A15000167

Date | Time : 18. Dec 2017 3:08:42 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
91503-SZ3-003	CLIP ABUMPER	2	3.90	25	5.85	0.41	6.26
91505-S9A-003	CLIP ABUMPER	25	3.90	25	73.12	5.12	78.24
34151-SNB-J51	LAMP UNITR.LID	1	202.20	25	151.65	10.62	162.27
34156-SNB-J51	LAMP UNITL.LID	1	202.20	25	151.65	10.62	162.27
74890-SNB-000ZJ	GARNISHRR.LICENCE	1	127.30	25	95.47	6.68	102.15
33501-SNB-J51	LAMP UNITR.TAIL	1	244.80	25	183.60	12.85	196.45
33551-SNB-J51	LAMP UNITL.TAIL	1	244.80	25	183.60	12.85	196.45
08F13-SNL-7V0X	TRUNK SPOILER	1	490.80	10	441.72	30.92	472.64
08F03-SNL-7T0QX	REAR UNDER SPOILER	1	530.80	10	477.72	33.44	511.16
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
Sum Item					4213.38	294.91	4,508.29
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	560.00		560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00		560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL.	1	2900.00		2900.00	203.00	3103.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00		4000.00	280.00	4280.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	360.00		360.00	25.20	385.20
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00		450.00	31.50	481.50
BOMISC1	REMOVE AND RENEW TRUNK AND REAR BUMPER SPOILER	1	450.00		450.00	31.50	481.50
Sum Labor					9740.00	681.80	10,421.80

Survey By

Date & Time

Excess

Total Amount 13,953.38 976.71 14,930.09

Total (Inclusive of GST) 14,930.09

Printed on 19/12/2017 1:41:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLK MND BUILDING
SINGAPORE 069110

Registration No : SKA2467M
Chassis No : JHMFD4620AS200108
Model : CIVIC 1.6L AUTO
Owner's Name : CHAN MEE LEEN
Ins Policy No. :
Date of Accident : 15/12/2017

Document No. : SQT17005125
Date : 18. Dec 2017
Customer No. : WZE011
Svc Advisor : NG SIN HAI
Engine No : R16A15000167
Date | Time : 18. Dec 2017 3:08:42 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incl GST
Status							
Signature							

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 19/12/2017 1:41:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)