

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Website: www.honda.com.sg

189702

For 24-hours Roadside Assistance, Call 98203838

**Document No.** 

: SQT17005075

Page

1

100 BEACH ROAD #19-00 SHAW TOWERS

: MRHFC5650GT001503

: CIVIC 1.6 VTI YM2016

: ZHONG JIAXIANG

: LONPAC INSURANCE BHD

SINGAPORE

Customer No.

: 13. Dec 2017 : WZL009

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

: SGT5888J

Svc Advisor

: PATRICK MOK LIP KAY

**Engine No** 

Date

: R16B21601808

Date | Time

: 13. Dec 2017 4:40:03 PM

Surveyor Name

:

**Survey Date** 

:

Authorisation Date

Ins Policy No.

Registration No

Owner's Name

Chassis No

Model

**Date of Accident** 

				GST	Amount
Qtv	Unit Price	Disc %	Amount	Amt	incld GST

Item	Description	Qty	Unit Price	Disc %	Amount	Amt	incld GST
	TP DIRECT SETTLEMENT (J/NO: )						
	OWNER: ZHONG JIAXIANG						
	OWNER INSURER: AVIVA LTD						
	ACC DATE: 12/012/2017						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: XB8692E						
	TP VEH: LONPAC INSURANCE						
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BOJSE	SEALANT FOR BOOT COVER	1	100.00		100.00	7.00	107.00
BOJSE	SEALANT FOR REAR END PANEL	1	100.00		100.00	7.00	107.00
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	3360.00		3360.00	235.20	3595.20
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00		180.00	12.60	192.60
3MI02D	REMOVE/REFIT BOOT TRIMS TO ASSIST REPAIR	1	280.00		280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00		180.00	12.60	192.60
BKBU01R	REMOVE/REFIT BOOT COVER REVERSE CAMERA FOR REPAIR	1	380.00		380.00	26.60	406.60
3P06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	1	3000.00		3000.00	210.00	3210.00
			\$	Sum Labor	7680.00	<u>537.60</u>	8,217.60
RS-TMP3040L	VPC 4PCS REAR SENSORS	1	320.00		320.00	22.40	342.40
6100-TEC-307ZZ	PANEL SETRR.	1	236.70	25	177.52	12.43	189.95
6114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	27.10	25	20.32	1.42	21.74
6154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	25.40	25	19.05	1.33	20.38
4890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	95.40	25	71.55	5.01	76.56
8500-TEA-N00ZZ	LID COMP TRUNK	1	461.50	25	346.12	24.23	370.35
4851-TEA-003	LOCK ASSYTRUNK	1	70.60	25	52.95	3.71	56.66
							56.18



### KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT17005075 : 13. Dec 2017

Page

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

100 BEACH ROAD

#19-00 SHAW TOWERS

: LONPAC INSURANCE BHD

**SINGAPORE** 189702

**Engine No** 

Date

: WZL009

: R16B21601808

Customer No. Svc Advisor

: PATRICK MOK LIP KAY

**Registration No** : SGT5888J

: MRHFC5650GT001503

Date | Time

: 13. Dec 2017 4:40:03 PM

Chassis No Model

Customer

: CIVIC 1.6 VTI YM2016

**Surveyor Name** 

Owner's Name

: ZHONG JIAXIANG

**Survey Date** 

**Authorisation Date** 

Total (Inclusive of GST)

Ins Policy No. : **Date of Accident** 

						GST Amt	Amount incld GST
Item	Description	Qty	Unit Price	Disc %	Amount	AIIIL	- Inclu GG1
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1	20.50	25	15.37	1.08	16.45
75722-TBA-A00	EMBLEM SETRR.	1	11.20	25	8.40	0.59	8.99
75725-TEA-T01	EMBLEMRR.	1	10.40	25	7.80	0.55	8.35
04715-TEC-Q00ZZ	FACE ASSYRR.BUMPER	1	9999.99	25	7499.99	525.00	8024.99
71502-TEX-Y00	GARNISHRR.BUMPER LOWER	1	34.50	25	25.87	1.81	27.68
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE	1	7.40	25	5.55	0.39	5.94
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.20	25	1.65	0.12	1.77
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	1	7.40	25	5.55	0.39	5.94
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	156.40	25	117.30	8.21	125.51
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.20	25	1.65	0.12	1.77
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
33500-TEA-T01	TAILLIGHT ASSYR.	1	248.10	25	186.07	13.02	199.09
33550-TEA-T01	TAILLIGHT ASSYL.	1	267.00	25	200.25	14.02	214.27
34150-TEX-Y01	LIGHT ASSYR.LID	1	116.00	25	87.00	6.09	93.09
34155-TEX-Y01	LIGHT ASSYL.LID	1	116.00	25	87.00	6.09	93.09
				Sum Item	9337.20	653.63	9,990.83

Date & Time Excess Status Signature

Total Amount 17,017.20 1,191.23 18,208.43

18,208.43

Printed on 13/12/2017 5:20:51 PM

Survey By

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

#### SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

Fax Number **Contact Number** 

**EMail Address** 

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
  6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date Of Report	13/12/2017 11:21
Date Of Accident	12/12/2017 19:55
Exact Location Of Accident	ALONG CHOA CHU KANG WAY TURNING INTO KJE
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SGT5888J
Insured/Policyholder	
Name Of Registered Owner	ZHONG JIAXIANG
NRIC No	S7382924J
Email Address	ZHON0011@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91097115
Alternative Phone No	OFFICE-91097115
Vehicle Particulars	
Manufacturer	HONDA
Model	CIVIC 1.6 VT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10750499
Cover Note Number	
Driver	
Name of Driver	ZHONG JIAXIANG
NRIC No	S7382924J
Date Of Birth	30/01/1973
Occupation	INDOOR
Date Of Driving Pass	03/01/2005
Driving Experience	12 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91097115

OFFICE-91097115

ZHON0011@GMAIL.COM

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

**OWNER** 

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

**COLLISION - HEAD TO REAR** 

Weather Conditions

**CLEAR** 

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Was any body injured in the Accident?

NO YES

Was any other material or property damaged? I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

The accident happened on 12/12/2017, 7:55pm, at junction along Chua Choo Kang Way turn to KJE. I was stopping my car when the traffic light turning red at junction, and the lorry behind my car, with plate number XB8692E, couldn't stop, and hit my car SGT5888J from back. My car SGT5888J was dented on the back, and rear light also scratched. No injuries involved. That's all.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

XB8692E

Vehicle Make/Model/Colour

MITSUBISHI/FP517DR2RDEB

**Details Of Properties** 

Name of Driver

MUHAMMAD AIMAN BIN ABDULLAH@ LEE BENG HUAT

NRIC/Passport Number

S1500651Z

**Contact Number** 

97373121

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**Details of Witness** 

Name

Phone Number

**Email Address** 

# Sketch Plan #2 Pg. 1

ACCIDENT	STATEMENT (2000	characters'
		ALIMINACOLO C

Way turn to KJE. I was stopping my car and the lorry behind my car, with plate	7:55pm, at junction along Chua Choo Kang r when the traffic light turning red at junction, number XB8692E, couldn't stop, and hit my car 3J was dented on the back, and rear light also all.
	The state of the s
Taxl Voucher No.:	
DECLARATION	·
We declare that the above particulars & information provi	ded above are true in every aspect
VERIFIED BY AJAX MARS REPORTING OFFICER - MOHD FADZLY BIN ISMAIL	孙本本
MARS Officer	
	Registered Owner or Driver's Signature
ob Complete Date/Time	Date/Time;
13 December 2017 10:52 am	13 December 2017 10:52-am

#### Sketch Plan

