



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD 100 BEACH ROAD #19-00 SHAW TOWERS SINGAPORE 189702	Document No.	: SQT17005075	Page	1
Registration No	: SGT5888J	Date	: 13. Dec 2017		
Chassis No	: MRHFC5650GT001503	Customer No.	: WZL009		
Model	: CIVIC 1.6 VTI YM2016	Svc Advisor	: PATRICK MOK LIP KAY		
Owner's Name	: ZHONG JIAXIANG	Engine No	: R16B21601808		
Ins Policy No.	:	Date Time	: 13. Dec 2017 4:40:03 PM		
Date of Accident	:	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ZHONG JIAXIANG OWNER INSURER: AVIVA LTD ACC DATE: 12/012/2017 SURVEYED BY: DATE: REF NO: TP INSURER: XB8692E TP VEH: LONPAC INSURANCE						
BOSUN	SUNDRIES	1	100.00	50.	100.00	7.00	107.00
BOJSE	SEALANT FOR BOOT COVER	1	100.00	✓	100.00	7.00	107.00
BOJSE	SEALANT FOR REAR END PANEL	1	100.00	?	100.00	7.00	107.00
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	3360.00	1960.	3360.00	235.20	3595.20
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	✓	180.00	12.60	192.60
BMI02D	REMOVE/REFIT BOOT TRIMS TO ASSIST REPAIR	1	280.00	✓	280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	✓	180.00	12.60	192.60
BKB01R	REMOVE/REFIT BOOT COVER REVERSE CAMERA FOR REPAIR	1	380.00	✓	380.00	26.60	406.60
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	1	3000.00	1350.	3000.00	210.00	3210.00
				450.			
				Sum Labor	7680.00	537.60	8,217.60
RS-TMP3040L	VPC 4PCS REAR SENSORS	1	320.00	?	320.00	22.40	342.40
66100-TEC-307ZZ	PANEL SETRR.	1	236.70	25	177.52	12.43	189.95
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	27.10	25	20.32	1.42	21.74
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE	1	25.40	25	19.05	1.33	20.38
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	95.40	25	71.55	5.01	76.56
68500-TEA-N00ZZ	LID COMP TRUNK	1	461.50	25	346.12	24.23	370.35
74851-TEA-003	LOCK ASSYTRUNK	1	70.60	25	52.95	3.71	56.66
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702

Registration No : SGT5888J
Chassis No : MRHFC5650GT001503
Model : CIVIC 1.6 VTI YM2016
Owner's Name : ZHONG JIAXIANG
Ins Policy No. :
Date of Accident :

Document No. : SQT17005075
Date : 13. Dec 2017
Customer No. : WZL009
Svc Advisor : PATRICK MOK LIP KAY
Engine No : R16B21601808
Date | Time : 13. Dec 2017 4:40:03 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
84640-TEA-Z01ZA	LINING ASSYRR.PANEL	1 ?	20.50	25	15.37	1.08	16.45
75722-TBA-A00	EMBLEM SETRR.	1 <i>new</i>	11.20	25	8.40	0.59	8.99
75725-TEA-T01	EMBLEMRR.	1 <i>new</i>	10.40	25	7.80	0.55	8.35
04715-TEC-Q00ZZ	FACE ASSYRR.BUMPER	1 <i>new</i>	9999.99*	25	7499.99	525.00	8024.99
71502-TEX-Y00	GARNISHRR.BUMPER LOWER	1 <i>new</i>	34.50	25	25.87	1.81	27.68
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE	1 ?	7.40	25	5.55	0.39	5.94
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1 ?	2.20	25	1.65	0.12	1.77
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	1 ?	7.40	25	5.55	0.39	5.94
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1 ?	156.40	25	117.30	8.21	125.51
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1 <i>new</i>	2.20	25	1.65	0.12	1.77
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1 <i>new</i>	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1 <i>new</i>	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	7 <i>new</i>	2.00	25	10.50	0.74	11.24
33500-TEA-T01	TAILLIGHT ASSYR.	1 ?	248.10	25	186.07	13.02	199.09
33550-TEA-T01	TAILLIGHT ASSYL.	1 ?	267.00	25	200.25	14.02	214.27
34150-TEX-Y01	LIGHT ASSYR.LID	1 ?	116.00	25	87.00	6.09	93.09
34155-TEX-Y01	LIGHT ASSYL.LID	1 ?	116.00	25	87.00	6.09	93.09
Sum Item					9337.20	653.63	9,990.83

Survey By

Date & Time

Excess

Status

Signature

*Taufik 97495749**10/1/18 @ 1130**WP**Taufik*

Resurvey before paint
sur@lkkauto.com.
taufik@lkkauto.com.

7 days.

Total Amount 17,017.20 1,191.23 18,208.43

Total (Inclusive of GST) **18,208.43**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 13/12/2017 5:20:51 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)