

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

EQ

18-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6670 R

1 pc	Boot lid ✓	\$	1,119.00
1 pc	Boot lid lock ✓	\$	99.00
1 pc	Bootlid lock cable X	\$	35.00
1 pc	Bootlid striker X	\$	21.00
1 pc	Bootlid emblem ✓	\$	27.00
1 pc	Bootlid CRDi ✓	\$	29.00
1 pc	Boot lid rubber weatherstrip X	\$	96.00
1 pc	Boot lid lower garnish X repair	\$	290.00
2 pcs	Bootlid hinge @ \$66.00 ✓	\$	132.00
1 pc	Bootlid inner trim X	\$	190.00
1 pc	End panel X repair	\$	250.00
1 pc	End panel garnish ?	\$	74.00
1 pc	Spare tyre clamp X	\$	6.00
2 pcs	Licence plate lamp @ \$30.00 ?	\$	60.00
2 pcs	Rear o/s & n/s tail lamp @ \$421.00 N/S ✓ o/s X	\$	842.00
2 pcs	Bootlid n/s & o/s reflector @ \$350.00 X	\$	700.00
1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover ✓	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ?	\$	58.00
1 pc	Rear bumper inner sponge ✓	\$	114.00
1 pc	Rear bumper reinforcement ✓	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ?	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ¹	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ²	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 X	\$	92.00
		\$	5,923.00
	Less 10%	\$	592.30
		\$	5,330.70

18-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6670 R

S/NETT

1 pc	Rear no. plate with casing X	\$	50.00
1 set	Rear bumper clips /	\$	48.00
1 set	End panel inner garnish clips X	\$	30.00
1 set	Bootlid inner trim clips X	\$	52.00
1 set	Bootlid lower garnish clips X	\$	60.00
2 sets	Rear fender inner shield clips @ \$38.00 X	\$	76.00
1 set	Bootlid stickers /	\$	100.00
1 set	Reverse sensor /	\$	280.00 200
1 set	Floorboard compartment insulating paddings X <i>Rear Bump to Rubber Mat</i>	\$	120.00 \$ 50
	Sundry	\$	50.00 20
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel. Including knock-out, straighten, repair, reshape and adjust of the floorboard compartment, rear n/s & o/s chassis, rear n/s & o/s tail lamp panel etc	\$	1,200.00 800
	To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear n/s & o/s chassis member, rear n/s & o/s taillamp panel.	\$	1,400.00 720
	To apply rustproofing on the repaired and replaced panels.	\$	250.00
		\$	<u>9,346.70</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin LKK
11 18/12/17
4 Repair Days
P/P
Before Paint pht

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: