

2/5 22.000

Not Authorized
Main

Estimate

Vehicle: SLC 982H

Make & Model: Mazda 2

19/12/17

30 day.

Year: _____

Chassis No: MM6DL2SAA GV191456

	Parts / Labour	Condition	Price	recommend
	Rear bumper	Dis	1209.00	✓
2pc	Rear bumper side retainers @ 31.70	n/s bent	63.40	1pc
2pcs	Rear bumper reflectors @ 60.40	n/s s/d	120.80	1pc
1set	Rear bumper clips	rec	50.00	✓
	Bootlid	bu l	1120.60	✓
2pc	Bootlid hinges @ 125.00	but/twr	250.00	✓
2pc	Bootlid hinge spring Tensioners @ 140.00	1 1	280.00	x
	Bootlid inner trim garnish	1p. 1	308.00	✓
1set	Bootlid inner trim garnish clips	rec	50.00	✓
	Bootlid inner lock	twi	231.00	✓
	Bootlid Rear logo	rec	58.60	✓
	Bootlid 'mazda 2' emblem	rec	58.10	✓
	Bootlid 'SKYACTIV' emblem	rec	69.30	✓
2pc	Bootlid licence plate lamps @ 81.20	1 1	162.40	x
2pc	Bootlid outer garnish covers @ 42.00	twi	84.00	✓
2pc	Bootlid reflectors @ 248.00	n/s cre	496.00	1pc
2pc	Bootlid rubber stoppers @ 15.00	rec	30.00	✓
2pc	tail lamps @ 451.20	cm	902.40	✓
2pc	tail lamp housing panels @ 178.00	n/s Dis	356.00	1pc
	Rear end panel 6sf	B. d/s	824.00	✓
	Rear end panel top garnish	twi	97.00	✓
1set	Rear end panel top garnish clips	rec	18.00	✓
	Rear end panel top striker	twi	48.00	✓
	Rear fender n/s	B. d/s/buc	1290.80	✓
	Rear fender inner wheel housing panel n/s	B. d/s	1580.00	✓
2pc	Rear fender inner trims @ 145.00	Dis/tom	290.00	✓
1set	Rear fender inner trim clips	rec	50.00	✓
	Rear fender splash shield n/s	twi	68.50	✓

120%

10165.90

Estimate

Vehicle: SLC982H

Make & Model: model 2

Year: _____

Chassis No: _____

	Parts / Labour	Condition	Price	recommend
1set	Fuel lip ventilation container hose clips	new	25.00	✓
	Rear door nls	Surf/Suc	1051.00	✓
	Rear door outer handle nls	17	109.00	X
	Rear door inner lock nls	new/shut	181.00	✓
	Rear door inner trim board nls	17	680.00	X
1set	Rear door inner trim board clips nls	17	30.00	X
	front door inner lock nls	17	223.00	X
	front driver seat Adjustment bracket	Surf/new	950.00	✓
	front passenger seat Adjustment bracket	new	950.00	X
2 Set	Rear seat locking Device @ 150.00	17	300.00	X
	Bonnet	new/suc	822.00	✓
	Bonnet rubber inner	new	33.00	✓
	Bonnet rubber outer	new	28.70	✓
	front bumper	new	933.00	✓
1set	front bumper clips	new	50.00	✓
2pc	front bumper fog lamp covers @ 53.00	new/suc	106.00	new
2pc	front bumper side retainers @ 28.00	Surf	56.00	✓
	front bumper logo	new	51.60	✓
2pc	front bumper chrome mouldings @ 163.00	new/suc	326.00	new
	front bumper tow hook cover	To.n	48.00	✓
	front bumper reinforcement	Surf	550.00	✓
	front bumper reinforcement stay nls	Surf	186.00	✓
	front fender nls	new	423.00	✓
	front fender inner shield nls	To.n	86.00	✓
1set	front fender inner shield clips nls	new	30.00	✓
	headlamp nls	new	746.00	✓
	front support panel	new	484.00	✓
	front support panel damper stay	17	58.30	X

202

Estimate

Vehicle: SLC 982H

Make & Model: Mazda 2

Year: _____

Chassis No: _____

Parts / Labour	Condition	Price	recommend
Rear chassis member n/s	n	1311.00	x
Rear floor panel side member n/s 331	Soft/ao	731.00	✓
Rear floor panel	crushed/buc	7319.00	✓
Rear floor panel top board	negad	308.00	✓
Rear floor panel sponge tray	n/s	264.00	✓
Rear spon tyre	n	200.00	x
Rear spon tyre lock nut	n	58.00	x
Rocker panel n/s	n	815.40	x
Rear windscreen glass.	320	978.00	✓
Rear windscreen moulding	ren	80.00	✓
Rear speaker panel support frame n/s	n	480.00	x
Rear speaker panel	n	550.00	x
Rear speaker panel top garnish	n	220.00	x
Rear axle beam 2130	But/crn	2530.00	✓
Rear coil spring n/s	2ye	286.00	✓
2pcs Rear shock absorbers @ 248.00	n/s But	496.00	12c
Rear wheel hub n/s	2ye	589.00	✓
Rear brake hose n/s	To.1	151.00	✓
Rear brake pipe n/s	3ut	95.00	✓
Rear handbrake cable	2ye	156.00	✓
Fuel lip panel	3ut	89.00	✓
Fuel lip panel lock	3m	68.00	✓
Fuel lip panel cable	3m	87.00	✓
Fuel lip refill hose neck	n/s	138.00	✓
Fuel lip refill pipe	n/s	266.00	✓
Fuel lip ventilation container	n	120.00	x
Fuel lip ventilation container hose (big)	To.1	141.00	✓
Fuel lip ventilation container hose (small)	To.1	81.00	✓

207

Estimate

Vehicle: SLC 982H

Make & Model: maxi 2

Year: _____

Chassis No: _____

Parts / Labour	Condition	Price	recommend
Bumper inner lock	tw	185.00	✓
Air con condenser	bul/pur	903.00	✓
Radiator	bul/pur	875.00	✓
Front grille	7.5	285.00	✓
petrol refill cap	1.1	128.70	α
fuel refill inlet pipe	7.5	187.20	✓
fuel refill inlet pipe (bypass)	7.5	92.00	✓
fuel refill inlet pipe top rubber spacer	1.1	144.50	✓
groove box garnish	1.1	183.80	✓
		35332.10	
S. Netf			
Boothub 'car club' sticker	1.1	20.00 S.N	✓
Rear fender 'car club' sticker 1/5	1.1	30.00 S.N	✓
Rear windscreen solar film	1.1	120.00 S.N	✓
Rear windscreen sealant	1.1	40.00 S.N	✓
Rear tyre 1/5 96	7.5	160.00 S.N	60% S.N
Rear sport rim 1/5	1.1	886.00 S.N	400 S.N
1524 Rear bumper reverse sensor	shp	220.00 S.N	200 S.N
Rear licence plate	1.1	30.00 S.N	✓
Rear floor panel insulator	1.1	150.00 S.N	100 S.N
160 Radiator coolant	1.1	48.00 S.N	✓
front licence plate	1.1	15.00 S.N	✓
Rear end panel sealant	1.1	150.00 S.N	50 S.N
			1149

Estimate

Vehicle: SLC 982H

Make & Model: mazda 2

Year: _____

Chassis No: _____

Rear portion part / Labour	Condition	Price	recommend
Auto rust proofing		100.00	✓
To check wiring rear		80.00	30
To R & R seat cushion upholstery		150.00	100
To R & R rear door components		120.00	60
To R & R rear windscreen		150.00	120
To R & R fuel tank		100.00	60
To R & R rear seat	Repeated	100.00	X
To R & R rear exhaust	11	100.00	X
labour for panel beating, cut, weld, straighten & replacing rear portion		2800.00	2000
To putty & spray painting rear portion		1800.00	1500
To conduct wheel alignment		150.00	60
To R & R rear undercarriage		280.00	✓
To computer & reprogramme system	11	120.00	X
front portion			
Auto rust proofing		100.00	60
To check wiring front		100.00	20
To R & R radiator	11	150.00	X
To R & R condenser & refill air con gas		150.00	100
labour for panel beating & replacing parts front portion		480.00	450
To putty & spray painting front portion		850.00	600

TOTAL

4660

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

A: knowledge by Repairer

SIGATURE