



AUTO ENGINEERING PTE LTD

Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015

Email: kangauto@singnet.com.sg



M/S DirectAsia.com
88 South Bridge Road
Singapore 058716
Singapore 049513
Attn: Attn : Motor Claims Dept

Date : 15/12/2017

Your Insured: SKU59R
Our Insured : SJB1293K
OUR REF: TP17/12/1086

Notice to conduct Pre-Repair Inspection within 2 working days pursuant to paragraph 6.2 of Pre-Action Protocol for NIMA Case.

We act for Ms JJ68 , the owner of motor vehicle SJB1293K who has appointed us Kang Auto Engineering Pte Ltd to act on his behalf to claim against your insured's vehicle SKU59R in regards to the road traffic accident on 14.12.2017 ALONG PARLIAMENT PLACE TOWARDS ST. ANDREW'S ROAD.

Please be informed that the said motor vehicle can be inspected at :

Kang Auto Engineering Pte Ltd
Sin Ming AutoCity
160 Sin Ming Drive, #02-16
Singapore 575722
Tel: 6556 0103 fax: 6556 1015
Contact : Serene / May

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding and intervening Saturday, Sunday or Public holiday, the said workshop will commence repairs thereafter without further reference to you.

YOURS FAITHFULLY,

KANG AUTO ENGINEERING PTE LTD

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium



AUTO ENGINEERING PTE LTD

Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015

Email: kangauto@singnet.com.sg



M/S JJ68

BLK 343 ANG MO KIO

AVENUE 3, #09-2174

SINGAPORE 560343

POLICY NO : THIRD PARTY CLAIMS

OUR REF : TP17/12/1086

VEHICLE NO : SJB1293K

MAKE/MODEL : HONDA STREAM

DATE OF ACCIDENT : 14.12.17

1	PC	WINDSCREEN INNER SHIELD		S\$	80.00
1	PC	TAILGATE			1,085.00
1	PC	TAILGATE RUBBER			123.50
1	PC	TAILGATE 'H' LOGO			30.50
1	PC	TAILGATE 'STREAM' BADGE			39.20
1	PC	TAILGATE LOCK			120.80
1	PC	TAILGATE HANDLE			158.00
1	PC	TAILGATE INNER GARNISH			191.30
2	PC	TAILGATE ABSORBER	180.50 EA		361.00
2	PCS	TAILLAMP	500.40 EA		1,000.80
1	PC	REAR END PANEL			485.00
1	PC	REAR END TOP GARNISH			115.00
1	PC	REAR BUMPER			992.30
1	SET	REAR BUMPER CLIP			28.00
2	PCS	REAR BUMPER SIDE RETAINER	30.50 EA		61.00
1	PC	REAR BUMPER LOWER LID			262.50
1	PC	TOWING COVER			45.00
					<hr/>
					S\$ 5,178.90
					LESS 20%
					<hr/>
					S\$ 4,143.12

1	SET	REAR REVERSE SENSOR		S\$	450.00 S'NETT
1	SET	CAMERA			250.00
1	PC	REAR NUMBER PLATE			50.00
1	PC	WINDSCREEN GUM			50.00

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium



AUTO ENGINEERING PTE LTD

Sin Ming Auto City

160 Sin Ming Drive #02-16 Singapore 575722 Tel: 6556 0103 (Main Line) Fax: 6556 1015

Email: kangauto@singnet.com.sg



M/S **JJ68**

BLK 343 ANG MO KIO
AVENUE 3, #09-2174
SINGAPORE 560343

POLICY NO : THIRD PARTY CLAIMS
OUR REF : TP17/12/1086
VEHICLE NO : SJB1293K
MAKE/MODEL : HONDA STREAM
DATE OF ACCIDENT : 14.12.17

TO CHECK WIRING SYSTEM	S\$	50.00
TO TRANSFER TAILGATE MECHANISM TO NEW TAILGATE		180.00
TO REMOVE AND TREFIT REAR WINDSCREEN		160.00
TO APPLY RUST PROOFING ON REPLACED/REPAIRED PANELS		120.00
TO PUTTY AND SPRAY PAINT CHARGES		800.00
LABOUR CHARGE		700.00
	<u>S\$</u>	<u>6,953.12</u>

SGD SIX THOUSAND NINE HUNDRED FIFTY-THREE AND CENTS TWELVE ONLY.

YOURS FAITHFULLY,


KANG AUTO ENGINEERING PTE LTD

Specialised in :

• Motor Insurance Claims • Repairs all Types of Motor Cars • Vehicle Inspection Services • Car Rental • Sourcing of Motor Insurance Premium