

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

China Taiping - (LKS) TS
LKK - Kalvin (Sat)

VEHICLE NO : SHD 4923U

DATE 12/16/2017

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Grille (LH) X repair			\$ 285.50
	Front Door Outer Moulding (LH) X			\$ 63.70
	Front Door Mirror (LH) -			\$ 980.50
	Front Wheel Hub Cap (LH) -			\$ 150.70
	Front Headlamp (LH) -			
	Front Bumper Repair			
	Front LH Fender X repair			
	SUB TOTAL			\$ 1,480.40
	LESS 20%			\$ 296.08
	DISCOUNTED TOTAL			\$ 1,184.32
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 300.00 410
	Wiring Charge			\$ 30.00 20
	Tuff Kote			\$ 50.00 X
	FRT Wheel Alignment			\$ 80.00 X
	TOTAL LABOUR			\$ 810.00
	ESTIMATE TOTAL			\$ 1,994.32

Kalvin 10/1/14
18/12/17 1040km
2 Reps.
4/5
After Repair photo

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Acknowledged by Repairer

Signature

Date: