

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4910G
 MAKE :
 MODEL : HYUNDAI i40

DATE 12/16/2017

Arg Asia - 4S TS
 (Sat)
 LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door (LH) X repair			\$ 1,351.10
	Rocker Panel (LH) X repair			
	Fender Rear (LH) X repair			
	SUB TOTAL			\$ 1,351.10
	LESS 20% DISCOUNTED TOTAL			\$ 270.22
				\$ 1,080.88
	Rear Door Tel No. Sticker/Apps (LH)			\$ 10.00 Nett
				\$ 10.00
	Labour Charge			200
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 400.00 600
	Tuff Kote			\$ 50.00 50
	Transfer of Door			\$ 120.00 X
	TOTAL LABOUR			\$ 920.00
	ESTIMATE TOTAL			\$ 2,010.88

Kalvin LKK
 18/12/17 1058hrs
 2 Days
 4/5
 After Repair p LKK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor surveyor appointed by the insurance company.