

ASSIGNED BY:

REF: CS/FCI17024053/Attd302

Special Instruction:

SHAWING

CWS

Adnan

ASSIGNMENT (Office)

From (Person):

Aung Ying Ming

of

FCI

Date/Time:

2.31pm @ 19/12/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 9760 T

Insured:

SHB 2244U

at Workshop m/s

Premium Automobiles

Tel:

63882323

of

55 Ubi Road 1

Policy No:

Claim No:

D17011605MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/12/17

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:03pm @ 19/12/17

Person Contacted:

Kee Siang

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLR 9760 T - CC6 / AIG17023948 / U1ka3

D.O.A.: 15/12/2017

SHB 2244U - CS / FCI15002007 / U1qbd I

D.O.A.: 31/01/2015

Part by part \$ 52,938.60 (Red: 23239.40 : 31%)

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 135K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 35 days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLR9760T Yr Regn: 2017 AugustType: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Audi A3 Sedan cc 999.Colour: White A/C: ☐ Insured / ☐ Std / ☐ NI / NASp. Reading: 7366 T.Radio: ☐ Insured / ☐ Std / ☐ NI / NA

Eng No: _____

C.No: WAU278V9J1007443Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☐ Nil / ☐ S/Rim / ☒ STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16BS / DUN / EXNOVA / ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mmL/Bal: 06 mm L/Bal: 06 mmD.O.A. _____ D.O.I. 19/12/17Survey held at: PremiumDes. of Damages: ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cp

RECEIVED 02 OCT 2018

Date/Time: File Pass to?

1) 3/10 Typist

Date/Time: File Return to?

2) _____

☐ Prel. Report
☒ Final Report
Days Of Repair: 35Resurvey No. of Trip: 1Add Fee: ☐ Site Insp: \$☐ Interview: \$☐ Tech. Invs: \$☐ Weekend: \$

Survey Fee:

Transportation:

Food: 580Other: OSPDate: 4/10/18Report Format: TPLump Sum / I.B.I: \$ 52,938.60

66x15

170+990

50

50

115

1375

MOTOR SURVEY ASSIGNMENT

Date	18-12-2017	Our Ref No. D17011605MFSH
Accident Date	15-12-2017	Claim Type. Third Party
Insured Vehicle	SHB2244U	Third Party Vehicle. SLR9760T
Survey Location	55 UBI ROAD 1	
Contact Person.	KEE SIANG	
Contact No.	63882323/ 67689911	Fax No. 68411183
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIUM AUTOMOBILES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/232041)



PRI Documents



Close



PRI Header Details

Claim No	D17011605MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & PREMIUM
Workshop Name	PREMIUM AUTOMOBILES PTE LTD (Contact Person : KEE SIANG)	Survey Location & Contact Details	55 UBI ROAD 1 Mobile: 67689911 , Phone: 63882323 , Fax: 6841118; EmailId: CLAIMS@PREMIUMAUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB2244U	TP Vehicle No	SLR9760T
PRI Recieved Date	19-12-2017 02:58:29 PM	Surveyor Appointed Date	19-12-2017 02:30:00 PM	Surveyor Accept Date	19-12-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	19-12-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17024053/Atd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 19-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2244U	Veh. Inspected	SLR 9760T
Policy No.		Coverage (\$)	0.00
Claim No.	D17011605MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	19/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/12/2017	Inspection Date	19/12/2017
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1, SINGAPORE 408699		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/12/2017 15:38
Date Of Accident	15/12/2017 19:50
Exact Location Of Accident	ALONG PIE (TUAS) NEAR ADAM EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR9760T
Insured/Policyholder	
Name Of Registered Owner	CHUN JIOK LUI
NRIC No	S1769078G
Email Address	SISV.CHUNJI@GAMIL.COM
Mobile Phone No	(LOCAL) +65-98227464
Alternative Phone No	OFFICE-98227464

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	JONATHAN FOO JIA HAO
NRIC No	S1769078G
Date Of Birth	12/12/1993
Occupation	INDOOR
Date Of Driving Pass	29/11/2013
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98227464
Fax Number	
Contact Number	OFFICE-98227464
Email Address	SISV.CHUNJI@GAMIL.COM

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured CHILDREN
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 15 DECEMBER 7.35PM ,ALONG PIE (TUAS) NEAR ADAM EXIT, I HAVE MET INTO A CHAIN COLLISION. THE FIRST CAR WAS BRAKING AND I WAS BRAKING ASWELL. HOWEVER A TAXI COLLIDED ON A HARD IMPACT INTO THE BACK OF MY CAR AND I BLANK OUT AND COLLIDED INTA CAR A. CAR C WAS TAILGATING US FROM THE BACK AND I FELT 3 TIMES IMPACT FROM THE BACK AFTER COLLIDING INTO THE FRONT CAR.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB2244U
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF INJURED PERSON 1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

6. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 16/12/2017

12:35pm


Reporting Centre Personnel's Signature
Name: Lim Kiat Seng
NRIC/IN No.: C2558256101

Name JONATHAN FOO JIA HAO
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLR9760T
Were seat belts worn? YES
Was injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan #2

SKETCH PLAN

Along PIE (Turns) Near Above Exit.



A: SJJ 7275 G

B: SLK 974 60 T

C: SHB 2244 U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15 December at about 3.35pm, along PIE (Turns) near Above Exit, I was met with a rear collision. The first car was driving and I was driving as well. However a taxi collided on a road impact ~~caused the~~ into the back of my car and I think cut and collided with car A. Car C was approaching from the side and I don't know where from the back after colliding with the first car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 16/12/2017

Reporting Centre Personnel's Signature
Name: [Signature]
NRIC/ID No.: 91855256919

12:35 pm

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo





Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE


 Licence Number: **S 93481251**
 Name: **JONATHAN FOO JIA HAO**
 Birth Date: **12 Dec 1993**
 Issue Date: **04 May 2012**

0030651540

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!

	EFFECTIVE DATE
Class 2B Motorcycles <= 204 CC	24 Mar 2012
Class 2 Motor cars <= 2000 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg	25 Nov 2012

S / No. 9000189295
 Licence No: S93481251
 NP 428A



EMPOWER YOUR DRIVE.
TAKE ON ANY ROAD WITH THE ALL-NEW BMW 520i.

[Book a test drive today](#)



[Sign Up New Account](#)
[Forgot Password](#)

Home » New Cars » New Car Brands » Audi » Audi A3 Sedan

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle

Vehicle Inspection



Audi A3 Sedan

[Overview](#) [Pricing](#) [Photos](#) [Research](#) [Reviews](#) [Specs](#) [Features](#) [Similar](#) [Accessories](#) [Promo](#)

[Add to Shortlist](#) [Submit a Review](#) [Report Error](#) [Share](#)



USER RATINGS: (11 reviews)

Details

Distributor Premium Automobiles
Hotline 68362223
Built in Hungary (launched 2013, facelifted Jan-2017)
Pricelist **28-Dec Pricelist**
Promotion No current promotions. Alert me when new promotions are inserted

[View all other promotions](#) [Download Brochure](#) [Add to Shortlist](#)

Submodel	Price	Depreciation ?	Fuel Economy	Power	Transmission	Detailed Info
1.0 TFSI S-tronic (A) FACELIFT Read facelift article	\$146,300	\$13,900 /yr	21.3km/L	116bhp	7-speed (A) S-tronic	Specs Features

Price updated **28-Dec-2017**

Related Articles



A cabriolet that is sporty, elegant and compact



Audi A3 e-tron wins eCar award



The latest generation of the Audi A3 series



Six reasons to buy a gilded number plate

[View More](#)

Audi A3 Sedan Photos



[+ View All 35 Audi A3 Sedan Photos](#)

Audi A3 Sedan Review

Car Review - Audi A3 Sedan 1.4 TFSI S-tronic Ambiente (A)

14 Apr 2014 | Audi Reviews

The Audi A3 sedan looks smart inside and out, drives exceptionally well and is positively frugal, distinguishing itself from the rest in its segment.

The Good

- It makes you look unique
- It's well-priced in practicality and style
- You can drive it like a roadster and feel rewarded

The Bad

- Not as frugal as the Sportback

FACELIFT The Audi A3 Sedan was facelifted on Jan 2017. [Read more](#)

CONSUMER REVIEWS

Great luxury car for a first continental...

Got my A3 during end Nov and love the ride since. Ride performance has been great given that it is only a 1.0L car. Overtaking and pick up is now much better than my previous non-turbo charged cars. Space is a...
[Read More](#)

[Submit a review](#)

Receive 3 MCF points when you submit a review

Simply loving it!

Got my ride recently and it is the best decision that I have ever made. Been driving Japanese makes all along and decided to give conti car a try. The A3 indeed woos me with its luxury feel! Interior is amazing...
[Read More](#)

[+ View All 11 Consumer Reviews](#)

Items for Audi



HID Conversion Kit Set



BBS RJ-A 18" Rim



19" Rim

RETAIL PRICE LIST

Collection on 28 August 2002



Model	Power (W)	Temp (°C)	Max Fuel Consumption (L/100km)	Actual Price	DPVS rebate / mileage	Actual Price after DPVS	
Model A1 Superbikes							
A1	1.0 1750 cc 4 stroke	95	100	4.4	0.147,200	0.12,000	0.15,500
Model A2 Superbikes							
A2	1.0 1750 cc 4 stroke	135	100	4.8	0.147,200	0.12,000	0.16,200
A2	2.0 1750 cc 4 stroke	180	100	5.6	0.152,700	0	0.152,700
Model A3 Bikes							
A3	0.8 1750 cc 4 stroke	114	100	4.7	0.091,400	0.01,000	0.075,400
A3	1.0 1750 cc 4 stroke	100	100	4.5	0.074,900	0	0.074,900
A3	1.5 1750 cc 4 stroke	100	100	4.5	0.098,500	0.01,000	0.090,500
Model A4 Crossover							
A4	1.4 1750 cc 4 stroke	110	100	5.0	0.142,200	0.01,000	0.117,200
Model A4 Crossover							
A4	1.8 1750 cc 4 stroke	130	100	5.2	0.175,200	0.01,000	0.160,200
A4	1.8 1750 cc 4 stroke (Overhaul)	150	100	5.2	0.184,300	0.01,000	0.170,300
A4	1.0 1750 cc 4 stroke (Overhaul)	153	100	4.9	0.118,000	0	0.118,000
A4	1.0 1750 cc 4 stroke (Overhaul)	154	100	5.0	0.099,000	0	0.099,000
Model A5 Superbikes							
A5	1.0 1750 cc 4 stroke (Overhaul)	100	100	5.0	0.098,500	0.01,000	0.090,500
A5	1.0 1750 cc 4 stroke (Overhaul)	153	100	4.4	0.075,800	0	0.075,800
A5	1.0 1750 cc 4 stroke	154	100	5.0	0.098,500	0	0.098,500
Model A5 Crossover							
A5	1.0 1750 cc 4 stroke (Overhaul)	100	100	5.0	0.111,300	0.01,000	0.100,300
A5	1.0 1750 cc 4 stroke (Overhaul)	153	100	4.4	0.046,900	0	0.046,900
Model A6 Crossover							
A6	1.0 1750 cc 4 stroke	100	100	5.0	0.098,500	0.01,000	0.090,500
A6	1.0 1750 cc 4 stroke (Overhaul)	153	100	4.4	0.046,900	0	0.046,900
A6	1.0 1750 cc 4 stroke	154	100	5.0	0.098,500	0	0.098,500
A6	1.0 1750 cc 4 stroke	153	100	5.0	0.111,300	0	0.111,300
Model A6 Crossover							
A6	1.0 1750 cc 4 stroke (Overhaul)	100	100	5.0	0.045,800	0	0.045,800
A6	1.0 1750 cc 4 stroke	153	100	5.0	0.064,000	0	0.064,000
A6	1.0 1750 cc 4 stroke	153	100	5.0	0.111,300	0	0.111,300
Model A7 Superbikes							
A7	1.0 1750 cc 4 stroke	152	100	4.9	0.065,000	0	0.065,000
A7	1.0 1750 cc 4 stroke	153	100	5.0	0.046,000	0	0.046,000
Model A8							
A8	1.0 1750 cc 4 stroke	100	100	5.0	0.047,000	0	0.047,000
A8	1.0 1750 cc 4 stroke	153	100	5.0	0.046,000	0	0.046,000
A8	1.0 1750 cc 4 stroke	152	100	4.8	0.040,000	0.01,000	0.030,000
Model Q1							
Q1	1.0 1750 cc 4 stroke	100	100	5.0	0.115,200	0.01,000	0.104,200
Q1	1.0 1750 cc 4 stroke (Overhaul)	118	100	5.0	0.141,000	0.01,000	0.130,000
Q1	1.4 1000 cc 1000 cc 4 stroke (Overhaul)	100	100	5.0	0.171,000	0.01,000	0.160,000
Model Q2							
Q2	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Q2	1.0 1750 cc 4 stroke (Overhaul)	100	100	4.7	0.187,000	0	0.187,000
Model Q3							
Q3	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q4							
Q4	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q5							
Q5	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q6							
Q6	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q7							
Q7	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q8							
Q8	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q9							
Q9	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q10							
Q10	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q11							
Q11	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q12							
Q12	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q13							
Q13	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q14							
Q14	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q15							
Q15	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q16							
Q16	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q17							
Q17	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q18							
Q18	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q19							
Q19	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000
Model Q20							
Q20	1.0 1750 cc 4 stroke	100	100	5.0	0.173,000	0	0.173,000

Testing used 1 condition:

10. Rental group is subject to its Rental Finance and Insurance Policy schedule 1 (2 months rent less, registration fee and G.S. for without insurance)
11. (S.B. is non-government and subject to G.S. 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835,

© Premium Automobiles

© PHOTOFEST Australia
 4011 Camara Singapore
 201, Newbridge Road Singapore 110004
 Tel: 6888 3373 | www.photofest.com.au

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9078G
Vehicle Details	
Vehicle No.:	SLR9760T
Vehicle to be Exported:	No
Intended De-registration Date:	29 Dec 2017
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	CHZ512284
Chassis No.:	WAUZZZ8V9J1007443
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,475.00
Original Registration Date:	31 Aug 2017
First Registration Date:	31 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$16,265.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2027
PARF Rebate Amount:	\$12,198.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,900.00
COE Rebate Amount:	\$41,481.00
Total Rebate Amount:	\$53,679.00

The information contained herein is correct as at 29 Dec 2017

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1231/2017/JT
Date : 18-Dec-17

Vehicle in workshop. Kindly arrange for survey.

First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : Ms. Chun Jlok Lui
Address : Blk 449 Hougang Ave 10
#04-S05
Singapore 530449
Telephone : HP +65 9822 7464
Type of Claim : Third Party Claims
Policy No. :
Vehicle No : **SLR 9760 T**
Model Code : Audi A3 Sedan 1.0 TFSI S-tronic
Model / Year : Aug-17
Engine No : CHZ 512284
Chassis No : WAUZZZ8V9J1007443
Mileage : -
Date In : 15-Dec-17
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Dec-17
Place of Accident : Along PIE (Tuas) near Adam exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 9760 T.

S/n	Nature of Jobs	Estimated Charges
1	To carry out towing from accident scene.	S/N \$ 280.00 ✓
2	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor & headlight washer assy.	S/N \$ 360.00 ✓
3	To dismantle and renew front bumper assy, bonnet and both front headlights. Re-organize front crash management components. Reinstall all parts removed.	\$ 2,400.00 1200 ✓
4	To respray front bumper, bonnet, hinges and both A-pillar.	\$ 2,600.00 1300 ✓
TOTAL LABOUR CHARGES		: <u>\$ 5,640.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 9760 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Replaced</i>	\$ 1,667.00	✓ ✓
2	FRONT BUMPER GUIDE - LHS/RHS <i>new</i>	\$ 62.00	+
3	FRONT BUMPER LOWER GRILLE - CENTRE <i>Replaced</i>	\$ 133.00	✓ X
4	FRONT BUMPER END PLATE - LHS/RHS <i>Replaced</i>	\$ 492.00	✓ X
5	RADIATOR GRILLE <i>Replaced</i>	\$ 1,176.00	✓ ✓
6	FRONT BUMPER CLOSING ELEMENT <i>Replaced</i>	\$ 158.00	X 166.50
7	REINFORCEMENT BEAM COVER <i>Replaced</i>	\$ 99.00	? 99
8	FRONT REINFORCEMENT BEAM FOAM PIECE <i>Replaced</i>	\$ 157.00	? ✓
9	FRONT REINFORCEMENT BEAM <i>Replaced</i>	\$ 608.00	? ✓
10	BONNET CATCH HOLDER <i>new</i>	\$ 53.00	X 52.00 ✓
11	FRONT AIR GRILLE - LHS/RHS <i>new</i>	\$ 312.00	X
12	LED HEADLIGHT - LHS/RHS <i>Replaced</i>	\$ 10,916.00	? X
13	BONNET <i>Replaced</i>	\$ 2,748.00	✓ ✓
14	BONNET ATTACHMENT PARTS <i>new</i>	\$ 138.00	✓ 172.50
15	BONNET HINGE - LHS/RHS <i>new</i>	\$ 104.00	X
16	BONNET CATCH <i>new</i>	\$ 76.00	+
17	BONNET STRIKER <i>new</i>	2 \$ 186.00	X
18	BONNET SEAL <i>new</i>	\$ 23.00	✓
19	BONNET SWITCH <i>new</i>	2 \$ 338.00	+
20	BONNET CABLE <i>new</i>	\$ 49.00	X
SUB-FRONT SPARE PARTS CHARGES		\$ 19,495.00	

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 9760 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	STICKER FOR AIR CONDITIONER <i>new</i>	\$ 6.00	<i>✓</i> 5.80
22	CAUTION STICKER <i>new</i>	\$ 12.00	<i>✓</i> 11.30
23	WINDSCREEN LOWER COVER <i>new</i>	\$ 150.00	<i>✓</i>
24	FRONT NUMBER PLATE <i>Bent</i>	S/N \$ 25.00	<i>✓</i> 25
TOTAL-FRONT PARTS CHARGES		:	\$ 19,688.00
TOTAL-FRONT LABOUR CHARGES		:	\$ 5,640.00
GRAND TOTAL PARTS AND LABOUR		:	\$ 25,328.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett

25,328.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 9760 T.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and renew rear parking aid. Check function.	S/N \$ 280.00 ✓	✓
2	To remove and reinstall rear wire harness, audio equipment, control units, relay and fuse trays, end panelling, spare wheel housing and rear lid harness.	S/N \$ 1,800.00 ✓	✓
3	To remove and reinstall rear seats, back rest, carpets, ABCD pillar trims, disengage airbag system.	S/N \$ 1,800.00 ?	✓
4	To remove exhaust system and fuel tank assy. Renew centre and rear exhaust silencer.	S/N \$ 780.00 ?	✓
5	To remove and reinstall rear suspension assy to facilitate cellette bench repairs. Inspect for damages.	S/N \$ 2,800.00 ?	✓
6	To set up and place vehicle on cellette bench.	S/N \$ 1,800.00 ?	✓
7	To dismantle rear bumper and rear lid. Cut out and reweld rear panels, spare wheel housing and cross members. Repair and align whole rear substructure to position. Renew rear bumper and rear lid. Reinstall all parts removed.	\$ 7,200.00 4800 600 x 800	✓
SUB LABOUR CHARGES REAR		\$ 16,460.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 9760 T.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
8	To remove stone chip primer works and rear panelling and spare wheel housing.	S/N	\$ 780.00	✓
9	To respray paint on rear bumper, rear lid, spare wheel housing, and boot floor. To carry out joint sealer works and cavity preservation.		\$ 3,300.00 2400	✓
10	To carry out wheel alignment.	S/N	\$ 240.00	?
11	To carry out diagnostic checks.	S/N	\$ 384.00	✓
TOTAL LABOUR REAR		:	<u>\$ 21,164.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 9760 T.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Distorted</i>	\$ 1,567.00	✓ ✓
2	REAR BUMPER GUIDE - LHS/RHS <i>new</i>	\$ 26.00	✓ 12.60
3	REAR BUMPER LOCKING GUIDE - LHS/RHS <i>new</i>	\$ 49.00	✓ 24.10
4	REAR BUMPER SPOILER <i>Distorted</i>	\$ 193.00	✓ 193
5	REAR BUMPER REFLECTOR - LHS/RHS <i>LH cut out</i>	\$ 48.00	24. 23.70
6	REAR PARKING AID SENSOR <i>2 pieces damaged</i>	4 \$ 830.00	415 ✓
7	PARKING AID WIRING SET <i>2H new</i>	\$ 446.00	? X
8	REAR LID <i>Distorted</i>	\$ 2,225.00	✓ ✓
9	REAR LID ATTACHMENT <i>new</i>	\$ 247.00	✓ 174
10	REAR LID HINGE - LHS/RHS <i>2H new</i>	\$ 434.00	? X
11	REAR WEATHERSTRIP <i>cut</i>	\$ 167.00	✓ 166.50
12	REAR LID STRIKER <i>Distorted</i>	\$ 42.00	✓ 41.80
13	REAR LID LOCK <i>2H new</i>	\$ 165.00	? X
14	REAR LID PUSH BUTTON <i>new</i>	\$ 156.00	✓ X
15	PACKING ADHESIVE <i>new</i>	\$ 14.00	✓ 13.90
16	AUDI EMBLEM <i>2H new</i>	\$ 105.00	✓
17	"A3" EMBLEM	\$ 81.00	✓ 80.90
18	"TFSI" EMBLEM	\$ 81.00	✓ 80.90
19	REAR CROSS PANEL <i>Distorted</i>	\$ 307.00	✓ ✓
20	CROSS PANEL REINFORCEMENT PANEL <i>Distorted</i>	\$ 622.00	✓ 621.80
SUB PART CHARGES - REAR		\$ 7,805.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 9760 T.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR CROSS PANEL CONNECTING PLATE - LHS/RHS ?	\$ 244.00	? ✓ DD
22	REAR REINFORCEMENT BEAM <i>Best</i>	\$ 481.00	✓ 480.50
23	REAR BUMPER BRACKET - LHS/RHS ?	\$ 45.00	? 43 90 Damage
24	REAR BUMPER GUIDE - LHS/RHS <i>new</i>	\$ 108.00	✓ X
25	SPARE WHEEL HOUSING - RHS <i>Disbled</i>	\$ 596.00	✓ 595.50
26	SPARE WHEEL HOUSE MOUNT <i>new</i>	\$ 41.00	? ✓
27	REAR CROSS MEMBER - TOP <i>new</i>	\$ 238.00	? ✓
28	REAR CROSS MEMBER - CTR <i>Repair</i>	\$ 308.00	? X
29	REAR CROSS PANEL TRIM <i>Disbled</i>	\$ 131.00	✓ 130.50
30	STOWAGE COMPARTMENT (FOAM) <i>could</i>	\$ 91.00	✓ 90.30
31	FRONT SILENCER <i>new</i>	\$ 439.00	? X
32	REAR SILENCER <i>Best</i>	\$ 631.00	? 630.50
33	DUAL CLIP <i>arc</i>	\$ 52.00	? 51.60
34	EXHAUST RETAINER <i>arc</i>	\$ 71.00	? 70.20
35	SILENCER HEAT SHIELD <i>new</i>	\$ 144.00	? ✓
36	REAR NUMBER PLATE <i>Best</i>	S/N \$ 25.00	✓ ✓
37	ACRYLIC SEALER <i>new</i>	S/N \$ 360.00	✓ ✓
38	CAVITY WAX <i>new</i>	S/N \$ 280.00	✓ ✓
39	STONE CHIP <i>new</i>	S/N \$ 360.00	✓ ✓
40	METAL FILLER POWDER <i>new</i>	S/N \$ 280.00	✓ ✓
41	SUNDRIES <i>all</i>	\$ 600.00	? 75.90
TOTAL PARTS - REAR		\$ 13,330.00	
TOTAL LABOUR REAR		\$ 21,164.00	
TOTAL PARTS / LABOUR CHARGES - REAR		\$ 34,494.00	
TOTAL PARTS / LABOUR FRONT		\$ 25,328.00	
GRAND TOTAL FOR FRONT AND REAR		\$ 59,822.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.


600.00 50

76332.90

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adam 
Surveyed Date : 19/12/17.
Authorised Date :
Excess Cost :
Liability :
Remarks : MP Authorised, 16 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 8366 2323 Fax : (65) 6841 1183

Supplementary Estimate

GST Reg No. 19-9902271-W

First Capital Insurance Ltd 36 Robinson Road # 16-01 City House Singapore 068877 Attn: Motor Claims Dept Tel:6854 3909 Fax: 6507 3849		Estimate No. PA/TP/1231/2017/JT Date 27-Dec-17 Service Advisor Chang Pages 1 Regn No SLR 9760 T Model No Audi A3 SEDAN 1.0 TFSI	
Quantity	Description	Unit Price	Amount
Labours			
1	To renew lhs 1/4 glass and rear windscreen to facilitate fender renewal. S/N	\$ 600.00	\$ 600.00
2	To cut out and weld lhs rear fender and connecting plates. Repair rhs rear fender.	\$ 4,200.00	\$ 3,600.00
3	To respray both rear fenders, lhs sill panel, door entrance, drain panel, and roof channel.	\$ 3,500.00	\$ 3,200.00
TOTAL LABOURS :		\$ 8,300.00	\$ 7,400.00
Parts			
1	REAR FENDER CONNECTING PLATE - LH <i>Right</i>	\$ 122.00	<i>X</i>
2	REAR FENDER - LH <i>Broken</i>	\$ 1,938.00	\$ 2,006.00
3	REAR 1/4 GLASS - LH <i>3</i>	\$ 455.00	\$ 501.50
4	REAR WINDSCREEN <i>3</i>	\$ 675.00	\$ 704.00
5	GLASS PRIMER	\$ 36.00	\$ 36.40
6	REAR FENDER SOUND ABSORBER <i>3</i>	\$ 213.00	\$ 216.00
7	REAR 1/4 GLASS SEALANT	\$ 100.00	\$ 100.00
8	REAR WINDSCREEN SEALANT	\$ 200.00	\$ 200.00
TOTAL PARTS :		\$ 3,739.00	\$ 3,763.90
Grand Total :		\$ 12,039.00	\$ 11,163.90

For Premium Automobiles Pte Ltd

12183 90

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate

GST Reg No. 19-9902271-W

First Capital Insurance Ltd 36 Robinson Road # 16-01 City House Singapore 068877 Attn: Motor Claims Dept Tel:6854 3909 Fax: 6507 3849		Estimate No. PA/TP/1231/2017/JT Date 12-Jan-18 Service Advisor Chang Pages 1 Regn No SLR 9760 T Model No Audi A3 SEDAN 1.0 TFSI	
Quantity	Description	Unit Price	Amount
Labours			
1	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system (S/N)	\$ 1,100.00	✓
2	To renew front lock carrier and align to position.	\$ 2,400.00	1240 1700
TOTAL LABOURS :		\$ 3,500.00	
Parts			
1	FRONT SEALING FRAME - RH	\$ 46.00	new ✓ 45.70
2	FRONT LOCK CARRIER	\$ 638.00	OE ✓ 637.50
3	COOLANT	\$ 133.00	new ✓ 130.80
TOTAL PARTS :		\$ 817.00	
Grand Total :		\$ 4,317.00	

Ran
12/01/18
Ran

For Premium Automobiles Pte Ltd



Authorised Signature

4316

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate

GST Reg No. 19-9902271-W

First Capital Insurance Ltd 36 Robinson Road # 16-01 City House Singapore 068877 Attn: Motor Claims Dept Tel:6854 3909 Fax: 6507 3849		Estimate No. PA/TP/1231/2017/JT Date 12-Jan-18 Service Advisor Chang Pages 1 Regn No SLR 9760 T Model No Audi A3 SEDAN 1.0 TFSI	
Quantity	Description	Unit Price	Amount
Labours			
1	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system (S/N)	\$ 1,100.00	\$ 1,100.00
2	To renew front lock carrier and align to position.	\$ 2,400.00	\$ 1,800.00
TOTAL LABOURS :		\$ 3,500.00	\$ 2,900.00
Parts			
1	FRONT SEALING FRAME - RH <i>re</i>	\$ 46.00	\$ 45.70
2	FRONT LOCK CARRIER <i>checked</i>	\$ 638.00	\$ 637.50
3	COOLANT <i>new</i>	\$ 133.00	\$ 132.80
TOTAL PARTS :		\$ 817.00	\$ 816.00
Grand Total :		\$ 4,317.00	\$ 3,716.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1231/2017/JT
Date : 18-Dec-17

Vehicle in workshop. Kindly arrange for survey.

First Capital Insurance Ltd

36 Robinson Road
16-01 City House
Singapore 068877

Hi Adrian

You recommended 16 days

We took 40 dayss exclude 5 Sundays
and 1 Public Holiday - Jb - 14 Jun 18

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : Ms. Chun Jlok Lui
Address : Blk 449 Hougang Ave 10
#04-505
Singapore 530449
Telephone : HP +65 9822 7464
Type of Claim : Third Party Claims
Policy No. :
Vehicle No : **SLR 9760 T**
Model Code : Audi A3 Sedan 1.0 TFSI S-tronic
Model / Year : Aug-17
Engine No : CHZ 512284
Chassis No : WAUZZZ8V9J1007443
Mileage : -
Date In : 15-Dec-17
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Dec-17
Place of Accident : Along PIE (Tuas) near Adam exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 9760 T.

S/n	Nature of Jobs	Estimated Charges			
1	To carry out towing from accident scene.	S/N	\$ 280.00	\$	280.00
2	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor & headlight washer assy.	S/N	\$ 360.00	\$	360.00
3	To dismantle and renew front bumper assy, bonnet and both front headlights. Re-organize front crash management components. Reinstall all parts removed.		\$ 2,400.00	\$	1,200.00
4	Added labour - frontal		\$ 3,500.00	\$	2,900.00
5	To respray front bumper, bonnet, hinges and both A-pillar.		\$ 2,600.00	\$	1,300.00
TOTAL LABOUR CHARGES		:	<u>\$ 9,140.00</u>	<u>\$</u>	<u>6,040.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 9760 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,667.00	\$ 1,667.00
2	FRONT BUMPER GUIDE - LHS/RHS	\$ 62.00	
3	FRONT BUMPER LOWER GRILLE - CENTRE	\$ 133.00	
4	FRONT BUMPER END PLATE - LHS/RHS	\$ 492.00	
5	RADIATOR GRILLE	\$ 1,176.00	\$ 1,176.00
6	FRONT BUMPER CLOSING ELEMENT	\$ 158.00	\$ 166.50
7	REINFORCEMENT BEAM COVER	\$ 99.00	\$ 99.00
8	FRONT REINFORCEMENT BEAM FOAM PIECE	\$ 157.00	\$ 157.00
9	FRONT REINFORCEMENT BEAM	\$ 608.00	\$ 608.00
10	BONNET CATCH HOLDER	\$ 53.00	\$ 52.80
11	FRONT AIR GRILLE - LHS/RHS	\$ 312.00	
12	LED HEADLIGHT - LHS/RHS	\$ 10,916.00	
13	BONNET	\$ 2,748.00	\$ 2,748.00
14	BONNET ATTACHMENT PARTS	\$ 138.00	\$ 122.50
15	BONNET HINGE - LHS/RHS	\$ 104.00	
16	BONNET CATCH	\$ 76.00	
17	BONNET STRIKER	2 \$ 186.00	
18	BONNET SEAL	\$ 23.00	\$ 23.00
19	BONNET SWITCH	2 \$ 338.00	
20	BONNET CABLE	\$ 49.00	
SUB-FRONT SPARE PARTS CHARGES		\$ 19,495.00	\$ 6,819.80

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 9760 T.

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
		c/f		\$ 6,819.80
21	STICKER FOR AIR CONDITIONER		\$ 6.00	\$ 5.80
22	CAUTION STICKER		\$ 12.00	\$ 11.30
23	WINDSCREEN LOWER COVER		\$ 150.00	
24	Added parts - frontal		\$ 817.00	\$ 816.00
25	FRONT NUMBER PLATE	S/N	\$ 25.00	\$ 25.00
	TOTAL-FRONT PARTS CHARGES	:	\$ 20,505.00	\$ 7,677.90
	TOTAL-FRONT LABOUR CHARGES	:	\$ 9,140.00	\$ 6,040.00
	GRAND TOTAL PARTS AND LABOUR	:	\$ 29,645.00	\$ 13,717.90

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 9760 T.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
	Labour front - c/f			\$ 6,040.00
1	To remove and renew rear parking aid. Check function.	S/N \$	280.00	\$ 280.00
2	To remove and reinstall rear wire harness, audio equipment, control units, relay and fuse trays, end panelling, spare wheel housing and rear lid harness.	S/N \$	1,800.00	\$ 1,800.00
3	To remove and reinstall rear seats, back rest, carpets, ABCD pillar trims, disengage airbag system.	S/N \$	1,800.00	\$ 1,800.00
4	To remove exhaust system and fuel tank assy. Renew centre and rear exhaust silencer.	S/N \$	780.00	\$ 780.00
5	To remove and reinstall rear suspension assy to facilitate cellette bench repairs. Inspect for damages.	S/N \$	2,800.00	\$ 2,800.00
6	To set up and place vehicle on cellette bench.	S/N \$	1,800.00	\$ 1,800.00
7	To dismantle rear bumper and rear lid. Cut out and reweld rear panels, spare wheel housing and cross members. Repair and align whole rear substructure to position. Renew rear bumper and rear lid. Reinstall all parts removed.	\$	7,200.00	\$ 4,800.00
SUB LABOUR CHARGES REAR		:	<u>\$ 16,460.00</u>	<u>\$ 20,100.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLR 9760 T.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 20,100.00
8	To remove stone chip primer works and rear panelling and spare wheel housing.	S/N	\$ 780.00	\$ 780.00
9	To respray paint on rear bumper, rear lid, spare wheel housing, and boot floor. To carry out joint sealer works and cavity preservation.		\$ 3,300.00	\$ 2,400.00
10	To carry out wheel alignment.	S/N	\$ 240.00	\$ 240.00
11	<i>Added labour charges -rear</i>		\$ 8,300.00	\$ 7,400.00
12	To carry out diagnostic checks.	S/N	\$ 384.00	\$ 384.00
TOTAL LABOUR REAR		:	\$ 29,464.00	\$ 31,304.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 9760 T.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
	<i>Materials front - c/f</i>		\$ 7,677.90
1	REAR BUMPER	\$ 1,567.00	\$ 1,567.00
2	REAR BUMPER GUIDE - LHS/RHS	\$ 26.00	\$ 12.60
3	REAR BUMPER LOCKING GUIDE - LHS/RHS	\$ 49.00	\$ 24.10
4	REAR BUMPER SPOILER	\$ 193.00	\$ 193.00
5	REAR BUMPER REFLECTOR - LHS/RHS	\$ 48.00	\$ 23.70
6	REAR PARKING AID SENSOR	4 \$ 830.00	\$ 415.00
7	PARKING AID WIRING SET	\$ 446.00	
8	REAR LID	\$ 2,225.00	\$ 2,225.00
9	REAR LID ATTACHMENT	\$ 247.00	\$ 174.00
10	REAR LID HINGE - LHS/RHS	\$ 434.00	
11	REAR WEATHERSTRIP	\$ 167.00	\$ 166.50
12	REAR LID STRIKER	\$ 42.00	\$ 41.80
13	REAR LID LOCK	\$ 165.00	
14	REAR LID PUSH BUTTON	\$ 156.00	
15	PACKING ADHESIVE	\$ 14.00	\$ 13.90
16	AUDI EMBLEM	\$ 105.00	\$ 105.00
17	"A3" EMBLEM	\$ 81.00	\$ 80.90
18	"TFSI" EMBLEM	\$ 81.00	\$ 80.90
19	REAR CROSS PANEL	\$ 307.00	\$ 307.00
20	CROSS PANEL REINFORCEMENT PANEL	\$ 622.00	\$ 621.50
	SUB PART CHARGES - REAR	\$ 7,805.00	\$ 13,729.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Net.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No. SLR 9760 T.

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17024053/Atd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 2244U	Veh. Inspected	SLR 9760T
	Policy No.	D-15072702MFSH	Coverage (\$)	0.00
	Claim No.	D17011605MFSH	Excess (\$)	0.00
	Assign From	AUNG YIN MIN	Assign Date	19/12/2017
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A3 SEDAN	c.c	999
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WAUZZZ8V9J1007443	Colour	WHITE
	Odometer	7366	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	GOODYEAR	6 mm
	L/H Front Tyre	205/55 R16	GOODYEAR	6 mm
	R/H Rear Tyre	205/55 R16	GOODYEAR	6 mm
	L/H Rear Tyre	205/55 R16	GOODYEAR	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	15/12/2017	Inspection Date	19/12/2017
	Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		35 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 9760T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT NUMBER PLATE (SN)	BENT	25.00	25.00
1	FRONT BUMPER (SN)	DEFORMED	1,667.00	1,667.00
1	FRONT BUMPER GUIDE - LHS/RHS (SN)	NOT NECESSARY	62.00	-
1	FRONT BUMPER LOWER GRILLE - CENTRE (SN)	NOT NECESSARY	133.00	-
1	FRONT BUMPER END PLATE - LHS/RHS (SN)	NOT NECESSARY	492.00	-
1	RADIATOR GRILLE (SN)	CRACKED	1,176.00	1,176.00
1	FRONT BUMPER CLOSING ELEMENT (SN)	DAMAGED	166.50	166.50
1	REINFORCEMENT BEAM COVER (SN)	DEFORMED	99.00	99.00
1	FRONT REINFORCEMENT BEAM FOAM PIECE (SN)	CRACKED	157.00	157.00
1	FRONT REINFORCEMENT BEAM (SN)	BENT	608.00	608.00
1	BONNET CATCH HOLDER (SN)	NOT NECESSARY	53.00	52.80
1	FRONT AIR GRILLE - LHS/RHS (SN)	NOT NECESSARY	312.00	-
1	LED HEADLIGHT - LHS/RHS (SN)	NOT NECESSARY	10,916.00	-
1	BONNET (SN)	BUCKLED	2,748.00	2,748.00
1	BONNET ATTACHMENT PARTS (SN)	NECESSARY	138.00	122.50
1	BONNET HINGE - LHS/RHS (SN)	NOT NECESSARY	104.00	-
1	BONNET CATCH (SN)	NOT NECESSARY	76.00	-
2	BONNET STRIKER (SN)	NOT NECESSARY	186.00	-
1	BONNET SEAL (SN)	NECESSARY	23.00	23.00
2	BONNET SWITCH (SN)	NOT NECESSARY	338.00	-
1	BONNET CABLE (SN)	NOT NECESSARY	49.00	-
1	STICKER FOR AIR CONDITIONER (SN)	NECESSARY	6.00	5.80
1	CAUTION STICKER (SN)	NECESSARY	12.00	11.30
1	WINDSCREEN LOWER COVER (SN)	NOT NECESSARY	150.00	-
1	REAR BUMPER (SN)	DISTORTED	1,567.00	1,567.00
1	REAR BUMPER GUIDE - LHS/RHS (SN)	NECESSARY	26.00	12.60
1	REAR BUMPER LOCKING GUIDE - LHS/RHS (SN)	NECESSARY	49.00	24.10
1	REAR BUMPER SPOILER (SN)	DISTORTED	193.00	193.00
1	REAR BUMPER REFLECTOR - LHS/RHS (SN)	N/S CRACKED	48.00	23.70
4	REAR PARKING AID SENSOR (SN)	DAMAGED - ONLY 2PCS	830.00	415.00

Report Ref No. CS/FCI17024053/Atd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET PARKING AID WIRING (SN)	NOT NECESSARY	446.00	-
1	REAR LID (SN)	DENTED	2,225.00	2,225.00
1	REAR LID ATTACHMENT (SN)	NECESSARY	247.00	174.00
1	REAR LID HINGE - LHS/RHS (SN)	NOT NECESSARY	434.00	-
1	REAR WEATHERSTRIP (SN)	CUT	167.00	166.50
1	REAR LID STRIKER (SN)	BENT	42.00	41.80
1	REAR LID LOCK (SN)	NOT NECESSARY	165.00	-
1	REAR LID PUSH BUTTON (SN)	NOT NECESSARY	156.00	-
1	PACKING ADHESIVE (SN)	NECESSARY	14.00	13.90
1	AUDI EMBLEM (SN)	NECESSARY	105.00	105.00
1	"A3" EMBLEM (SN)	NECESSARY	81.00	80.90
1	"TFSI" EMBLEM (SN)	NECESSARY	81.00	80.90
1	REAR CROSS PANEL (SN)	DISTORTED	307.00	307.00
1	CROSS PANEL REINFORCEMENT PANEL (SN)	DISTORTED	622.00	621.50
1	REAR CROSS PANEL CONNECTING PLATE - LHS/RHS (SN)	DENTED	244.00	244.00
1	REAR REINFORCEMENT BEAM (SN)	BENT	481.00	480.50
1	REAR BUMPER BRACKET - LHS/RHS (SN)	DAMAGED	45.00	43.90
1	REAR BUMPER GUIDE - LHS/RHS (SN)	NOT NECESSARY	108.00	-
1	SPARE WHEEL HOUSING - RHS (SN)	DISTORTED	596.00	595.50
1	SPARE WHEEL HOUSE MOUNT (SN)	NECESSARY	41.00	41.00
1	REAR CROSS MEMBER - TOP (SN)	BENT	238.00	238.00
1	REAR CROSS MEMBER - CTR (SN)	TO REPAIR SEE LABOUR	308.00	-
1	REAR CROSS PANEL TRIM (SN)	DEFORMED	131.00	130.50
1	STOWAGE COMPARTMENT (FOAM) (SN)	CRACKED	91.00	90.30
1	FRONT SILENCER (SN)	NOT NECESSARY	439.00	-
1	REAR SILENCER (SN)	BENT	631.00	630.50
1	DUAL CLIP (SN)	DAMAGED	52.00	51.60
1	EXHAUST RETAINER (SN)	DAMAGED	71.00	70.20
1	SILENCER HEAT SHIELD (SN)	DAMAGED	144.00	144.00
1	REAR NUMBER PLATE (SN)	BENT	25.00	25.00
1	ACRYLIC SEALER (SN)	NECESSARY	360.00	360.00
1	CAVITY WAX (SN)	NECESSARY	280.00	280.00

Report Ref No. CS/FCI17024053/Atd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STONE CHIP (SN)	NECESSARY	360.00	360.00
1	METAL FILLER POWDER (SN)	NECESSARY	280.00	280.00
1	SUNDRIES (SN)	NECESSARY	600.00	75.90
1	REAR FENDER CONNECTING PLATE - LH (SN) (ADDITIONAL)	TO REPAIR SEE LABOUR	122.00	-
1	REAR FENDER - LH (SN) (ADDITIONAL)	BUCKLED	2,006.00	2,006.00
1	REAR 1/4 GLASS - LH (SN) (ADDITIONAL)	NECESSARY	501.50	501.50
1	REAR WINDSCREEN (SN) (ADDITIONAL)	NECESSARY	704.00	704.00
2	GLASS PRIMER (SN) (ADDITIONAL)	NECESSARY	36.40	36.40
1	REAR FENDER SOUND ABSORBER (SN) (ADDITIONAL)	NECESSARY	216.00	216.00
1	REAR 1/4 GLASS SEALANT (SN) (ADDITIONAL)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN SEALANT (SN) (ADDITIONAL)	NECESSARY	200.00	200.00
1	FRONT SEALING FRAME - RH (SN)(ADDITIONAL)	NECESSARY	45.70	45.70
1	FRONT LOCK CARRIER (SN) (ADDITIONAL)	DEFORMED	637.50	637.50
1	COOLANT (SN) (ADDITIONAL)	NECESSARY	132.80	132.80
			37,728.40	21,634.60
	LABOUR			
	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH A-PILLAR.		2,600.00	1,300.00
	TO CARRY OUT TOWING FROM ACCIDENT SCENE.		280.00	280.00
	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR & HEADLIGHT WASHER ASSY.		360.00	360.00
	TO DISMANTLE AND RENEW FRONT BUMPER ASSY, BONNET AND BOTH FRONT HEADLIGHTS. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		2,400.00	1,200.00
	TO REMOVE AND RENEW REAR PARKING AID. CHECK FUNCTION.		280.00	280.00
	TO REMOVE AND REINSTALL REAR WIRE HARNESS, AUDIO EQUIPMENT, CONTROL UNITS, RELAY AND FUSE TRAYS, END PANELLING, SPARE WHEEL HOUSING AND REAR LID HARNESS.		1,800.00	1,800.00
	TO REMOVE AND REINSTALL REAR SEATS, BACK RESTS, CARPETS, ABCD PILLAR TRIMS, DISENGAGE AIRBAG SYSTEM.		1,800.00	1,800.00

Report Ref No. CS/FCI17024053/Atd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE EXHAUST SYSTEM AND FUEL TANK ASSY. RENEW CENTRE AND REAR EXHAUST SILENCER.		780.00	780.00
	TO REMOVE AND REINSTALL REAR SUSPENSION ASSY TO FACILITATE CELLETE BENCH REPAIRS. INSPECT FOR DAMAGES.		2,800.00	2,800.00
	TO SET UP AND PLACE VEHICLE ON CELETTE BENCH.		1,800.00	1,800.00
	TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND REWELD REAR PANELS. SPARE WHEEL HOUSING AND CROSS MEMBERS. REPAIR AND ALIGN WHOLE REAR SUBSTRUCTURE TO POSITION. RENEW REAR BUMPER AND REAR LID. REINSTALL ALL PARTS REMOVED. INCLUSIVE OF THE REPAIR OF REAR CROSS MEMBER - CTR AND REAR FENDER CONNECTING PLATE - LH.		7,200.00	4,800.00
	TO REMOVE STONE CHIP PRIMER WORKS AND REAR PANELLING AND SPARE WHEEL HOUSING.		780.00	780.00
	TO RESPRAY PAINT ON REAR BUMPER, REAR LID, SPARE WHEEL HOUSING, AND BOOT FLOOR. TO CARRY OUT JOINT SEALER WORKS AND CAVITY PRESERVATION.		3,300.00	2,400.00
	TO CARRY OUT WHEEL ALIGNMENT.		240.00	240.00
	TO CARRY OUT DIAGNOSTIC CHECKS.		384.00	384.00
	TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL. (ADDITIONAL)		600.00	600.00
	TO CUT OUT AND WELD LHS REAR FENDER AND CONNECTING PLATES. REPAIR RHS REAR FENDER. (ADDITIONAL)		4,200.00	3,600.00
	TO RESPRAY BOTH REAR FENDERS, LHS SILL PANEL, DOOR ENTRANCE, DRAIN PANEL, AND ROOF CHANNEL (ADDITIONAL)		3,500.00	3,200.00
	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM/ REGAS AND TO PRESSURISE COOLING SYSTEM. (ADDITIONAL)		1,100.00	1,100.00
	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. (ADDITIONAL)		2,400.00	1,800.00
			38,604.00	31,304.00
GRAND TOTAL			76,332.40	52,938.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				52,938.60

Report Ref No. CS/FCI17024053/Atd3e2



Report Ref No. CS/FCI17024053/Atd3e2

000.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.