

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate

GST Reg No. 19-9902271-W

First Capital Insurance Ltd 36 Robinson Road # 16-01 City House Singapore 068877 Attn: Motor Claims Dept Tel:6854 3909 Fax: 6507 3849		Estimate No. PA/TP/1231/2017/JT Date 27-Dec-17 Service Advisor Chang Pages 1 Regn No SLR 9760 T Model No Audi A3 SEDAN 1.0 TFSI	
Quantity	Description	Unit Price	Amount
Labours			
1	To renew lhs 1/4 glass and rear windscreen to facillitate fender renewal. S/N	\$ 600.00	\$ 600.00
2	To cut out and weld lhs rear fender and connecting plates. Repair rhs rear fender.	\$ 4,200.00	\$ 3,600.00
3	To respray both rear fenders, lhs sill panel, door entrance, drain panel, and roof channel.	\$ 3,500.00	\$ 3,200.00
	TOTAL LABOURS :	\$ 8,300.00	\$ 7,400.00
Parts			
1	REAR FENDER CONNECTING PLATE - LH Rgt	\$ 122.00	X
2	REAR FENDER - LH Bricol	\$ 1,938.00	\$ 2,006.00
3	REAR 1/4 GLASS - LH } per	\$ 455.00	\$ 501.50
4	REAR WINDSCREEN	\$ 675.00	\$ 704.00
5	GLASS PRIMER 2	\$ 36.00	\$ 36.40
6	REAR FENDER SOUND ABSORBER } per	\$ 213.00	\$ 216.00
7	REAR 1/4 GLASS SEALANT S/N	\$ 100.00	\$ 100.00
8	REAR WINDSCREEN SEALANT S/N	\$ 200.00	\$ 200.00
	TOTAL PARTS :	\$ 3,739.00	\$ 3,763.90
	Grand Total :	\$ 12,039.00	\$ 11,163.90

For Premium Automobiles Pte Ltd

12185 90

 Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate

GST Reg No. 19-9902271-W

First Capital Insurance Ltd 36 Robinson Road # 16-01 City House Singapore 068877 Attn: Motor Claims Dept Tel:6854 3909 Fax: 6507 3849		Estimate No. PA/TP/1231/2017/JT Date 12-Jan-18 Service Advisor Chang Pages 1 Regn No SLR 9760 T Model No Audi A3 SEDAN 1.0 TFSI	
Quantity	Description	Unit Price	Amount
Labours			
1	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system (S/N)	\$ 1,100.00	✓
2	To renew front lock carrier and align to position.	\$ 2,400.00	1200 1800
TOTAL LABOURS :		\$ 3,500.00	
Parts			
1	FRONT SEALING FRAME - RH	\$ 46.00	✓ 45.70
2	FRONT LOCK CARRIER	\$ 638.00	✓ 637.50
3	COOLANT	\$ 133.00	✓ 132.80
TOTAL PARTS :		\$ 817.00	
Grand Total :		\$ 4,317.00	

Ram
12/01/18
fun

For Premium Automobiles Pte Ltd



Authorised Signature

4316