



Carmen Lim <carmen@esteemperf.com.sg>

FINALISED - SLQ 4110 H

Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
To: Carmen Lim <carmen@esteemperf.com.sg>

Fri, Aug 3, 2018 at 9:13 AM

L/Sump \$3500.00, 5days please confirmed. Kenneth

From: Carmen Lim [mailto:carmen@esteemperf.com.sg]
Sent: Wednesday, 1 August, 2018 6:18 PM
To: Kenneth Kong (LKKAUTO)
Subject: Re: FINALISED - SLQ 4110 H

REMINDER



Freundliche Grüße / Best Regards

Carmen Lim

Accident Claim Executive | Operation Division
Esteem Performance Pte Ltd

M: 8799 0066
P: 6484 1221
E: carmen@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259
(Head Office)
385 Sin Ming Drive Vicom Inspection Centre
(Showroom)

www.esteemperformance.com





ESTEEM PERFORMANCE PTE LTD

Blk 6033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLQ 4110 H

Parts (a) Cost / List Price Items	\$	6,485.20
Plus/Less 25%	\$	1,621.30
Total of Cost / List	\$	4,863.90
(b) Nett Price Items	\$	359.00
Less 10%	\$	35.90
Total of Nett Item	\$	323.10
(c) Special Nett Items		
Total Parts Cost	\$	5,187.00
Labour	\$	3,310.00
Total	\$	8,497.00

The above total will be subjected to 7% G.S.T.

Finalised

2855.10
713.78

2141.32
359
- 35.90

323.10

2464.42
1680

4144.42

Not Authored
1.12.1
Permy B & pain

Lump Sum

2500

Name of Surveyor

Kennerh

Company

CKK

Survey conducted on

19/12/17

at

11:30 am

Remarks By Surveyor

(a) The repair of this vehicle is *authorized* / is not authorized until further notice.

(b) Recommended Days of Repair : *05* day(s)

(c) Resurvey : Required / *Not Required*

(d) Excess : \$ _____

(e) Signature of surveyor : _____

Le

Date:

19/12/17



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569538.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLQ 4110 H

TOYOTA ALTIS
MR053REH104559973

Submit By :
Year Manufacture :
Engine No. :
Cost / List

Carmen Lim

2016

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>CRA C 122</i>	2	\$359.00	N	✓
2	Rear bumper <i>Bu</i>	1	\$496.30		✓
3	Rear bumper clip <i>M</i>	10	\$40.00		✓
4	Rear bumper side retainer LH <i>B's</i>	1	\$104.40		✓
5	Rear bumper side retainer RH <i>D's</i>	1	\$104.40		✓
6	Rear bumper bracket LH <i>B</i>	1	\$76.20		✓
7	Rear bumper bracket RH	1	\$76.20		?
8	Rear bumper reinforcement <i>B</i>	1	\$386.60		✓
9	Bootlid <i>R</i>	1	\$861.70		X
10	Bootlid lock <i>R</i>	1	\$369.20		X
11	Bootlid emblem <i>M</i>	1	\$51.40		✓
12	Wording "COROLLA" <i>M</i>	1	\$47.80		✓
13	Wording "ALTIS" <i>M</i>	1	\$49.60		✓
14	Bootlid chrome <i>S</i>	1	\$275.40		X
15	Bootlid lamp LH <i>S</i>	1	\$281.60		X
16	Bootlid lamp RH <i>S</i>	1	\$281.60		X
17	Tail end panel <i>B</i>	1	\$679.20		✓
18	Tail end panel garnish <i>Ang B's</i>	1	\$227.80		✓
19	Tail end panel garnish clip <i>M</i>	8	\$28.00		✓
20	Boot weatherstrip <i>D's / M</i>	1	\$194.20		✓
21	Tail lamp LH	1	\$351.75		?
22	Tail lamp RH	1	\$351.75		?
23	Spare tyre well panel <i>R</i>	1	\$780.90		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLQ 4110 H

TOYOTA ALTIS

MR053REH104559973

Submit By :

Carmen Lim

Year Manufacture :

2016

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Spare tyre board <i>CMA</i>	1	\$369.20		☒
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperl.com.sg

Labour

Vehicle No. : SLQ 4110 H Submit By : Carmen Lim
Make & Model : TOYOTA ALTIS Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, BOOTLID, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER)	\$1,200.00	700
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, BOOTLID, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER)	\$1,400.00	800
3	To check wiring	\$50.00	20
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
5	To tuff coat.	\$150.00	30
6	To transfer boot mechanism to new boot <i>nn</i>	\$120.00	X
7	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
8	To remove & refit reverse sensor	\$120.00	50

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.