



TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Singapore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

3RD PARTY CLAIM ESTIMATION

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01

AXA Tower

Singapore 068811

Vehicle number	SJX8073S
Make / Model	CHEVROLET/CRUZE
Chassis number	KL1JA6961AK610077
Accident date	09 December 2017
Reference	1721-21

Qty Particulars

PARTS REPLACEMENT - LIST ITEMS				
1	FRONT BUMPER <i>Dent</i>	1120.00	1287.60	✓
2	FRONT BUMPER RETAINER <i>H/S broken o/s svc</i>	70.00	140.00	✓
2	FRONT BUMPER BRACKET <i>HN</i>		150.00	X
1	BONNET <i>ray</i>		1624.80	X
2	BONNET HINGE <i>ray</i>		98.40	X
1	BUMPER UPPER GRILLE <i>Crack mounting</i>		222.00	✓
1	BUMPER GRILLE ASSY <i>Crack</i>		329.70	✓
1	BUMPER LOWER GRILLE <i>dent</i>		318.00	✓
2	FRONT HEADLAMP <i>mounting crack</i>	1662.00	1888.80	✓
2	HEADLAMP PANEL <i>ray</i>		844.80	X
2	FRONT HEADLAMP BRACKET <i>HN</i>		150.00	X
2	FRONT FOG LAMP COVER <i>dent</i>		230.00	✓
2	FRONT FOG LAMP <i>H/S mounting broken o/s HN</i>	261.60	600.00	✓
1	SUPPORT PANEL <i>ray</i>		549.60	X
1	FRONT BUMPER REINFORCEMENT <i>Dent</i>	859.00	1032.00	✓
1	FRONT LH WHEEL HOUSE <i>ray</i>		1560.00	X
1	FRONT LH FENDER <i>Bnc</i>		912.00	✓
1	FRONT LH FENDER INNER GARNISH <i>NF</i>		81.60	X
1	FRONT LH FENDER INNER SHIELD <i>tear</i>		121.00	✓
1	FRONT LH FENDER SIGNAL LAMP <i>crack</i>		43.00	✓
1	FRONT LH WING MIRROR <i>HN</i>		460.89	X
1	FRONT LH DOOR PANEL <i>ray</i>		2182.00	X
2	FRONT SHOCK ABSORBER <i>H/S 1st o/s HN</i>	375.00	1124.80	✓
2	FRONT KNUCKLE ARM <i>H/S broken o/s HN</i>	434.60	869.20	✓
2	FRONT KNUCKLE BEARING <i>H/S Dam o/s HN</i>	539.00	1423.20	✓
2	FRONT LOWER ARM <i>H/S Distorted o/s HN</i>	647.00	1410.60	✓
2	FRONT DRIVER SHAFT <i>H/S distorted o/s HN</i>	978.00	1956.00	✓
1	FRONT CROSS MEMBER <i>HN</i>		2664.00	X
1	POWER STEERING RACK <i>broken</i>		1720.80	✓
1	ENGINE UNDER COVER <i>tear</i>		18.00	✓
2	AIR BAG SENSOR <i>activated</i>		312.00	✓
1	AIR BAG CONTROL UNIT <i>activated</i>	1471.00	1600.80	✓
2	FRONT SEAT BELT <i>activated</i>		1432.80	✓
1	DRIVER AIR BAG <i>activated</i>		1417.20	✓
1	PASSENGER AIR BAG <i>activated</i>		1206.00	✓
1	FRONT DASHBOARD <i>Dam</i>		2503.39	✓
1	FRONT WINDSCREEN <i>crack</i>		1015.20	✓
1	FRONT WINDSCREEN MOULDING <i>HN</i>		128.40	✓
1	AIR RESONATOR <i>HN</i>		196.80	X
1	BUMPER LOWER LIP <i>dent</i>		160.00	✓
1	BUMPER SIDE COVER <i>HN</i>		210.00	X

1	FRONT BUMPER SPONGE <i>turn</i>	170.00 ✓
1	SUPPORT PANEL INNER GUIDE <i>turn</i>	140.20 ✓
1	AIRCON DISCHARGE PIPE <i>src</i>	592.40 ✗
1	AIRCON COOLING PIPE <i>src</i>	511.02 ✗
		37609.00
		Less 10%
		3760.90
		Subtotal
		33848.10
		Balance C/F
		33848.10
		<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>
		Balance B/F
		33848.10
1	FRONT NUMBER PLATE <i>bst</i>	70.00 45/-
1 SET	FRONT BUMPER CLIP <i>huc</i>	60.00 30/-
1 SET	FRONT FENDER INNER TRIM CLIP <i>huc</i>	60.00 20/-
1	RIM <i>broken</i>	800.00 600/-
1	TYRE <i>cut 50% dep</i>	250.00 175/-
1	BRAKE FULID <i>src</i>	50.00 ✗
1	WINDSCREEN SEALANT <i>huc</i>	150.00 40/-
1	COOLANT <i>src</i>	60.00 ✗
		Subtotal
		1500.00
		Balance C/F
		35348.10
		<u>LABOUR AND MISCELLANEOUS CHARGES</u>
		Balance B/F
		35348.10
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	REMOVE AND REFIT CONDENSER AND TOP UP GAS	150.00 120/-
3	REMOVE AND REFIT RADITOR AND TOP UP COOLANT	150.00 50/-
4	DIAGNOIS CHECK AND CLEAR FAULT CODE	500.00 250/-
5	CHECK FRONT WHEEL ALIGNMENT	150.00 60/-
6	REMOVE AND RENEW FRONT UNDERCARRIAGE PARTS	200.00 180/-
7	REMOVE AND RENEW AIR BAG ASSY, DOWNLOAD ECU AND CLEAR FAULT C	500.00 200/-
8	REMOVE AND RENEW FRONT DASHBOARD	500.00 180/-
9	REMOVE AND RENEW FRONT WINDSCREEN	150.00 120/-
10	TRANSFER PARTS, ATACHEMENT FROM OLD DOOR TO NEW	200.00 140/-
11	PANEL BEATING ON AFFECTED AREAS	1800.00 1200/-
12	SPRAY PAINTING ON AFFECTED AREAS	2000.00 1200/-
13	APPLY ANTI RUST ON AFFECTED AREAS	150.00 60/-
		Subtotal
		6510.00
		Grand total
		41858.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15/12/2017 e 1100w

Hrt Antenna

41858.10 10 days

rym

LKK Auto

8

23295.20

41858.10