

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1230/2017/JT
Date : 18-Dec-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Chang Wu-Yin
Address : 91 Hillview Avenue
#01-19
Singapor 669625
Telephone : HP +65-9656 2027
Type of Claim : Own Damage Claim
Policy No. : 2100501120
Vehicle No : **SLL 2075 R**
Model Code : Audi A3 Sedan 1.0 TFSI S-tronic
Model / Year : Feb-17
Engine No : CHZ 189341
Chassis No : WAUZZZ8V2H1048782
Mileage : -
Date In : 16-Dec-17
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Dec-17
Place of Accident : Along CTE before exit 7B Jalan Bahagia

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLL 2075 R.

S/n	Nature of Jobs	Estimated Charges		
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor & headlight washer assy.	S/N \$ 360.00	✓	✓
2	To dismantle and ^{repair} renew front bumper assy. Re-organize front crash management components. Reinstall all parts removed.	\$ 900.00 500		✓
3	To respray front bumper.	\$ 800.00 500		✓
TOTAL LABOUR CHARGES		: \$ 2,060.00		

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLL 2075 R.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function and renew according to damages.	S/N	\$ 280.00 ✓	✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N	\$ 280.00 ✓	✓
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 480.00 ✓	✓
4	To dismantle rear bumper and rear lid. Cut out and weld rear outer, inner rear cross panel and connecting plates. Re-align rear lock carrier. Renew rear bumper and rear lid. Re-organize rear crash management components. Reinstall all parts removed.		\$ 3,600.00 1000 2750	✓
5	To respray rear bumper, rear lid and cross panelling. To carry out joint sealer works and stone chip treatments.		\$ 2,200.00 1650	✓
6	To remove and renew rear exhaust silencer. Align to position.	S/N	\$ 480.00 ✓	280
7	To carry out diagnostic checks.	S/N	\$ 192.00 ✓	✓
TOTAL LABOUR CHARGES			\$ 7,512.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 2075 R.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Dented</i>	\$ 1,567.00	✓ 1253.60
2	REAR BUMPER SPOILER <i>Dented</i>	\$ 193.00	✓ 154.40
3	REAR BUMPER GUIDE - LHS/RHS <i>new</i>	\$ 26.00	x
4	REAR BUMPER LOCKING PIN <i>new</i>	2 \$ 49.00	x
5	REAR BUMPER REFLECTOR - LHS/RHS <i>new</i>	\$ 48.00	? x
6	REAR REINFORCEMENT BEAM <i>Bent</i>	\$ 481.00	? 384.40
7	REAR BUMPER BRACKET - LHS/RHS <i>24 Daged.</i>	\$ 45.00	? 18
8	REAR BUMPER INNER GUIDE - LHS/RHS <i>new</i>	\$ 108.00	x
9	REAR PARKING AID SENSOR <i>new</i>	2 \$ 415.00	x
10	REAR LID <i>Dented</i>	\$ 2,225.00	✓ 1780
11	REAR LID ATTACHMENT PARTS <i>new</i>	\$ 247.00	- x
12	REAR WEATHER STRIP <i>new</i>	\$ 167.00	x
13	REAR LOCK STRIKER <i>new</i>	\$ 42.00	+
14	REAR LID LOCK <i>new</i>	\$ 165.00	+
15	REAR LID PACKING ADHESIVE <i>new</i>	\$ 14.00	✓ 11.12
16	AUDI EMBLEM <i>? new</i>	\$ 105.00	✓ 84
17	"A3" EMBLEM	\$ 81.00	✓ 64.72
18	"TFSI" EMBLEM	\$ 81.00	✓ 64.72
19	REAR CROSS PANEL <i>Dented</i>	\$ 307.00	? 245.60
20	CROSS PANEL REINFORCEMENT PIECE <i>Dented</i>	\$ 622.00	? 497.20
SUB-TOTAL SPARE PARTS CHARGES		\$ 6,988.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 2075 R.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
21	CROSS PANEL CONNECTING PLATE - LHS/RHS <i>HEM</i>	\$ 244.00 ?	} X
22	REAR SILENCER <i>HEM</i>	\$ 631.00 ?	
23	REAR SILENCER DUAL CLIP <i>HEM</i>	\$ 52.00 ?	
24	REAR SILENCER RETAINER <i>HEM</i>	2 \$ 71.00 ?	
25	HEAT SHEILD COVER <i>HEM</i>	\$ 144.00 ?	
26	ACRYLIC SEALER <i>HEM</i>	S/N \$ 180.00 ?	180
27	CAVITY WAX <i>HEM</i>	S/N \$ 140.00 ?	140
28	STONE CHIP <i>HEM</i>	S/N \$ 180.00 ?	180
29	REAR NUMBER PLATE <i>HEM</i>	S/N \$ 25.00 x.	
30	SUNDRIES <i>HEM</i>	\$ 500.00 ?	85.28
TOTAL PARTS - REAR		\$ 9,155.00	
TOTAL LABOUR REAR		\$ 7,512.00	
TOTAL PARTS / LABOUR CHARGES - REAR		\$ 16,667.00	
TOTAL PARTS / LABOUR FRONT		\$ 2,060.00	
GRAND TOTAL FOR FRONT AND REAR		\$ 18,727.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 19/12/17
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant