

INS. CASE OWNER:

CC 6/CTI170 24088, A 2a3n2

LKK:
IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(YES / NO)

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SLB 8297

SOV 1899D

GBG 7389Y

SUJ 5391T



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

modern
TP

Date / Time

3/1/18
Am

Pending estimate.

4/1/18 = 10:19

Called OI mention that would like us to drop
Email.

8/1/18

Email WSP Liability Clarification.

10-05-18

BOLA IS APPLICABLE. LIABLE TO THE 1ST VEHICLE.

24.8.18

File pass to typist to prepare report.

RECEIVED 21 NOV 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: EMAIL 8/1/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 24.8.18

Sent By: ASH

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Lwp

Repair Cost:

43 \$53,200

(5 days) Reduction:

61 %

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time: 07-11-18

Confirm with CHIN

Email ☒Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 0%

Repair Cost:

w/651

\$53,224.00

4 VEH C.I. OTD 2ND

Loss of Rental (LOR):

\$5 100.00

(7 days) x 100

Loss of Use (LOU):

\$5 -

(\$ x days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$5 0.00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$400

Total:

\$5 4,126.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 07-11-18

Confirm with: CHIN

Email ☒Call ☐

Payee 1:

\$5 4,126.00

Name 1:

MODERN AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

REF:

Wood (Area 3)

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLJ 5391T Yr Regn: 2016 / DecType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Sienta cc 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 14838 T.Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NSP1727001047.Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15R: 185/60R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 19/12/17Survey held at ModernDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Ching.

4/5: +3.200 (RED: +4.904.08 61/-)

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S - RS (\$ _____)

Photos: _____

Others: _____

Report Format: _____

Lump Sum / I.B.I. (\$) _____

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI17024088/Aea3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 19-12-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 7389Y	Veh. Inspected	SLJ 5391T
Policy No.	DMCVSN1762641700	Coverage (\$)	0.00
Claim No.	SNM17D07150C02/9	Excess (\$)	0.00
Assign From		Assign Date	19/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/12/2017	Inspection Date	19/12/2017
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Mei Kwan (LKKAUTO)

From: Joel Goh <joel.goh@sg.cntaiping.com>
Sent: Wednesday, 27 December, 2017 5:59 PM
To: Mei Kwan (LKKAUTO)
Cc: Asher Sng (LKKAUTO); Vic (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving GBG7389Y (OI : CAI - SNM17D07150C02/9) AND SJ5391T (TP : LKK REF - CC6/CTI17024088/ea3) on 16/12/2017
Attachments: MANC17166013-GBG7389Y.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Mei Kwan

Attached our insured's accident report for your attention.

Best Regards

Joel Goh
Claims Executive (Motor Division)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-02
Springleaf Tower Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6184
Fax: 6224 7175 / 6224 7478
Email: claimsdept@sg.cntaiping.com
joel.goh@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer : This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 27 December, 2017 10:22 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Joel Goh <joel.goh@sg.cntaiping.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GBG7389Y (OI : CAI - TBA) AND SJ5391T (TP : LKK REF - CC6/CTI17024088/ea3) on 16/12/2017

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

"Wishes you a Happy New Year 2018"

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6111
 Fax : 6224 - 7478 / 7175

Agree

Quotation
 DATE : 19.12.2017
 VEH NO : SLJ5391T
 MODEL : Toyota Sienta Welcab
 D O A : 16.12.2017
 YR REF : GBG7389Y

Attn: Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLJ5391T (Toyota Sienta Welcab)

Item	Description	Qty	Amt
NO.	LIST ITEMS		
1	Rear Bumper <i>del</i>	1	445.20 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Side Bumper - LH & RH <i>Repair</i>	2	420.40 ✓
4	Rear Side Bumper Garnish - LH & RH <i>new</i>	2	170.20 x
5	Rear Side Bumper Reflector - LH & RH <i>new</i>	2	134.60 x
6	Tailgate <i>del</i>	1	1,086.80 ✓
7	Tailgate Lock <i>del</i>	1	372.90 ✓
8	Tailgate Weatherstripe <i>del</i>	1	374.60 ✓
9	Tailgate Outer Garnish <i>del</i>	1	289.40 ✓
10	Tailgate Reflector - LH & RH <i>new</i>	2	770.00 x
11	Tailgate Inner Trim Board <i>new</i>	1	398.50 x
12	Tailgate Inner Trim Board Clips <i>new</i>	1 set	30.00 ✓
13	Tailgate Glass Moulding <i>new</i>	1	115.00 ✓
14	Tailgate Wiper Motor <i>Not new</i>	1	425.00 x
15	Tailgate Wiper Blade <i>new</i>	1	185.80 x
16	Toyota Logo <i>new</i>	1	75.30 ✓
17	Rear End Panel <i>Repair</i>	1	498.20 x
18	Wheelchair Platform Side Garnish - LH & RH <i>del</i>	2	490.20 ✓
			\$ 6,312.10
Less 25%			(1,578.03)
			\$ 4,734.08
S/NETT ITEMS			
1	Tailgate Glass Sealant <i>new</i>	1	60.00 ✓
2	Rear Camera <i>Not new</i>	1	480.00 x
			\$ 540.00

60

3309.40

2482.05

RE : ESTIMATE FOR ACCIDENT REPAIR SLJ5391T (Toyota Sienta Weicab)

Total parts \$ 5,274.08

LABOUR CHARGE

- | | | | |
|---|--|----|-------------------------|
| 1 | To knocking out rear portion & renew above parts | \$ | 1,200.00 600 |
| 2 | To putty & spray up paint works | \$ | 1,000.00 600 |
| 3 | To check wiring system | \$ | 50.00 30 |
| 4 | To underseal | \$ | 150.00 X |
| 5 | To remove rear camera | \$ | 100.00 50 |
| 6 | To transfer tailgate fittings | \$ | 150.00 80 |
| 7 | To remove tailgate glass | \$ | 180.00 120 |

Total Labour \$ 2,830.00

Grand Total **\$ 8,104.08**

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 4022.05
r/s: 3.2k
05 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI17024088/Aea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 27-11-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 7389Y	Veh. Inspected	SLJ 5391T
Policy No.	DMCVSN1762641700	Coverage (\$)	0.00
Claim No.	SNM17D07150C02/9	Excess (\$)	0.00
Assign From		Assign Date	19/12/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NSP1727001047	Colour	BLUE
Odometer	14838	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
L/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/12/2017	Inspection Date	19/12/2017
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 5391T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	445.20	445.20
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR SIDE BUMPER-LH & RH	TO REPAIR SEE LABOUR	420.40	-
2	REAR SIDE BUMPER GARNISH-LH & RH	NOT NECESSARY	170.20	-
2	REAR SIDE BUMPER REFLECTOR-LH & RH	NOT NECESSARY	134.60	-
1	TAILGATE	DENTED	1,086.80	1,086.80
1	TAILGATE LOCK	DAMAGED	372.90	372.90
1	TAILGATE WEATHERSTRIPE	CUT	374.60	374.60
1	TAILGATE OUTER GARNISH	DEFORMED	289.40	289.40
2	TAILGATE REFLECTOR-LH & RH	NOT NECESSARY	770.00	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	398.50	-
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	30.00	30.00
1	TAILGATE GLASS MOULDING	NECESSARY	115.00	115.00
1	TAILGATE WIPER MOTOR	NOT NECESSARY	425.00	-
1	TAILGATE WIPER BLADE	NOT NECESSARY	185.80	-
1	TOYOTA LOGO	NECESSARY	75.30	75.30
1	REAR END PANEL	TO REPAIR SEE LABOUR	498.20	-
2	WHEELCHAIR PLATFORM SIDE GARNISH-LH & RH	DEFORMED	490.20	490.20
	LESS 25% DISCOUNT		-1,578.02	-827.35
			4,734.08	2,482.05
SPECIAL NETT ITEMS				
1	TAILGATE GLASS SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR CAMERA (SN)	NOT NECESSARY	480.00	-
			540.00	60.00
LABOUR				
	TO KNOCKING OUT REAR PORTION & RENEW ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR SIDE BUMPER-LH & RH AND REAR END PANEL.		1,200.00	600.00
	TO PUTTY & SPRAY UP PAINT WORKS.		1,000.00	600.00

Report Ref No. CC6/CTI17024088/Aea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING SYSTEM.	NOT NECESSARY	50.00	30.00
	TO UNDERSEAL.		150.00	-
	TO REMOVE REAR CAMERA.		100.00	50.00
	TO TRANSFER TAILGATE FITTINGS.		150.00	80.00
	TO TRANSFER TAILGATE GLASS.		180.00	120.00
			2,830.00	1,480.00
	GRAND TOTAL		8,104.08	4,022.05
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00

Report Ref No. CC6/CT117024088/Aea3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.