

ASS. REC. BY:

REF:

TP / CS / TP17024091 / Kdpnz

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SIB 79523 Yr Regn: 01, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Chevrolet Epica c.c. 1991

Colour: white 1P1 A/C: Insured / Std / NI / NA

Sp. Reading: 95781P T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KL11A69TBB - 123408

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: N11 / S/Rim / STD A/Rim or

Tyre Size: King Long 195/65R15

R: Westlake

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

Rear

R/Bal. 7 mm

L/Bal. 9 mm

L/Bal. 7 mm

D.O.A. 15/12/17

D.O.I. 19/12/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/12 file pass to Corrine

11/01/18 By 812502 (Red to 18060-58, 94%)
no survey report.

SIB 79523 - 006 1AXA17007829 / mihg392

* need send invoice first before pass the report to trans-ab.

OUT: 10042017

RECEIVED 03 JAN 2018

Date/Time, File Pass to?

11/01/18 : Prelim. Report

11/01/18 : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

9x15=135

170+135

50

11

80

446

Report Format:

Lump Sum / I.B.I. (\$

TP
1250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TRANS-CAB AUTO SERVICES PTE LTD

Ref : CS/TP17024091/Kqb

NO.2 ANG MO KIO STREET 63 SINGAPORE 569111

Date : 20-12-2017



Code : TP378

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SHB 7952B
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	19/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/12/2017	Inspection Date	20/12/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Survey Department Check List (Case Handler)

Reference No.: CS/TP/70 24091/K9/b
Policy Type: OD / TP / TP RES / TL / EVA

SMB 7957B

Case Handler

Typist

Admin (Cath): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Kenneth): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Cath 29/12/17

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHB7952B
Vehicle to be Exported:	No
Intended De-registration Date:	29 Dec 2017
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1462180K
Chassis No.:	KL1LA69RJBB123408
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,971.00
Original Registration Date:	29 Jan 2013
First Registration Date:	29 Jan 2013
Transfer Count:	0
Actual ARF Paid:	\$13,971.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2021
PARF Rebate Amount:	\$10,478.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$60,655.00
COE Rebate Amount:	\$23,357.00
Total Rebate Amount:	\$33,835.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHB7952B
Vehicle to be Exported:	Yes
Intended De-registration Date:	18 Dec 2017
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1462180K
Chassis No.:	KL1LA69RJBB123408
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,971.00
Original Registration Date:	29 Jan 2013
First Registration Date:	29 Jan 2013
Transfer Count:	0
Actual ARF Paid:	\$13,971.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2021
PARF Rebate Amount:	\$10,478.00
Intended COE Rebate Details	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	18/12/2017 13:10
Date Of Accident	15/12/2017 17:50
Exact Location Of Accident	HILLVIEW ROAD ROUND ABOUT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHB7952B
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666
Vehicle Particulars	
Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	YAK YAM SENG
NRIC No	S7024822J
Date Of Birth	23/06/1970
Occupation	OUTDOOR
Date Of Driving Pass	26/06/1993
Driving Experience	24 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98370302
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 119 TECK WHYE LANE #09-792
Postcode	680119
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JFD5616 (PRIVATE CAR)
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CHOA CHU KANG NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 116 TECK WHYE LANE , POSTCODE: 680116 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7629999 - FAX NO: 67636615
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20171215/2147

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JFD5616
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	WONG YONG LONE
NRIC/Passport Number	G8000477Q
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attached police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20171215/2147

Police Station Of Origin:

Choa Chu Kang NPP

1 16 Teck Whye Lane #01-740 SINGAPORE

680116

Tel No: 1800-7629999

1 of 3

Report No: T/20171215/2147

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/12/2017 20:47	Vide Report No.:	Station Diary No.: 55
--	------------------	--------------------------

Informant's Particulars

Name of Informant: YAK YAM SENG			Address: APT BLK 119 TECK WHYE LANE #09-792 SINGAPORE 680119		
ID Type / ID No.: NRIC NO / S7024822J			Contact No.: Home/Office: Mobile: 98370302		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 47	Date of Birth: 23/06/1970	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 15/12/2017 17:50	Type of Location: Roundabout
Location: Along Road 1 HILLVIEW AVENUE <i>540 Kio North, 57 Ang Mo Kio Ave 3, Singapore 569734 Tel: 4540900</i> <i>the Road</i> HILLVIEW AVENUE ROUND ABOUT				
Weather: Raining	Road Surface: Wet		Road Speed Limit:	
Traffic Flow: Dual Carriage Way	Traffic Control: Not Controlled		Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
JFD5616					Slightly Damaged	0
SHB7952B	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA		



**SINGAPORE
POLICE FORCE**



T/20171215/2147

2 of 3

Report No. T/20171215/2147

Police Station Of Origin:
Chua Chu Kang NPP
116 Teck Whye Lane #01-740 SINGAPORE
580116
Tel No: 1800-7629999

CONTINUATION OF REPORT

Driver			
Name	WONG YONG LONE	ID No.	G8000477Q
Related Vehicle	JFD5616	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	YAK YAM SENG	ID No.	S7024822J
Related Vehicle	SHB7952B (Car)	Contact No.	98370302
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 15/12/2017 at about 1750hrs, I was driving my vehicle, V1: SHB7952B along Hillview Ave heading into the roundabout from Upper Bukit Timah Road. As I entered the slip road into the round about, I stopped at the giveway line as there were oncoming vehicles. Suddenly, I felt an impact from the rear of my vehicle. I went out and saw a Malaysian registered vehicle, JFD5616 had collided onto my rear. Traffic police came to scene. We exchanged particulars.



**SINGAPORE
POLICE FORCE**



T/20171215/2147

Police Station Of Origin:

Choa Chu Kang NPP

1 16 Teck Whye Lane #01-740 SINGAPORE

S 80116

Tel No: 1800-7629999

3 of 3

Report No. T/20171215/2147

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 MUHAMMAD AIMAN BIN OTHMAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

15/12/2017 20:47

Officer In Charge Of Case:

TP / AEIT /

SI ANG YI TING, STEPHANIE

Contact No.: 65476414

Classification Of Case:

Authentication Stamp

NP168

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7952B -**AAD1712-167***Not Authenticated
1/12/2017*

Vehicle No.:

SHB7952B - CANDY

Chassis No.:

KL1LA69RJB123408

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

15.12.2017

Third Party Insurer :

PART**LIST**

1	1	Rear Bumper	\$	<i>Bu</i>	1,202.00	—
2	1	Rear Bumper Beam	\$	<i>R</i>	239.94	} X
3	1	Rear Bumper Centre Absorber	\$	<i>Sn</i>	260.00	
4	1	Rear Bumper Side Retainer RH	\$	<i>Sn</i>	68.76	
5	1	Rear Bumper Side Retainer LH	\$	<i>Sn</i>	68.76	
6	1	Rear Bumper Reflectors RH	\$	<i>Sn</i>	119.74	
7	1	Rear Bumper Reflectors LH	\$	<i>Sn</i>	119.74	
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i>	93.00	
9	1	Rear End Panel Outer	\$	<i>R</i>	623.76	
10	1	Rear End Panel Inner Trim	\$	<i>Sn</i>	263.84	
11	1	Bootlid	\$	<i>R</i>	973.00	
12	1	Bootlid Inner trim board	\$	<i>Sn</i>	400.00	
13	1	Bootlid Weatherstrip	\$	<i>Sn</i>	344.28	
14	1	Bootlid Lock - Top	\$	<i>R</i>	466.56	
15	1	Bootlid 'CHEVROLET' Badge	\$	<i>Sn</i>	120.62	
16	1	Bootlid Logo	\$	<i>Sn</i>	138.84	
17	1	Bootlid 'EPICA LT' Badge	\$	<i>Sn</i>	119.84	
18	1	Bootlid Reflector Centre	\$	<i>Sn</i>	217.97	
19	1	Bootlid Reflector RH	\$	<i>Sn</i>	128.40	
20	1	Bootlid Reflector LH	\$	<i>Sn</i>	128.40	
21	1	Rear Tail Lamp RH	\$	<i>Sn</i>	479.30	
22	1	Rear Tail Lamp Panel RH	\$	<i>R</i>	359.00	
23	1	Rear Tail Lamp LH	\$	<i>Sn</i>	479.30	
24	1	Rear Tail Lamp Panel LH	\$	<i>R</i>	359.00	
25	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i>	1,110.00	
26	1	Rear Fender RH	\$	<i>R</i>	1,145.00	
27	1	Rear Fender Inner Trim RH	\$	<i>Sn</i>	418.44	
28	1	Rear Fender LH	\$	<i>R</i>	1,145.00	
29	1	Rear Fender Inner Trim LH	\$	<i>Sn</i>	418.44	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-167

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7952B -

TOTAL	\$	12,010.93
10%	\$	1,201.09
	\$	10,809.84

Specical Nett

1	1Set	Licence Plate With Holder	\$	60.00	}	X
2	1Set	Bootlid inner trim board Clip	\$	40.00		
3	1Set	Rear Bumper Parking Sensor	\$	300.00		
4	1Set	Rear Bumper Fastener Clip	\$	44.00		
5	1Set	Rear Fender Inner Trim Clip LH	\$	30.00		
6	1Set	Rear Fender Inner Trim Clip RH	\$	30.00		
7	1Set	Rear Bumper End Dust Cover Clip	\$	30.00		
8	1	Rear Boot Sticker 'Trans-cab'	\$	30.00		
9	1	Rear Boot Sticker '6555-3333'	\$	30.00		
10	1	Rear Exhaust Mounting	\$	10.00		
11	2	Rear Windscreen Sealant	\$	80.00		
12	1	Rear Windscreen Inner Sponge Seal	\$	100.00		
13	1	Spare Tyre	\$	180.00		
14	1	Spare Wheel Rim	\$	126.74		

TOTAL	\$	1,090.74
TOTAL PARTS	\$	11,900.58

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,700.00 200

To Check Electrical Lighting Concerned.

\$ 170.00 100

To Rust-Proofing Of The Affected Areas.

\$ 170.00 X

Putty And Spray Painting Of The Affected
Portion.

\$ 2,800.00 200

To reinstall rear bumper parking sensor.

\$ 170.00 600

To transfer of end panel fittings and conduct
water seepage test.

\$ 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-167

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7952B -

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00	X
To transfer of boot fittings and conduct water seepage test.	\$	<i>nn</i> 170.00	X
Towing fees	\$	<i>nn</i> 120.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X

	\$	7,410.00
TOTAL	\$	19,310.58

Repair Days

~~10 Days~~*2 day,*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier's items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TRANS-CAB AUTO SERVICES PTE LTD

Ref : CS/TP17024091/Kqbn2

NO.2 ANG MO KIO STREET 63 SINGAPORE 569111

Date : 10-01-2018



Code : TP378

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SHB 7952B
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	19/12/2017

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KL1LA69RJBB123408	Colour	WHITE / RED
Odometer	957819	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	LING LONG	9 mm
L/H Front Tyre	195/65 R15	LING LONG	9 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	7 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/12/2017	Inspection Date	19/12/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 7952B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED	1,202.00	1,202.00
1	REAR BUMPER BEAM	TO REPAIR SEE LABOUR	239.94	-
1	REAR BUMPER CENTRE ABSORBER	SERVICEABLE	260.00	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	68.76	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	68.76	-
1	REAR BUMPER REFLECTORS RH	SERVICEABLE	119.74	-
1	REAR BUMPER REFLECTORS LH	SERVICEABLE	119.74	-
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	93.00	-
1	REAR END PANEL OUTER	TO REPAIR SEE LABOUR	623.76	-
1	REAR END PANEL INNER TRIM	SERVICEABLE	263.84	-
1	BOOTLID	TO REPAIR SEE LABOUR	973.00	-
1	BOOTLID INNER TRIM BOARD	SERVICEABLE	400.00	-
1	BOOTLID WEATHERSTRIP	SERVICEABLE	344.28	-
1	BOOTLID LOCK-TOP	TO REPAIR SEE LABOUR	466.56	-
1	BOOTLID "CHEVROLET" BADGE	NOT NECESSARY	120.62	-
1	BOOTLID LOGO	NOT NECESSARY	138.84	-
1	BOOTLID "EPICA LT" BADGE	NOT NECESSARY	119.84	-
1	BOOTLID REFLECTOR CENTRE	SERVICEABLE	217.97	-
1	BOOTLID REFLECTOR RH	SERVICEABLE	128.40	-
1	BOOTLID REFLECTOR LH	SERVICEABLE	128.40	-
1	REAR TAIL LAMP RH	SERVICEABLE	479.30	-
1	REAR TAIL LAMP PANEL RH	TO REPAIR SEE LABOUR	359.00	-
1	REAR TAIL LAMP LH	SERVICEABLE	479.30	-
1	REAR TAIL LAMP PANEL LH	TO REPAIR SEE LABOUR	359.00	-
1	REAR EXHAUST BOX (MUFFLER A-EXH,RR)	TO REPAIR SEE LABOUR	1,110.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,145.00	-
1	REAR FENDER INNER TRIM RH	SERVICEABLE	418.44	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,145.00	-

Report Ref No. CS/TP17024091/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER TRIM LH	SERVICEABLE	418.44	-
	LESS 10% DISCOUNT		-1,201.09	-120.20
			10,809.84	1,081.80
	<u>SPECIAL NETT ITEMS</u>			
1	SET LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	60.00	-
1	SET BOOTLID INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	40.00	-
1	SET REAR BUMPER PARKING SENSOR (SN)	SERVICEABLE	300.00	-
1	SET REAR BUMPER FASTENER CLIP (SN)	NOT NECESSARY	44.00	-
1	SET REAR FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER END DUST COVER CLIP (SN)	NOT NECESSARY	30.00	-
1	REAR BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	REAR BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	REAR EXHAUST MOUNTING (SN)	SERVICEABLE	10.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE (SN)	SERVICEABLE	180.00	-
1	SPARE WHEEL RIM (SN)	SERVICEABLE	126.74	-
			1,090.74	-
	<u>LABOUR</u>			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR BUMPER BEAM,REAR END PANEL OUTER,BOOTLID,BOOTLID LOCK-TOP,REAR TAIL LAMP PANEL RH,REAR TAIL LAMP PANEL LH,REAR EXHAUST BOX (MUFFLER A-EXH,RR),REAR FENDER RH AND REAR FENDER LH.		2,700.00	200.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,800.00	200.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOT FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-

Report Ref No. CS/TP17024091/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			7,410.00	470.00
	GRAND TOTAL		19,310.58	1,551.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,250.00

Report Ref No. CS/TP17024091/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.