



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/LCR17024106/K1ja3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 20-12-2017	
		Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLB 4386H	Veh. Inspected	SHA 3203L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	18/12/2017	Inspection Date	19/12/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305099345

Date : 25/12/17

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr KALVIN ANG

Vehicle Reg No. : SHA3203L CTPL

18.12.17

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **AIG** --- **SLB4386H**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount **\$1,952.16**
 - (b) Labour Charges **\$680.00**
 - Total for Part-By-Part Repair Cost** **\$2,632.16**
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : KALVIN

Date : 26/12/17

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305099345
REGN NO : SHA3203L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 05.01.2017
DATE/TIME IN : 19.12.2017 09:40
ACCIDENT DATE : 18.12.2017

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2292-G I40V3 COVER-FR BUMPER# 1 L 1,052.20 20.00 841.76
0002 04-01-0103-0782-A I40V2 LAMP ASSY-HEAD RH# 1 L 1,388.00 20.00 1,110.40

SUB-TOTAL : 1,952.16

JOB NATURE

0000 20-05 RENEW ADVERTISEMENT STICKER- 100.00
0001 L PANEL BEATING 200.00
0002 23-502 SPRAYPAINT ON AFFECTED AREA 360.00
0003 17-01 CHECK ALL LIGHTING 20.00

SUB-TOTAL : 680.00

TOTAL : 2,632.16

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 3203L

DATE 19/12/2017 14:20

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>photo</i>			\$ 1,052.20
	Front Bumper Bracket (RH) <i>Xm</i>			\$ 24.60
	Headlamp (RH) <i>6-974</i>			\$ 1,388.00
	Frt Wheel Hub Cap (RH) <i>X sm</i>			\$ 150.70
	<i>Front Fender (RH) X key air</i>			
	SUB TOTAL			\$ 2,615.50
	LESS 20%			\$ 523.10
	DISCOUNTED TOTAL			\$ 2,092.40
	Front Fender Advertisement Logo (RH) <i>huc</i>			\$ 100.00 Nett
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 400.00 ²⁰⁰
	Spray Painting Charge			\$ 400.00 ³⁶⁰
	Wiring Charge			\$ 50.00 ²⁰
	Frt Wheel Alignment			\$ 80.00 ^{Xm}
	TOTAL LABOUR			\$ 930.00
	ESTIMATE TOTAL			\$ 3,122.40
<i>Kalvin LUCKY</i> <i>19/12/17 1515hrs</i> <i>2 Days</i> <i>P/P</i> <i>Before Paint photo</i>				
LKK Auto Consultants hereby notify the Repairer of the following: • To resurvey and to inform the insurance company • To display damaged parts for resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification is allowed • Supplementary items must be resurveyed and is subject to final approval from the insurance company Acknowledged by repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey and to inform the insurance company
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from the insurance company

Acknowledged by repairer
Signature:
Date:

Member of COMFORTDELGRO

Date/Time: 19.12.2017 15:06

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO:305099345

TOMER

COMFORT TRANSPORTATION PTE LTD

AS: 7010045

TOMER NO: 383 SIN MING DRIVE

RESS: Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

OUNT CARD NO.

REGN NO: SHA3203L

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL: I-40

19.12.2017 09:40

YR OF MANU: 05.01.2017

TARGET DATE

CHASSIS CODE: RMHLB41UMHU097768

COMPLETION DATE/TIME:

JOB DESCRIPTION

ccident Date: 18.12.2017

ATURE: 3P 18.12.2017

/NO

LABOR CODE

DESCRIPTION

CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wledge ment Slip

Exit Pass

No.: SHA3203L

LKE/KALVIN

Vehicle No.:

SHA3203L

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 3203L

DATE 19/12/2017 14:20

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 1,052.20
	Front Bumper Bracket (RH) ?			\$ 24.60
	Headlamp (RH) ✓			\$ 1,388.00
	Frt Wheel Hub Cap (RH) ✕			\$ 150.70
	Front Fender (RH) ✕ by air			
	SUB TOTAL			\$ 2,615.50
	LESS 20%			\$ 523.10
	DISCOUNTED TOTAL			\$ 2,092.40
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 400.00 ²⁰⁰
	Spray Painting Charge			\$ 400.00 ³⁶⁰
	Wiring Charge			\$ 50.00 ²⁰
	Frt Wheel Alignment			\$ 80.00 ✕
	TOTAL LABOUR			\$ 930.00
	ESTIMATE TOTAL			\$ 3,122.40

Kalvin LUCKY
 19/12/17 1515hrs
 2 Days
 P/P
 Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Express

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Dec 2017 Edit Reg		19 Dec 2017 00:00 Edit Adj Rpt	\$2,632.16 Edit Estimates	\$2,632.16 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured:	LCRF PTE LTD , Co. Reg. No.: 201624597K								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHA3203L	Date of Loss:	18/12/2017 16:00 - :59						
Claim Type:	TP / 0327281743SG	Policy/Cover Note No.:	0999995067						
Vehicle Reg. No. (Insured):	SLB4386H	Policy No. (Claimant):	MCOM0016						
		Excess:							
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angie-GL] Angiegeokling.Gan@aig.com								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 02/01/2018]								
Driver/Custodian (Insured):	NG KIM WAH (), NRIC: S7606558F								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS 		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHA3203L (0327281743SG)**
[SLB4386H]

TP

COMFORT TRANSPORTATION PTE LTD

Dec 18 2017 4:00PM

[LCRF PTE LTD]

ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	
Assessment Reports			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/12/17 12:49	Accident Statement From: SC - Reg. No: SLB4386H, Claimant: LCRF PTE LTD	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/12/17 16:49	General View	 Load JPG	☒
2	20/12/17 16:49	General View	 Load JPG	☒
3	20/12/17 16:49	General View	 Load JPG	☒
4	20/12/17 16:49	General View	 Load JPG	☒
5	20/12/17 16:49	General View	 Load JPG	☒
6	20/12/17 16:49	General View	 Load JPG	☒
7	20/12/17 16:49	General View	 Load JPG	☒
8	20/12/17 16:49	General View	 Load JPG	☒
9	20/12/17 16:49	General View	 Load JPG	☒
10	20/12/17 16:49	General View	 Load JPG	☒
11	20/12/17 16:49	General View	 Load JPG	☒
12	20/12/17 16:49	General View	 Load JPG	☒
13	20/12/17 16:49	General View	 Load JPG	☒
14	20/12/17 16:49	General View	 Load JPG	☒
15	20/12/17 16:49	General View	 Load JPG	☒
16	20/12/17 16:49	General View	 Load JPG	☒
17	20/12/17 16:49	General View	 Load JPG	☒
18	20/12/17 16:49	General View	 Load JPG	☒
19	20/12/17 16:49	General View	 Load JPG	☒
20	20/12/17 16:49	General View	 Load JPG	☒
21	20/12/17 16:49	General View	 Load JPG	☒
22	21/12/17 17:03	Reinspection Photo	 Load JPG	☒
23	21/12/17 17:03	Reinspection Photo	 Load JPG	☒
24	21/12/17 17:03	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/12/17 15:25	TP ESTIMATE - MARKED	 Load PDF	
2	20/12/17 15:25	TP GIA REPORT	 Load PDF	

3	22/12/17 10:07	LETTER TO INSURED		Load PDF	
4	19/01/18 15:38	AUTHORISATION TO ACT		Load PDF	
5	19/01/18 15:38	LTA SEARCH		Load PDF	
6	19/01/18 15:38	RELEASE VOUCHER		Load PDF	
7	19/01/18 15:38	RENTAL RECEIPT		Load PDF	
8	19/01/18 15:38	WORKSHOP INVOICE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLB4386H (Insd veh)	Model:	HYUNDAI I40 1.7 L CRDI AT
	SHA3203L (TP veh)		ABS AIRBAG 4DR (A)
Date of Accident:	18/12/2017		

Global Sum Settlement	: [X] Yes	[] No
Repair Estimate	: \$	3,340.97
Final Repair Cost	: \$	3,250.00
Loss of Use	: \$	2.50 days at \$50.00 per day
Rental (if any)	: \$	2.5 days
LTA / GIA Search Fee	: \$	
Others:	: \$	
	: \$	
Final Settlement Sum (GLOBAL SUM)	: \$	3,250.00
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)		
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability _____ (%)		
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks _____		

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	: \$	3,250.00
2)		: \$	
3)		: \$	
4)		: \$	
5)		: \$	

NUR SHAQILAH BTE ABDOL
WAHAB

LKK Auto Consultants Pte Ltd

19 Jan
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR17024106/K1JA3S2

Date: 19/01/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995067
 Claimant Vehicle No: SHA3203L Insured Vehicle No: SLB4386H
 Date of Loss: 18/12/2017 Nature of Claim: TP Claim No: 0327281743SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA3203L
 Make & Model: HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A) Engine No: D4FDGU700722
 Reg. Date: 05/01/2017 (Man. Year: 2016) Chassis No: KMHLB41UMHU097768
 Colour: Blue Odometer: 167388 km
 Engine Capacity: 1685 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
 Front Left Side: Optimo 7 mm Rear Left Side: Optimo 7 mm
 Front Right Side: Optimo 7 mm Rear Right Side: Optimo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,192.40	2,052.16	140.24	6.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	930.00	580.00	350.00	37.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,122.40	2,632.16	490.24	15.70
+ GST 7.00/7.00% (S\$)	218.57	184.25	34.32	15.70
Nett Amount (S\$)	3,340.97	2,816.41	524.56	15.70
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$125.00/day) (S\$)		312.50		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		3,259.26		
Global Sum Settlement (S\$)		3,250.00		

INSPECTION

Date of Assignment: 19/12/2017
 Date Inspected: 19/12/2017 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	1,052.20 FL	*1,052.20 FL
2	1		*FRONT BUMPER BRACKET (RH)	Serviceable	24.60 FL	*- FL
3	1		*HEADLAMP (RH)	Grazed	1,388.00 FL	*1,388.00 FL
4	1		*FRT WHEEL HUB CAP (RH)	Serviceable	150.70 FL	*- FL
5	1		*FRONT FENDER (RH) (NPA)	Repair	0.00 FL	*- FL
6	1		*FRONT FENDER ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,715.50	2,540.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	523.10	488.04
Total Parts (\$\$)	2,192.40	2,052.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	400.00	200.00
2	SPRAY PAINTING CHARGE.	New	400.00	360.00
3	WIRING CHARGE.	New	50.00	20.00
4	FRT WHEEL ALIGNMENT.	New	80.00	0.00
Gross Labour Cost (S\$)			930.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >