

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 3203L

DATE 19/12/2017 14:20

MAKE :

MODEL : HYUNDAI i40

LKK/kalvin

PbyT

Like

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 1,052.20
	Front Bumper Bracket (RH) ?			\$ 24.60
	Headlamp (RH) ✓			\$ 1,388.00
	Frt Wheel Hub Cap (RH) X			\$ 150.70
	Front Fender (RH) X Key air			
	SUB TOTAL			\$ 2,615.50
	LESS 20%			\$ 523.10
	DISCOUNTED TOTAL			\$ 2,092.40
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 400.00 200
	Spray Painting Charge			\$ 400.00 360
	Wiring Charge			\$ 50.00 20
	Frt Wheel Alignment			\$ 80.00 X
	TOTAL LABOUR			\$ 930.00
	ESTIMATE TOTAL			\$ 3,122.40
<p>Kalvin LKK</p> <p>19/12/17 1515hrs</p> <p>2 Days</p> <p>P/P</p> <p>Before Paint photo</p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				