

RVS Allied Global Pte Ltd

Office: 50 Tagore Lane 05-06 TG (S787494)
Workshop : 8 Woodlands Industrial Park E3 (S757786)

Reg :201703521G
Tel :9668 9668

Sebastian. 26/12/2017.
- Lump Sum Repair.
- Photo After Paint.
90036121
sebastian.yeap@lkkauto.com
8 days.

Our Ref: TP/CB77H/0027

18/12/17

Aik Shen Bus Service

QUOTATION

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Dear Sir,

DOA :14/12/2017

Cost of Repair to Vehicle CB77H

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)	
1.	Front Windscreen ✓ C&K .	1	5,300.00	5,300.00	4000
2.	Front Bumper ✓ C&K .	1	1,800.00	1,800.00	1600
3.	Front Panel ✓ DT	1	2,400.00	2,400.00	2000
4.	Side View Mirror (LH) ✓ D&G .	1	560.00	560.00	✓
5.	Head Lamp (LH) ✓ C&K .	1	380.00	380.00	✓
6.	Sealant ✓ K&C .	6	25.00	150.00	✓
7.	Spray Painting on Rear Affected Area with Artwork	1	1,200.00	1,200.00	800 .
8.	Labour & Misc. Charges: To remove the affected parts & all relevant attachment & fittings to commence repairs; cut & weld the necessary parts as listed above; panel beat & reshapes the affected areas; replace the damaged components, reinstall & realign all necessary parts	1	2,200.00	2,200.00	1800 2) 2600
			SUB-TOTAL	S\$13,990.00	

Thanks you.
Yours faithfully,
STEVEN

Steven Tan
Claims Executive

Additional : Rain Cutter \$200 ✓ Defcon .
LH Side Wiper Arm \$180 ✓ D&G .
1) Parts: \$ 8073
2) Labour: \$ 2600
\$ 10673
Lump Sum -20%
8538.40
Total: \$ 8550 @ 8 days.
8970
-10%
1) 8073