

ASS. REC. BY:

REF: CS/TP17024114/R1rbj2

Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Patrick Saverimuthu of Insight adjusters Date/Time: 20-12-2017 10.02am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKN 3607B Insured: Public Liability

at Workshop m/s Volkswagen Tel:

of 247 Alexandra Road

Policy No: Claim No: [1A2017-36694]

Sum Insured: Excess:

Make of Veh: D.O.A.
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp: 65 Chulia St - Mr. Choo (96923331)

H.O.D. Endorsement:

Date/Time: Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKN 3607B - X
	Public Liability - X
	* Vehicle Not sent in for repair
	Submit preli report

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKN 3607Bat Workshop m/s Insight adjustmentsof 65, CHALIA ST

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Call me chro

(Policy Condition)

96923331Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKN 3607B

Yr Regn: _____

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLKSWAGEN

C.C. _____

Colour: GREY

A/C: Insured / Std / NI / NA

Sp. Reading: 43965

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW2221KZ0K012728Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R17R: ~BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A.

D.O.I.

20/12/17Survey held at Insight Adjuster

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s for

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 18 JAN 2018

Date/Time, File Pass to?



: Preli. Report

1) typist

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + PS \$

Photos

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format:

TP - Independent.

Lump Sum / I.B.I. (\$

-
 $24 \times 15 = 360$
 $360 + 170 = 530$
530502180681



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD

Ref : CS/TP17024114/R1rb

C/O: INSIGHT ADJUSTERS & SURVEYORS PL
133 CECIL STREET
#14-02 KECK SENG TOWER
SINGAPORE 069535

Date : 20-12-2017



Code : TMI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKN 3607B
Policy No.		Coverage (\$)	0.00
Claim No.	[IA2017-36694]	Excess (\$)	0.00
Assign From	PATRICK SAVERIMUTHU	Assign Date	20/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date		Inspection Date	20/12/2017
Survey held at	65 CHULIA STREET		
Repairer	VOLKSWAGEN GROUP SINGAPORE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: Patrick Saverimuthu <patrick@insightadjusters.com>
Sent: Wednesday, 20 December, 2017 10:02 AM
To: 'bryanang@lkkauto.com'
Cc: 'assignments@lkkauto.com'
Subject: [IA2017-36694]RE: Appointment of surveyor for damage assessment
Attachments: QUOTATION SKN3607B attachment 1.pdf; SKN3607B.JPG; SKN3607 1.jpg; SKN3607 2.jpg; SKN3607 3.jpg; SKN3607 4.jpg

Dear Mr Bryan,

We are the Loss Adjusters appointed by Tokio Marine Insurance Singapore Ltd to look into a Public Liability matter.

This incident involves impact damage to the Third Party's vehicle as the carpark barrier arm fell on the roof of the vehicle.

We attach photographs provided by the Third Party and a quotation from the Automobile agent.

Below are the brief details of the incident:-

➤ Third Party's Vehicle

- Model : 5172Q5
- Brand : Volkswagen
- Registration no: SKN 3607B
- Remarks : Barrier arm fell onto the roof of the Third Party's vehicle

We require your assistance to conduct a damage assessment on a "Without Prejudice" basis.

Please proceed to contact the owner of the Third Party Vehicle, Mr Choo Koon San at 96923331.

Thank you for your kind assistance and we look forward to receiving the report in due course.

Please do not hesitate to contact me should you have any further enquires. Thank you.

Best regards,
Patrick Saverimuthu
E-Mail : patrick@insightadjusters.com

Insight Adjusters and Surveyors Pte Ltd
133 Cecil Street, #14-02
Keck Seng Tower
Singapore 069535
(65) 6223 2008 • Fax : (65) 6226 2356

<http://www.insightadjusters.com>

- ASIÄ Regional Office for vrs adjusters
- Loss Adjuster of the Year, Asia Insurance Industry Award
- A Singapore Top 500 SME
- CESAM Average Agents, AIMU Correspondents

*CONFIDENTIAL NOTE: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law.

If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited.

If you have received this message in error, please immediately notify the sender and delete the mail.

Thank you.

PDI TUAS

PDI TUAS

CHOO KOON SAN
35 ROBIN ROAD
#08-01
Singapore, 258210
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV034289
Quote No. SER/QUO/1702084
QuoteDate 18/12/17
Salesperson
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF CABRIO A6 1.4 TSI (DSG)	41,240	Ong Germaine
License No.	VIN	Initial Registration	Sales Advisor
SKN3607B	WVWZZZ1KZDK012728	05/06/14	
Engine Code	Labor Type	Engine No.	Model Code
	1R	CTH 058504	5172Q5

No.	Description	Qty.	UoM	Unit Price	Amount
B&P ALEX LABOUR	R&R ROOF	3	UNIT	840.00	1680 2,520.00
B&P ALEX LABOUR	LABOUR	3	UNIT	840.00	840 2,520.00
B&P ALEX PAINT	SPRAY PAINT	3	UNIT	800.00	420 2,400.00
B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un	480.00	480.00
	COMPULSORY TO DO AFTER AC				
B&P MECH	ELECT WIRING & MECH COMPO	1	Time Un	280.00	280.00
	Nett				
	Sum Labor				8,200.00
5K7871021G 2Y5	ROOF FRAME	1	Pieces	25,628.55	25,628.55
	Predecessor 5K7871021F 2Y5				
5K7871465D	SEAL	1	Pieces	403.74	403.74
	Use Predecessor 5K7871465C				
	Sum Item				26,032.29

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Payment Terms No Credit
Signature:
Date:

Sum Labor 8,200.00
Sum Item 26,032.29
Total SGD 34,232.29
7% GST 2,396.26
Total SGD Incl. GST 36,628.55

Payments to: - BBN: - Acc.-No.:

Janice Lee (LKKAuto)

From: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>
Sent: Thursday, December 21, 2017 11:18 AM
To: SUR
Cc: Wong, Meiy (VWG Singapore); Cheong, Pearlyn (VWG Singapore); Goh, Edmund (VWG Singapore); Ong, Germaine (VWG Singapore); Oh, Aik Seong (VWG Singapore)
Subject: SKN3607B ESTIMATE
Attachments: 171221124719.tif

Dear Catherine,

Estimate attached as requested.

Thanks.

Best Regards,

Charmaine Kong
Insurance Service Advisor
Aftersales

Volkswagen Group Singapore Pte Ltd
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7176
Main Line: +65 6305 7299
Main Fax: +65 6474 3643
charmaine.kong@vw.com.sg
<http://www.vw.com.sg>



From: charmaine.kong@vw.com.sg [mailto:charmaine.kong@vw.com.sg]
Sent: Thursday, 21 December, 2017 12:47 PM
To: Kong, Charmaine (VWG Singapore)
Subject: ricohscan



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INSIGHT ADJUSTERS AND SURVEYORS PL

Ref : CS/TP17024114/R1rbs2

133 CECIL STREET
#14-02 KECK SENG TOWER
SINGAPORE 069535

Date : 22-01-2018



Code : TP364

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKN 3607B
Policy No.		Coverage (\$)	0.00
Claim No.	[IA2017-36694]	Excess (\$)	0.00
Assign From	PATRICK SAVERIMUTHU	Assign Date	20/12/2017

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN	c.c	0
Engine No.	HIDDEN	Year of Reg.	0
Chassis No.	WWWZZZ1KZDK012728	Colour	GREY
Odometer	43965	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45R17	MICHELIN	6 mm
L/H Front Tyre	225/45R17	MICHELIN	6 mm
R/H Rear Tyre	225/45R17	MICHELIN	6 mm
L/H Rear Tyre	225/45R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	Inspection Date	20/12/2017
Survey held at	65 CHULIA STREET	
Repairer	VOLKSWAGEN GROUP SINGAPORE PTE LTD	

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIR. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 3607B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	ROOF FRAME (SN)	* CHECK NECESSARY	25,628.55	-
1	SEAL (SN)		403.74	403.74
			26,032.29	403.74
	<u>LABOUR</u>			
	R&R ROOF.		2,520.00	1,680.00
	LABOUR.		2,520.00	840.00
	SPRAY PAINT.		2,400.00	420.00
	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC.		480.00	480.00
	ELECT WIRING & MECH COMPO.		280.00	280.00
			8,200.00	3,700.00
	GRAND TOTAL		34,232.29	4,103.74

RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$25,628.55 NETT)			4,103.74
---------------------------------------------------------------------------------------------------------------	--	--	-----------------

Report Ref No. CS/TP17024114/R1rbs2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.