

15/5/2018

CC 3 / CTI1702 4121, KUBB22

LKK:

IDAC:

INS. CASE OWNER:

Surveyor:

Fenneth

DOI:

ASSIGNMENT

16/12/17

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE

Insured Vehicle No.:

SLQ 1111A

Claim No.:

SNM 17007124 / 102/1

Name of Insured:

TAY WEI LOON

Policy No.:

DMPCLSW1727781700

Insured Tel No.:

HP: 9636 0648

Make / Model:

BMW

Excess Sec II :\$S

D.O.A:

16/12/17

Place of Accident:

PHILIP ST TWDS LURCH ST

Is driver the owner?

(YES / NO)

Nature of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHC 5067P

INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans
Cab.

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 8/1/17 > 517 1111

After call ltr to OI: 12/01/18 - vic

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

8/1/18 @ 12:30 pm. Spoke to Mr Tay, OI 9636 0648 agreed to
Settle on TP (claim aware of NID 1552 -
Letter will be sent out - mentioned he have
videotapes as evidence -

12/01/18 - Letter sent to OI.

RECEIVED 12 MAR 2018

RECEIVED 15 MAY 2018

LIMINARY ADVICE

Date/Time:

20/12/17

Sent By:

BM

Confirm by:

Email

Call

ALIZATION

Date/Time:

Confirm with:

SS

(

days) Reduction:

%

Repair Cost:

AL SETTLEMENT

Date/Time:

10/5/18

Confirm with JASMINE

Email

Call

Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

COI 100% - ENJOYED - W

Repair Cost:

SS

3210.00

Loss of Rental (LOR):

SS

248.30

(2.5 days) x 99.32

Loss of Use (LOU):

SS

125.00

(50 x 2.5 days)

Loss of Income (LOI):

SS

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

LTA Search

SS

5.35

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Repair Cost

SS

Total:

SS

3588.65

Global Sum SS:

Email

Call

AL PAYMENT

Date/Time:

Confirm with:

SS

3588.65

Name 1:

TRANS-CAB AUTO SERVICES PTE LTD

Name 2: (Strike if N.A.)

SS

Name 3:

Name 3: (Strike if N.A.)

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT
16/5/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI17024121/Kub3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 20-12-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 1111A	Veh. Inspected	SHC 5067P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/12/2017	Inspection Date	19/12/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTH17024121/Kub3

Date: 20.12.2017

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC5067P


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19.12.2017 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	33,366.89
Revised Estimate Amount	: S\$	3,000.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Shu Pei (LKKAUTO)

From: Jowyn Tay <jowyn.tay@sg.cntaiping.com>
Sent: Friday, 22 December, 2017 10:21 AM
To: Shu Pei (LKKAUTO); Thin Thin (LKKAUTO)
Cc: Alfred Toh; Jas Khine (LKKAUTO); Admin A; Jowyn Tay
Subject: RE: Direct Settlement - Accident Involving SLQ1111A (OI : SNM17D07185/C02/1) and SHC5067P (TP : LKK REF - CC3/CTI17024121/Kub3) on 16.12.2017
Attachments: MCCA17166016-SLQ1111A.pdf; SNM17D07185C02 20171222-TO INSD-APPT LKK AS SETTLEMENT AGENT.pdf
Importance: High

Dear Thin Thin &/or Shu Pei,

Refer to the said matter.

Please refer to the attachments.

Thank you.

Regards,

Jowyn Tay

Deputy Claims Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6174
Fax: 6224 7175 / 6224 7478
Email: claimsdept@sg.cntaiping.com
jowyn.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 20 December, 2017 5:47 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Joel Goh <joel.goh@sg.cntaiping.com>; Jowyn Tay <jowyn.tay@sg.cntaiping.com>; Thin Thin (LKKAUTO) <thinthin@lkkauto.com>; Jas Khine (LKKAUTO) <jaskhine@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving SLQ1111A (OI : CTI - TBA) and SHC5067P (TP : LKK REF - CC3/CTI17024121/Kub3) on 16.12.2017

WITHOUT PREJUDICE

Dear Sir/ Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHC 5067P at M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springvale Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.ctaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM17D07185/C02/1**

Date : **22 DECEMBER 2017**

via Ordinary & Registered Mail

**TAY WEI LOONG JULIAN
31 JALAN SENANG**

SINGAPORE 418323

Dear Sir / Madam

**ACCIDENT INVOLVING SLQ1111A AND SHC5067P ON 18 DECEMBER 2017
ALONG PHILLIP STREET TOWARDS CHURCH STREET**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC5067P**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : THIN THIN

Ref : CC3/CT117024121/KUB3

Contact No : 68412360

via Email : thinthin@lkkauto.com

CC : Agent - (AN0006A) - ALFA CREDIT PTE LTD

F01/LKKDS-2013

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5067P
Vehicle to be Exported:	Yes
Intended De-registration Date:	18 Dec 2017
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000687
Chassis No.:	VF1ABL15AUC276146
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	02 Dec 2013
First Registration Date:	02 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Dec 2021
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

TRANS-CAB AUTO SERVICES PTE LTD
 NO. 2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHC5067P -

AAD1712-160

Not Authored
21 Sep @ 3000

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC5067P - CANDY
 VF1ABL15AUC276146
 RENAULT
 LATITUDE
 16.12.2017
China Triping

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>Br</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Ad/Lr</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61 X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61 X
10	1	BUMPER BEAM REAR	\$	<i>Br</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95
13	1	BOOT REAR	\$	<i>R</i> 2,872.68
14	1	BOOT FINISHER	\$	<i>Sn</i> 470.06
15	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
16	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
17	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
18	1	BOOT BADGE 'RENAULT'	\$	<i>rr</i> 225.36
19	1	BOOT BADGE	\$	<i>rr</i> 225.36
20	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52 X
21	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81
22	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13
23	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13
24	1	TAILLAMP RH	\$	<i>Sn</i> 552.55
25	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70
26	1	TAILLAMP LH	\$	<i>Sn</i> 552.55
27	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70
28	1	EXHAUST REAR	\$	<i>R</i> 7,489.05
29	1	EXHAUST CAP REAR	\$	<i>R</i> 230.49
TOTAL			\$	26,441.19
10%			\$	2,644.12
			\$	23,797.07

Specical Nett

1	1SET	PARKING AID	\$	Shot 700.00 ✓
2	1SET	REAR BUMPER CLIP	\$	na 66.00 ✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	na 33.00 ✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	na 10.00 X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	na 20.00 X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	na 10.00 X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	na 20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$	na 22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$	na 66.00 ✓
10	1	EXHAUST MOUNTING REAR	\$	Sh 17.82
11	1	BOOT STICKER "Trans-cab"	\$	na 30.00
12	1	BOOT STICKER "6555-3333"	\$	na 30.00
13	1	TAILLAMP CLIP RH	\$	na 5.00
14	1	TAILLAMP CLIP LH	\$	na 5.00
15	2	REAR WINDSCREEN SELANT	\$	na 80.00
16	1	WINDSCREEN MOULDING	\$	Sh 100.00
17	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	Sh 100.00
18	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sh 385.00
19	1	SPARE TYRE	\$	Sh 330.00

TOTAL	\$	2,029.82
TOTAL PARTS	\$	25,826.89

Putty And Spray Painting Of The Affected Portion.	\$	2201 3,000.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2001 2,800.00
To Rust-Proofing Of The Affected Areas.	\$	na 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na 170.00 X
To repair and realign rear exhaust pipe.	\$	na 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-160

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5067P -

To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
Towing Fees	\$	<i>nn</i> 120.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X

TOTAL	\$	7,540.00
Over All Total	\$	33,366.89

(PARTS BY PARTS)
Repair Days

87
10 Days*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI17024121/Kub3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 17-05-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 1111A	Veh. Inspected	SHC 5067P
Policy No.	DMPCSN1737781700	Coverage (\$)	0.00
Claim No.	SNM17D07185/C02/1	Excess (\$)	0.00
Assign From		Assign Date	19/12/2017

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VF1ABL15AUC276146	Colour	METALLIC WHITE / RED
Odometer	594884	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	LING LONG	8 mm
L/H Front Tyre	215/60 R16	LING LONG	8 mm
R/H Rear Tyre	215/60 R16	LING LONG	8 mm
L/H Rear Tyre	215/60 R16	LING LONG	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/12/2017	Inspection Date	19/12/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5067P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PKUG	SERVICEABLE	221.81	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-

Report Ref No. CC3/CTI17024121/Kub3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No..2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-2,644.12	-265.48
			23,797.05	2,389.34
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SHORTED	700.00	700.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	SERVICEABLE	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	SERVICEABLE	100.00	-
1	SPARE TRYE RIM (ROUE 7J 16H 2547)(SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,029.82	865.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	220.00

Report Ref No. CC3/CTI17024121/Kub3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR,BUMPER BEAM BRACKET RH REAR,BOOT REAR,FENDER PANEL REAR LH,FENDER PANEL REAR RH,TAILLAMP PANEL RH,TAILLAMP PANEL LH,EXHAUST REAR AND EXHAUST CAP REAR.		2,800.00	200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			7,540.00	480.00
GRAND TOTAL			33,366.87	3,734.34
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CC3/CT17024121/Kub3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.