

ASS. REC. BY:

REF: CS/FWD/7024/23/Svd32

Search Instructions

Survivor
Meinmen

Sebastian

ASSIGNMENT (Office)

From (Person):

clary H^0

FWD

Date/Time: 19/12/17 @ 5.39pm

Estimated Cost

Bill to:

$$(OD) / TP + WS / TP \text{ RES} / OD \text{ RES} / EVA / INV / MV / CS$$

To Inspect Vehicle No:

SLG 488 Y

Insured:

at Workshop m/s

Automotive Repair Centre

Tel:

64688834

 σ

38, Woodlands Ind Park E7, # 05-18, 757700

757700

Policy No.

PNPV 2017-00007547

Claim No:

1201700009372

Sum Insured:

Excess:

\$500.00

Make of Veh:

D.O.A 16/12/17

(Client's Record)

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

P. 529m @ 20/12/17

Person Contacted:

Raymond

Vehicle IN OUT

[illegible]

Signature

REF: FWD

ASSIGNMENT

From: _____ Date: 20/12/17

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLG 488Y
at Workshop m/s Automotive Repair
of 38 Woodlands Ind. Prk E1 #05-18

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$500.00
(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 45k.

IDAC Accident Rpt: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLG 488Y Yr Regn: 26/4/2012

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Suzuki Swift C.C. 1372

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 86582 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JSAPZC 8250013931

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ S/Rim / STD A/Rim or

Tyre Size: F: 185/55R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Good year

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm


D.O.A. 16/12/2017. D.O.I. 20/12/2017.

Survey held at Automotive Repair.

Des. of Damages ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt, N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time	Action / Instruction
20/12/2017	ID number incorrect. Max Repair Limit \$7.5k.
21/12/17	REV total loss in merimen. MV: \$45000, LTA: \$37344, NV: \$7656
RECEIVED 27 DEC 2017	

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 27/12 - typist

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: 300

Transportation

1) S+RS SI

Photos

Others

TOTAL

Report Format: Uneconomical T/L

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ Site Insp (\$ _____)

☐ Interview (\$ _____)

☐ Tech. Invs (\$ _____)

☐ Weekend (\$ _____)

10

Survey Department Check List (Case Handler)

Reference No.: CS/FWD 17024123 Svd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assignment Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: VERON 23/12/17
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS/FWD17024123/Svd3

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 20-12-2017



Code : FWD

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLG 488Y
Policy No.	PNPV2017-00007547	Coverage (\$)	0.00
Claim No.	1201700009372	Excess (\$)	500.00
Assign From	MERIMEN (CLARA LI)	Assign Date	20/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/12/2017	Inspection Date	20/12/2017
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Dec 2017 Sendback Est	19 Dec 2017 17:34 \$13,656.50	19 Dec 2017 17:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	KHOO KO KEAN, ID: S8367360E		
Vehicle Reg. No.:	SLG488Y	Date of Loss:	16/12/2017 00:00 - :59
Claim Type:	OD / 1201700009372	Policy/Cover Note No.:	PNPV2017-00007547 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18, 757700 Woodlands - Tel: 64688834		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/12/2017]		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	19 Dec 2017 14:54	Cim Veh Model Changed	(202335) SUZUKI SWIFT 1.4 GLX (A).	[R] Raymond Tan
2	19 Dec 2017 14:54	Cim Created	Reg No: SLG488Y. Policy No: PNPV2017-00007547. Acct Date: 2017/12/16. Claim Type: OD. Insurer: FWD Singapore Pte. Ltd. (HQ). Workshop: Automotive Repair Centre Pte Ltd (HQ)	[R] Raymond Tan
3	19 Dec 2017 17:34	Cim Submitted	13656.50.	[R] Raymond Tan
4	19 Dec 2017 17:39	Cim Registration Modified	Excess: -> 500.00.	[I] Clara Li Zi Rong
5	19 Dec 2017 17:39	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ);; RR Region: FWD - Ext Auto Adj Assignment. Suggested Adj. : LKK Auto Consultants Pte Ltd.	[I] Clara Li Zi Rong
6	19 Dec 2017 17:39	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/29	[I] Clara Li Zi Rong
7	19 Dec 2017 17:39	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Clara Li Zi Rong
8	19 Dec 2017 17:44	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	20 Dec 2017 14:59	Adj Adjuster Assigned	[None] -> Sebastian Yeang Wai Keen	[A] Nivitha Govindasamy
10	21 Dec 2017 16:18	Adj Rpt Initiated		[A] LOW AI PHING
11	21 Dec 2017 16:30	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/12/29	[A] LOW AI PHING
12	21 Dec 2017 16:32	Adj Mandate Request	Cur.Reg:0.00:DAMAGES CONSISTENT. REPAIR COST NOT ECONOMICAL.	[A] LOW AI PHING
13	21 Dec 2017 16:49	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/29	[I] Clara Li Zi Rong
14	21 Dec 2017 16:49	Adj Mandate Set	Revoked.	[I] Clara Li Zi Rong

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1672877	19/12/2017 14:54	Motor	Automotive Repair Centre Pte Ltd (HQ)	Automotive Repair Centre Pte Ltd (HQ)	SLG488Y		xx.xx
1675292	21/12/2017 16:18	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLG488Y		10.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 21 Dec 2017

Preliminary Advice

Vehicle No	: SLG488Y	Accident Date	: 16/12/2017
Make	: SUZUKI SWIFT	Policy No.	: PNPV2017-00007547
Assignment Date	: 19/12/2017	Excess	: S\$500.00
Date of Inspection	: 20/12/2017	Est. Duration of Repair	: 15.00
Inspection At	: AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ) 38 WOODLANDS INDUSTRIAL PARK E1, #05-18 SINGAPORE 757700		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,612.46
Revised Amount	:S\$	9,718.50
Check Items (Estimated)	:S\$	3,448.00
Total	:S\$	13,166.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	37,344.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,656.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorise repair.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/12/2017 11:21
Date Of Accident	16/12/2017 03:30
Exact Location Of Accident	ALONG JALAN FLORA, MALAYSIA
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG488Y
Insured/Policyholder	
Name Of Registered Owner	KHOO KO KEAN
NRIC No	S8367360E
Email Address	TRI_K83@YAHOO.COM
Mobile Phone No	(LOCAL) +65-93207001
Alternative Phone No	OTHERS-93207001

Vehicle Particulars

Manufacturer	SUZUKI
Model	SWIFT 1.4 GLX AUTO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00007547
Cover Note Number	

Driver

Name of Driver	KHOO KO KEAN
NRIC No	S8367360E
Date Of Birth	17/01/1983
Occupation	INDOOR
Date Of Driving Pass	07/10/2016
Driving Experience	1 YEAR AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93207001
Fax Number	
Contact Number	OTHERS-93207001
EMail Address	TRI_K83@YAHOO.COM

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 18/12/2017

11:30 AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	8404N
Vehicle Details	
Vehicle No.:	SLG488Y
Vehicle to be Exported:	No
Intended De-registration Date:	21 Dec 2017
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT 1.4 GLX AUTO
Primary Colour:	Green
Manufacturing Year:	2011
Engine No.:	K14B1019891
Chassis No.:	JSAFZC82S00113931
Maximum Power Output:	70.0 kW (93 bhp)
Open Market Value:	\$13,505.00
Original Registration Date:	26 Apr 2012
First Registration Date:	26 Apr 2012
Transfer Count:	1
Actual ARF Paid:	\$13,505.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Apr 2022
PARF Rebate Amount:	\$9,453.00
Intended COE Rebate Details	
COE Expiry Date:	25 Apr 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$64,201.00
COE Rebate Amount:	\$27,891.00
Total Rebate Amount:	\$37,344.00

The information contained herein is correct as at 21 Dec 2017

OK

Enquire PARF/COE Rebate for Registered Vehicle

D.A.D. 15/12/17

Bolt: 4 yrs 4.3 months

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	8404N
Vehicle Details	
Vehicle No.:	SLG488Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	21 Dec 2017
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT 1.4 GLX AUTO
Primary Colour:	Green
Manufacturing Year:	2011
Engine No.:	K14B1019891
Chassis No.:	JSAFZC82S00113931
Maximum Power Output:	70.0 kW (93 bhp)
Open Market Value:	\$13,505.00
Original Registration Date:	26 Apr 2012
First Registration Date:	26 Apr 2012
Transfer Count:	1
Actual ARF Paid:	\$13,505.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Apr 2022
PARF Rebate Amount:	\$9,453.00
Intended COE Rebate Details	

6,752 ✓

COE Expiry Date:	25 Apr 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$64,201.00
COE Rebate Amount:	\$27,891.00
Total Rebate Amount:	\$37,344.00

The information contained herein is correct as at 21 Dec 2017

OK



Email Add

Home » Used Cars » Axcell Pte Ltd » Suzuki Swift 1.4A GL

Tools & Tips

- Car Buying
- Car Selling
- Car Aftermarket
- Car Ownership
- On The Move
- Lifestyle



Suzuki Swift 1.4A GL

Overview Financial Accessories Similar Research Photos Map

Car Details

Price	\$47,000	?
Depreciation	\$8,920 /yr View models with similar depreciation	
Reg Date	28-Jun-2012 (4yrs 6mths 6days COE left)	
Manufactured	2011	?
Mileage	97,000 km (17.7k /yr)	
Transmission	Auto	
Engine Cap	1,372 cc	?
Road Tax	\$610 /yr	
Power	70.0 kW (93 bhp) View specs of the Suzuki Swift (2011-2017)	?
Curb Weight	1,035 kg	
Features	1.5L 16 Valves DOHC VVT Engine, Smooth And Responsive Auto Transmission, Auto Climate Aircon, Dual Airbags, ABS Brake, Fuel Efficiency.	
Accessories	Sports Rims, Leather Seats, Fog Lights, Factory Fitted Premium Audio Systems, Reverse Sensors, Solar Film, Retractable Side Mirror, Steering Controls.	
Description	1 Owner Only. One Of The Popular Japanese Hatchback! Powerful And Responsive Car! Reliable Engine That Requires No Repairs, Car In Original Condition! Hesitate No More! Trade In Welcome, Call Us Now To Book A Appointment To View Before It Is Gone!	
COE	\$59,004	?
OMV	\$13,390	?
ARF	\$13,390	?
Dereg Value	\$36,030 as of today (change)	?
No. of Owners	2	?
Type of Veh	Hatchback	
Category	PARF Car	
Availability	Available	

Posted on: 12-Dec-2017 | Last Updated on: 17-Dec-2017

Tags: Suzuki Swift, Suzuki Swift, 2012 Suzuki Swift, 2012 Suzuki Swift, Suzuki, Swift, Swift, Used Suzuki



Seller Information

Company	Axcell Pte Ltd » dealer's pricelist » 1 vehs sold 2 vehs available
Address	61 Kaki Bukit Avenue 1 #03-05 Search cars nearby this location
Location	Shun Li Industrial Park
Contact Person(s)	Richie 98767145 Daegan 86168818

Useful Services

STA **VEHICLE INSPECTION** Make sure of this car condition with STA Evaluation.
Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.
Free Valuation

Upfront Payment

» more Financial info

Transfer Fee	\$25	?
Down Payment	\$14,100 (change)	Maximum 70% Loan ?

Malaysia Police Report

Salinan Repot Polis



POLIS DIRAJA MALAYSIA REPOT POLIS

Balai : TRAFIK ISKANDAR PUTERI
Daerah : ISKANDAR PUTERI
Kontinjen : JOHOR
No Repot : TRAFIK (PUTERI) 011504/17
Tarikh : 16/12/2017
Waktu : 0906 AM
Bahasa Diterima : B. Malaysia

Pegawai Penyelamat : R190317

Butir-butir Penerima Repot
Nama : MOHO SAIPUDI BIN OMAR
Butir-butir Jurubahasa (Jika Ada)
Nama : ---
No Pasport : ---
Alamat : ---

No Personel : R130168

Pangkat : KPL

No K/P (Baru) : ---
Bahasa Asal : ---

No Polis/Tentera : ---

Butir-butir Pengadu
Nama : KHOO KO KEAN
No K/P (Baru) : 630117036649
No Sijil Beranak : ---
Jantina : Lelaki
Keturunan : Cina
Pekerjaan : SWASTA
Alamat Tempat Tinggal : NO.56 JALAN FLORA 3/9 FLORA VILLA SKUDAI, 81300, JOHOR
Alamat Ibu/Bapa : ---
Alamat Pejabat : ---
No Tel (Rumah) : ---
Emel : tn_k83@yahoo.com

No Polis/Tentera : ---

No Pasport : ---

Tarikh Lahir : 17/01/1983
Warganegara : Malaysia

Umur : 34 tahun 10 bulan

No Tel (Pejabat) : ---

No Tel (HP) : 010-9527290

Pengadu Menyatakan:-

PADA 16/12/2017 JAM L/KURANG 0330 PAGI SEMASA SAYA MEMANDU MOTOKAR NO. SLG488Y DARI RUMAH MENUJU KE TEMPAT KERJA DI SINGAPURA. PADA KETIKA ITU APABILA SAMPAI DI JALAN FLORA, TIBA-TIBA SEEKOR ANJING MELINTAS HADAPAN KENDERAAN SAYA, SAYA MENGELAK LALU TERBABAS LANGGAR SEBATANG POKOK. KEROSAKAN MOTOKAR SAYA DI BAHAGIAN BONET DEPAN, CERMIN SISI KANAN, ENJIN, BUMPER DEPAN, SET LAMPU DEPAN KIRI/KANAN, TANGKI AIR/AIRCON, PANEL, SARONG DAN LAIN LAIN KEROSAKAN BELUM PASTI. SAYA TIDAK CEDERA. SEMASA SAYA MEMBUAT LAPORAN, SAYA TIDAK BAWA MOTOKAR NO. SLG488Y DI BALAI TRAFIK ISKANDAR PUTERI, JOHOR. SEKIAN LAPORAN SAYA.

Tandatangan Pengadu:

Tandatangan Jurubahasa (Jika ada):

Tandatangan Penerima Repot:

ID Pencetak | Tarikh @ Masa Cetak

PELAKSANAAN REPOT
TRAFIK ISKANDAR PUTERI
R190317
SALINAN YANG DISAHKAN BENAR
(HANYA UNTUK TUNTUTAN SAHAJA)

<https://pri.mop.gov.my/pri/coffice/viewpol?real2.asp?type=printed&salinan=yak&jenjangsalinan=Salinan Pertama&repot...> 12/16/2017

Automotive Repair Centre Pte Ltd (Co.Reg.No:201312913C)

38 Woodlands Industrial Park E1, #05-18

Singapore 757700

Tel: 64688834 Fax: 64622278 Email: raymond@automotiverepaircentre.com.sg

INSURER:

FWD Singapore Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type: OD (Own Damage)
Policy No: PNPV2017-00007547
Vehicle Reg. No.: SLG488Y
Driver Age/Info:
TP Injury Involved? NO

Ref. No:
Date of Loss: 16/12/2017
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES

Insured/Claimant: KHOO KO KEAN

Make/Model: SUZUKI SWIFT, 1.4 GLX (A)

Vehicle Reg. 26/04/2012
Date:

Vehicle Colour: Green
Engine No: K14B1019891
Odometer: 0 KM

Chassis No: JSAFZC82S00113931

Paint Type:

Total Loss? NO

Est. Duration of Repair 20
(day)

Remarks: VEHICLE AT WORKSHOP READY FOR SURVEY.

Present Location: AUTOMOTIVE REPAIR CENTRE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	9,431.50
Miscellaneous Items	425.00
Labour	3,800.00
Paintwork Labour	0.00
Towing	0.00

Calculated Gross Total (S\$) 13,656.50

- Excess (S\$) 500.00

(S\$) 13,156.50

+ GST 7.00% (S\$) 920.96

Nett Amount (S\$) 14,077.46

14,077.46

This claim is handled by: RAYMOND TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Dec 2017)
 Parts: 144 SUZUKI SWIFT 1.4 GLX (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Automotive Repair Centre Pte Ltd/SLG488Y/19/12/2017 17:34
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER ✓ MS	0.00	0.00	*428.00 F
2	1		*FRONT BUMPER CLIP X 10 ✓ NEC	0.00	0.00	*15.00 F
3	1		*FRONT BUMPER TOW EYE COVER ✓ MS	0.00	0.00	*16.00 F
4	1		*FRONT BUMPER LOWER RUBBER SKIRT ✓ MS	0.00	0.00	*32.00 F
5	1		*FRONT BUMPER RETAINER RH ✓ CRK	0.00	0.00	*12.00 F
6	1		*FRONT BUMPER RETAINER LH ✓ CRK	0.00	0.00	*12.00 F
7	1		*FRONT BUMPER LOWER GRILLE ✓ MS	0.00	0.00	*40.00 F
8	1		*FRONT REINFORCEMENT ✓ BT	0.00	0.00	*260.00 F
9	1		*FRONT ABSORBER ✓ MS	0.00	0.00	*56.00 F
10	1		*FRONT GRILLE ✓ CRK	0.00	0.00	*46.00 F
11	1		*FRONT EMBLEM ✓ NEC	0.00	0.00	*18.00 F
12	1		*FRONT HEAD LAMP RH ✓ CRK	0.00	0.00	*260.00 F
13	1		*FRONT HEAD LAMP LH ✓ CRK	0.00	0.00	*260.00 F
14	1		*FRONT HEAD LAMP BRACKET LH ✓ BT	0.00	0.00	*8.00 F
15	1		*FRONT HEAD LAMP BRACKET RH ✓ BT	0.00	0.00	*8.00 F
16	1		*AIR FILTER BOX CASING ASSY ?	0.00	0.00	*135.00 F
17	1		*AIR INTAKE DUCT PIPE ?	0.00	0.00	*56.00 F
18	1		*FRONT SUPPORT PANEL - TOP ✓ BT	0.00	0.00	*65.00 F
19	1		*FRONT SUPPORT PANEL @ HEADLAMP RH ✓ BT	0.00	0.00	*20.00 F
20	1		*FRONT SUPPORT PANEL @ HEADLAMP LH ✓ BT	0.00	0.00	*20.00 F
21	1		*FRONT SUPPORT PANEL SIDE RH ✓ BT	0.00	0.00	*35.00 F
22	1		*FRONT SUPPORT PANEL SIDE LH ✓ BT	0.00	0.00	*35.00 F
23	1		*FRONT SUPPORT PANEL LOWER ✓ BT	0.00	0.00	*135.00 F
24	1		*RADIATOR ✓ DT	0.00	0.00	*480.00 F
25	1	-	*RADIATOR FAN ?	0.00	0.00	*42.00 F
26	1	-	*RADIATOR FAN MOTOR ?	0.00	0.00	*275.00 F
27	1	-	*RADIATOR FAN SHROUD ?	0.00	0.00	*75.00 F
28	1		*RADIATOR SIDE AIR GUIDE RH ✓ CRK	0.00	0.00	*25.00 F
29	1		*RADIATOR SIDE AIR GUIDE LH ?	0.00	0.00	*10.00 F
30	1		*RADIATOR UPPER HOSE ✓ Deform.	0.00	0.00	*16.00 F
31	1		*RADIATOR LOWER HOSE ?	0.00	0.00	*15.00 F
32	1		*RADIATOR TOP BRACKET RH ✓ NEC	0.00	0.00	*8.00 F
33	1		*RADIATOR TOP BRACKET LH ✓ NEC	0.00	0.00	*8.00 F
34	1		*RADIATOR UPPER BUSH X 2 ✓ NEC	0.00	0.00	*10.00 F
35	1		*RADIATOR LOWER BUSH X 2 ✓ NEC	0.00	0.00	*10.00 F
36	1		*A/C CONDENSER ✓ DT	0.00	0.00	*370.00 F
37	1	-	*A/C PIPE DISCHARGE HOSE ✓ BT	0.00	0.00	*68.00 F
38	1	-	*A/C OUTLET PIPE ✓ BT	0.00	0.00	*125.00 F
39	1	-	*A/C COMPRESSOR SUCTION HOSE ✓ BT	0.00	0.00	*92.00 F
40	1		*FRONT BONNET ✓ DT	0.00	0.00	*320.00 F
41	1		*FRONT BONNET HINGE RH ✓ BT	0.00	0.00	*20.00 F
42	1		*FRONT BONNET HINGE LH ✓ BT	0.00	0.00	*20.00 F
43	1		*FRONT BONNET INSULATOR ✓ Deform.	0.00	0.00	*50.00 F
44	1		*FRONT BONNET INSULATOR CLIP X 10 ✓ NEC	0.00	0.00	*20.00 F
45	1		*FRONT BONNET LOCK ✓ BT	0.00	0.00	*35.00 F
46	1		*FRONT BONNET LOCK CABLE ✓ NEC	0.00	0.00	*22.00 F
47	1		*FRONT BONNET STAY U-CLIP ✓ MS	0.00	0.00	*4.50 F

48	1	*FRONT BONNET RUBBER SEAL ✓ Deform	0.00	0.00	*20.00 F
49	1	*FRONT BONNET LOWER STOPPER X 2 ✓ N/C	0.00	0.00	*9.00 F
50	1	*FRONT BONNET LOWER LEVEL STOPPER X 2 ✓ N/C	0.00	0.00	*12.00 F
51	1	*FRONT FOG LAMP RH ✓ MS	0.00	0.00	*110.00 F
52	1	*FRONT FOG LAMP LH ✓ MS	0.00	0.00	*110.00 F
53	1	*FRONT FOG LAMP GARNISH RH ✓ MS	0.00	0.00	*12.00 F
54	1	*FRONT FOG LAMP GARNISH LH ✓ MS	0.00	0.00	*12.00 F
55	1	*FRONT UNDERCARRIAGE COVER ✓ CAC	0.00	0.00	*95.00 F
56	1	*FRONT UNDERCARRIAGE COVER RH ✓ MS	0.00	0.00	*30.00 F
57	1	*FRONT UNDERCARRIAGE COVER LH ✓ MS	0.00	0.00	*30.00 F
58	1	*FRONT UNDERCARRIAGE CLIP X 10 ✓ N/C	0.00	0.00	*15.00 F
59	1	*FRONT FENDER RH ✓ BT	0.00	0.00	*160.00 F
60	1	*FRONT FENDER LH ✓ BT	0.00	0.00	*160.00 F
61	1	*FRONT FENDER SHIELD RH ✓ TN	0.00	0.00	*58.00 F
62	1	*FRONT FENDER SHIELD LH ✓ MS	0.00	0.00	*58.00 F
63	1	*FRONT FENDER BRACKET RH ?	0.00	0.00	*12.00 F
64	1	*FRONT FENDER BRACKET LH ✓ BT	0.00	0.00	*12.00 F
65	1	*FRONT FENDER VVT EMBLEM RH ✓ N/C	0.00	0.00	*10.00 F
66	1	*FRONT FENDER VVT EMBLEM LH ✓ N/C	0.00	0.00	*10.00 F
67	1	*FRONT FENDER CLIP X 20 ✓ N/C	0.00	0.00	*30.00 F
68	1	*FRONT WINDSCREEN CENTER COWLING ✓ CRK	0.00	0.00	*85.00 F
69	1	*FRONT WINDSCREEN NOZZLE X 2 ✓ DMG	0.00	0.00	*20.00 F
70	1	*FRONT WINDSCREEN COWLING SIDE GARNISH RH ✓ Deform	0.00	0.00	*13.00 F
71	1	*INNER DASH BOARD A/C LOUVER RH X NN	0.00	0.00	*40.00 F
72	1	*WASHER TANK ✓ BT	0.00	0.00	*48.00 F
73	1	*FRONT INNER BRAKE PUMP ?	0.00	0.00	*240.00 F
74	1	*FRONT HORN ✓ DMG	0.00	0.00	*35.00 F
75	1	*ENGINE MOUNTING RH ?	0.00	0.00	*145.00 F
76	1	*ENGINE/GEARBOX MOUNTING LH ?	0.00	0.00	*85.00 F
77	1	*ENGINE MOUNTING REAR ?	0.00	0.00	*90.00 F
78	1	*ENGINE TIMING COVER ✓ CRK	0.00	0.00	*210.00 F
79	1	*SIDE MIRROR WITH SIGNAL RH ✓ DMG	0.00	0.00	*280.00 F
80	1	*SIDE SILL PANEL LOWER GARNISH LH ✓ BT	0.00	0.00	*45.00 F
81	1	*FRONT STABILISER LINKAGE RH ✓ BT	0.00	0.00	*35.00 F
82	1	*FRONT STABILISER ?	0.00	0.00	*120.00 F
83	1	*FRONT TIE ROD RH ✓ BT	0.00	0.00	*40.00 F
84	1	*FRONT TIE ROD END RH ✓ BT	0.00	0.00	*55.00 F
85	1	*FRONT ABSORBER RH ?	0.00	0.00	*190.00 F
86	1	*FRONT ABSORBER TOP MOUNT RH ?	0.00	0.00	*38.00 F
87	1	*FRONT DRIVESHAFT RH ✓ BT	0.00	0.00	*480.00 F
88	1	*FRONT LOWER ARM RH ✓ BT	0.00	0.00	*160.00 F
89	1	*FRONT CROSSMEMBER ?	0.00	0.00	*580.00 F
90	1	*FRONT EXHAUST MANIFOLD ?	0.00	0.00	*1,250.00 F
91	1	*FRONT EXHAUST PIPE ?	0.00	0.00	*90.00 F

F=Franchise part.

Total Parts (S\$)

9,431.50

Automotive Repair Centre Pte Ltd/SLG488Y/19/12/2017 17:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			30.00
1	1	COOLANT FLUID 4 LITRES ✓ NEC	60.00
2	1	ENGINE OIL ✓ NEC	35.00
3	1	FRONT LICENSE PLATE WITH CASING ✓ MS	200.00
4	1	FRONT TIRE LH ✓ cut	40.00
5	1	POWER STEERING OIL ✓ NEC	60.00
6	1	TRANSMISSION OIL ✓ NEC	
Sub Total (S\$)			425.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	SPRAY PAINT WHOLE FRONT INCLUDING 2 FRONT DOORS, SILL PANEL LH	New	1,000.00 900
2	REMOVE, REFIT & REPAIR AFFECT ACCIDENT INCLUDE WHEEL HOUSE, UNDER PANEL AND SILL PANEL LH	New	1,400.00 1200
3	REMOVE, REFIT ENGINE TO FACILITATE REPAIR	New	350.00 300
4	REMOVE, REFIT ENGINE WIRING HARNESS	New	200.00 150
5	REMOVE AND REFIT UNDERCARRIAGE FRONT SUBFRAME	New	350.00 300
6	WHEELS COMPUTER ALIGNMENT	New	80.00 ✓
7	REMOVE, REFIT A/C CONDENSER, RADIATOR & REFILL A/C GAS	New	100.00 ✓
8	SPRAY PAINT FRONT RIMS	New	100.00 ✓
9	REMOVE AND REFIT EXHAUST SYSTEM	New	100.00 ✓
10	REPAIR AND REFIT CABLE AT REAR UNDERCARRIAGE FOR HANDBRAKE	New	20.00 ✓
11	CHECK AND RECTIFY ELECTRICAL WIRING		
Gross Labour Cost (S\$)			3,800.00

Automotive Repair Centre Pte Ltd/SLG488Y/19/12/2017 17:34. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

15 days

Sebastian
20/12/2017

- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint
- Revert
- Excess \$500

90036121

sebastian.yeang@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	19 Dec 2017	19 Dec 2017 17:34	19 Dec 2017 17:39	\$9,718.50 Edit Estimates	\$9,718.50 View Rpt	Pending for Survey Report
		\$13,656.50	Edit Adj Rpt			

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS				
Insured:	KHOO KO KEAN, ID: S8367360E			
Vehicle Reg. No.:	SLG488Y	Date of Loss:	16/12/2017 00:00 - :59	
Claim Type:	OD / 1201700009372	Policy/Cover Note No.:	PNPV2017-00007547 (Comprehensive)	
		Excess:	\$5500.00	
Repairer:	Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18, 757700 Woodlands - Tel: 64688834			
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 29/12/2017]			
Driver/Custodian:	KHOO KO KEAN (), NRIC: S8367360E			
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail
● FWD_SG (21/12/2017): Alert - Adj Mandate Revoked - SLG488Y - Claim Handler: Clara Li Zi Rong				
ALL ASSOCIATED TASKS				
View All Search Tasks Create New Task Complete Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?				
No results.				

Claim Documents

SLG488Y (1201700009372)
 OD
 Dec 16 2017 12:00AM
 [KHOO KO KEAN]
 Automotive Repair Centre Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View Use Viewer		
Assessment Reports									1 per page		☒
No	Finalized On	Automotive Repair Centre Pte Ltd (HQ)							Thumbnail	Print	
1	19/12/17 17:34	Repairer Estimates							Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	21/12/17 16:30	Adjuster Immediate Advice							Load HTM		
									3 per page		☒
Photos/Images									Thumbnail	Print	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									
1	21/12/17 14:44	General View							Load JPG	☒	
2	21/12/17 14:44	General View							Load JPG	☒	
3	21/12/17 14:44	General View							Load JPG	☒	
4	21/12/17 14:44	General View							Load JPG	☒	
5	21/12/17 14:44	General View							Load JPG	☒	
6	21/12/17 14:44	General View							Load JPG	☒	
7	21/12/17 14:44	General View							Load JPG	☒	
8	21/12/17 14:44	General View							Load JPG	☒	
9	21/12/17 14:44	General View							Load JPG	☒	
10	21/12/17 14:44	General View							Load JPG	☒	
11	21/12/17 14:44	General View							Load JPG	☒	
12	21/12/17 14:44	General View							Load JPG	☒	
13	21/12/17 14:44	General View							Load JPG	☒	
14	21/12/17 14:44	General View							Load JPG	☒	
15	21/12/17 14:44	General View							Load JPG	☒	
16	21/12/17 14:44	General View							Load JPG	☒	
17	21/12/17 14:44	General View							Load JPG	☒	
18	21/12/17 14:44	General View							Load JPG	☒	
19	21/12/17 14:44	General View							Load JPG	☒	
20	21/12/17 14:44	General View							Load JPG	☒	
21	21/12/17 14:44	General View							Load JPG	☒	
22	21/12/17 14:44	General View							Load JPG	☒	
23	21/12/17 14:44	General View							Load JPG	☒	
24	21/12/17 14:44	General View							Load JPG	☒	
25	21/12/17 14:44	General View							Load JPG	☒	
26	21/12/17 14:44	General View							Load JPG	☒	
27	21/12/17 14:44	General View							Load JPG	☒	
28	21/12/17 14:44	General View							Load JPG	☒	
29	21/12/17 14:44	General View							Load JPG	☒	
30	21/12/17 14:44	General View							Load JPG	☒	
31	21/12/17 14:44	General View							Load JPG	☒	
32	21/12/17 14:44	General View							Load JPG	☒	
33	21/12/17 14:44	General View							Load JPG	☒	
34	21/12/17 14:44	General View							Load JPG	☒	
35	21/12/17 14:44	General View							Load JPG	☒	
36	21/12/17 14:44	General View							Load JPG	☒	
37	21/12/17 14:44	General View							Load JPG	☒	
38	21/12/17 14:44	General View							Load JPG	☒	

39	21/12/17 14:44	General View	1	Load JPG	☒
40	21/12/17 14:44	General View	1	Load JPG	☒
41	21/12/17 14:44	General View	1	Load JPG	☒
42	21/12/17 14:44	General View	1	Load JPG	☒
43	21/12/17 14:44	General View	1	Load JPG	☒
44	21/12/17 14:44	General View	1	Load JPG	☒
45	21/12/17 14:44	General View	1	Load JPG	☒
46	21/12/17 14:44	General View	1	Load JPG	☒
47	21/12/17 14:44	General View	1	Load JPG	☒
48	21/12/17 14:44	General View	1	Load JPG	☒
49	21/12/17 14:44	General View	1	Load JPG	☒
50	21/12/17 14:44	General View	1	Load JPG	☒
51	21/12/17 14:44	General View	1	Load JPG	☒
52	21/12/17 14:44	General View	1	Load JPG	☒
53	21/12/17 14:44	General View	1	Load JPG	☒
54	21/12/17 14:44	General View	1	Load JPG	☒
55	21/12/17 14:44	General View	1	Load JPG	☒
56	21/12/17 14:44	General View	1	Load JPG	☒
57	21/12/17 14:44	General View	1	Load JPG	☒
58	21/12/17 14:44	General View	1	Load JPG	☒
59	21/12/17 14:44	General View	1	Load JPG	☒
60	21/12/17 14:44	General View	1	Load JPG	☒
61	21/12/17 14:44	General View	1	Load JPG	☒
62	21/12/17 14:44	General View	1	Load JPG	☒
63	21/12/17 14:44	General View	1	Load JPG	☒
64	21/12/17 14:44	General View	1	Load JPG	☒
65	21/12/17 14:44	General View	1	Load JPG	☒
66	21/12/17 14:44	General View	1	Load JPG	☒
67	21/12/17 14:44	General View	1	Load JPG	☒
68	21/12/17 14:44	General View	1	Load JPG	☒
69	21/12/17 14:44	General View	1	Load JPG	☒
70	21/12/17 14:44	General View	1	Load JPG	☒
71	21/12/17 14:44	General View	1	Load JPG	☒
72	21/12/17 14:44	General View	1	Load JPG	☒
73	21/12/17 14:44	General View	1	Load JPG	☒
74	21/12/17 14:44	General View	1	Load JPG	☒
75	21/12/17 14:44	General View	1	Load JPG	☒
76	21/12/17 14:44	General View	1	Load JPG	☒
77	21/12/17 14:44	General View	1	Load JPG	☒
78	21/12/17 14:44	General View	1	Load JPG	☒
79	21/12/17 14:44	General View	1	Load JPG	☒
80	21/12/17 14:44	General View	1	Load JPG	☒
81	21/12/17 14:44	General View	1	Load JPG	☒
82	21/12/17 14:44	General View	1	Load JPG	☒
83	21/12/17 14:44	General View	1	Load JPG	☒
84	21/12/17 14:44	General View	1	Load JPG	☒
85	21/12/17 14:44	General View	1	Load JPG	☒
86	21/12/17 14:44	General View	1	Load JPG	☒
87	21/12/17 14:44	General View	1	Load JPG	☒
88	21/12/17 14:44	General View	1	Load JPG	☒
89	21/12/17 14:44	General View	1	Load JPG	☒
90	21/12/17 14:44	General View	1	Load JPG	☒
91	21/12/17 14:44	General View	1	Load JPG	☒
92	21/12/17 14:44	General View	1	Load JPG	☒

93	21/12/17 14:44	General View	1	Load JPG	☒
94	21/12/17 14:44	General View	1	Load JPG	☒
95	21/12/17 14:44	General View	1	Load JPG	☒
96	21/12/17 14:44	General View	1	Load JPG	☒
97	21/12/17 14:44	General View	1	Load JPG	☒
98	21/12/17 14:44	General View	1	Load JPG	☒
99	21/12/17 14:44	General View	1	Load JPG	☒
100	21/12/17 14:44	General View	1	Load JPG	☒
101	21/12/17 14:44	General View	1	Load JPG	☒
102	21/12/17 14:44	General View	1	Load JPG	☒
103	21/12/17 14:44	General View	1	Load JPG	☒
104	21/12/17 14:44	General View	1	Load JPG	☒
105	21/12/17 14:44	General View	1	Load JPG	☒
106	21/12/17 14:44	General View	1	Load JPG	☒
107	21/12/17 14:45	General View	1	Load JPG	☒
108	21/12/17 14:45	General View	1	Load JPG	☒
109	21/12/17 14:45	General View	1	Load JPG	☒
110	21/12/17 14:45	General View	1	Load JPG	☒
111	21/12/17 14:45	General View	1	Load JPG	☒
112	21/12/17 14:45	General View	1	Load JPG	☒
113	21/12/17 14:45	General View	1	Load JPG	☒
114	21/12/17 14:45	General View	1	Load JPG	☒
115	21/12/17 14:45	General View	1	Load JPG	☒
116	21/12/17 14:45	General View	1	Load JPG	☒
117	21/12/17 14:45	General View	1	Load JPG	☒
118	21/12/17 14:45	General View	1	Load JPG	☒
119	21/12/17 14:45	General View	1	Load JPG	☒
120	21/12/17 14:45	General View	1	Load JPG	☒
121	21/12/17 14:45	General View	1	Load JPG	☒
122	21/12/17 14:45	General View	1	Load JPG	☒
123	21/12/17 14:45	General View	1	Load JPG	☒
124	21/12/17 14:45	General View	1	Load JPG	☒
125	21/12/17 14:45	General View	1	Load JPG	☒
126	21/12/17 14:45	General View	1	Load JPG	☒
				1 per page	☒
Documentation				Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			
1	21/12/17 16:16	ESTIMATE	1	Load PDF	
2	21/12/17 16:46	Log card (if available)	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Repairer ☐ Handling Insurer				
Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD17024123/SVD3S2

Date: 28/12/2017

REFERENCE

Insured/Claimant: KHOO KO KEAN Policy No: PNPV2017-00007547
Date of Loss: 16/12/2017 Nature of Claim: OD Claim No: 1201700009372

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG488Y Engine No: K14B1019891
Make & Model: SUZUKI SWIFT, 1.4 GLX (A) Chassis No: JSAFZC82S00113931
Reg. Date: 26/04/2012 (Man. Year: 2011) Odometer: 86582 km
Colour: Green
Engine Capacity: 1372 cc
Market Value/New Car Price: S\$45,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R16 Rear Tyre Size: 185/55R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,431.50	5,943.50	3,488.00	36.98
Miscellaneous Items	425.00	425.00	0.00	0.00
Labour	3,800.00	3,350.00	450.00	11.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,656.50	9,718.50	3,938.00	28.84
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	13,156.50	9,218.50	3,938.00	29.93
+ GST 7.00/7.00% (S\$)	920.96	645.30	275.66	29.93
Nett Amount (S\$)	14,077.46	9,863.80	4,213.66	29.93

INSPECTION

Date of Assignment: 19/12/2017 Present Location:
Date Inspected: 20/12/2017 Inspected At:

Automotive Repair Centre Pte Ltd (HQ)
Automotive Repair Centre Pte Ltd (HQ)
38 Woodlands Industrial Park E1, #05-18
Singapore 757700

Estimated Period of Repair: 0.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Please be informed that owner vehicle is not economical to repair.

(EXCLUDE CHECK ITEMS S\$3,448.00 NETT)

TOTAL LOSS ASPECT

Market Value :	\$45,000.00
OMV :	\$13,505.00
PARF Rebate (1) :	\$9,453.00
Quota Premium Paid :	\$64,201.00
COE Rebate (2) :	\$27,891.00
Total Rebate (1) + (2) = :	\$37,344.00

The total amount incurred will be Market Value \$45,000.00 minus Total Rebate \$37,344.00 = \$7,656.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2017)
Parts:	144	SUZUKI SWIFT 1.4 GLX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG488Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Missing	428.00 F	*428.00 F
2	1	*FRONT BUMPER CLIP X 10	Necessary	15.00 F	*15.00 F
3	1	*FRONT BUMPER TOW EYE COVER	Missing	16.00 F	*16.00 F
4	1	*FRONT BUMPER LOWER RUBBER SKIRT	Missing	32.00 F	*32.00 F
5	1	*FRONT BUMPER RETAINER RH	Cracked	12.00 F	*12.00 F
6	1	*FRONT BUMPER RETAINER LH	Cracked	12.00 F	*12.00 F
7	1	*FRONT BUMPER LOWER GRILLE	Missing	40.00 F	*40.00 F
8	1	*FRONT REINFORCEMENT	Bent	260.00 F	*260.00 F
9	1	*FRONT ABSORBER	Missing	56.00 F	*56.00 F
10	1	*FRONT GRILLE	Cracked	46.00 F	*46.00 F
11	1	*FRONT EMBLEM	Necessary	18.00 F	*18.00 F
12	1	*FRONT HEAD LAMP RH	Cracked	260.00 F	*260.00 F
13	1	*FRONT HEAD LAMP LH	Cracked	260.00 F	*260.00 F
14	1	*FRONT HEAD LAMP BRACKET LH	Bent	8.00 F	*8.00 F
15	1	*FRONT HEAD LAMP BRACKET RH	Bent	8.00 F	*8.00 F
16	1	*AIR FILTER BOX CASING ASSY	*Check	135.00 F	*- F
17	1	*AIR INTAKE DUCT PIPE	*Check	56.00 F	*- F
18	1	*FRONT SUPPORT PANEL - TOP	Bent	65.00 F	*65.00 F
19	1	*FRONT SUPPORT PANEL @ HEADLAMP RH	Bent	20.00 F	*20.00 F
20	1	*FRONT SUPPORT PANEL @ HEADLAMP LH	Bent	20.00 F	*20.00 F
21	1	*FRONT SUPPORT PANEL SIDE RH	Bent	35.00 F	*35.00 F
22	1	*FRONT SUPPORT PANEL SIDE LH	Bent	35.00 F	*35.00 F
23	1	*FRONT SUPPORT PANEL LOWER	Bent	135.00 F	*135.00 F
24	1	*RADIATOR	Dented	480.00 F	*480.00 F
25	1	*RADIATOR FAN	*Check	42.00 F	*- F
26	1	*RADIATOR FAN MOTOR	*Check	275.00 F	*- F
27	1	*RADIATOR FAN SHROUD	*Check	75.00 F	*- F
28	1	*RADIATOR SIDE AIR GUIDE RH	Cracked	25.00 F	*25.00 F
29	1	*RADIATOR SIDE AIR GUIDE LH	*Check	10.00 F	*- F
30	1	*RADIATOR UPPER HOSE	Deformed	16.00 F	*16.00 F
31	1	*RADIATOR LOWER HOSE	*Check	15.00 F	*- F
32	1	*RADIATOR TOP BRACKET RH	Necessary	8.00 F	*8.00 F
33	1	*RADIATOR TOP BRACKET LH	Necessary	8.00 F	*8.00 F
34	1	*RADIATOR UPPER BUSH X 2	Necessary	10.00 F	*10.00 F
35	1	*RADIATOR LOWER BUSH X 2	Necessary	10.00 F	*10.00 F
36	1	*A/C CONDENSER	Dented	370.00 F	*370.00 F
37	1	*A/C PIPE DISCHARGE HOSE	Bent	68.00 F	*68.00 F
38	1	*A/C OUTLET PIPE	Bent	125.00 F	*125.00 F
39	1	*A/C COMPRESSOR SUCTION HOSE	Bent	92.00 F	*92.00 F
40	1	*FRONT BONNET	Dented	320.00 F	*320.00 F
41	1	*FRONT BONNET HINGE RH	Bent	20.00 F	*20.00 F
42	1	*FRONT BONNET HINGE LH	Bent	20.00 F	*20.00 F
43	1	*FRONT BONNET INSULATOR	Deformed	50.00 F	*50.00 F
44	1	*FRONT BONNET INSULATOR CLIP X 10	Necessary	20.00 F	*20.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*FRONT BONNET LOCK	Bent	35.00 F	*35.00 F
46	1	*FRONT BONNET LOCK CABLE	Necessary	22.00 F	*22.00 F
47	1	*FRONT BONNET STAY U-CLIP	Missing	4.50 F	*4.50 F
48	1	*FRONT BONNET RUBBER SEAL	Deformed	20.00 F	*20.00 F
49	1	*FRONT BONNET LOWER STOPPER X 2	Necessary	9.00 F	*9.00 F
50	1	*FRONT BONNET LOWER LEVEL STOPPER X 2	Necessary	12.00 F	*12.00 F
51	1	*FRONT FOG LAMP RH	Missing	110.00 F	*110.00 F
52	1	*FRONT FOG LAMP LH	Missing	110.00 F	*110.00 F
53	1	*FRONT FOG LAMP GARNISH RH	Missing	12.00 F	*12.00 F
54	1	*FRONT FOG LAMP GARNISH LH	Missing	12.00 F	*12.00 F
55	1	*FRONT UNDERCARRIAGE COVER	Cracked	95.00 F	*95.00 F
56	1	*FRONT UNDERCARRIAGE COVER RH	Missing	30.00 F	*30.00 F
57	1	*FRONT UNDERCARRIAGE COVER LH	Missing	30.00 F	*30.00 F
58	1	*FRONT UNDERCARRIAGE CLIP X 10	Necessary	15.00 F	*15.00 F
59	1	*FRONT FENDER RH	Bent	160.00 F	*160.00 F
60	1	*FRONT FENDER LH	Bent	160.00 F	*160.00 F
61	1	*FRONT FENDER SHIELD RH	Torn	58.00 F	*58.00 F
62	1	*FRONT FENDER SHIELD LH	Missing	58.00 F	*58.00 F
63	1	*FRONT FENDER BRACKET RH	*Check	12.00 F	*- F
64	1	*FRONT FENDER BRACKET LH	Bent	12.00 F	*12.00 F
65	1	*FRONT FENDER VVT EMBLEM RH	Necessary	10.00 F	*10.00 F
66	1	*FRONT FENDER VVT EMBLEM LH	Necessary	10.00 F	*10.00 F
67	1	*FRONT FENDER CLIP X 20	Necessary	30.00 F	*30.00 F
68	1	*FRONT WINDSCREEN CENTER COWLING	Cracked	85.00 F	*85.00 F
69	1	*FRONT WINDSCREEN NOZZLE X 2	Damaged	20.00 F	*20.00 F
70	1	*FRONT WINDSCREEN COWLING SIDE GARNISH RH	Deformed	13.00 F	*13.00 F
71	1	*INNER DASH BOARD A/C LOUVER RH	Not Necessary	40.00 F	*- F
72	1	*WASHER TANK	Dented	48.00 F	*48.00 F
73	1	*FRONT INNER BRAKE PUMP	*Check	240.00 F	*- F
74	1	*FRONT HORN	Damaged	35.00 F	*35.00 F
75	1	*ENGINE MOUNTING RH	*Check	145.00 F	*- F
76	1	*ENGINE/GEARBOX MOUNTING LH	*Check	85.00 F	*- F
77	1	*ENGINE MOUNTING REAR	*Check	90.00 F	*- F
78	1	*ENGINE TIMING COVER	Cracked	210.00 F	*210.00 F
79	1	*SIDE MIRROR WITH SIGNAL RH	Damaged	280.00 F	*280.00 F
80	1	*SIDE SILL PANEL LOWER GARNISH LH	Dented	45.00 F	*45.00 F
81	1	*FRONT STABILISER LINKAGE RH	Bent	35.00 F	*35.00 F
82	1	*FRONT STABILISER	*Check	120.00 F	*- F
83	1	*FRONT TIE ROD RH	Bent	40.00 F	*40.00 F
84	1	*FRONT TIE ROD END RH	Bent	55.00 F	*55.00 F
85	1	*FRONT ABSORBER RH	*Check	190.00 F	*- F
86	1	*FRONT ABSORBER TOP MOUNT RH	*Check	38.00 F	*- F
87	1	*FRONT DRIVESHAFT RH	Bent	480.00 F	*480.00 F
88	1	*FRONT LOWER ARM RH	Bent	160.00 F	*160.00 F
89	1	*FRONT CROSSMEMBER	*Check	580.00 F	*- F
90	1	*FRONT EXHAUST MANIFOLD	*Check	1,250.00 F	*- F
91	1	*FRONT EXHAUST PIPE	*Check	90.00 F	*- F

F=Franchise part.

Total Parts (\$\$) 9,431.50 5,943.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	COOLANT FLUID 4 LITRES (NECESSARY)	30.00	30.00
2	1	ENGINE OIL (NECESSARY)	60.00	60.00
3	1	FRONT LICENSE PLATE WITH CASING (MISSING)	35.00	35.00
4	1	FRONT TIRE LH (CUT)	200.00	200.00
5	1	POWER STEERING OIL (NECESSARY)	40.00	40.00
6	1	TRANSMISSION OIL (NECESSARY)	60.00	60.00
Sub Total (S\$)			425.00	425.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT WHOLE FRONT INCLUDING 2 FRONT DOORS, SILL PANEL LH	New	1,000.00	900.00
2	REMOVE, REFIT & REPAIR AFFECT ACCIDENT INCLUDE WHEEL HOUSE, UNDER PANEL AND SILL PANEL LH	New	1,400.00	1,200.00
3	REMOVE, REFIT ENGINE TO FACILITATE REPAIR	New	350.00	300.00
4	REMOVE, REFIT ENGINE WIRING HARNESS	New	200.00	150.00
5	REMOVE AND REFIT UNDERCARRIAGE FRONT SUBFRAME	New	350.00	300.00
6	WHEELS COMPUTER ALIGNMENT	New	80.00	80.00
7	REMOVE, REFIT A/C CONDENSER, RADIATOR & REFILL A/C GAS	New	100.00	100.00
8	SPRAY PAINT FRONT RIMS	New	100.00	100.00
9	REMOVE AND REFIT EXHAUST SYSTEM	New	100.00	100.00
10	REPAIR AND REFIT CABLE AT REAR UNDERCARRIAGE FOR HANDBRAKE	New	100.00	100.00
11	CHECK AND RECTIFY ELECTRCIAL WIRING	New	20.00	20.00
Gross Labour Cost (S\$)			3,800.00	3,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >