

22/03/2012

ASS. REC. BY:

REF: CS/CTI17024126/Krd3n2 Special Instructions:

Supervisor: Kenneth

ASSIGNMENT (Office)

From (Person): Joel Goh

of CTI

Date/Time: 19/12/17 @ 5.22pm

Estimated Cost: Bill to:

OD: TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 2614D

Insured: XE 35682

at Workshop m/s

Esfeem Performance

Tel: 6484 1221

of BIK 5033, Amk Ind. Park 2 # 01-259

Policy No: DMCVSN1763171700

Claim No: SNM17D07107C02/8

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 8.57am @ 20/12/17

Person Contacted:

Carmen

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLR 2614D - X
	XE 35682 - X
	Kenneth confirm \$6008.80 @ 12 days (Red: \$4948.73, 451.)

REF: CTI

ASSIGNMENT

From: _____ Date: 20/12/17

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLR 2614D

at Workshop m/s: Esteem Performance

of BIK 5033, AMK Ind Prk 2, # 01-259

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 1.31% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLR 2614D Yr Regn: 08 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Vics G.O. 1496

Colour: M. Reddy A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: M14FB291-3982012553

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 13/12/17

Rear

R/Bal. 9 mm

L/Bal. 9 mm

D.O.I. 20/12/17

Survey held at: _____

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/12 File pass to Catherine, Battery Plan

86008.80 Cash

RECEIVED 1 NOV 2018

Date/Time, File Pass to?

1) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final Report

Days Of Repair: 12

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ - RS - \$

) Photos

) Others

Add Fee: ☐ : Site Insp: (\$☐ : Interview: (\$☐ : Tech. Invs: (\$☐ : Weekend: (\$

Report Format: TP

Lump Sum / I.B.I. (\$: 6008.80

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI17024126/Krd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 20-12-2017	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 2568Z	Veh. Inspected	SLR 2614D	
Policy No.	DMCVSN1763171700	Coverage (\$)	0.00	
Claim No.	SNM17D07107C02/8	Excess (\$)	0.00	
Assign From	MERIMEN (JOEL GOH)	Assign Date	20/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/12/2017	Inspection Date	20/12/2017	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Dec 2017		19 Dec 2017 17:22 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD, Co. Reg. No.: 199904117E		
Main Claimant:	GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D		
Vehicle Reg. No.:	SLR2614D	Date of Loss:	13/12/2017 17:00 - :59
Claim Type:	TP / SNM17D07107C02/8	Policy/Cover Note No.:	DMCVSN1763171700 (Comprehensive)
Vehicle Reg. No. (Insured):	XE3568Z	Policy No. (Claimant):	SD16V16658/VPZ/R02
		Excess:	S\$0.00
Repairer:	Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259, 569536 Ang Mo Kio - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/12/2017]		
Driver/Custodian (Insured):	LIM CHEE SENG (54 / Male), NRIC: S1595197D, Tel: +6597382742		
Adj Asg. Remarks:	NO ESTIMATES KENNETH KONG SELECTED AS SJE FOR WP PRS		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Kenneth Kong (LKKAUTO)

From: Carmen Lim <carmen@esteemperf.com.sg>
Sent: Tuesday, 16 January, 2018 9:57 AM
To: Kenneth Kong (LKKAUTO)
Subject: Re: FINALISED SLR2614D

Dear Kenneth,

We are agreed to finalised COR at \$6008.80.

Thank you & regards,
Carmen

On Fri, Jan 12, 2018 at 9:06 AM, Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com> wrote:

Attach finalised for SLR 2614D. Kenneth

From: Carmen Lim [mailto:carmen@esteemperf.com.sg]
Sent: Wednesday, 10 January, 2018 10:19 AM
To: Kenneth Kong (LKKAUTO)
Subject: FINALISED SLR2614D

Dear Kenneth,

Pls refer as attached.

Kindly confirm the finalised amount asap.

--

Thank you & regards,

Carmen Lim

Esteem Performance Pte Ltd
Tel : 64841221
Fax : 64847829

--

Thank you & regards,

Carmen Lim

Esteem Performance Pte Ltd

Tel : 64841221

Fax : 64847829

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0651D
Vehicle Details	
Vehicle No.:	SLR2614D
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	2NRX162642
Chassis No.:	MHFB29F3902012553
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,715.00
Original Registration Date:	07 Aug 2017
First Registration Date:	07 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$7,715.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Aug 2027
PARF Rebate Amount:	\$5,786.00
Intended COE Rebate Details	
COE Expiry Date:	06 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,201.00
COE Rebate Amount:	\$39,842.00
Total Rebate Amount:	\$45,628.00

The information contained herein is correct as at 13 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 18/12/2017 10:24
Date Of Accident 13/12/2017 17:45
Exact Location Of Accident TAMPINES ROAD EXIT 9A
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLR2614D
Insured/Policyholder
Name Of Registered Owner GOLDBELL CAR RENTAL PTE LTD
Co Reg No 200710651D
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-66039399

Vehicle Particulars

Manufacturer TOYOTA
Model VIOS-1.5 E (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company LIBERTY INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy YES
Policy Number SD16V16658NPZ/R02
Cover Note Number

Driver

Name of Driver BODIN ANTOINE GILLES
Passport No/FIN G3401169N
Date Of Birth 21/07/1972
Occupation INDOOR
Date Of Driving Pass 11/09/1987
Driving Experience 30 YEARS AND 3 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-94834054
Fax Number
Contact Number
Email Address ANTOINE_BODIN@HOTMAIL.COM

Address 283 DEMISE TERRACE CABONA
 Postcode 805312
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER AS ATTACHED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XE3568Z
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver LIM CHEE SENG
 NRIC/Passport Number S1595197D
 Contact Number 97357558 / 97382752
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


 - (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authorities (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.





Policyholder's Signature & Time _____ Date & Time _____
 Driver's Signature (if driver is not the policyholder) _____ Date & Time _____
 Witnessed by Reporting Centre Personnel _____

Sketch Plan *




Describe Circumstances of the Accident *


I stopped the car due to the red traffic light but the truck hit our car from behind. The truck did not stop due to the heavy rain. My wife and I went to the doctor for a medical check up (please see attached). I was sick the following day, I stayed 1H under the rain after the accident (fever 38°C). My wife is suffering for shoulder strain and headache.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature



* 14/12/17 
Driver's Signature (If driver is not the policyholder, state name & Title)

Witnessed by Reporting Centre Personnel



ESTEEM PERFORMANCE PTE LTD

Blk 6033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLR 2614 D

Parts (a) Cost / List Price Items	\$	8,055.00
Plus/Less 25%	\$	2,013.75
Total of Cost / List	\$	6,041.25
(b) Nett Price Items	\$	379.20
Less 10%	\$	37.92
Total of Nett Item	\$	341.28
(c) Special Nett Items	\$	95.00
Total Parts Cost	\$	6,477.53
Labour	\$	4,480.00
Total	\$	10,957.53

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

Not Authored
1-B1

Resurvey B & paint

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : CEC

Survey conducted on : 20/12/17 at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 12 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor : Le

Date: 20/12/17



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLR 2614 D
Make & Model : TOYOTA VIOS
Chassis No : MHFB29F3902012553

Submit By : Carmen Lim
Year Manufacture : 2017
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding <i>uv</i>	1	\$128.50		<i>X</i>
2	Rear windscreen sealant <i>uv</i>	1	\$50.00	S.N	<i>X</i>
3	Reverse sensor <i>sn</i>	2	\$379.20	N	<i>X</i>
4	Rear number plate <i>nd</i>	1	\$45.00	S.N	<i>X</i>
5	Rear No.plate lamp LH <i>sn</i>	1	\$72.80		<i>X</i>
6	Rear No.plate lamp RH <i>sn</i>	1	\$72.80		<i>X</i>
7	Rear bumper <i>bu</i>	1	\$497.10		<i> </i>
8	Rear bumper clip <i>uv</i>	10	\$40.00		<i> </i>
9	Rear bumper side retainer LH <i>di</i>	1	\$113.90		<i> </i>
10	Rear bumper side retainer RH <i>cm</i>	1	\$113.90		<i> </i>
11	Rear bumper reinforcement <i>u</i>	1	\$355.80		<i>X</i>
12	Rear bumper reflector LH <i>sn</i>	1	\$195.02		<i>X</i>
13	Rear bumper reflector RH <i>sn</i>	1	\$195.02		<i>X</i>
14	Bootlid <i>by</i>	1	\$851.16		<i> </i>
15	Bootlid lock <i>nd</i>	1	\$118.88		<i> </i>
16	Bootlid hinge LH <i>u</i>	1	\$78.20		<i>X</i>
17	Bootlid hinge RH <i>by</i>	1	\$78.20		<i> </i>
18	Bootlid emblem <i>uv</i>	1	\$56.24		<i> </i>
19	Wording "VIOS" <i>uv</i>	1	\$49.70		<i> </i>
20	Wording "E" <i>uv</i>	1	\$39.98		<i> </i>
21	Tail end panel <i>by</i>	1	\$753.60		<i> </i>
22	Tail end panel garnish <i>di</i>	1	\$259.40		<i> </i>
23	Tail end panel garnish clip <i>uv</i>	10	\$35.00		<i> </i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLR 2614 D

TOYOTA VIOS
 MHFB29F3902012553

Submit By :
 Year Manufacture :
 Engine No. :

Carmen Lim

2017

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Boot weatherstrip <i>DR / R</i>	1	\$235.10		✓
25	Tail lamp LH <i>CRA</i>	1	\$353.20		✓
26	Tail lamp RH <i>BR</i>	1	\$353.20		✓
27	Tail lamp clip <i>MC</i>	4	\$14.80		✓
28	Tail lamp panel LH <i>R</i>	1	\$161.70		X
29	Tail lamp panel RH <i>Ry</i>	1	\$161.70		✓
30	Spare tyre well panel <i>R</i>	1	\$693.30		X
31	Spare tyre board <i>SW</i>	1	\$269.60		X
32	RH rear fender <i>R BR</i>	1	\$853.60		✓ X
33	LH rear fender <i>R</i>	1	\$853.60		X
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 589536.
Tel: +65-6484 1221 Fax: +65-6484 7629 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLR 2614 D** Submit By : **Carmen Lim**
Make & Model : **TOYOTA VIOS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL, SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$1,800.00	1400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL, SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$1,400.00	1000
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor to assist work load	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$200.00	90
8	To remove & refit inner seat & upholstery to assist work load.	\$250.00	80
9	To transfer boot mechanism to new boot	\$120.00	50
10	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
11	To remove & refit exhaust system to assist work load.	\$150.00	60

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 589536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLR 2614 D

Parts	(a) Cost / List Price Items	\$	8,055.00
	Plus/Less 25%	\$	2,013.75
	Total of Cost / List	\$	6,041.25
	(b) Nett Price Items	\$	379.20
	Less 10%	\$	37.92
	Total of Nett Item	\$	341.28
	(c) Special Nett Items	\$	95.00
Total Parts Cost		\$	6,477.53
Labour		\$	4,480.00
Total		\$	10,957.53

The above total will be subjected to 7% G.S.T.

finalized

Not authorized
1. B1

4303.56

1075.89

3227.67

Penalty Bx pricing

85

3312.67

2990

6302.67

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 12 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor :

Date: 20/12/17



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLR 2614 D
Make & Model : TOYOTA VIOS
Chassis No : MHFB29F3902012553

Submit By : Carmen Lim
Year Manufacture : 2017
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding <i>Me</i>	1	\$128.50	✓	✓
2	Rear windscreen sealant <i>Me</i>	1	\$50.00	S.N 40	✓
3	Reverse sensor	2	\$379.20	N	✓
4	Rear number plate <i>Rel</i>	1	\$45.00	✓ S.N	✓
5	Rear No.plate lamp LH	1	\$72.80		✓
6	Rear No.plate lamp RH	1	\$72.80		✓
7	Rear bumper <i>Bu</i>	1	\$497.10	✓	✓
8	Rear bumper clip <i>Me</i>	10	\$40.00	✓	✓
9	Rear bumper side retainer LH <i>D.Y</i>	1	\$113.90	✓	✓
10	Rear bumper side retainer RH <i>CM</i>	1	\$113.90	✓	✓
11	Rear bumper reinforcement	1	\$355.80		✓
12	Rear bumper reflector LH <i>Sm</i>	1	\$195.02		X
13	Rear bumper reflector RH <i>Sm</i>	1	\$195.02		X
14	Bootlid <i>Ry</i>	1	\$851.16	✓	✓
15	Bootlid lock <i>Rel</i>	1	\$118.88	✓	✓
16	Bootlid hinge LH <i>R</i>	1	\$78.20		X
17	Bootlid hinge RH <i>Ry</i>	1	\$78.20	✓	✓
18	Bootlid emblem <i>Me</i>	1	\$56.24	✓	✓
19	Wording "VIO" <i>Me</i>	1	\$49.70	✓	✓
20	Wording "E" <i>Me</i>	1	\$39.98	✓	✓
21	Tail end panel <i>Ry</i>	1	\$753.60	✓	✓
22	Tail end panel garnish <i>D.Y</i>	1	\$259.40	✓	✓
23	Tail end panel garnish clip <i>Me</i>	10	\$35.00	✓	✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

2,188.56.
88 (S.N)

Spare Parts

Vehicle No. :
 Make & Model :
 Chassis No. :

SLR 2614 D

TOYOTA VIOS

MHFB29F3902012553

Submit By :
 Year Manufacture :
 Engine No. :

Carmen Lim

2017

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Boot weatherstrip <i>DR / DR</i>	1	\$235.10 ✓		✓
25	Tail lamp LH <i>CRA</i>	1	\$353.20 ✓		✓
26	Tail lamp RH <i>BR</i>	1	\$353.20 ✓		✓
27	Tail lamp clip <i>MC</i>	4	\$14.80 ✓		✓
28	Tail lamp panel LH <i>R</i>	1	\$161.70		X
29	Tail lamp panel RH <i>Ry</i>	1	\$161.70 ✓		✓
30	Spare tyre well panel <i>R</i>	1	\$693.30		X
31	Spare tyre board	1	\$269.60		7
32	RH rear fender <i>BR</i>	1	\$853.60 x	Reprv	✓
33	LH rear fender <i>R</i>	1	\$853.60		X
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 689536.
Tel: +65-6484 1221 Fax: +65-6484 7629 Website: www.eesteampart.com.sg

Labour

Vehicle No. : **SLR 2614 D** Submit By : **Carmen Lim**
Make & Model : **TOYOTA VIOS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL, SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$1,800.00	1800
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL, SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$1,400.00	1000
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor to assist work load	\$120.00	30
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
6	To remove & refit rear windscreen.	\$120.00	✓
7	To buff coat.	\$200.00	90
8	To remove & refit inner seat & upholstery to assist work load.	\$250.00	80
9	To transfer boot mechanism to new boot	\$120.00	50
10	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
11	To remove & refit exhaust system to assist work load.	\$150.00	60

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17024126/KRD3N2
Date: 21/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1763171700
Claimant Vehicle No :	SLR2614D	Insured Vehicle No :	XE3568Z
Date of Loss:	13/12/2017	Nature of Claim:	TP
		Claim No:	SNM17D07107C02/8

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR2614D	Engine No:	2NRX162642
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MHFB29F3902012553
Reg. Date:	07/08/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50R16	Rear Tyre Size:	195/50R16
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,477.53	3,138.79	3,338.74	51.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,480.00	2,870.00	1,610.00	35.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,957.53	6,008.79	4,948.74	45.16
+ GST 7.00/7.00% (S\$)	767.03	420.62	346.41	45.16
Nett Amount (S\$)	11,724.56	6,429.41	5,295.15	45.16

INSPECTION

Date of Assignment:	19/12/2017	
Date Inspected:	20/12/2017 Inspected At:	Esteem Performance Pte Ltd (HQ) Blk 5033 Ang Mo Kio Ind Park 2, #01-259 Singapore 569536

Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$6008.80

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2018)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLR2614D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	128.50 FL	*- FL
2	1		*REAR NO PLATE LAMP LH	Serviceable	72.80 FL	*- FL
3	1		*REAR NO PLATE LAMP RH	Serviceable	72.80 FL	*- FL
4	1		*REAR BUMPER	Buckled	497.10 FL	*497.10 FL
5	10		*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
6	1		*REAR BUMPER SIDE RETAINER LH	Distorted	113.90 FL	*113.90 FL
7	1		*REAR BUMPER SIDE RETAINER RH	Cracked	113.90 FL	*113.90 FL
8	1		*REAR BUMPER REINFORCEMENT	Repair	355.80 FL	*- FL
9	1		*REAR BUMPER REFLECTOR LH	Serviceable	195.02 FL	*- FL
10	1		*REAR BUMPER REFLECTOR RH	Serviceable	195.02 FL	*- FL
11	1		*BOOTLID	Bent	851.16 FL	*851.16 FL
12	1		*BOOTLID LOCK	Dented	118.88 FL	*118.88 FL
13	1		*BOOTLID HINGE LH	Repair	78.20 FL	*- FL
14	1		*BOOTLID HINGE RH	Bent	78.20 FL	*78.20 FL
15	1		*BOOTLID EMBLEM	Necessary	56.24 FL	*56.24 FL
16	1		*WORDING VIOS	Necessary	49.70 FL	*49.70 FL
17	1		*WORDING E	Necessary	39.98 FL	*39.98 FL
18	1		*TAIL END PANEL	Bent	753.60 FL	*753.60 FL
19	1		*TAIL END PANEL GARNISH	Distorted	259.40 FL	*259.40 FL
20	10		*TAIL END PANEL GARNISH CLIP	Necessary	35.00 FL	*35.00 FL
21	1		*BOOT WEATHERSTRIP	Distorted/Dented	235.10 FL	*235.10 FL
22	1		*TAIL LAMP LH	Cracked	353.20 FL	*353.20 FL
23	1		*TAIL LAMP RH	Broken	353.20 FL	*353.20 FL
24	4		*TAIL LAMP CLIP	Necessary	14.80 FL	*14.80 FL
25	1		*TAIL LAMP PANEL LH	Repair	161.70 FL	*- FL
26	1		*TAIL LAMP PANEL RH	Bent	161.70 FL	*161.70 FL
27	1		*SPARE TYRE WELL PANEL	Repair	693.30 FL	*- FL
28	1		*SPARE TYRE BOARD	Serviceable	269.60 FL	*- FL
29	1		*RH REAR FENDER	Repair	853.60 FL	*- FL
30	1		*LH REAR FENDER	Repair	853.60 FL	*- FL
31	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
32	2		*REVERSE SENSOR	Serviceable	379.20 FN	*- FN
33	1		*REAR NUMBER PLATE	Dented	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	8,529.20	4,170.06
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,013.75	1,031.27
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	37.92	0.00
Total Parts (\$\$)	6,477.53	3,138.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (REAR BUMPER,BOOTLID,END PANEL,SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	New	1,800.00	1,400.00
2	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (REAR BUMPER,BOOTLID,END PANEL,SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	New	1,400.00	1,000.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE & REFIT REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	50.00
5	TO REMOVE & REFIT SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM TO ASSIST WORK LOAD	New	150.00	100.00
6	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	-
7	TO TUFF COAT	New	200.00	90.00
8	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD	New	250.00	80.00
9	TO TRANSFER BOOT MECHANISM TO NEW BOOT	New	120.00	50.00
10	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	20.00
11	TO REMOVE & REFIT EXHAUST SYSTEM TO ASSIST WORK LOAD	New	150.00	60.00
Gross Labour Cost (S\$)			4,480.00	2,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >