

Survivor:

MA

ASSIGNMENT (Office)

Menmen

From (Person):

Jawyn Tay

of

CTI

Date/Time: 19/12/17 @ 5:17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 5482S

Insured:

SJH 1230K

at Workshop m/s

C.S. Ong Auto

Tel:

6484 1933

of BIK 10 AMK, Ind Park 2A # 02-16, S 68047

Policy No:

DMPCSN 303711700

Claim No:

SNM17D07161C0210

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up?

H.O.D. Endorsement:

Date/Time:

8:56am @ 20/12/17

Person Contacted:

Mrs. Ong

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLS 5482S - X
	SJH 1230K - X
21/8/18 @ 3:16pm	Analised with CS'ong Anal Prog \$5773.15, 5 days. (Red \$ 10123.79, 64%)

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s C-2 only

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: LS55828 Yr Regn: 28/09/17Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA C.C. 1496Colour: BROWN A/C: Insured / Std / NI / NASp. Reading: 19816 T/Radio: Insured / Std / NI / NA

Eng.No: _____

C.No: HP 170707179Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60/R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or DUNFront 8 mm Rear 8 mmR/Bal. 8 mmL/Bal. 8 mmD.O.A. 20/2/2017

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No estimate upon survey.6/8/2018

RECEIVED 23 AUG 2018.

Date/Time, File Pass to?

1) 21/8/2018

Date/Time, File Return to?

2) _____

☐ : Preli. Report
☐ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - R - S

Phone:

Others:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: MEF-TPLump Sum / I.B.I. (\$) 5773.15

220

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Dec 2017		19 Dec 2017 17:17 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	KOONG KIAN MIN STEPHEN, ID: S2502837F								
Main Claimant:	LEE THIAM KWEE (COMPANY), Co. Reg. No.: 53336437W								
Vehicle Reg. No.:	SLS5482S	Date of Loss:	15/12/2017 20:00 - :59						
Claim Type:	TP / SNM17D07161C02/0	Policy/Cover Note No.:	DMPCSN3037111700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJH1230K	Policy No. (Claimant):	5094466506 CLASSIC						
		Excess:	\$0.00						
Repairer:	C.s.ong Auto Pte. Ltd (HQ) BLK 10 ANG MO KIO IND PARK 2A #02-16 AMK AUTOPOINT, 568047 Ang Mo Kio - Tel: 64841933								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/12/2017]								
Driver/Custodian (Insured):	KOONG KIAN MIN STEPHEN (59 / Male), NRIC: S2502837F								
Adj Asg. Remarks:	NO ESTIMATES, KENNETH KONG SELECTED AS SJE FOR WP PRS								
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17024129/M1qd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 20-12-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 1230K	Veh. Inspected	SLS 5482S	
Policy No.	DMPCSN3037111700	Coverage (\$)	0.00	
Claim No.	SNM17D07161C02/0	Excess (\$)	0.00	
Assign From	MERIMEN (JOWYN TAY)	Assign Date	20/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/12/2017	Inspection Date	20/12/2017	
Survey held at	C. S. ONG AUTO PTE LTD BLOCK 10 ANG MO KIO IND PK 2A #04-01/#03-11 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Shiau Chan (LKKAuto)

From: Sam San Joi UBI <SanJoi.Sam@borneomotors.com.sg>
Sent: Tuesday, 21 August 2018 8:49 AM
To: Shiau Chan (LKKAuto)
Subject: Re: KINDLY ASSIST TO CHECK PARTS PRICES OF SLS 5482S

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Wednesday, 8 August 2018 5:46 PM
To: Sam San Joi UBI
Subject: KINDLY ASSIST TO CHECK PARTS PRICES OF SLS 5482S

Dear Sam,

Kindly assist to check parts prices of vehicle SLS 5482S, TOYOTA SIENTA 1.5 HYBRID CVT, chassis number: NHP170709xxxx

Parts are below:

1. FRONT BONNET - 642.20
2. FRONT BONNET HINGE LH/RH - 65.70
3. FRONT BONNET LOCK - 133.20
4. FRONT BUMPER - 327.20
5. FRONT CHROME GRILLE - 668.60
6. CONDENSER - 1336.60
7. FRONT BRACE PANEL - 146.80
8. FRONT HEADLIGHT RH/LH SIDE BEAM - 77.50
9. FRONT SUPPORT PANEL- 1132.20
10. HORN - 114.20
11. FRONT SUPPORT TOP COVER - 143.20
12. FRONT BUMPER TOP MOULDING RUBBER - 38.00

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

Shiau Chan (LKKAUTO)

From: C. S. ONG AUTO PTE. LTD. <csongauto@yahoo.com.sg>
Sent: Tuesday, 21 August 2018 3:16 PM
To: SUR; Shiau Chan (LKKAUTO)
Subject: Re: RE: RE: RE: SLS5482S Estimate

Dear Mdm,

Accept with thanks, the LOD who do i send it to?

Warmest Regards,

C. S. ONG AUTO PTE. LTD.

Blk 10, Ang Mo Kio Ind Park 2A,
#02-16 AMK AutoPoint, Singapore 568047
Tel: 6484 1933 | Fax: 6484 1922
E-Mail: csongauto@yahoo.com.sg

On Tuesday, 21 August 2018, 2:58:26 PM GMT+8, Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear Sir/Madam,

WITHOUT PREJUDICE

Offer final fig \$5,773.15 and 5 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: C. S. ONG AUTO PTE. LTD. <csongauto@yahoo.com.sg>
Sent: Thursday, 2 August 2018 5:27 PM
To: SUR
Subject: SLS5482S Estimate
Attachments: csongauto@starhub.net.sg_20180802_164337.pdf

Dear Mdm,

Kindly refer to attach estimate marked by Mr Ma, Highlited items are parts changed but not marked by him. Thank you.

Warmest Regards,

C. S. ONG AUTO PTE. LTD.

Blk 10, Ang Mo Kio Ind Park 2A,
#02-16 AMK AutoPoint, Singapore 568047
Tel: 6484 1933 | Fax: 6484 1922
E-Mail: csongauto@yahoo.com.sg

Shiau Chan (LKKAUTO)

From: C. S. ONG AUTO PTE. LTD. <csongauto@yahoo.com.sg>
Sent: Tuesday, 7 August 2018 2:59 PM
To: SUR; Shiau Chan (LKKAUTO)
Subject: Re: RE: SLS5482S Estimate
Attachments: file3-2.jpeg; file8-1.jpeg; file15.jpeg; file1-5.jpeg; file12-1.jpeg; file-5.jpeg; file5-2.jpeg; file14.jpeg

Dear Mdm,

*"Dear Sir/Madam,
WITHOUT PREJUDISE
Offer Lump Sum \$3,200.00 before GST and 5 repair days.
Kindly confirm.*

*Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)"*

Kindly refer to attach photos, condenser, front brace panel, front headlight RH & LH side beam and also front support top cover have been replaced.
Also, according to the estimate, this is not a lump sum repair.

Below is our breakdown,

Parts: 4308.41
Labour: 1910
Total: 6218.41

Warmest Regards,

C. S. ONG AUTO PTE. LTD.

Blk 10, Ang Mo Kio Ind Park 2A,
#02-16 AMK AutoPoint, Singapore 568047
Tel: 6484 1933 | Fax: 6484 1922
E-Mail: csongauto@yahoo.com.sg

On Monday, 6 August 2018, 5:34:36 PM GMT+8, Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear Sir/Madam,

WITHOUT PREJUDISE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6437W
Vehicle Details	
Vehicle No.:	SLS5482S
Vehicle to be Exported:	No
Intended De-registration Date:	02 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA HYBRID 1.5X CVT
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	1NZR536151
Chassis No.:	NHP1707094179
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$24,578.00
Original Registration Date:	27 Sep 2017
First Registration Date:	27 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Sep 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	26 Sep 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,001.00
COE Rebate Amount:	\$32,940.00
Total Rebate Amount:	\$36,690.00

The information contained herein is correct as at 02 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/12/2017 11:24
Date Of Accident	15/12/2017 20:20
Exact Location Of Accident	WOODLANDS DRIVE 50, B/897B CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS5482S
Insured/Policyholder	
Name Of Registered Owner	LEE THIAM KWEE (COMPANY)
Co Reg No	53336437W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97334580

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA HYBRID 1.5X CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094466506 CLASSIC
Cover Note Number	

Driver

Name of Driver	LEE THIAM KWEE (LI TIANGUI)
NRIC No	S7145217D
Date Of Birth	08/12/1971
Occupation	OUTDOOR
Date Of Driving Pass	04/09/1999
Driving Experience	18 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97334580
Fax Number	
Contact Number	
Email Address	NOEMAIL

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

3. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: kakib@singnet.com.sg

Name:

NRIC/FIN No.:

Policyholder's Signature:

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

R. S. K.

16 DEC 2011

sur@ikrauto.com

Att: Mr 16/01/18

C. S. ONG AUTO PTE. LTD.

Company & GST Reg No.: 201408916W
10, Ang Mo Kio Ind. Park 2A, #02-16, AMK AutoPoint, Singapore (568047)
Tel: 6484 1933 | Fax: 6484 1922
E-Mail: csongauto@yahoo.com.sg

To: Motor Claims Department,
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Date: 18/12/2017

Accident Involving Vehicles SLS5482S & SJH1230K [Your Insured] 15/12/2017 @
2020HRS at Woodlands Dr 50, B/897B Carpark

Estimated Repair Costs For SLS5482S Toyota Sienta (1.5 Hybrid CVT) Chassis No. NHP1707094179

1 Pc	Front Windscreen with Moulding	N/C	ava	✓	\$ 1,672.30	
1 Pc	Front Bonnet	642.70	1358.00	✓	\$ 660.00	bt
2 Pcs	Front Bonnet Hinge LH and RH @ \$69.90 per pc	69.70	70.00	✓	\$ 139.80	bt
1 Pc	Front Bonnet Lock	133.70	77.60	✓	\$ 159.00	bt
1 Pc	Front Bumper	327.20		✓	\$ 409.80	det.
1 Set	Front Bumper Clips			✓	\$ 35.00	h/c
2 Pc	Front Bumper Side Retainer LH and RH @ \$64.70 per pc			✓	\$ 129.40	dis
1 Pc	Front Chrome Grille	668.60	380	✓	\$ 847.60	dis
2 Pcs	Front Bumper Bracket RH and LH @ \$162.70 per pc			✓	\$ 325.40	NH
2 Pcs	Front Headlight RH and LH with Bracket (LED) @ \$3047 per pc			✓	\$ 6,094.00	mc
1 Pc	Front Bumper Reinforcement With Bracket			✓	\$ 390.60	mc
1 Pc	Toyota Logo (Blue Colour)			✓	\$ 85.60	over
1 Pc	Condenser	1336.60	1100.00	✓	\$ 1,398.80	BT
1 Pc	Front Brace Panel	146.80	147.60	✓	\$ 163.40	BT
2 Pcs	Front Headlight RH and LH Side Beam @ \$117.20 Each		079.50	✓	\$ 234.40	SCRV
1 Pc	Front Support Panel			✓	\$ 1,077.80	bt
1 Pc	Horn	114.20		✓	\$ 127.20	dis
1 Pc	Front Support Top Cover	143.20		✓	\$ 167.85	CRAV
1 Pc	Front Bumper Top Moulding Rubber	38		✓	\$ 109.20	mc
1 Pc	Front Radiator			✓	\$ 902.40	mc
Total:					\$ 15,129.25	
Parts Less 25%:					\$ 3,782.31	
Parts Total:					\$ 11,346.94	

Labour & MISC Charges

*To remove front windscreen and refit new windscreen

*No plate Front With Holder

Description

Amount

\$ 300.00 X

40.00 \$50 CRAV ✓

SLS 5682s. Affn: Ma 16/01/18.

* To remove damaged front portion, repair & replace all front damaged panels and all of the above items	1000. \$ 2,000.00
* To putty & re-spray new paintwork on all rear affected areas.	800. \$ 2,000.00
* To conduct a check on all wiring systems.	30 \$ 400.00
* To anti-rust all affected areas.	80 \$ 150.00
Labour & Charges Total:	\$ 4,550.00
Parts Total:	\$ 11,346.94
Labour & Charges Total:	\$ 4,550.00
Total Cost of Repair:	\$ 15,896.94
(Non inclusive of 7% GST)	

15946.94

Not Authorised
PLP Repair
Before paint Plaid
H&E Auto (M)
21/12/2017
(S w/ day)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17024129/DQD3N2

Date: 23/08/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3037111700
Claimant Vehicle No :	SLS5482S	Insured Vehicle No :	SJH1230K
Date of Loss:	15/12/2017	Nature of Claim:	TP
		Claim No:	SNM17D07161C02/0

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS5482S	Engine No:	1NZR536151
Make & Model:	TOYOTA SIENTA HYBRID, 1.5 X CVT (A)	Chassis No:	NHP1707094179
Reg. Date:	27/09/2017 (Man. Year: 2017)	Odometer:	19816 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,396.94	3,913.15	7,483.79	65.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,550.00	1,860.00	2,690.00	59.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	15,946.94	5,773.15	10,173.79	63.80
+ GST 7.00/7.00% (\$\$)	1,116.29	404.12	712.17	63.80
Nett Amount (\$\$)	17,063.23	6,177.27	10,885.96	63.80

INSPECTION

Date of Assignment:	19/12/2017	
Date Inspected:	20/12/2017 Inspected At:	C.s.ong Auto Pte. Ltd (HQ) BLK 10 ANG MO KIO IND PARK 2A #02-16 AMK AUTOPOINT Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2018)
Parts:	M1-MPV	TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS5482S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN WITH MOULDING (CRACKED)	Not Consistent With The Impact	1,672.30 FL	*- FL
2	1		*FRONT BONNET	Bent	660.00 FL	*642.20 FL
3	2		*FRONT BONNET HINGE LH AND RH	Bent	139.80 FL	*131.40 FL
4	1		*FRONT BONNET LOCK	Bent	159.00 FL	*133.20 FL
5	1		*FRONT BUMPER	Deformed	409.80 FL	*327.20 FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
7	2		*FRONT BUMPER SIDE RETAINER LH AND RH	Distorted	129.40 FL	*129.40 FL
8	1		*FRONT CHROME GRILLE	Distorted	847.60 FL	*668.60 FL
9	2		*FRONT BUMPER BRACKET RH AND LH	Not Necessary	325.40 FL	*- FL
10	2		*FRONT HEADLIGHT RH AND LH WITH BRACKET (LED)	Serviceable	6,094.00 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT WITH BRACKET	Serviceable	390.60 FL	*- FL
12	1		*TOYOTA LOGO (BLUE COLOUR)	Cracked	85.60 FL	*85.60 FL
13	1		*CONDENSER	Bent	1,398.80 FL	*1,336.60 FL
14	1		*FRONT BRACE PANEL	Bent	163.10 FL	*146.80 FL
15	2		*FRONT HEADLIGHT RH AND LH SIDE BEAM	Scratched	234.40 FL	*155.00 FL
16	1		*FRONT SUPPORT PANEL	Bent	1,077.80 FL	*1,077.80 FL
17	1		*HORN	Distorted	127.20 FL	*114.20 FL
18	1		*FRONT SUPPORT TOP COVER	Distorted/Cracked	167.85 FL	*143.20 FL
19	1		*FRONT BUMPER TOP MOULDING RUBBER	Necessary	109.20 FL	*38.00 FL
20	1		*FRONT RADIATOR	Serviceable	902.40 FL	*- FL
21	1		*FRONT NO PLATE WITH HOLDER	Cracked	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,179.25	5,204.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,782.31	1,291.05
Total Parts (\$\$)	11,396.94	3,913.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE FRONT WINDSCREEN AND REFIT NEW WINDSCREEN	New	300.00	-
2	TO REMOVE DAMAGED FRONT PORTION,REPAIR & REPLACE ALL FRONT DAMAGED PANELS AND ALL OF THE ABOVE ITEMS	New	2,000.00	1,000.00
3	TO PUTTY & RE-SPRAY NEW PAINTWORK ON ALL REAR AFFECTED AREAS	New	2,000.00	800.00
4	TO CONDUCT A CHECK ON ALL WIRING SYSTEMS	New	100.00	30.00
5	TO ANTI-RUST ALL AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (S\$)			4,550.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >