

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5845K -**AAD1712-162***Not Authorised**Penalty B4 points*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5845K - CANDY

VF1ABL15AUC281422

RENAULT

LATITUDE

17.12.2017

*AAA***PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>B</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>T</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>CM</i> 113.47 ✓
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>S</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>S</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61 ✓
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>S</i> 135.97 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>S</i> 44.99 X
9	1	BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61 ✓
10	1	BUMPER BEAM REAR	\$	<i>B</i> 777.52 ✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>B</i> 225.95 ✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>B</i> 225.95 ✓
13	1	BOOT REAR	\$	<i>B</i> 2,872.68 ✓
14	1	BOOT FINISHER	\$	<i>S</i> 470.06 X
15	1	BOOT WHEATERSTRIP	\$	<i>CM</i> 323.05 ✓
16	1	BOOT REFLECTOR LAMP LH	\$	<i>N</i> 493.35 ✓
17	1	BOOT REFLECTOR LAMP RH	\$	<i>N</i> 493.35 ✓
18	1	BOOT BADGE 'RENAULT'	\$	<i>N</i> 225.36 ✓
19	1	BOOT BADGE	\$	<i>N</i> 225.36 ✓
20	1	BOOT STRUT LH	\$	<i>S</i> 276.08
21	1	BOOT STRUT RH	\$	<i>S</i> 276.08
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84
24	1	BOOT INNER TRIM	\$	<i>S</i> 586.45
25	1	BOOT SWITCH	\$	<i>S</i> 168.13
26	1	BOOT LOCK	\$	<i>R</i> 202.67
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2	LICENCE PLATE LAMP	\$	<i>S</i> 50.52
29	2	BOOT RUBBER PLUG	\$	<i>S</i> 221.81
30	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>S</i> 671.45
31	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13
32	1	WHEELARCH REAR LH	\$	<i>S</i> 543.47
33	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>S</i> 671.45
34	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13

X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-162**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5845K -

35	1	WHEELARCH REAR RH	\$	<i>Sn</i> 543.47	X
36	1	TAILLAMP RH	\$	<i>ngent</i> 552.55	✓
37	1	TAILLAMP PANEL RH	\$	<i>n</i> 986.70	X
38	1	TAILLAMP LH	\$	<i>ngent</i> 552.55	✓
39	1	TAILLAMP PANEL LH	\$	<i>n</i> 986.70	X
40	1	OUTER PANEL REAR (End Panel)	\$	<i>Bj</i> 1,471.77	✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>nd</i> 404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>Bj</i> 2,189.88	✓
43	1	SPARE WHEEL PANEL TRIM	\$	<i>Sn</i> 612.21	X
44	1	EXHAUST REAR	\$	7,489.05	?
45	1	EXHAUST CAP REAR	\$	<i>nir</i> 230.49	✓

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Specical Nett

1	1SET	PARKING AID	\$	<i>Shart</i> 700.00	✓
2	1SET	REAR BUMPER CLIP	\$	<i>na</i> 66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	<i>Sn</i> 17.82	X
11	1SET	BOOT FINISHER CLIP	\$	<i>na</i> 24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	<i>na</i> 30.00	✓
13	1	BOOT STICKER "6555-3333"	\$	<i>na</i> 30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	<i>na</i> 45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	<i>na</i> 35.00	X
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>na</i> 35.00	X
17	1	FENDER INNER TRIM CLIP LH	\$	<i>na</i> 28.00	X
18	1	FENDER INNER TRIM CLIP LH	\$	<i>na</i> 28.00	X
19	1	TAILLAMP CLIP RH	\$	<i>na</i> 5.00	✓
20	1	TAILLAMP CLIP LH	\$	<i>na</i> 5.00	✓
21	2	REAR WINDSCREEN SELANT	\$	<i>na</i> 80.00	X
22	1	WINDSCREEN MOULDING	\$	<i>na</i> 100.00	X
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00	X
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>Sn</i> 385.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-162**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5845K -

25	1	SPARE TYRE	\$	<i>330.00 X</i>
----	---	------------	----	-----------------

TOTAL	\$	2,225.02
TOTAL PARTS	\$	34,507.07

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>1100</i>
---	----	----------------------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>1200</i>
---	----	----------------------

To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>90</i>
---	----	------------------

To reinstall rear bumper parking sensor.	\$	170.00 <i>60</i>
--	----	------------------

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>60</i>
--	----	------------------

To repair and realign rear exhaust pipe.	\$	170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00

} 60

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00

} 60

To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 <i>80</i>
--	----	------------------

To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>380.00 X</i>
---	----	-----------------

Towing Fees	\$	<i>120.00 X</i>
-------------	----	-----------------

To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>170.00 X</i>
---	----	-----------------

To check steering geometry and computer wheel alignment	\$	<i>220.00 X</i>
---	----	-----------------

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-162

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5845K -

TOTAL	\$	11,160.00
Over All Total	\$	45,667.07

(PARTS BY PARTS)**Repair Days**~~15 Days~~

10 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: