

ASS. REC. BY:

REF: CS/TMU 7024134/Klgbs

Special Instruction:

Surveyor: Kalvin

ASSIGNMENT (Office)

From (Person): Maimun

Zheng Hengyung

of

TMC

Date/Time: 20.12.2017 1.51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 7012U

Insured:

SJH 8663Z

at Workshop m/s

Comfort Delgro

Tel:

6214 8315

of

51 Loyang Drive

Policy No:

MI000805

Claim No:

M170 6418

Sum Insured:

Excess:

Make of Veh:

D.O.A

19.12.17

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

20.12.2017 2.25pm

Person Contacted:

Jumari

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHA 7012U - (CS / MI15013495 / Klgbs)	DA: 060815
	SJH 8663Z - x	

Signature Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SHA 70124 Yr Regn: 31 May 2011
 Type: M.Car / M.Cycle / Bus / Van / Lorry / T@ / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai Sonata cc: 199
 Colour: Blue A.C. Insured / Std / NI / NA
 Sp. Reading: 218157 T. Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMHET41VMBA 811586
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / Stb A/Rim or _____
 Tyre Size: F: 215/60R16
 R: _____

N/S	O/S

(Policy Condition)
 Remark: **The veh had commenced its repair at the time of inspection.**
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? Yes or No
 GIA / PR Seen: _____ Consistent? Yes or No
 Est. Repairs: 2 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Wet/Le
 Front: _____ Rear: _____
 R.Bal: 7 mm R.Bal: 7 mm
 L.Bal: 7 mm L.Bal: 7 mm
 D.O.A. 19/12/12 D.O.I. 20/12/12
 Survey held at: CDAC (10723)
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
26/12/12 a continued L/S \$1250 / 2 Pys. (Paid \$ 9987.70, 44%) to Kri / L/S.

RECEIVED 6 2011

Date/Time File Pass to? : Preli. Report
26/12/12 : Final Report
 Date/Time File Return to?
 Report Format: MCR-TP
 Lump Sum / I.B.K. \$: 1250

Days Of Repair: 2
 Resurvey No. of Trip: 1
 Add Fee: Site Insp \$
 Interview \$
 Tech Insp \$
 Weekend \$

Survey Fee	250
Transportation	
L.S. + P.S. (\$)	
Photos	
Total	10

Survey Department Check List (Case Handler)

Reference No.: CY/TMI/7074134/Klgjb
 Policy Type: OD (TP) / TP RES / TL / EVA

SHA 70120

Case Handler

Typist

Admin (Cash): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

	Y-Date	N-Date	Y-Date	N-Date
C Reference No.	✓			
C Customer Code	✓			
N Assign From	✓			
C Assign Date	✓			
C Veh No (Inspected)	✓			
C Veh No (Insured)	✓			
C D.O.A	✓			
C Policy No	✓			
C Claim No	✓			
C Insurance Authorisation (CA /REV/REP)	✓			
C Report Type	✓			
C Weekend Charges	✓			
N Survey held at/Repairer	✓			
C Excess				

Surveyor (Kalvin): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C Vehicle No	✓			
C Regn Month/Year	✓			
N Vehicle Type	✓			
N Make & Model	✓			
C Engine Capacity. (C.C)	✓			
N Colour	✓			
C Odometer. (Sp.Reading)	✓			
C Chassis No	✓			
N General Condition	✓			
N Steering	✓			
N Brake	✓			
N Modification (Modi)	✓			
C Tyre Size	✓			
N Tyre Make	✓			
C Tyre Balance	✓			
C Date of Inspection	✓			
N Survey held	✓			
N Des.of Damages	✓			

(2) System - (Views/Merimen)

C Damaged Vehicle Photographs Uploaded

(3) Workshop Estimate/Assignment Form

N ALL Parts condition
 C Market Value for OD cases
 C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
 C Days of repair
 C Finalised Amount
 C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

C Resurvey photo Uploaded

Check By: Cash 26/12/17
Case Handler Date



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD Ref : CS/TMI17024134/K1qb

20 MCCALLUM STREET #09-01
TOKIO MARINE CENTRESINGAPORE 069046

Date : 20-12-2017



Code : TMI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 8663Z	Veh. Inspected	SHA 7012U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (ZHENG HANYANG)	Assign Date	20/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	19/12/2017	Inspection Date	20/12/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Dec 2017 10:37 Sendback Est	20 Dec 2017 10:56 S\$2,248.72	20 Dec 2017 13:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CTPL, Co. Reg. No.: 199303821R		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHA7012U	Date of Loss:	19/12/2017 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SJH8663Z	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Zheng Hanyang - 65926416]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/01/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/12/2017 08:51
Date Of Accident	19/12/2017 23:55
Exact Location Of Accident	GUILLEMARD ROAD X SLIP ROAD OF SIMS WAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7012U
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0016
Cover Note Number	

Driver

Name of Driver	LIM KIM YONG (LIN JINRONG)
NRIC No	S7322436E
Date Of Birth	27/06/1973
Occupation	OUTDOOR
Date Of Driving Pass	26/09/2002
Driving Experience	15 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86126464
Fax Number	
Contact Number	
E Mail Address	KIMLENG156@HOTMAIL.COM

Address	156 11-218 HOUGANG STREET 11
Postcode	530156
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : -
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH8663Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT RHT


No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	IM KIM YONG (LIN JINRONG)
Approximate Age	44
Injuries Sustain	BACK,NECK
Injured person in which vehicle?	SHA7012U
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: SHA 70124
 B: SJH 86637

As
 attached

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Lim Eo Soon
 CSO

SHA 7012 U

- ACCIDENT STATEMENT

Yesterday near to mid-night hours (19/12/2017), a male Chinese boarded my taxi at Orchard Road for a trip to Lorong 8 Geylang.


As seen in the video footage, it was green light in my direction when I reached the junction from Nicoll Highway and as such, I travelled straight across the junction to Guillemard Road.

While I was proceeding towards Lorong 8, Geylang, my taxi was suddenly hit into by car B(SJH 8663Z), a Mazda, amid exiting the slip road of Sims Way into Guillemard Road.

The impact inflicted damage to the left rear portion of my taxi while the front of car B sustained dents,

While my passenger was not hurt, I felt pains behind my back, neck and body following the accident and I intended to seek medical attention.



I affirmed the above-statement is true and correct.






Driver name : Lim Kim Yong
NRIC NO : S 7322436E
Date: 20/12/2017

Recorded by Alex Lim









Team: IN ARC Repair TP(CLSO)1

JOB CARD Sales Order: 3791323

JC NO:305099497

CUSTOMER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO: SHA7012U	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL: SONATA	DATE/TIME IN: 20.12.2017 06:08
	YR OF MANU: 31.05.2011	TARGET DATE
	CHASSIS CODE: KMHE141VMB811540	COMPLETION DATE/TIME

SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 19.12.2017
 NATURE: 3P 19.12.17

S/NO	LABOR CODE	DESCRIPTION
000	23-01	TOWING FEE

CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Vehicle No.: SHA7012U
 Description: JU TOKIO LKK

Exit-Pass

Vehicle No.: SHA7012U

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Jumani

Singapore

*Masudin***PARTICULARS OF CLAIM**

Claim Type: THIRD PARTY	Ref. No:	
Policy No:	Date of Loss:	19/12/2017
Vehicle Reg. SHA7012U	Driveable?	YES
No.:		
Party At UNKNOWN		
Fault:		
Make/Model: HYUNDAI SONATA, 2.0 CRDI (A)	Vehicle Reg. Date:	31/05/2011
Vehicle BLUE	Gen Condition:	GOOD
Colour:		
Engine No: D4EAB965835	Chassis No:	KMHET41VMBA811540
Odometer: 0 KM		
Paint Type:		
List Item 20.00 %		
Discount:		
Total Loss? NO		
Est. 4		
Duration of Repair (day)		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)	

COST OF CLAIMS	Amount
Parts	938.72
Miscellaneous Items	10.00
Labour	1,300.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,248.72
+ GST 7.00% (S\$)	157.41
Nett Amount (S\$)	2,406.13

This claim is handled by: JUMANI MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Dec 2017)
 Parts: 143 HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: **ComfortDelGro Engineering Pte Ltd/SHA7012U/20/12/2017 10:56**
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY xxxxxx / <i>behind</i>	20.00	0.00	*578.40 FL
2	10		*REAR BUMPER CLIPS <i>x 11</i>	20.00	0.00	*22.00 FL
3	1		*REAR FENDER MUDFLAP LH <i>+ see</i>	20.00	0.00	*15.50 FL
4	1		*REAR WHEEL HUP CAP LH <i>grated</i>	20.00	0.00	*145.00 FL
5	1		*REAR BUMPER MAT <i>see</i>	0.00	0.00	*50.00 F
6	1		*REAR FENDER COMFORT STICKER LH <i>see</i>	0.00	0.00	*30.00 F
7	2		*REAR FENDER ADVERTISEMENT LOGO LH/RH <i>see</i>	0.00	0.00	*200.00 F
8	1		*REAR BUMPER ADVERTISEMENT LOGO <i>see</i>	0.00	0.00	*50.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,090.90
- List Item Discount on L Items (S\$)	152.18
Total Parts (S\$)	938.72

ComfortDelGro Engineering Pte Ltd/SHA7012U/20/12/2017 10:56. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	560.00
2	SPRAYPAINT	New	400.00
3	WIRING	New	50.00
4	REMOVE/REFIX REVERSE SENSOR	New	120.00
5	REAR WHEEL ALIGNMENT	New	120.00
6	TOWING (Not accident location)	New	50.00
Gross Labour Cost (S\$)			1,300.00

ComfortDelGro Engineering Pte Ltd/SHA7012U/20/12/2017 10:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Kalan 10/1/14
 ✓ 20/12/17 11:15 hrs
 20/17
 4/5
 After Repair photo.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition		
1. Date: <u>20/12/17</u> Time Received: <u>0608</u> 2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer : _____ Contact No. : <u>8612 6464</u> Vehicle No. : <u>SHA702U</u> Make / Model / Colour : <u>Sonata</u> Email : _____	3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)	4. Type of Towing: <input type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up
7. Location: <u>156 Hongkong St 11</u>	5. Nature of Service: <input type="checkbox"/> Jumpstart <input type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery	6. Parts Replaced/Remarks: _____ _____
9. Preferred Workshop: <input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Senoko <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others: _____	8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi	
10. Odometer Reading : _____ Fuel Level : <input type="checkbox"/> F <input type="checkbox"/> 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> E	11. Radio / CD Player <input type="checkbox"/> OK <input type="checkbox"/> Faulty <input type="checkbox"/> Not tested	 #: Cracked X: Dented /: Scatched O: Missing _____ Signature of Customer
Job Attended		
12. Tow Truck / Recovery Van : <input type="checkbox"/> VRS <input checked="" type="checkbox"/> QA <input type="checkbox"/> GAO <input type="checkbox"/> TZ <input type="checkbox"/> YISHUN <input type="checkbox"/> OTHERS TOWING Name of Driver : <u>SAW</u> Vehicle No. : <u>YN39761</u> Time Dispatch : <u>0609</u> Time of Arrival : <u>0625</u> Time Completed : <u>0700</u>		
Cash Invoice Details (if applicable)		
13. Cash Invoice No. : _____		
Customer Acknowledgement		
a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses. c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.		
<u>20/12/17</u> Date	<u>0625</u> Time	_____ Signature of Customer
14. WORKSHOP		
_____ Name of Attending Staff/Guard	_____ Date & Time of Arrival	_____ Signature of Attending Staff/Guard

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508999
Fax: 6546 8156

Our Job Ref No : 305099497

Date : 23/17/221

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHA7012U

Date of Accident : 19/12/2017

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO --- SJH8663Z
###
2. The finalized amount shall be:

(a) Spare Parts after List discount		
(b) Labour Charges	###	
Total for Part-By-Part Repair Cost		
(c.) Lumpsum Repair (if applicable)		
Total for Lumpsum repair cost after Less: <u>20%</u>		<u>\$1,250.00</u>
Final Lumpsum Repair cost		

3. Estimated normal period for repairs: 2 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : [Signature]

Name : JUMANI

Tel : 6214 8315

Fax : 65468156

Signature : [Signature]

Name : Kaha

Date : 26/12/17

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee		7.49		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Dec 2017 Sendback Est	20 Dec 2017 10:56 S\$2,248.72	20 Dec 2017 13:51 Edit Adj Rpt	S\$1,250.00 Edit Estimates	S\$1,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS	
Insured:	SF LEASING PTE LTD, Co. Reg. No.: 201623564D
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R
Vehicle Reg. No.:	SHA7012U
Claim Type:	TP / M1706418
Vehicle Reg. No. (Insured):	SJH8663Z
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Zheng Hanyang - 65926416]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 02/01/2018]
Date of Loss:	19/12/2017 00:00 - :59
Policy/Cover Note No.:	MI000805 (Comprehensive) Coverage: 11/05/2017 - 10/05/2018
Policy No. (Claimant):	
Excess:	S\$2,000.00

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

SHA7012U (M1706418)
 [SJH8663Z]
 TP
COMFORT TRANSPORTATION PTE LTD
 Dec 19 2017 12:00AM
 [SF LEASING PTE LTD]
 ComfortDelGro Engineering Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View Use Viewer ▼	
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print		
1	20/12/17 10:56	Repairer Estimates		Load HTM	<input checked="" type="checkbox"/>		
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
2	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
3	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
4	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
5	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
6	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
7	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
8	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
9	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
10	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
11	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
12	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
13	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
14	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
15	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
16	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
17	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
18	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
19	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
20	20/12/17 16:56	General View		Load JPG	<input checked="" type="checkbox"/>		
21	22/12/17 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
22	22/12/17 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
23	22/12/17 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
24	22/12/17 17:24	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>		
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print		
1	20/12/17 10:57	E-filed GIA report		Load PDF	<input checked="" type="checkbox"/>		

Documents Checklist

Reset	Save	Print
DOCUMENTS CHECKLIST		
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer. <small>Note: Remarks are private unless you show it to other parties.</small>		

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI17024134/K1QBS2

Date: 27/12/2017

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MI000805
Claimant Vehicle No :	SHA7012U	Insured Vehicle No :	SJH8663Z
Date of Loss:	19/12/2017	Nature of Claim:	TP
		Claim No:	M1706418

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA7012U	Engine No:	D4EAB965835
Make & Model:	HYUNDAI SONATA, 2.0 CRDI (A)	Chassis No:	KMHET41VMBA811540
Reg. Date:	31/05/2011 (Man. Year: 2011)	Odometer:	218157 km
Colour:	Blue		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	938.72	908.72	30.00	3.20
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	1,300.00	660.00	640.00	49.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,248.72	1,578.72	670.00	29.79
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	2,248.72	1,250.00	998.72	44.41
+ GST 7.00/7.00% (S\$)	157.41	87.50	69.91	44.41
Nett Amount (S\$)	2,406.13	1,337.50	1,068.63	44.41

INSPECTION

Date of Assignment:	20/12/2017 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	20/12/2017 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2017)
Parts: 143	HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA7012U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount	
1	1	*REAR BUMPER ASSY	Deformed	578.40 FL	*578.40 FL	
2	10	*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL	
3	1	*REAR FENDER MUDFLAP LH	Serviceable	15.50 FL	*- FL	
4	1	*REAR WHEEL HUP CAP LH	Grazed	145.00 FL	*145.00 FL	
5	1	*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F	
6	1	*REAR FENDER COMFORT STICKER LH	Necessary	30.00 F	*30.00 F	
7	2	*REAR FENDER ADVERTISEMENT LOGO LH/RH	Necessary	200.00 F	*200.00 F	
8	1	*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 F	*50.00 F	
				Sub Total (S\$)	1,090.90	1,053.40
				- List Item Discount on L Items 20.00/20.00% (S\$)	152.18	144.68
				Total Parts (S\$)	938.72	908.72

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (\$\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	560.00	300.00
2	SPRAYPAINT	New	400.00	360.00
3	WIRING	New	50.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	120.00	0.00
5	REAR WHEEL ALIGNMENT	New	120.00	0.00
6	TOWING	New	50.00	0.00
Gross Labour Cost (\$\$)			1,300.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >