

Submitted by: Marcus ASSIGNMENT OFFICER

Prepared by: Irene Tan MSIG

Date: 2012/17 @ 9:50am

Estimated Cost: _____ Bill to: _____

OD: TRWS / IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP1886C Insured: SLC982H

at Workshop in: Pegasus Engineering Tel: 68581846

of: 51 Defu Lane 10

Policy No: MSD/VCC/17-000024 Claim No: MSC/V/17-001952

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 16/12/17
(Client's Record)

CA / REV / REP. / REV 24 HRS wp!

Date/Time: 11:07am @ 2012/17 Person Contacted: Alvin H.O.D. Enclosed: _____
Vehicle IN OUT

Date/Time: _____ Action/Instruction: (✓) Estimate

SLP1886C -

SLP982H - CC4/AXA17024035/U903 D.O.A: 16/12/17

7/17/17 @ 4.15pm revised to Irene Tan via Meimen.

SYDNEY *perous*

REF:

MS16/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *SL1/1886C*
 at Workshop m/s: *perous*
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: *SL1/1886C* Yr Regn: *15 17*
 Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or *CA/*
 Make: *Toyota* UIC No: *1496*
 Colour: *Grey* A.O. Insured / Std / NI / NA
 Sp. Reading: *25716* T.Radio: Insured / Std / NI / NA
 Eng.No: _____
 C/No: *MHFB29F3202009817*
 Gen. Cond: *Good* / Fair / Poor / Burnt
 Steering: *None* / Jammed / Leaked / Burnt or
 Brake: *None* / Jammed / Leaked / Burnt or
 Modi: *Nil* / S/Rim / STD A/Rim or
 Tyre Size: F: *195/50R15*
 R: _____
6 ST/DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 CA / PR Seen: *2* Consistent? : Yes or No
 Est. Repairs: *7* days Res.: Yes or No
 Lump Sum: *15* % 3 Val.: Yes or No

Front _____ Rear _____
 R/Bal. *7* mm R/Bal. *7* mm
 L/Bal. _____ mm L/Bal. *7* mm
 D.O.A. *16/12/17* D.O.I. *20/12/17*
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Rear
 The UIC / Chassis frame / Body Structure affected due to collision.

CA / REV / REP. / 24 HRS _____
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT _____

28/12/17 Repair sum *\$5300* confirmed with Sen.
 Note: new parts replacement. *the narrative*
(Paid @ 8481.50, 62%)

RECEIVED 2018 12 29

Date/Time: File Pass to? : Preli. Report
29/12/17 : Final Report
 Date/Time: File Return to? _____

Days Of Repair: *7*
 Resurvey No. of Trip: *1*

Add Fee: Site Insp \$
 Interview \$
 Tech. Ins \$
 Weekend \$

Survey Fee	<i>300</i>
Transportation	
Photo	<i>10</i>
Other	
TOTAL	<i>310</i>

Report Format: *MARK TP*
 Lump Sum / I.B.I. \$ *5300*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17024138/Uqd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 20-12-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 982H	Veh. Inspected	SLP 1886C
Policy No.	MSD/VCC/17-000024	Coverage (\$)	0.00
Claim No.	MSCN/17-001952	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	20/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/12/2017	Inspection Date	20/12/2017
Survey held at	51 DEFU LANE 10		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Dec 2017		20 Dec 2017 09:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	CAR CLUB PTE LTD, Co. Reg. No.: 200912077G								
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLP1886C	Date of Loss:	16/12/2017 22:00 - :59						
Claim Type:	TP / MSC/V/17-001952	Policy/Cover Note No.:	MSD/VCC/17-000024 (Comprehensive) Coverage: 01/01/2017 - 31/12/2017						
Vehicle Reg. No. (Insured):	SLC982H	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/12/2017]								
Driver/Custodian (Insured):	MUHAMMAD NAZERUL BIN ZULKEPLI (/ Male), NRIC: S8636765C								
Adj Asg. Remarks:	Please assign to Marcus Chua								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Tan Jin Hao

From: Pegasus Engineering <claims@pegasusengrg.com.sg>
Sent: Wednesday, 20 December, 2017 9:15 AM
To: Tan Jin Hao; Claims
Subject: Re: Third Party Survey - SLP1886C Your Insured -SLC982H D.O.A - 16.12.2017

Without prejudice

Dear Jin Hao,

We select Marcus Chua to survey our client vehicle.

Thanks & Regards,

Alvin Low
-WL

Pegasus Engineering & Trading Pte Ltd
51 Defu Lane 10
Singapore 539216

Tel : 6858 1846
Fax : 6487 6070
Email : claims@pegasusengrg.com.sg

On Tue, Dec 19, 2017 at 2:46 PM, Tan Jin Hao <jinhao_tan@sg.msig-asia.com> wrote:

WITHOUT PREJUDICE

Dear Alvin,

We are appointing M/s LKK Auto Consultants Pte Ltd to be the SJE (Single Joint Expert) . Please be informed that our surveyor will also be conducting the post repair inspection within the timeline stipulated under the protocol.

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the surveyors listed below as the SJE, depending on their availability:

- | | |
|-------------------|-------------------|
| 1. Adrian Ling | 6. Frankie Pang |
| 2. Kenneth Kong | 7. Ng You Han |
| 3. Marcus Chua | 8. Gary Soon |
| 4. Henry Ng | 9. Chow Bo Xiong |
| 5. Lau Kwok Kwong | 10. Benjamin Chua |

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case any of our nominated SJE is not available.

If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre-repair survey within the timeline stipulated under the NIMA Protocol

Have A Great Week Ahead!

Tan Jin Hao

Admin Officer, Claims Services (Motor)

Direct line [+65 6594 2583](tel:+6565942583) | Direct fax [+65 6225 7402](tel:+6562257402) | jinhao_tan@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: [+65 6220 9644](tel:+6562209644) | F: [+65 6225 6371](tel:+6562256371) | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Pegasus Engineering [<mailto:claims@pegasusengrg.com.sg>]

Sent: Monday, 18 December, 2017 7:35 PM

To: Claims <claims@sg.msig-asia.com>

Subject: Third Party Survey - SLP1886C Your Insured -SLC982H D.O.A - 16.12.2017

Without Prejudice

Dear Sir/Mdm,

We refer to the above matter.

We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair.

Pursuant to paragraph 6.2 of Pre-Action Protocol for NIMA Cases, please let us know within 2 working days whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

In addition, please confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

We await for your favourable reply.

Please provide us the list of surveyors.

Thanks & Regards,

Alvin Low

-WL

Pegasus Engineering & Trading Pte Ltd
51 Defu Lane 10
Singapore 539216

Tel : 6858 1846

Fax : 6487 6070

Email : claims@pegasusengrg.com.sg

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 21 Dec 2017

Preliminary Advice

Insured Vehicle No	: SLC982H	Accident Date	: 16/12/2017
TP Vehicle No	: SLP1886C	Assignment Date	: 20/12/2017
Make	: TOYOTA VIOS	Est. Duration of Repair	: 7.00
Date of Inspection	: 20/12/2017		
Inspection At	: PEGASUS ENGINEERING & TRADING PTE LTD (HQ) 51 DEFU LANE 10 SINGAPORE 539216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,781.50
Revised Amount	:S\$	6,187.58
Check Items (Estimated)	:S\$	993.68
Total	:S\$	7,181.26

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	7200G

Vehicle Details

Vehicle No.	SLP1886C
Vehicle to be Exported	Yes
Intended De-registration Date	18 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	VIOS 1.5E CVT
Primary Colour	Grey
Manufacturing Year	2017
Engine No.	2NRX145315
Chassis No.	MHFB29F3202009817
Maximum Power Output	79.0 kW (105 bhp)
Open Market Value	\$12,946.00
Original Registration Date	29 May 2017
First Registration Date	29 May 2017
Transfer Count	0
Actual ARF Paid	\$7,946.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	28 May 2027
PARF Rebate Amount	\$5,959.00

Intended COE Rebate Details

COE Expiry Date	28 May 2027
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$51,600.00
COE Rebate Amount	\$41,280.00
Total Rebate Amount	\$47,239.00

The information contained herein is correct as at 18 Dec 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/12/2017 12:59
Date Of Accident	16/12/2017 22:20
Exact Location Of Accident	UPPER CHANGI ROAD EAST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP1886C
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	MTGRAB20171595
Driver	
Name of Driver	PANG KAH YIT
NRIC No	S7970645J
Date Of Birth	30/12/1979
Occupation	OUTDOOR
Date Of Driving Pass	28/11/2002
Driving Experience	15 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83239595
Fax Number	
Contact Number	
EMail Address	APKIYS@GMAIL.COM

Address BLOCK 114 HO CHING ROAD
#02-76
Postcode 610114
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

Refer to Police Report: - T/20171217/7010

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLC982H
Vehicle Make/Model/Colour MAZDA 3
Details Of Properties SALOON CAR
Name of Driver MUHAMMAD NAZERUL BIN ZULKEPLI
NRIC/Passport Number
Contact Number 8299 4761
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGN7971U
Vehicle Make/Model/Colour HYUNDAI
Details Of Properties SALOON CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF INJURED PERSON 1

Name PANG KAH YIT
Approximate Age 37
Injuries Sustain
Injured person in which vehicle? SLP1886C
Were seat belts worn? YES
Was injured conveyed to hospital by ambulance? NO
Address BLOCK 114 HO CHING ROAD
#02-76
Postcode 610114

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time: 18/12/2017 1330h



Reporting Centre Personnel's Signature
Name: Lim Wai Shun
NRIC/FIN No.: G6864052R

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to police report: - 7/2017/17/7010

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Lam Wai Shun
NRIC/FIN No.: G6864052K

17/02/2017 13:30

18/2/2017 13:30

Police Report Pg. 1



**SINGAPORE
POLICE FORCE**



T/20171217/7010

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4
Report No. T/20171217/7010

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/12/2017 22:26	Vide Report No.: G/20171216/0270	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars			
Name of Informant: PANG KAH YIT		Address: APT BLK 114 HO CHING ROAD #02-76 SINGAPORE 610114	
ID Type / ID No.: NRIC NO / S7970645J		Contact No.: Home/Office: Mobile: 83239595	
Nationality: SINGAPORE CITIZEN		Email: apkiys@gmail.com	
Sex: Male	Age: 37	Date of Birth: 30/12/1979	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Other car and light goods vehicle drivers nec		Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 16/12/2017 22:20	Type of Location: T-Junction
Location: UPPER CHANGI ROAD EAST Upper Changi Road East towards TPE/Expo direction, after Bedok Road junction but before Simei Ave/Xilin Ave junction, directly above canal at the small traffic light T-junction.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SGN7971U	Car	KIA				0
SLC982H	Car	MAZDA				0
SLP1886C	Car	TOYOTA	Vios			1

Police Report Pg. 2



**SINGAPORE
POLICE FORCE**



T/20171217/7010

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 4
Report No. T/20171217/7010

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	Unknown Passenger	ID No.	NIL
Related Vehicle	SLP1886C (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	PANG KAH YIT	ID No.	S7970645J
Related Vehicle	SLP1886C (Car)	Contact No.	83239595
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 16/12/17 at about 2220 hrs, I was fetching a grabcar passenger to Pasir-Ris in my vehicle when my vehicle (SLP1886C) came to a halt at the above-mentioned T-junction. I was the first vehicle at the traffic light T-junction while waiting for traffic light to change in my favour to move. Suddenly I heard a loud bang behind and shortly after, I felt my vehicle jerked forward and I suffered a mild whiplash from the impact. I then disembarked from my vehicle and proceeded to check with my passenger on her condition. She also suffered slight physical shock from the impact but mentioned that she felt fine at that time.

After that I proceeded to check on the nature of the accident, of which a third vehicle, vehicle no. SGN7971U driven by Mr. Sim Poh Choon (Shen Baojun) (NRIC No. S7825556J) has crashed into the second vehicle, vehicle no. SLC982H driven by Mr. Muhammad Nazerul Bin Zulkepli (NRIC No. S8636765C) behind my vehicle, resulting in vehicle SLC982H to rear-end into my vehicle SLP1886C. Upon further check I found Mr. Muahmmad Nazerul's wife suffered injuries, as well as driver Mr. Sim Poh Choon. I proceeded to call 999 for ambulance and police assistance.

The Police came and Report:G/20171216/0270 was lodged. The Police also advised me to lodge a NP168.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20171217/7010

3 of 4

Report No. T/20171217/7010

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20171217/7010

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

4 of 4

Report No. T/20171217/7010

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable
Signature Of Interpreter: Not applicable
Officer In Charge Of Case:

Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Date/Time: 17/12/2017 22:26
Classification Of Case:

Authentication Stamp
NP168



Messrs Grab Rentals Pte Ltd

Estimate To Repair Toyota Vios 1.5E CVT
 Vehicle No : SLP1886C
 Chassis No : MHFB29F3202009817

*Not About
 here
 Take photo before repair
 7 days
 20/12/17*

Email on 18/12/17
 1930hrs

Third Party Insurer : MSIG
 Insured's Veh No : SLC982H
 Date of accident : 18.12.2017

Date : 18.12.2017

*Letk - Marcus
 20/12/2017*

Pages : 1 of 2

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	bootlid <i>B. d. s. m</i>	\$ 762.47	\$ 762.47
2	1 pc	bootlid lock <i>7m</i>	\$ 90.40	\$ 90.40
3	1 pc	bootlid lock stricker <i>nee</i>	\$ 18.50	\$ 18.50
4	1 pc	bootlid weatherstrip <i>7m</i>	\$ 188.80	\$ 188.80
5	2 ps	bootlid hinges <i>n</i>	\$ 79.80	\$ 159.60
6	1 pc	bootlid Vios badge <i>nee</i>	\$ 44.10	\$ 44.10
7	1 pc	bootlid E badge <i>nee</i>	\$ 39.40	\$ 39.40
8	1 pc	bootlid centre logo badge <i>nee</i>	\$ 59.80	\$ 59.80
9	1 pc	bootlid outer garnish <i>wasap</i>	\$ 164.70	\$ 164.70
10	1 pc	bootlid outer key lock <i>11</i>	\$ 198.70	\$ 198.70
11	1 pc	bootlid inner trim cover <i>11</i>	\$ 398.10	\$ 398.10
12	6 ps	bootlid inner trim cover clips <i>11</i>	\$ 4.30	\$ 25.80
13	3 ps	bootlid lock cable clips <i>11</i>	\$ 4.30	\$ 12.90
14	3 ps	bootlid wire harness clips <i>11</i>	\$ 4.30	\$ 12.90
15	2 ps	front licence plate lamps <i>11</i>	\$ 79.80	\$ 159.60
16	1 pc	rear end panel <i>30 d. s. m</i>	\$ 694.70	\$ 694.70
17	1 pc	rear end panel inner trim <i>7m</i>	\$ 234.30	\$ 234.30
18	3 ps	rear end panel inner trim clips <i>nee</i>	\$ 4.30	\$ 12.90
19	2 ps	rear lamps <i>n/s one o/s s/w</i>	\$ 375.80	\$ 751.60
20	4 ps	rear lamp clip holders <i>11</i>	\$ 9.50	\$ 38.00
21	2 ps	rear lamp panels <i>n</i>	\$ 238.90	\$ 477.80
22	1 pc	rear bumper <i>dis</i>	\$ 504.90	\$ 504.90
23	1 pc	rear bumper reinforcement <i>dis</i>	\$ 323.00	\$ 323.00
24	2 ps	rear bumper side retainer <i>but</i>	\$ 116.30	\$ 232.60
25	2 ps	rear bumper side holders <i>but</i>	\$ 22.30	\$ 44.60
26	2 ps	rear bumper reflectors <i>n/s s/w</i>	\$ 130.50	\$ 261.00
27	10 ps	rear bumper clips <i>nee</i>	\$ 4.30	\$ 43.00
28	1 pc	o/s rear fender <i>n</i>	\$ 969.70	\$ 969.70
29	1 pc	o/s rear fender inner cowling <i>11</i>	\$ 395.10	\$ 395.10
30	10 ps	o/s rear fender inner cowling clips <i>11</i>	\$ 4.50	\$ 45.00
31	1 pc	o/s rear fender air vent <i>11</i>	\$ 45.10	\$ 45.10
32	1 pc	rear luggage floor panel <i>n</i>	\$ 678.70	\$ 678.70
33	2 ps	rear luggage floor side compartment foam <i>o/s s/w</i>	\$ 75.00	\$ 150.00
34	1 pc	spare tyre cardboard <i>70.11</i>	\$ 145.00	\$ 145.00
35	1 pc	spare tyre fastener clamp <i>11</i>	\$ 29.80	\$ 29.80
Balance C/F				\$ 8,412.57

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



Messrs Grab Rentals Pte Ltd

Estimate To Repair **Toyota Vios 1.5E CVT**
 Vehicle No : **SLP1886C**
 Chassis No : **MHFB29F3202009817**

WKA Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To identify damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No extra modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Third Party Insurer : **MSIG**
 Insured's Veh No : **SLC982H**
 Date of accident : **16.12.2017**
 Date : **18.12.2017**

Pages : 2 of 2

S/No	Quantity	Description	Unit price	Amount
		Balance B/F		\$ 8,412.57
		LIST ITEMS		
36	1 pc	rear exhaust box <i>n</i>	\$ 638.80	\$ 638.80 <i>27</i>
37	1 pc	rear exhaust box mount <i>n</i>	\$ 78.90	\$ 78.90 <i>27</i>
38	1 pc	rear exhaust box heat shield <i>n</i>	\$ 46.60	\$ 46.60 <i>27</i>
				\$ 9,176.87
		Less 20% <i>25%</i>		\$ 1,835.37
				\$ 7,341.50
		SPECIAL NETT ITEMS		
39	1 pc	rear licence plate <i>set</i>	\$ 80.00	\$ 80.00 <i>42</i>
40	1 set	rear bumper parking sensor <i>set</i>	\$ 450.00	\$ 450.00 <i>20</i>
41	1 pc	rear windscreen glass sealant <i>n</i>	\$ 180.00	\$ 180.00 <i>X</i>
42	1 pc	rear windscreen glass inner sponge seal <i>n</i>	\$ 100.00	\$ 100.00 <i>X</i>
43	1 pc	rear luggage floor panel insulation <i>n</i>	\$ 280.00	\$ 280.00 <i>27</i>
				\$ 1,090.00
		LABOUR & MISC. CHARGES		
1		Towing charges.	<i>50</i>	\$ 80.00
2		To reinstall of rear bumper parking sensor.	<i>50</i>	\$ 150.00
3		To remove and refit rear windscreen glass.	<i>n x</i>	\$ 180.00
4		To rust-proofing of the affected areas.	<i>80</i>	\$ 220.00
5		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	<i>n x</i>	\$ 550.00
6		To transfer of bootlid fittings, attachments and perform water seepage test.	<i>60</i>	\$ 150.00
7		To drop rear exhaust box and renew the same.	<i>60</i>	\$ 160.00
8		To check electrical lighting concerned.	<i>20</i>	\$ 60.00
9		To check steering geometry and computer wheel alignment.	<i>n x</i>	\$ 150.00
10		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	<i>80</i>	\$ 150.00
11		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	<i>1200</i>	\$ 1,900.00
12		Putty and spray painting of the affected portion.	<i>1000</i>	\$ 1,600.00
				\$ 5,350.00
		Grand Total	<i>2840</i>	\$ 13,781.50

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Dec 2017		20 Dec 2017 09:50 Edit Adj Rpt	S\$5,300.00 Edit Estimates	S\$5,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	CAR CLUB PTE LTD, Co. Reg. No.: 200912077G		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLP1886C	Date of Loss:	16/12/2017 22:00 - :59
Claim Type:	TP / MSC/V/17-001952	Policy/Cover Note No.:	MSD/VCC/17-000024 (Comprehensive) Coverage: 01/01/2017 - 31/12/2017
Vehicle Reg. No. (Insured):	SLC982H	Policy No. (Claimant):	
		Excess:	S\$2,000.00
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 19/01/2018]		
Driver/Custodian (Insured):	MUHAMMAD NAZERUL BIN ZULKEPLI (/ Male), NRIC: S8636765C		
Adj Asg. Remarks:	Please assign to Marcus Chua		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS											View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?					
No results.														

Claim Documents

***SLP1886C (MSC/V/17-001952)**
[SLC982H]

TP
GRAB RENTALS PTE LTD
Dec 16 2017 10:00PM
[CAR CLUB PTE LTD]
Pegasus Engineering & Trading Pte Ltd

Upload Documents | Upload Photos | Compose New Letter | **View**

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/12/17 15:09	Accident Statement From:SC - Reg. No: SLC982H, Claimant: CAR CLUB PTE. LTD.	Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/12/17 16:15	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/12/17 17:56	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	20/12/17 17:56	General View	Load JPG	<input checked="" type="checkbox"/>
3	20/12/17 17:57	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
4	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
5	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
6	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
7	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
8	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
9	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
10	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
11	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
12	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
13	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
14	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
15	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
16	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
17	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
18	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
19	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
20	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
21	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
22	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
23	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
24	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
25	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
26	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
27	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
28	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
29	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>
30	20/12/17 17:57	General View	Load JPG	<input checked="" type="checkbox"/>

					<input checked="" type="checkbox"/>
31	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
32	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
33	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
34	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
35	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
36	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
37	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
38	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
39	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
40	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
41	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
42	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
43	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
44	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
45	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
46	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
47	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
48	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
49	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
50	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
51	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
52	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
53	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
54	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
55	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
56	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
57	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
58	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
59	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
60	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
61	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
62	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
63	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
64	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
65	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
66	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
67	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
68	20/12/17 17:57	General View		Load JPG	<input checked="" type="checkbox"/>
69	29/12/17 09:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
70	29/12/17 09:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
71	29/12/17 09:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
72	29/12/17 09:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
73	29/12/17 09:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
74	29/12/17 09:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
75	29/12/17 09:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
76	29/12/17 09:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
77	29/12/17 09:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
78	29/12/17 09:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
79	29/12/17 09:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

80	29/12/17 09:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
81	29/12/17 09:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
82	29/12/17 09:56	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	19/12/17 15:09	TP GIA REPORT- SLP1886C From:SC - Reg. No: SLC982H, Claimant: CAR CLUB PTE. LTD.		Load PDF	
2	19/12/17 15:10	TP estimate		Load PDF	
3	20/12/17 09:51	Email from TP agree SJE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p style="text-align: right;"> </p> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17024138/UQD3E2

Date: 04/01/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VCC/17-000024
Claimant Vehicle No :	SLP1886C	Insured Vehicle No :	SLC982H
Date of Loss:	16/12/2017	Nature of Claim:	TP
		Claim No:	MSCV/17-001952

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP1886C		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	2NRX145315
Reg. Date:	29/05/2017 (Man. Year: 2017)	Chassis No:	MHFB29F3202009817
Colour:	Grey	Odometer:	25716 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,431.50	3,660.20	4,771.30	56.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,350.00	2,600.00	2,750.00	51.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,781.50	6,260.20	7,521.30	54.58
Approved Total (Overridden) (S\$)		5,300.00		
	(S\$)	13,781.50	5,300.00	8,481.50
	+ GST 7.00/7.00% (S\$)	964.71	371.00	593.71
	Nett Amount (S\$)	14,746.21	5,671.00	9,075.21

INSPECTION

Date of Assignment:	20/12/2017	
Date Inspected:	20/12/2017 Inspected At:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10 Singapore 539216
Estimated Period of Repair:	7.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2018)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLP1886C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Badly Dented	762.47 FL	*762.47 FL
2	1		*BOOTLID LOCK	Twisted	90.40 FL	*90.40 FL
3	1		*BOOTLID LOCK STRIKER	Necessary	18.50 FL	*18.50 FL
4	1		*BOOTLID WEATHERSTRIP	Twisted	188.80 FL	*188.80 FL
5	2		*BOOTLID HINGES	Repair	159.60 FL	*- FL
6	1		*BOOTLID VIOS BADGE	Necessary	44.10 FL	*44.10 FL
7	1		*BOOTLID E BADGE	Necessary	39.40 FL	*39.40 FL
8	1		*BOOTLID CENTRE LOGO BADGE	Necessary	59.80 FL	*59.80 FL
9	1		*BOOTLID OUTER GARNISH	Warped	164.70 FL	*164.70 FL
10	1		*BOOTLID OUTER KEY LOCK	Not Necessary	198.70 FL	*- FL
11	1		*BOOTLID INNER TRIM COVER	Not Necessary	398.10 FL	*- FL
12	6		*BOOTLID INNER TRIM COVER CLIPS	Not Necessary	25.80 FL	*- FL
13	3		*BOOTLID LOCK CABLE CLIPS	Not Necessary	12.90 FL	*- FL
14	3		*BOOTLID WIRE HARNESS CLIPS	Not Necessary	12.90 FL	*- FL
15	2		*FRONT LICENCE PLATE LAMPS	Not Necessary	159.60 FL	*- FL
16	1		*REAR END PANEL	Badly Dented	694.70 FL	*694.70 FL
17	1		*REAR END PANEL INNER TRIM	Twisted	234.30 FL	*234.30 FL
18	3		*REAR END PANEL INNER TRIM CLIPS	Necessary	12.90 FL	*12.90 FL
19	2		*REAR LAMPS	N/S Cracked / O/S Broken	751.60 FL	*751.60 FL
20	4		*REAR LAMP CLIP HOLDERS	Not Necessary	38.00 FL	*- FL
21	2		*REAR LAMP PANELS	Repair	477.80 FL	*- FL
22	1		*REAR BUMPER	Distorted	504.90 FL	*504.90 FL
23	1		*REAR BUMPER REINFORCEMENT	Distorted	323.00 FL	*323.00 FL
24	2		*REAR BUMPER SIDE RETAINER	Bent	232.60 FL	*232.60 FL
25	2		*REAR BUMPER SIDE HOLDERS	Bent	44.60 FL	*44.60 FL
26	1		*REAR BUMPER REFLECTORS	O/S Broken	261.00 FL	*130.50 FL
27	10		*REAR BUMPER CLIPS	Necessary	43.00 FL	*43.00 FL
28	1		*O/S REAR FENDER	Repair	969.70 FL	*- FL
29	1		*O/S REAR FENDER INNER COWLING	Not Necessary	395.10 FL	*- FL
30	10		*O/S REAR FENDER INNER COWLING CLIPS	Not Necessary	45.00 FL	*- FL
31	1		*O/S REAR FENDER AIR VENT	Not Necessary	45.10 FL	*- FL
32	1		*REAR LUGGAGE FLOOR PANEL	Repair	678.70 FL	*- FL
33	1		*REAR LUGGAGE FLOOR SIDE COMPARTMENT FOAM	O/S Torn	150.00 FL	*75.00 FL
34	1		*SPARE TYRE CARDBOARD	Torn	145.00 FL	*145.00 FL
35	1		*SPARE TYRE FASTENER CLAMP	Not Necessary	29.80 FL	*- FL
36	1		*REAR EXHAUST BOX	Repair	638.80 FL	*- FL
37	1		*REAR EXHAUST BOX MOUNT	Not Necessary	78.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*REAR EXHAUST BOX HEAT SHIELD	Not Necessary	46.60 FL	*- FL
39	1		*REAR LICENCE PLATE	Bent	80.00 FS	*40.00 FS
40	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS
41	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	180.00 FS	*- FS
42	1		*REAR WINDSCREEN GLASS INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
43	1		*REAR LUGGAGE FLOOR PANEL INSULATION	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,266.87	4,800.27
- List Item Discount on L Items 20.00/25.00% (\$\$)	1,835.37	1,140.07
Total Parts (\$\$)	8,431.50	3,660.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES	New	80.00	50.00
2	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	150.00	50.00
3	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
4	TO RUST-PROOFING OF THE AFFECTED GLASS	New	220.00	80.00
5	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND PARALLEL MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	New	550.00	0.00
6	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	150.00	60.00
7	TO DROP REAR EXHAUST BOX AND RENEW THE SAME	New	160.00	60.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	150.00	0.00
10	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	New	150.00	80.00
11	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	1,900.00	1,200.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	1,000.00
Gross Labour Cost (\$\$)			5,350.00	2,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >