



Signature

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

4

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time | Action / Instruction

US \$2,250.00

(RED. \$1,500.00 / 57%)

Veh No: \_\_\_\_\_

SGL 3007R

Yr Regn: \_\_\_\_\_

11/9/2006

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: \_\_\_\_\_

Honda Civic

CC

1575

Colour \_\_\_\_\_

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading \_\_\_\_\_

243474

T/Radio:

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

JHMP0962065200051

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size: \_\_\_\_\_

F:

205/55R16

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Bridgestone

Front

Rear

R/Bal. \_\_\_\_\_

6

mm

R/Bal. \_\_\_\_\_

6

mm

L/Bal. \_\_\_\_\_

6

mm

L/Bal. \_\_\_\_\_

6

mm

D.O.A. \_\_\_\_\_

11/12/17

D.O.I. \_\_\_\_\_

12/3/18

Survey held at \_\_\_\_\_

ARC

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: \_\_\_\_\_

☐

Site Insp (\$

) \$+RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Copies

☐

Weekend (\$

) TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQI17024141/hb3

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEXSINGAPORE 069110

Date : 20-12-2017



Code : EQI

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	GBF 7723X	Veh. Inspected	SGL 3007R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/12/2017

**2. Vehicle Particulars & Condition**

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

**4. Description of Damages**

--	--

**5. General Information**

Accident Date	16/12/2017	Inspection Date	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

11 CHIO AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref: To Be Advised  
Our ref: CC6/EQI17024141/Shb3

Date: 14.03.2018

The Motor Claims Department  
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SGL3007R**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12.03.2018 at the premises of M/s Automotive Repair Centre Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,600.00
Revised Estimate Amount	: S\$	3,090.00
"Check" Items Amount	: S\$	60.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the  
N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

SEBASTIAN YEANG  
Licensed Appraiser

38 Woodlands Industrial Park E1  
#05-18, Singapore 757700  
Tel: 64688834 Fax: 64622278  
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1712-110  
DATE : 20-Dec-2017  
POLICY NO. : NTUC 5023299260-10  
VEHICLE REG. NO. : SGL3007R  
VEHICLE MAKE :

TO Motor Claim Department  
EQ Insurance Company Limited  
22 Gemmill Lane, Singapore 069257  
Tel: 6223 9433  
Fax: 6224 3903

FOR SURVEYOR

### ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<b>SPARE PARTS</b>				
1	Rear Bumper ✓ CRE	1	\$ 680.00	\$ 680.00
2	Rear Bumper Clips ✓ NEC	10	\$ 5.00	\$ 50.00
3	Rear Retainer LH ✓ NEC	1	\$ 30.00	\$ 30.00
4	Rear Door Protector LH ✓ NEC	1	\$ 120.00	\$ 120.00
5	Rear Door Protector Chrome Trim LH ✓ NEC	1	\$ 30.00	\$ 30.00
6	Rear Fender Mud Flap LH ✓ NW	1	\$ 60.00	\$ 60.00
7	Rear Tail Lamp LH ✓ CRE	1	\$ 240.00	\$ 240.00
8	Side Mirror LH ✓ DMG	1	\$ 580.00	\$ 580.00
Total Spare Parts				\$ 1,790.00
<b>SPECIAL NETT</b>				
Total Special Nett				\$ -
<b>LABOUR</b>				
9	S-painting Rear Bumper, Rear Fender LH, Sill LH and 2 Doors LH	1	\$ 1,000.00	\$ 1,000.00
10	Repair, Replace and Refill Affected Accident Area	1	\$ 600.00	\$ 600.00
11	Repair and Respray Rear Rim LH	1	\$ 100.00	\$ 100.00
12	Wheels Computer Alignment / Wheel Balancing	1	\$ 80.00	\$ 80.00
13	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,810.00
Amount Before Excess				\$ 3,600.00
Add GST @ 7%				252.00
Total Amount Payable				\$ 3,852.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.

Sebastian  
12/3/18  
- Lnp Sun Repair  
- Photo After Paint.  
90036121  
sebastianjeang@kkauto.com

4 days

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Vic (LKKAUTO)

---

**From:** Vic (LKKAUTO)  
**Sent:** Thursday, 11 October, 2018 11:26 AM  
**To:** raymond@automotiverepaircentre.com.sg  
**Cc:** 'Lin Shu Juan'; Admin A; Vic (LKKAUTO)  
**Subject:** RE: SGL3007R - TP Claim against GBF7723X \*\*\*LKK REF:CC6/EQI17024141/Shb3  
**Attachments:** My Movie.mp4

Without Prejudice

Dear Raymond,

We refer to your below email and to our telephone conversation earlier.

Please be informed that our principal had further reviewed the matter.

Our principal is in the view that our insured is not liable of the accident in view that your client has forced its way towards our Insured's path twice without due care (see attached footage).

As such, we were instructed by our principal to deny you client's claim.

We will now close this matter in or end.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** raymond@automotiverepaircentre.com.sg [mailto:raymond@automotiverepaircentre.com.sg]  
**Sent:** Friday, 10 August, 2018 9:46 AM  
**To:** Vic (LKKAUTO)  
**Cc:** 'Lin Shu Juan'; Admin A  
**Subject:** RE: SGL3007R - TP Claim against GBF7723X \*\*\*LKK REF:CC6/EQI17024141/Shb3

Dear Vic,

Any update from your principle EQ Insurance Company on the liability detail before we can issue our LOD and other support documents for the claim. We wished to close this case (pending close 9 months) soonest as possible.

## Vic (LKKAuto)

---

**From:** Janet Tan <janet.tan@eqinsurance.com.sg>  
**Sent:** Thursday, 11 October, 2018 11:12 AM  
**To:** Vic (LKKAuto)  
**Cc:** Admin A; Justin Wong  
**Subject:** RE: Direct Settlement - Accident Involving GBF7723X (OI : EQI - DM17HO02864/JT) AND SGL3007R (TP : LKK REF - CC6/EQI17024141/hb3) on 16.12.2017  
**Attachments:** My Movie.mp4

Dear Vic

Please proceed to reject claim.

Regards,

**Janet Tan**  
Senior Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)

 A Member of Citystate

*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.*

---

**From:** Vic (LKKAuto) [mailto:vicalpeh@lkkauto.com]  
**Sent:** Thursday, October 11, 2018 10:41 AM  
**To:** Janet Tan <janet.tan@eqinsurance.com.sg>  
**Cc:** Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Justin Wong <justin.wong@eqinsurance.com.sg>  
**Subject:** RE: Direct Settlement - Accident Involving GBF7723X (OI : EQI - TBA) AND SGL3007R (TP : LKK REF - CC6/EQI17024141/hb3) on 16.12.2017

Dear Janet,

We refer to our below email,

For your approval and/or further instructions please.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Vic (LKKAuto)

**Sent:** Monday, 16 July, 2018 4:53 PM

**To:** Janet Tan

**Cc:** Admin A; Vic (LKKAuto)

**Subject:** RE: Direct Settlement - Accident Involving GBF7723X (OI : EQI - TBA) AND SGL3007R (TP : LKK REF - CC6/EQI17024141/hb3) on 16.12.2017

**Your Ref:** TBA

**Our Ref:** CC6/EQI17024141/Shb3

Dear Janet,

We refer further to our below email.

TP driver reported on his report that he was driving along when he heard a bang on his vehicle and realised that Insured vehicle had hit his rear left corner.

Insured driver reported that he was driving along Scotts Road at the leftmost lane when he found that TP vehicle cut into his lane from the right, so the Insured driver had tried to avoid, when suddenly, TP vehicle came ahead and purposely hit his vehicle while he is making a right lane change due to a bus ahead of him.

We had spoken to the Insured's PIC on the update of their claim against TP insurer, but till date, no update yet was provided by their repairer. We were also provided with a copy of the Insured's video footage. Please refer to the attached footage for your reference.

We are of the view that our Insured driver is not totally at fault for this matter. TP driver had forced it's way to our Insured's lane twice.

As such, we intend to reject the TP claim.

For your approval and/or further instructions please.

Thank you.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Shu Pei (LKKAuto)

**Sent:** Wednesday, 14 March, 2018 5:52 PM

**To:** Janet Tan

**Cc:** Vic (LKKAuto)

**Subject:** RE: Direct Settlement - Accident Involving GBF7723X (OI : EQI - TBA) AND SGL3007R (TP : LKK REF - CC6/EQI17024141/hb3) on 16.12.2017

**WITHOUT PREJUDICE**

Dear Janet,

We refer to the above matter.

We had inspected TP vehicle SGL 3007R at M/s Automotive Repair Centre Pte Ltd.

Enclosed for your perusal is:

- Preliminary advice
- Estimated cost of repair

Thank you.

Best Regards,

**Shu Pei** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Janet Tan [<mailto:janet.tan@eqinsurance.com.sg>]

**Sent:** Wednesday, 20 December 2017 5:20 PM

**To:** Shu Pei (LKKAuto) <[shupeil@lkkauto.com](mailto:shupeil@lkkauto.com)>

**Cc:** Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>

**Subject:** FW: Direct Settlement - Accident Involving GBF7723X (OI : EQI - TBA) AND SGL3007R (TP : LKK REF - CC6/EQI17024141/hb3) on 16.12.2017

Dear Shu Pei

OI report as attached.

Regards,

**Janet Tan**

Senior Executive | Claims



**EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg



A Member of Citystate



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of*

**From:** Shu Pei (LKKAuto) [mailto:shupe@lkkauto.com]

**Sent:** Wednesday, December 20, 2017 3:59 PM

**To:** Janet Tan <janet.tan@eqinsurance.com.sg>

**Cc:** Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

**Subject:** Direct Settlement - Accident Involving GBF7723X (OI : EQI - TBA) AND SGL3007R (TP : LKK REF - CC6/EQI17024141/hb3) on 16.12.2017

**WITHOUT PREJUDICE**

Dear Janet,

We refer to the above matter.

This is a TP direct settlement case from M/s Automotive Repair Centre Pte Ltd.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair

Please be informed that preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

• **Joy Irene (LKKAuto)**

---

**From:** Joy Irene (LKKAuto)  
**Sent:** Friday, 22 December, 2017 1:53 PM  
**To:** 'edelsteel@gmail.com'  
**Cc:** Vic (LKKAuto)  
**Subject:** ACCIDENT INVOLVING GBF 7723X AND SGL 3007R ON 16/12/2017

CC6/EQI17024141/hb3

**EDELSTEEL ENGINEERING PTE LTD**

Policy holder

ATTENTION: Ms. Ivy (Office-in-Charge)

Dear Madam,

**ACCIDENT INVOLVING GBF 7723X AND SGL 3007R ON 16/12/2017**

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6749-5792 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC6/EQ117024141/Shb3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 24-10-2018		
		Code : EQ1		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBF 7723X	Veh. Inspected	SGL 3007R	
Policy No.	DMCPHQ17-001662	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CIVIC	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JHMFD46206S200051	Colour	SILVER	
Odometer	243474	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	16/12/2017	Inspection Date	12/03/2018	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGL 3007R**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	CRACKED	680.00	680.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	30.00
1	REAR RETAINER LH	NECESSARY	30.00	30.00
1	REAR DOOR PROTECTOR LH	NECESSARY	120.00	120.00
1	REAR DOOR PROTECTOR CHROME TRIM LH	NECESSARY	30.00	30.00
1	REAR FENDER MUD FLAP LH	NOT NECESSARY	60.00	-
1	REAR TAIL LAMP LH	CRACKED	240.00	240.00
1	SIDE MIRROR LH	DAMAGED	580.00	580.00
	LESS 10% DISCOUNT		-	-171.00
			1,790.00	1,539.00
	<b><u>LABOUR</u></b>			
	S-PAINTING REAR BUMPER, REAR FENDER LH, SILL LH AND 2 DOORS LH.		1,000.00	800.00
	REPAIR, REPLACE AND REFILL AFFECTED ACCIDENT AREA.		600.00	400.00
	REPAIR AND RESPRAY REAR RIM LH.		100.00	80.00
	WHEELS COMPUTER ALIGNMENT /WHEEL BALANCING.		80.00	70.00
	CHECK AND RECTIFY ELECTRICAL WIRING.		30.00	30.00
			1,810.00	1,380.00
	<b>GRAND TOTAL</b>		<b>3,600.00</b>	<b>2,919.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,250.00</b>

Report Ref No. CC6/EQ117024141/Shb3q2

**YEANG WAI KEEN**

Automotive Assessor

**HO LEONG CHUAN**

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.