

ARC

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1712-110
DATE : 20-Dec-2017
POLICY NO. : NTUC 5023299260-10
VEHICLE REG. NO. : SGL3007R
VEHICLE MAKE :

TO Motor Claim Department
EQ Insurance Company Limited
22 Gemmill Lane, Singapore 069257
Tel: 6223 9433
Fax: 6224 3903

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper ✓ CRE	1	\$ 680.00	\$ 680.00
2	Rear Bumper Clips ✓ NEC	10	\$ 5.00	\$ 50.00
3	Rear Retainer LH ✓ NEC	1	\$ 30.00	\$ 30.00
4	Rear Door Protector LH ✓ NEC	1	\$ 120.00	\$ 120.00
5	Rear Door Protector Chrome Trim LH ✓ NEC	1	\$ 30.00	\$ 30.00
6	Rear Fender Mud Flap LH ✓ CRE	1	\$ 60.00	\$ 60.00
7	Rear Tail Lamp LH ✓ CRE	1	\$ 240.00	\$ 240.00
8	Side Mirror LH ✓ DMG	1	\$ 580.00	\$ 580.00
Total Spare Parts				\$ 1,790.00
SPECIAL NETT				
Total Special Nett				\$ -
LABOUR				
9	S-painting Rear Bumper, Rear Fender LH, Sill LH and 2 Doors LH	1	\$ 1,000.00	\$ 1,000.00
10	Repair, Replace and Refill Affected Accident Area	1	\$ 600.00	\$ 600.00
11	Repair and Respray Rear Rim LH	1	\$ 100.00	\$ 100.00
12	Wheels Computer Alignment / Wheel Balancing	1	\$ 80.00	\$ 80.00
13	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,810.00
Amount Before Excess				\$ 3,600.00
Add GST @ 7%				252.00
Total Amount Payable				\$ 3,852.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.

Parts : \$ 1416
Labour : \$ 1380

2796

Lump Sum -20%

2236.80

4/5 : \$ 2250

Sebastian
12/3/18
- Lump Sum Repair
- Photo After Paint
90036121
sebastianj@kkauto.com

4 days

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: