

Automotive Repair Centre Pte Ltd CO. Reg. No.: 201312913C GST Reg. No.: 201312913C

Estimate

38 Woodlands Industrial Park E1 #05-18, Singapore 757700 Tel: 64688834 Fax: 64622278

> Motor Claim Department **EQ Insurance Company Limited** 22 Gemmill Lane, Singapore 069257

Tel: 6223 9433 Fax: 6224 3903

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. :

EST1712-110

DATE:

20-Dec-2017

POLICY NO. :

NTUC 5023299260-10

VEHICLE REG. NO. :

SGL3007R

VEHICLE MAKE:

FOR SURVEYOR

 			_

ESTIMATE REPAIR COST

10.	DESCRIPTION	QUANTITY	UNIT COST		TOTAL COST	
	SPARE PARTS					
1	Rear Bumper V CRK	1	\$	680.00	\$	680.00
2	Rear Bumper Clips ✓ №€ <	10	\$	5.00	\$	50:00
3	Rear Retainer LH VNF.c	1	\$	30.00	\$	30.00
4	Rear Door Protector LH ✓ NEC	1	\$	120.00	\$	120.00
5	Rear Door Protector Chrome Trim LH ✓ NEC	1	\$	30.00	\$	30.00
6	Rear Fender Mud Flap LH 1.	1	\$	60.00	\$	60.00
7	Rear Tail Lamp LH VCRL.	1	\$	240.00	\$	240.00
8	Side Mirror LH V DMG.	1	\$	580.00	\$	580.00
			Total Sp	are Parts	\$	1,790.00
	SPECIAL NETT				ATTE	
					131	
			Total Sp	ecial Nett	\$	5.05
	LABOUR		Total Sp	ecial Nett	\$	
9	LABOUR S-painting Rear Bumper, Rear Fender LH, Sill LH and 2 Doors LH	1	Total Sp	ecial Nett 1,000.00	\$	1,000,00
9		1 1				1,006-20
	S-painting Rear Bumper, Rear Fender LH, Sill LH and 2 Doors LH	-	\$	1,000.00	\$	
10	S-painting Rear Bumper, Rear Fender LH, Sill LH and 2 Doors LH Repair, Replace and Refill Affected Accident Area	1	\$	1,000.00	\$	600-00
10	S-painting Rear Bumper, Rear Fender LH, Sill LH and 2 Doors LH Repair, Replace and Refill Affected Accident Area Repair and Respray Rear Rim LH	1	\$ \$ \$	1,000.00 600.00 100.00	\$ \$ \$	600-00
10 11 12 13	S-painting Rear Bumper, Rear Fender LH, Sill LH and 2 Doors LH Repair, Replace and Refill Affected Accident Area Repair and Respray Rear Rim LH Wheels Computer Alignment / Wheel Balancing	1 1 1	\$ \$ \$ \$ \$	1,000.00 600.00 100.00 80.00	\$ \$ \$	699-Q0 .109-Q0 80:9Q
10 11 12 13 stima	S-painting Rear Bumper, Rear Fender LH, Sill LH and 2 Doors LH Repair, Replace and Refill Affected Accident Area Repair and Respray Rear Rim LH Wheels Computer Alignment / Wheel Balancing Check and rectify electrical wiring te prepared by: Raymond Tan ove is an estimate based on our inspection and does not cover any	1 1 1 1 1 Am	\$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ Tota	1,000.00 600.00 100.00 80.00 30.00	\$ \$ \$ \$ \$	600-Q0 .100-Q0 80:0Q 30.00
10 11 12 13 stima	S-painting Rear Bumper, Rear Fender LH, Sill LH and 2 Doors LH Repair, Replace and Refill Affected Accident Area Repair and Respray Rear Rim LH Wheels Computer Alignment / Wheel Balancing Check and rectify electrical wiring te prepared by: Raymond Tan	1 1 1 1 1 Am	\$ \$ \$ \$ \$ \$ Tota	1,000.00 600.00 100.00 80.00 30.00 I Labour	\$ \$ \$ \$ \$	600-Q0 .100-Q0 80:60 30.00 1,810.00

Please arrange this vehicle to be surveyed soones upossible. Thank Make notify

Sebastian 12/3/18. - Lup Sun Repeir. - Photo After Paint. 90036121

sebastiony early @lkkauto.com.

Page 1 of 1

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during recurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resulveyed and is subject to final approval from insurance Company

Acknowledged by Repairer Signature:

Date:

4days.