

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1712-110

DATE : 20-Dec-2017

POLICY NO. : NTUC 5023299260-10

VEHICLE REG. NO. : SGL3007R

VEHICLE MAKE :

TO Motor Claim Department
EQ Insurance Company Limited
 22 Gemmill Lane, Singapore 069257
 Tel: 6223 9433
 Fax: 6224 3903

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 680.00	\$ 680.00
2	Rear Bumper Clips	1	\$ 5.00	\$ 5.00
3	Rear Retainer LH	1	\$ 20.00	\$ 20.00
4	Rear Door Protector LH	1	\$ 120.00	\$ 120.00
5	Rear Door Protector Chrome Trim LH	1	\$ 25.00	\$ 25.00
6	Rear Fender Mud Flap LH	1	\$ 60.00	\$ 60.00
7	Rear Tail Lamp LH	1	\$ 240.00	\$ 240.00
Total Spare Parts				\$ 1,150.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
8	S-painting Rear Bumper, Rear Fender LH, Sill LH and 2 Doors LH	1	\$ 1,000.00	\$ 1,000.00
9	Repair, Replace and Refill Affected Accident Area	1	\$ 600.00	\$ 600.00
10	Repair and Respray Rear Rim	1	\$ 100.00	\$ 100.00
11	Wheels Computer Alignment / Wheel Balancing	1	\$ 80.00	\$ 80.00
12	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,810.00
Amount Before Excess				\$ 2,960.00
Add GST @ 7%				207.20
Total Amount Payable				\$ 3,167.20

Estimate prepared by: **Raymond Tan**

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.