

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kwee May

Date: 22 Dec 2017

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : SHD253X | Accident Date | : 14/12/2017 |
| TP Vehicle No | : SHC5694D | Assignment Date | : 21/12/2017 |
| Make | : RENAULT LATITUDE | Est. Duration of Repair | : 2 days |
| Date of Inspection | : 19/12/2017 | | |
| Inspection At | : Trans-Cab Auto Services Pte Ltd No.2 Ang Mo Kio St63 Singapore 569111 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesrear O/S..... portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 28,582.74 |
| Revised Amount | :S\$ | 3,976.94 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 3,976.94 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.