

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5694D -**AAD1712-149***Not Authored*
Resony B4 paint 83976.94

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5694D - CANDY

VF1ABL15AUC281559

RENAULT

LATITUDE

14.12.2017

AXA

PART			LIST	
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 —
2	1	BUMPER LOWER REAR	\$	<i>Adlwr</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99 X
6	1	BUMPER REFLECTOR RH	\$	<i>CN</i> 43.61 ✓
7	1	BUMPER BEAM REAR	\$	<i>Bu</i> 777.52 ✓
8	1	BUMPER BEAM BRACKET RH REAR	\$	<i>Bu</i> 225.95 ✓
9	1	BOOT REAR	\$	<i>R</i> 2,872.68
10	1	BOOT FINISHER	\$	<i>Sn</i> 470.06
11	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
12	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
13	1	BOOT BADGE 'RENAULT'	\$	<i>ru</i> 225.36
14	1	BOOT BADGE	\$	<i>ru</i> 225.36
15	1	BOOT SWITCH	\$	<i>Sn</i> 168.13
16	1	BOOT LOCK	\$	<i>R</i> 202.67
17	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40
18	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52
19	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81
20	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13
21	1	TAILLAMP RH	\$	<i>Sn</i> 552.55
22	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70
23	1	EXHAUST REAR	\$	<i>R</i> 7,489.05
24	1	EXHAUST CAP REAR	\$	<i>R</i> 230.49

TOTAL	\$	21,104.13
10%	\$	2,110.41
	\$	18,993.72

Specical Nett

1	1SET	PARKING AID	\$	<i>Sham</i> 700.00 ✓
2	1SET	REAR BUMPER CLIP	\$	<i>ru</i> 66.00 —
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>ru</i> 33.00 —

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5694D -**AAD1712-149**

4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>nn</i>	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>nn</i>	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>nn</i>	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>nn</i>	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i>	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	<i>nn</i>	17.82	} X
11	1SET	BOOT FINISHER CLIP	\$	<i>nn</i>	24.20	
12	1	BOOT STICKER "Trans-cab"	\$	<i>nn</i>	30.00	
13	1	BOOT STICKER "6555-3333"	\$	<i>nn</i>	30.00	
14	1	TAILLAMP CLIP RH	\$	<i>nn</i>	5.00	
15	2	REAR WINDSCREEN SELANT	\$	<i>nn</i>	80.00	
16	1	WINDSCREEN MOULDING	\$	<i>nn</i>	100.00	
17	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	} X
18	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>nn</i>	385.00	
19	1	SPARE TYRE	\$	<i>nn</i>	330.00	

TOTAL	\$	2,049.02
TOTAL PARTS	\$	21,042.74

Putty And Spray Painting Of The Affected Portion.	\$	<i>2202</i> 3,000.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	<i>2009</i> 2,800.00
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 <i>609</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
Towing Fees	\$	<i>nn</i> 120.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-149**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5694D -

To transfer of rear windscreen fittings and
conduct water seepage test.

\$ *nn* 170.00 X

To check steering geometry and computer
wheel alignment

\$ *nn* 220.00 X**TOTAL \$ 7,540.00****Over All Total \$ 28,582.74****(PARTS BY PARTS)****Repair Days****~~10~~ Days***2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: