



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TP

Vehicle No. : SKP9753L

Make & Model : MAZDA 3 4 DR SDN 1.5L SP

Year of Manufacture : 2014

Chassis No. : JM6BM42A8F0150927

Ins Company : III VS FWD S'PORE P. L.

Engine No. : P520234829

Excess : -

Policy No. : -

Date of Accident : 10.12.2017

Time of Accident : 10:20

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimate

Case Owner : WILLIAM

Signature : _____

Parts (a) Cost / List Price Items \$ 1,311.50

Plus/Less 20% \$ 262.30

Total of Cost / List \$ 1,049.20

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ 1,049.20

Labour (Appendix B) \$ 1,470.00

Total Repair Cost \$ 2,519.20

Contact No
Frnt Counter Operation
 63837466 – Patrick Tia
 63837730 - Brenda Ng
 63837890 – Rohani
braddell_cr@sparkcarcare.com

Workshop Operation
 63837656 - Ngo Toh Wee
 63837362 -
 63838115 - William Wang
 63838115 - Andrew Goh
braddell_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	_____
Company	:	_____
Survey conducted on	:	_____ at _____
<u>Remarks By Surveyor</u>		
(a) The repair of this vehicle is authorized / is not authorized until further notice.		
(b) Recommended Days of Repair	:	_____ day(s)
(c) Resurvey	:	Required / Not Required
(d) Excess	:	\$ _____
(e) Signature of surveyor	:	_____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SKP9753L Case Owner : WILLIAM

Make & Model : MAZDA 3 4 DR SDN 1.5L S Year Manufacture : 2014

Chassis No : JM6BM42A8F0150927 Engine No : P520234829

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1		\$ 1,074.80			
2	Rear bumper splash shield RH	1		\$ 79.20			
3	Rear bumper splash shield rivet	4		\$ 14.00			
4	Rear bumper retainer LH	1		\$ 36.10			
5	Rear bumper retainer RH	1		\$ 36.10			
6	RH rear fender air grille	1		\$ 71.30			
7	0	1					
8	0	1					
9	0	1					
10	0	1					
11	0	1					
12	0	1					
13	0	1					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

