

Surveyor: Adrian ASSIGNMENT (Office):

From (Person): Grace Teo of SMO Date/Time: 12.40pm @ 20/12/17

Estimated Cost: _____ Bill to: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SFL 262 B Insured: SJM 4685K

at Workshop no: YSK Auto Workshop Tel: 9007 5148

of No. 1 Kaki Bukit Ave 6 # 01-71 Autobay, 417883

Policy No: _____ Claim No: CMTD1704596 / GPL

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A: 19/12/2017
(Client's Record)

CA / REV / REP. / REV 24 HRS (wp) H.O.D. Endorsement: _____

Date/Time: 2.10pm @ 20/12/17 Person Contacted: Ah Chai Vehicle: (IN) (U)

Date/Time	Action/Instruction (X) Estimate
	SFL 262 B - X
	SJM 4685K - CCA / AXA 13015078 / Uv 1y 3w2 D.O.A: 17/05/2013
21/12/17 @ 5.22pm	Informed Grace Teo, we are pending estimate from receiver.
04/1/18 @ 10.28am	visited to Gosh Pan Leong by email.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17024148/Aqd3

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 20-12-2017



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 4685K	Veh. Inspected	SFL 262B
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704596/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	20/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/12/2017	Inspection Date	
Survey held at	Y S K AUTO WORKSHOP 1 KAKI BUKIT AVE 6 AUTOBAY #01-71 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1704596/GPL

Date: 04th April 2018

Our Ref: CS/SMO17024148/Uqd3

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SFL 262B .


We thank you for the instruction on 20/12/2017.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/12/2017 at the premises of M/s YSK AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>9,689.21</u> .
Revised Estimate Amount	: S\$ <u>3,000.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 5 days.

We have NOT authorize repair.

Yours faithfully

Marcus Chua
Licensed Appraiser

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, 20 December, 2017 12:40 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: irene@centrollc.com.sg; Han, Bernard; Gnoh, Pau Loong; Chan, Shu Hui Agnes; Henry, Irene James
Subject: CMTD1704596/GPL - Accident invlg SJM4685K & SFL262B on 19.12.2017 - PRI
Attachments: PRI-Tenet -YSK.DOCX

Dear Sir/Madam,

Please make arrangement to conduct the survey for SFL262B.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: irene@centrollc.com.sg [mailto:irene@centrollc.com.sg]

Sent: Wednesday, December 20, 2017 11:29 AM

To: Teo, Grace

Cc: Han, Bernard; Gnoh, Pau Loong; Chan, Shu Hui Agnes; Henry, Irene James

Subject: CMTD1704596/GPL - Accident invlg SJM4685K & SFL262B on 19.12.2017 - PRI

Importance: High

WITHOUT PREJUDICE

Dear Sir/Madam,

We have selected Mr Mohd Rasul from LKK to do the PRI.

Kindly proceed.

Thank you.

Regards,

Irene Seow

Centro-Legal Law Corporation Advocates & Solicitors

151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel : 6235 0633
Fax : 6235 6939
Hp : 90301020

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Wednesday, 20 December 2017 11:25 AM

To: irene@centrollc.com.sg

Cc: Han, Bernard <Bernard.han@sompo.com.sg>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: CMTD1704596/GPL - Accident invlg SJM4685K & SFL262B on 19.12.2017 - PRI

Your Reference: CLLC.1355.2017

Our Reference: CMTD1704596/GPL

Without Prejudice

Date: 20th December 2017

Attention:

M/S CENTRO-LEGAL LAW CORPORATION

Accident invlg SJM4685K & SFL262B on 19.12.2017

Dear Irene,

We refer to your Notice of Accident dated 20/12/2017.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	

		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: irene@centrollc.com.sg [<mailto:irene@centrollc.com.sg>]

Sent: Wednesday, December 20, 2017 9:47 AM

To: Claims - Motor Survey

Cc: Han, Bernard

Subject: PRI

Importance: High

WITHOUT PREJUDICE

Dear Sir/Madam,

Kindly arrange your surveyor to do a PRI urgently.

Enclose is our document attached.

Thank you.

Regards,

Irene Seow

Centro-Legal Law Corporation Advocates & Solicitors

151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel : 6235 0633
Fax : 6235 6939
Hp : 90301020

151 Chin Swee Road

Singapore 169876

Tel: 6235 0633

Fax: 6235 6939

ADVOCATES AND SOLICITORS

Your ref : SJM4685K (To be advised)

Our ref : CLLC.1355.2017

20TH DECEMBER 2017

SOMPO INSURANCE PTE LTD
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623
Fax: 6221 3147

BY FAX & HAND

Attn: **Officer-In-Charge**

Dear Sirs,

**NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION
WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-
ACTION PROTOCOL FOR NIMA CASE**

We act for TING TSE XUAN SEAN, the owner of motor vehicle **SFL262B**, who has appointed us to act on his behalf to claim against your insured's vehicle no SJM4685K in regards to the road traffic accident on 19.12.2017.

Please be informed that the said motor vehicle can be inspected at:-

YSK AUTO WORKSHOP

No. 1 Kaki Bukit Ave 6
#01-71 AutoBay, Singapore 417883
Tel: 9007 5148 | Fax: 6556 0801
Email:dannyskyeo@gmail.com

Kindly contact **Ah Chai** h/p : 9007 5148

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or public Holiday, the said workshop will commence repairs thereafter without further reference to you.

1

Yours faithfully,

CENTRO-LEGAL LAW CORPORATION
Cc Ah Chai Fax: 6752 9868

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 4 April 2018 10:28 AM
To: 'Teo, Grace'; assignments; Gnoh, Pau Loong
Cc: 'Han, Bernard'; 'Chan, Shu Hui Agnes'; 'Henry, Irene James'; SUR
Subject: RE: CMTD1704596/GPL - Accident invlg SJM4685K & SFL262B on 19.12.2017 - PRI
Attachments: CSSMO17024148Uqd3.pdf

Dear Mr Gnoh,

Enclosed herewith preliminary advice of SFL 262B.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Friday, 22 December 2017 5:22 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Han, Bernard' <Bernard.han@sompo.com.sg>; 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1704596/GPL - Accident invlg SJM4685K & SFL262B on 19.12.2017 - PRI

Dear Grace,

Please be informed that we have inspected the vehicle SFL 262B on 21/12/2017.

We are pending for estimate from repairer.

Wishes you a Merry Christmas & Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 20 December, 2017 2:18 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Han, Bernard' <Bernard.han@sompo.com.sg>; 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1704596/GPL - Accident invlg SJM4685K & SFL262B on 19.12.2017 - PRI

Dear Sir/Mdm,

Thank you for the assignment.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 22 December, 2017 5:22 PM
To: 'Teo, Grace'; assignments
Cc: 'Han, Bernard'; 'Gnoh, Pau Loong'; 'Chan, Shu Hui Agnes'; 'Henry, Irene James'; SUR
Subject: RE: CMTD1704596/GPL - Accident invlg SJM4685K & SFL262B on 19.12.2017 - PRI

Dear Grace,

Please be informed that we have inspected the vehicle SFL 262B on 21/12/2017.

We are pending for estimate from repairer.

Wishes you a Merry Christmas & Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 20 December, 2017 2:18 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Han, Bernard' <Bernard.han@sompo.com.sg>; 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1704596/GPL - Accident invlg SJM4685K & SFL262B on 19.12.2017 - PRI

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Wednesday, 20 December, 2017 12:40 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: irene@centrollc.com.sg; Han, Bernard; Gnoh, Pau Loong; Chan, Shu Hui Agnes; Henry, Irene James
Subject: CMTD1704596/GPL - Accident invlg SJM4685K & SFL262B on 19.12.2017 - PRI

Dear Sir/Madam,

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1068A
Vehicle Details	
Vehicle No.:	SFL262B
Vehicle to be Exported:	Yes
Intended De-registration Date:	26 Mar 2018
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT 1.6 MT
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	M16A1379004
Chassis No.:	JSAEZC31S00201909
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$12,448.00
Original Registration Date:	23 May 2008
First Registration Date:	23 May 2008
Transfer Count:	2
Actual ARF Paid:	\$12,448.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 May 2018
PARF Rebate Amount:	\$6,224.00
Intended COE Rebate Details	
COE Expiry Date:	22 May 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$11,009.00
COE Rebate Amount:	\$169.00
Total Rebate Amount:	\$6,393.00

The information contained herein is correct as at 26 Mar 2018

OK



Posted: 14-Feb-2018 Tags: 2008 Suzuki Swift, Suzuki Swift, Suzuki, Swift, Used Suzuki



Suzuki Swift 1.3M XG (New 5-yr COE) \$28,888 \$5,770 /yr 14-Apr-2008 1,328 cc 107,862 km Hatchback Available

A Deal Not To Be Missed! Low Mileage Clocked Car! Well Maintained And Timed Serviced By Ex Owner, Car In Very Good Condition, No Repairs Needed. Trade In Welcomed, Bank And In House Loan Provided, Hig...

PREMIUM ED

Posted: 10-Mar-2018 Tags: 2008 Suzuki Swift, Suzuki Swift, Suzuki, Swift, Used Suzuki



Suzuki Swift 1.5A (New 5-yr COE) \$31,800 \$6,360 /yr 18-Apr-2008 1,490 cc - Hatchback Available

1 Owner, Low Down Payment, Cheapest In The Market, New Arrival! Bank Or In House Loan Available, Trade In Welcome, Most Popular Suzuki Hatchback For Your Family And Daily Usage, Very Clean Interior An...

Posted: 24-Mar-2018 Tags: 2008 Suzuki Swift, Suzuki Swift, Suzuki, Swift, Used Suzuki



Suzuki Swift 1.2A XG (New 5-yr COE) \$28,800 \$5,760 /yr 28-Apr-2008 1,242 cc 131,532 km Hatchback Available

New 5 Years COE! 1 Owner Only! Low Mileage! No Repairs Needed! All Trade In Welcome, Major Bank And In House Loan Available! Night And Door Step Viewing Available! Hurry Call Our Friendly Staff To Vie...

Posted: 23-Mar-2018 Tags: 2008 Suzuki Swift, Suzuki Swift, Suzuki, Swift, Used Suzuki



Insurance renewal at cheaper price!

We'll find you the cheapest car insurance quotes from over 10 insurers. Make your choice on zero excess and own workshop. Everything done at the comfort of your own home. Roadside assistance & claims support completely free.

Find out more!



Suzuki Swift 1.2A XG \$9,800 N.A 28-Apr-2008 1,242 cc - Hatchback Available

\$0 Downpayment Available! 1 Owner Only! Extended Warranty Available! Very Affordable Road Tax / Insurance! Well Kept By Previous Owner, In Excellent Condition, See It For Yourself To Believe! Buy It Fr...

Dickson Automobile

Posted: 03-Feb-2018 Tags: 2008 Suzuki Swift, Suzuki Swift, Suzuki, Swift, Used Suzuki



Suzuki Swift Sport 1.6A (New 5-yr COE) \$34,800 \$6,960 /yr 09-May-2008 1,586 cc 135,000 km Hatchback Available

One Year In House Warranty! Purchase With Official Warranty Certificate With Peace Of Mind, Our Company Renew COE Cars For Sale Base On Car Conditions Not On Ownership, Fully Refurbished, New Paintwor...

Carway

Posted: 22-Mar-2018 Tags: 2008 Suzuki Swift, Suzuki Swift, Suzuki, Swift, Used Suzuki



Suzuki Swift 1.2A XG (New 5-yr COE) \$29,800 \$5,960 /yr 10-May-2008 1,242 cc 50,000 km Hatchback Available

Posted: 05-Mar-2018 Tags: 2008 Suzuki Swift, Suzuki Swift, Suzuki, Swift, Used Suzuki



Suzuki Swift 1.5A (New 5-yr COE) (OPC) \$32,000 \$6,400 /yr 28-May-2008 1,490 cc 89,000 km Hatchback Available

Look No Further, Best Condition, View To Believe, Low 89k Km Mileage And Low Depreciation, Definitely Not To Be Missed, Call Us Now. Quality Car You Can Trust Only At Choon Bee.

Posted: 19-Mar-2018 Tags: 2008 Suzuki Swift, Suzuki Swift, Suzuki, Swift, Used Suzuki



Suzuki Swift 1.2A XG (New 5-yr COE) \$28,555 \$5,710 /yr 05-Jun-2008 1,242 cc 156,000 km Hatchback Available

Lowest Depreciation In Market. Regularly Service/Maintain By Previous Owner, 4 x Almost New Tyres, Pristine Condition, No Repairs Needed, Flawless Exterior And Clean Interior, Accident Free, Viewing K...

Posted: 09-Mar-2018 Tags: 2008 Suzuki Swift, Suzuki Swift, Suzuki, Swift, Used Suzuki



Suzuki Swift Sport 1.6M (New 5-yr COE) \$34,800 \$6,960 /yr 05-Jun-2008 1,586 cc 120,000 km Hatchback Available

Low Down Payment! Flexible Repayment With In House Financing. Our Vehicle Inspected By Professional Team For Highest Quality. Owning A Car Is So Much Easier With Us. View To Believe. Call Us Now

Posted: 06-Mar-2018 Tags: 2008 Suzuki Swift, Suzuki Swift, Suzuki, Swift, Used Suzuki

Suzuki Swift Sport 1.6A (New 5-yr COE) \$33,800 \$6,760 /yr 24-Jun-2008 1,586 cc - Hatchback Available

Up To 90% Loan! Flexible Repayment With In House Financing. Our Vehicle Inspected By Professional Team For Highest Quality. Owning A Car Is So Much Easier With Us. View To Believe. Call Us Now!

PREMIUM ED

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/12/2017 17:05
Date Of Accident	19/12/2017 09:15
Exact Location Of Accident	ALONG SERANGOON RD TOWARDS UPPER SERANGOON RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFL262B
Insured/Policyholder	
Name Of Registered Owner	TING TSE XUAN SEAN
NRIC No	S9051068A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93631794
Alternative Phone No	OFFICE-93631794

Vehicle Particulars

Manufacturer	SUZUKI
Model	SWIFT 1.6 MT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093372256
Cover Note Number	

Driver

Name of Driver	TING TSE XUAN SEAN
NRIC No	S9051068A
Date Of Birth	16/12/1990
Occupation	INDOOR
Date Of Driving Pass	30/09/2009
Driving Experience	8 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93631794
Fax Number	
Contact Number	OFFICE-93631794
Email Address	NOEMAIL

Email Address

DETAILS OF INJURED PERSON 1

Name	TING TSE XUAN SEAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SFL262B
Were seat belts worn?	YES
Was injured conveyed to hospital by ambulance?	NO
Address	22 MAR THOMA ROAD #08-03
Postcode	328702

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer

To

Police

Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRC/FIN No.:

ACCIDENT STATEMENT

Road traffic accident
along upper Seangrou road

Vehicle SSM 4685K, driver
Mandy Mok wen qi S9122059H,

Hit vehicle SFL262B, driver
Ting Tse Xuan, Sean.

Driver S9122059H
Mandy Mok
Mandy Mok

Driver S9051088A
Sean Ting
Sean

~~Driver S9122059~~





**SINGAPORE
POLICE FORCE**



T/20171219/2081

1 of 3

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

Report No. T/20171219/2081

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/12/2017 15:09		Vide Report No.:		Station Diary No.: 35	
Informant's Particulars					
Name of Informant: TING TSE XUAN, SEAN			Address: 22 MAR THOMA ROAD #08-03 SINGAPORE 328702		
ID Type / ID No.: NRIC NO / S9051068A			Contact No.:		Mobile: 93631794
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 27	Date of Birth: 16/12/1990	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: PHARMACEUTICAL SALES			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 19/12/2017 09:15	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 SERANGOON ROAD UPPER SERANGOON ROAD BEFORE PAN ISLAND EXPRESSWAY ENTRANCE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFL262B	Car	SUZUKI	SWIFT 1.6 MT	Black	Slightly Damaged	0
SJM4685K	Car				Slightly Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SFL262B	NTUC Income Insurance Co-Operative Limited	5093372256	12/08/2017	22/05/2018



**SINGAPORE
POLICE FORCE**



T/20171219/2081

2 of 3

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

Report No. T/20171219/2081

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TING TSE XUAN, SEAN	ID No.	S9051068A
Related Vehicle	SFL262B (Car)	Contact No.	93631794
Hospital/Clinic	WONG CLINIC	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	19/12/2017	Date Discharge	19/12/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the 19/12/2017 at about 0917hrs, I was travelling along Serangoon Rd towards Upper Serangoon Rd, before the Pan Island Expressway (PIE) Entrance. I was driving in vehicle SFL262B (Black Suzuki Swift Sport). My vehicle was stationary along the road due to heavy traffic when I felt an impact from the rear of my vehicle.

I immediately went out of my vehicle to check what had happened and realized a vehicle bearing plate number SJM4685K (Black Mazda 6) had hit my vehicle's rear. The impact had caused the rear part of my vehicle to be dented.

I went to exchange particulars with the driver of the said vehicle and took photos of the damages. Both of us agreed to settle the issue with our respective insurance companies. After the accident, I also went to the clinic for a checkup as I experienced some discomfort at my back area due to the impact. The doctor diagnosed me with having Backache and certified me as unfit for work for 3 days from 19/12/2017 to 19/12/2017. I also received some medications for it.

I also wish to state that I have a front facing in-vehicle camera.



SINGAPORE
POLICE FORCE



T/20171219/2081

Police Station Of Origin:
Bedok South N.P.C
20 Chai Chee Drive SINGAPORE 469045
Tel No: 1800-2448999

3 of 3

Report No. T/20171219/2081

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: 
G /
Staff Sgt MUHAMMAD HAFIZ BIN ABDUL RAZAK

Signature Of Informant:


Signature Of Interpreter:
Not applicable

Date/Time:
19/12/2017 15:09

Officer In Charge Of Case:
TP / AEIT /
SIANG YI TING, STEPHANIE
Conf No: SINGAPORE 6414
POLICE FORCE

Classification Of Case:

Authentication Stamp
NF 168

SIGNATURE

KINGCRIMSON MARKETING PTE LTD
NO. 4 LENG KEE ROAD #04-03A
SIS BUILDING, SINGAPORE 159088
TEL: 6299 1269 / 6299 9239
EMAIL: kingcrim@singnet.com.sg

DUPLICATE

2

Jan

EG-GENEHMIGUNG

EEC Type-Approval certificate / homologation CEE
für / for / pour

REMUS

SPORTEXHAUST

Genehmigungsnummer:
Approval number /
Numéro d'homologation:

e4*81/334*1999/101*2165*00 *3rd owner*

Genehmigungszeichen:
Approval sign /
signe d'homologation

e4 032165

Schalldämpfertyp:
silencer type / silencieux type

1357

Hersteller:
Manufacturer/
fabricant

REMUS Innovation Forschungs-
und Abgasanlagen
Produktionsgesellschaft mbH
Dr.-Niederdorfer-Straße 25
A-8572 Bärnbach

VICOM
YISHUN
VIR 20170105X92

OWNER'S PARTICULARS	
Name:	VISHNU CHANDRAN
I. C. No:	S 917 4177 F
Vehicle No:	SFL 262 B
Date of Installation:	04.10.16
Warranty Card No:	4817

Bitte führen Sie die Genehmigung mit den Fahrzeugpapieren mit.
Please carry the approval along with the vehicle documents.
SVP conserver ce document avec les papiers du véhicule.

03 JAN 2017

Nachdruck und jegliche Vervielfältigung dieser EG-Genehmigung, auch auszugsweise, sind untersagt. Zuwiderhandlungen werden gerichtlich verfolgt.
Any reprint or copying of this EC approval, even in extracts, are prohibited. Infringements will be prosecuted.
Toute reproduction ou copie de cette homologation CEE, complète ou partielle sont interdites. Toute infraction sera sanctionnée.

EINBAUANWEISUNG FÜR REMUS-ABGASANLAGEN
INSTRUCTIONS FOR INSTALLATION OF REMUS EXHAUST SYSTEMS
INSTRUCTIONS DE MONTAGE DES ÉCHAPPEMENTS REMUS

1. **Auszutauschende Serienteile demontieren.** / Dismount the exchangeable original equipment parts. / Démontez les parties à changer
2. **Dichtungssitze reinigen.** / Clean flange and sleeve contact areas. / Nettoyer la zone d'attachement pour une meilleure connexion
3. **Schadhafte Befestigungsteile sowie Dichtungen erneuern.** / Renew defective or worn attachment parts. / Remplacer les attaches ou silentblochs défectueux, ainsi que les joints
4. **Wenn erforderlich, Originalschalldämpfer gemäß Beschnittanleitung trennen.** / If necessary, detach the original silencer by cutting according to the instructions. / Si nécessaire, retirer le silencieux d'origine conformément aux instructions
5. **REMUS-Schalldämpfer in den dafür vorgesehenen Originalbefestigungspunkten mit den serienmäßigen Befestigungsteilen montieren.** / Install the REMUS silencer at the assigned original attachment links with the standard attachment parts. / Installer le silencieux dans les silentblochs d'origine, neufs ou en très bon état avec les fixations standard
6. **Klemm- oder Schraubverbindungen locker vorziehen. Achten Sie dabei darauf, daß bei einer Klemmverbindung die Klemmschelle nur ca. 5mm vom Anfang des geschlitzten Teiles montiert ist.** / When fitting, pre-tighten sleeve and U-clamp connections loosely. Take care to place sleeve clamps only about 5 mm from the beginning of the slotted sleeve. / Serrer et desserrer les joints de compression ou les vis de serrage. S'assurer que le collier de serrage du joint de compression est fixé à seulement 5 mm environ du début de la partie rainurée.
7. **REMUS-Schalldämpfer so einrichten, daß das (die) Endrohr(e) waagrecht liegt(en).** / Install the REMUS silencer so that the tail-pipe(s) is/are horizontally level. / Positionner le silencieux REMUS de telle sorte que l'échappement soit en position horizontale et ne soit pas trop proche de certaines parties du châssis ou de la carrosserie
8. **Alle Klemm- oder Schraubverbindungen festziehen.** / Tighten all sleeve and flange joints. / Dans le cas de montage d'une ligne complète ou d'un ensemble de silencieux, il faut d'abord monter toutes les pièces sans les serrer, afin de leur faire prendre leur place, ensuite seulement serrer tous les joints de compression avec les vis, boulon, écrous.
9. **Motor kurz anlassen und den kompletten REMUS-Schalldämpfer auf Dichtheit überprüfen. Achten Sie dabei darauf, daß der Montageaum ausreichend belüftet ist.** / Start the engine to check the entire REMUS system for leaks. Please take care to assure sufficient ventilation. / Faire tourner le moteur un bref instant et contrôler tous les joints, les fixations et resserrer les vis de serrage
10. **Nach ca. 500 km alle Befestigungspunkte bzw. Befestigungselemente auf deren Funktionstüchtigkeit überprüfen. Befestigungsschrauben nachziehen.** / Re-check all components and fitting elements after about 500 km (300 miles). Re-tighten clamps and screws as required. / Au bout de 500 km environ contrôler tous les joints des fixations et resserrer les vis de serrage
11. **Die Innenrohre der(s) Endrohre(s) sind aus hochwertigem rost- und säurebeständigem Edelstahl. Diverse Rückstände auf den Innenrohren können jedoch zu Flugrostbildung führen. Diese Ablage ist aus optischen Gründen mit einer Bürste oder dergleichen zu entfernen. Gelegentliches Ölen der Innenrohre ist von Vorteil.** / The inner pipes and tailpipe(s) are constructed from high-grade rust-and acid-proof steel. Residual deposits can, however, lead to the formation of a thick rust film. For optical reasons these deposits should be removed with a brush or similar device. The occasional oiling of the components is recommended. / Les tubes à l'intérieur de l'échappement sont en acier inoxydable de premier choix résistant aux acides. Quelques résidus peuvent toutefois former une fine couche de rouille sur les tubes intérieurs. Pour les garder nets, enlevez le dépôt avec une goupillon ou quelque chose de similaire. Il est utile de graisser de temps en temps les tubes intérieurs.
12. **Um das gepflegte Aussehen der rostfreien sowie verchromten Edelstahlendrohre auf Dauer zu gewährleisten, ist eine einfache Reinigung notwendig. Vor allem Salzablagerungen müssen umgehend mit Wasser entfernt werden.** / To keep the shiny appearance of the Stainless Steel and chromed parts, periodic cleaning must be carried out. Please ensure that road salt is removed as soon as possible using water. / Pour conserver l'éclat des sorties en acier inoxydable et des sorties chromées, il suffit d'effectuer un simple nettoyage régulier. En cas de dépôts de sel, ceux-ci doivent être nettoyés à l'eau rapidement
13. **Paßt die Endrohr-Position bzw. Verdrehung nicht optimal, sollten Sie versuchen, den Original-Vorschalldämpfer bzw. das Original-Verbindungsrohr zu lockern, um die gesamte Schalldämpferanlage einrichten zu können.** / If the position of the tail pipe(s) does not fit optimal, you should try to loose the original front silencer or the original connecting pipe, so you can fit the complete exhaust system. / Si la position de la sortie(s) n'est pas optimale, vous devriez essayer de desserrer le silencieux primaire d'origine ou le tube de connexion d'origine ainsi vous pouvez repositionner l'ensemble de l'échappement correctement.

Viel Spaß mit unserem Qualitätsprodukt wünscht Ihnen Ihr REMUS-Team
Enjoy your high quality product! Your REMUS-Team
Passez du bon temps avec votre produit de qualité! Votre équipe REMUS

ESTIMATE

YSK AUTO WORKSHOP

NO. 1 KAKI BUKIT AVENUE 6, #01-49 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

Date: 21/12/2017

TP Sampo
Xiao Chen

Not Allowed
after
1/5 ~~3000~~ / 2
5 day.
21/12/18

Vehicle Number: ~~SFL 262B~~

SFL 262B

Chassis Number: JSAE3C31S00201909

S/No.	Descriptions	Qty	Unit Price	Amount
1	Tail gate	1	\$632.50	\$632.50 X
2	Tail gate trimboard	1	\$185.00	\$185.00 X
3	Tail gate trimboard clip	10	\$3.90	\$39.00 X
4	Tail gate weatherstrip	1	\$93.25	\$93.25 X
5	Tail gate damper	2	\$121.55	\$243.10 X
6	Tail gate switch	1	\$54.40	\$54.40 X
7	Tail gate switch cover	1	\$69.96	\$69.96 X
8	Tail gate lock	1	\$181.50	\$181.50 X
9	Tail gate striker	1	\$17.16	\$17.16 X
10	Rear bumper	1	\$504.00	\$504.00 //
11	Rear bumper bracket RH	1	\$35.00	\$35.00 //
12	Rear bumper bracket LH	1	\$35.00	\$35.00 //
13	Rear bumper side retainer RH	1	\$26.00	\$26.00 //
14	Rear bumper side retainer LH	1	\$26.00	\$26.00 //
15	Rear bumper clip	1	\$3.90	\$3.90 //
16	Rear bumper grille	1	\$411.00	\$411.00 //
17	Reverse lamp	2	\$55.00	\$110.00 X
18	Tail lamp RH	1	\$263.00	\$263.00 //
19	Tail lamp LH	1	\$263.00	\$263.00 //
20	Tail lamp panel RH	1	\$73.81	\$73.81 X
21	Tail lamp panel LH	1	\$73.81	\$73.81 X
22	Tail lamp lower bracket RH	1	\$22.00	\$22.00 X
23	Tail lamp lower bracket LH	1	\$22.00	\$22.00 X
24	Rear number plate lamp (set)	1	\$58.00	\$58.00 X
25	Rear fender inner trim RH	1	\$109.00	\$109.00 X
26	Rear fender inner trim LH	1	\$109.00	\$109.00 X
27	Air vent	1	\$58.00	\$58.00 X
28	Rear end panel	1	\$276.95	\$276.95 //
29	Rear end panel garnish	1	\$83.27	\$83.27 //
30	Rear end panel garnish clip	8	\$3.90	\$31.20 X
31	Tow hook cover	1	\$22.00	\$22.00 X
32	Spare tyre panel	1	\$386.10	\$386.10 X
33	Spare tyre board	1	\$138.77	\$138.77 X
34	Rear windscreen	1	\$589.45	\$589.45 X
				\$5,246.13
Less 15%				\$786.92
Sub Total 1				\$4,459.21

S/Nett	Descriptions	Qty	Unit Price	Amount
1	Reverse sensor (set)	1	\$260.00	\$260.00 200
2	Sealant <i>end panel</i>	1	\$80.00	\$80.00 50
3	Rear number plate	1	\$35.00	\$35.00 20
4	Rear number plate casing	1	\$35.00	\$35.00 X
5	Exhaust silencer	1	\$1,500.00	\$1,500.00 X
Sub Total 2				\$1,910.00

Labour	Descriptions	Amount
1	Re-wiring	\$120.00 30
2	Panel beating to remove and replace, to knock and reshape damaged parts.	\$1,200.00 800

1927.12
1638.25

S/No.	Descriptions	Qty	Unit Price	Amount
3	To putty and spray paint the repaired and replaced parts, cleaning and sanding of surfaces, final polishing and waxing.			\$1,200.00 800
4	Anti-rust undercoat.			\$150.00 50
5	Remove and refit rear seats, floor carpet & upholstery to facilitate repairs.			\$280.00 80
6	Remove and replace rear windscreen glass.			11 \$120.00 X
7	Remove and replace rear exhaust silencer.			\$250.00 100
			Labour	\$3,320.00
			TOTAL	\$9,689.21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature: _____
 Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17024148/Uqd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 05-04-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 4685K	Veh. Inspected	SFL 262B
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704596/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	20/12/2017

2. Vehicle Particulars & Condition

Make & Model	SUZUKI SWIFT (M)	c.c	1586
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JSAEZC31S00201909	Colour	BLACK
Odometer	172580	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/45 ZR16	PIRELLI	6 mm
L/H Front Tyre	205/45 ZR16	PIRELLI	6 mm
R/H Rear Tyre	205/45 ZR16	PIRELLI	6 mm
L/H Rear Tyre	205/45 ZR16	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/12/2017	Inspection Date	21/12/2017
Survey held at	Y S K AUTO WORKSHOP 1 KAKI BUKIT AVE 6 AUTOBAY #01-71 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFL 262B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE	NOT NECESSARY	632.50	-
1	TAIL GATE TRIMBOARD	NOT NECESSARY	185.00	-
10	TAIL GATE TRIMBOARD CLIP @\$3.90	NOT NECESSARY	39.00	-
1	TAIL GATE WEATHERSTRIP	NOT NECESSARY	93.25	-
2	TAIL GATE DAMPER @\$121.55	NOT NECESSARY	243.10	-
1	TAIL GATE SWITCH	NOT NECESSARY	54.40	-
1	TAIL GATE SWITCH COVER	NOT NECESSARY	69.96	-
1	TAIL GATE LOCK	NOT NECESSARY	181.50	-
1	TAIL GATE STRIKER	NOT NECESSARY	17.16	-
1	REAR BUMPER	DENTED / DEFORMED	504.00	504.00
1	REAR BUMPER BRACKET RH	TWISTED	35.00	35.00
1	REAR BUMPER BRACKET LH	TWISTED	35.00	35.00
1	REAR BUMPER SIDE RETAINER RH	BENT	26.00	26.00
1	REAR BUMPER SIDE RETAINER LH	BENT	26.00	26.00
1	REAR BUMPER CLIP	NECESSARY	3.90	3.90
1	REAR BUMPER GRILLE	CRACKED	411.00	411.00
2	REVERSE LAMP @\$55.00	NOT NECESSARY	110.00	-
1	TAIL LAMP RH	CRACKED	263.00	263.00
1	TAIL LAMP LH	CRACKED	263.00	263.00
1	TAIL LAMP PANEL RH	NOT NECESSARY	73.81	-
1	TAIL LAMP PANEL LH	NOT NECESSARY	73.81	-
1	TAIL LAMP LOWER BRACKET RH	NOT NECESSARY	22.00	-
1	TAIL LAMP LOWER BRACKET LH	NOT NECESSARY	22.00	-
1	SET REAR NUMBER PLATE LAMP	NOT NECESSARY	58.00	-
1	REAR FENDER INNER TRIM RH	NOT NECESSARY	109.00	-
1	REAR FENDER INNER TRIM LH	NOT NECESSARY	109.00	-
1	AIR VENT	NOT NECESSARY	58.00	-
1	REAR END PANEL	DENTED / BENT	276.95	276.95
1	REAR END PANEL GARNISH	TWISTED	83.27	83.27
8	REAR END PANEL GARNISH CLIP @\$3.90	NOT NECESSARY	31.20	-
1	TOW HOOK COVER	NOT NECESSARY	22.00	-
1	SPARE TYRE PANEL	NOT NECESSARY	386.10	-
1	SPARE TYRE BOARD	NOT NECESSARY	138.77	-

Report Ref No. CS/SMO17024148/Uqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN LESS 15% DISCOUNT	NOT NECESSARY	589.45 -786.92	- -289.07
			4,459.21	1,638.05
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSOR (SN)	SHORTED	260.00	200.00
1	SEALANT END PANEL (SN)	NECESSARY	80.00	50.00
1	REAR NUMBER PLATE (SN)	CRACKED	35.00	20.00
1	REAR NUMBER PLATE CASING (SN)	NOT NECESSARY	35.00	-
1	EXHAUST SILENCER (SN)	TO REPAIR SEE LABOUR	1,500.00	-
			1,910.00	270.00
	<u>LABOUR</u>			
	RE-WIRING.		120.00	30.00
	PANEL BEATING TO REMOVE AND REPLACE, TO KNOCK AND RESHAPE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF EXHAUST SILENCER.		1,200.00	800.00
	TO PUTTY AND SPRAY PAINT THE REPAIRED AND REPLACED PARTS, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING.		1,200.00	800.00
	ANTI-RUST UNDERCOAT.		150.00	50.00
	REMOVE AND REFIT REAR SEATS, FLOOR CARPET & UPHOLSTERY TO FACILITATE REPAIRS.		280.00	80.00
	REMOVE AND REPLACE REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE AND REPLACE REAR EXHAUST SILENCER.		250.00	100.00
			3,320.00	1,860.00
	GRAND TOTAL		9,689.21	3,768.05
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00

Report Ref No. CS/SMO17024148/Uqd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.